Office District I – (575) 393-6161		New Mexico	Form C-103		
	Energy, Minerals	and Natural Resources	Revised August 1, 2011		
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283			WELL API NO.		
811 S. First St., Artesia, NM 88210		ATION DIVISION	30-025-30006 5. Indicate Type of Lease		
<u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410		St. Francis Dr.	STATE S FEE		
District IV - (505) 476-3460	Santa Fe	e, NM 87505	6. State Oil & Gas Lease No.		
1220 S. St. Francis Dr., Santa Fe, NM 87505			313857		
	ICES AND REPORTS ON	N WELLS	7. Lease Name or Unit Agreement Name		
(DO NOT USE THIS FORM FOR PROPO		CO ION FOR GUOW	WEST DOLLARHIDE QUEEN SAND		
DIFFERENT RESERVOIR. USE "APPL PROPOSALS.)	ICATION FOR PERMIT" (FORM	W C-101 FOR SUCH	UNIT		
1. Type of Well: Oil Well	Gas Well Other	"OBBS	8. Well Number 82		
		Ca CO	6. Well Number 62		
2. Name of Operator RAM ENERGY LLC		SEP 0 4 2019	9. OGRID Number 309777		
3. Address of Operator		Pr- 20/9	10. Pool name or Wildcat		
2100 S. UTICA AVE., SUITE	175, TULSA, OK 74114	RECEIVED	DOLLARHIDE QUEEN (018810).		
4. Well Location		-, AED			
Unit LetterD_	_330feet from theNo	ORTH line and1	150feet from theWESTline		
Section 32	Township	24S Range 38E	NMPM LEA County		
	1	ether DR, RKB, RT, GR, etc.,			
	3192	2' KB			
12 Charle	Ammonmisto Dou to Inc	dianta Natana a Chiatian	Descent on Other Date		
12. Check	Appropriate Box to inc	dicate Nature of Notice,	Report of Other Data		
NOTICE OF IN	NTENTION TO:	J Y SUB	SEQUENT REPORT OF:		
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WOR			
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRI	LLING OPNS. P AND A		
PULL OR ALTER CASING	MULTIPLE COMPL	☐ CASING/CEMEN	T JOB		
DOWNHOLE COMMINGLE					
OTHER:		□ OTHER:	П		
	alated exertions (Clearly		d give pertinent dates, including estimated date		
13. Describe proposed of comp	neted operations. (Clearly		a give pertinent dates, meruding estimated date		
of starting any proposed w	ork). SEE RULE 19.15.7.1		inpletions: Attach wellbore diagram of		
	ork). SEE RULE 19.15.7.1				
of starting any proposed w proposed completion or rec	ork). SEE RULE 19.15.7.1 completion.				
of starting any proposed w proposed completion or reconstruction. 1. NOTIFY NMOCD 24 HRS	ork). SEE RULE 19.15.7.1 completion. S. BEFORE MIRU.				
of starting any proposed w proposed completion or rec 1. NOTIFY NMOCD 24 HRS 2. MIRU. ND WH, NU BOP	ork). SEE RULE 19.15.7.1 completion. S. BEFORE MIRU. E.	14 NMAC. For Multiple Cor	mpletions: Attach wellbore diagram of		
of starting any proposed w proposed completion or rec 1. NOTIFY NMOCD 24 HR: 2. MIRU. ND WH, NU BOP: 3. SET CIBP@3600' AND S 4. CIRCULATE 9.5 PPG MI	ork). SEE RULE 19.15.7.1 completion. S. BEFORE MIRU. E. POT 25SX OF CLASS "C" JF AND TEST CASING.	14 NMAC. For Multiple Cor	mpletions: Attach wellbore diagram of		
of starting any proposed w proposed completion or reconstruction. NOTIFY NMOCD 24 HR3 MIRU. ND WH, NU BOP. SET CIBP@3600' AND S CIRCULATE 9.5 PPG MI. SPOT 40SX OF CLASS "6	ork). SEE RULE 19.15.7.1 completion. S. BEFORE MIRU. E. POT 25SX OF CLASS "C" JF AND TEST CASING. C" CEMENT FROM 2800	14 NMAC. For Multiple Cor "CEMENT FROM 3600'-33" "-2468'. WOC&TAG. (YAT)	mpletions: Attach wellbore diagram of 350'. (PERFS) ES/B.SALT)		
of starting any proposed w proposed completion or reconstruction. NOTIFY NMOCD 24 HRS MIRU. ND WH, NU BOP. SET CIBP@3600' AND S CIRCULATE 9.5 PPG MI. SPOT 40SX OF CLASS "66. SPOT 25SX OF CLASS "67.	ork). SEE RULE 19.15.7.1 completion. S. BEFORE MIRU. E. POT 25SX OF CLASS "C" JF AND TEST CASING. C" CEMENT FROM 2800" C" CEMENT FROM 1306"	14 NMAC. For Multiple Cor "CEMENT FROM 3600'-33" '-2468'. WOC&TAG. (YAT) '-1156'. WOC&TAG. (T.SA	mpletions: Attach wellbore diagram of 350'. (PERFS) ES/B.SALT) LT)		
of starting any proposed w proposed completion or recompletion or recompletion or recompletion or recompletion or recompletion of recompletion	ork). SEE RULE 19.15.7.1 completion. S. BEFORE MIRU. E. POT 25SX OF CLASS "C" LF AND TEST CASING. C" CEMENT FROM 2800" C" CEMENT FROM 1306" C" CEMENT FROM 450'-	14 NMAC. For Multiple Cor "CEMENT FROM 3600'-33 '-2468'. WOC&TAG. (YAT) '-1156'. WOC&TAG. (T.SA SURFACE. VERIFY CEME	npletions: Attach wellbore diagram of 350°. (PERFS) ES/B.SALT) LT) ENT TO SURFACE. (FW/SHOE/SURFACE).		
of starting any proposed w proposed completion or recompletion or recompletion or recompletion or recompletion or recompletion of recompletion	ork). SEE RULE 19.15.7.1 completion. S. BEFORE MIRU. E. POT 25SX OF CLASS "C" LF AND TEST CASING. C" CEMENT FROM 2800" C" CEMENT FROM 1306" C" CEMENT FROM 450'-	14 NMAC. For Multiple Cor "CEMENT FROM 3600'-33 '-2468'. WOC&TAG. (YAT) '-1156'. WOC&TAG. (T.SA SURFACE. VERIFY CEME	mpletions: Attach wellbore diagram of 350'. (PERFS) ES/B.SALT) LT)		
of starting any proposed w proposed completion or recompletion or recompletion or recompletion or recompletion or recompletion or recompletion of recompletion	ork). SEE RULE 19.15.7.1 completion. S. BEFORE MIRU. E. POT 25SX OF CLASS "C" LF AND TEST CASING. C" CEMENT FROM 2800' C" CEMENT FROM 1306' C" CEMENT FROM 450'- NCHORS 3' BELOW SUI	14 NMAC. For Multiple Cor "CEMENT FROM 3600'-33 '-2468'. WOC&TAG. (YAT) '-1156'. WOC&TAG. (T.SA SURFACE. VERIFY CEME RFACE AND INSTALL DR	npletions: Attach wellbore diagram of 350'. (PERFS) ES/B.SALT) LT) ENT TO SURFACE. (FW/SHOE/SURFACE). YHOLE MARKER. TURN OVER FOR		
of starting any proposed w proposed completion or recompletion or recompletion or recompletion or recompletion or recompletion or recompletion. NOTIFY NMOCD 24 HR. 2. MIRU. ND WH, NU BOP. 3. SET CIBP@3600' AND S. CIRCULATE 9.5 PPG MI. 5. SPOT 40SX OF CLASS "6. SPOT 25SX OF CLASS "6. SPOT 50SX OF CLASS "6. CUTOFF WELLHEAD, A.	ork). SEE RULE 19.15.7.1 completion. S. BEFORE MIRU. E. POT 25SX OF CLASS "C" LF AND TEST CASING. C" CEMENT FROM 2800' C" CEMENT FROM 1306' C" CEMENT FROM 450'- NCHORS 3' BELOW SUI	14 NMAC. For Multiple Cor "CEMENT FROM 3600'-33 '-2468'. WOC&TAG. (YAT) '-1156'. WOC&TAG. (T.SA SURFACE. VERIFY CEME RFACE AND INSTALL DR	mpletions: Attach wellbore diagram of 350'. (PERFS) ES/B.SALT) LT) ENT TO SURFACE. (FW/SHOE/SURFACE). YHOLE MARKER. TURN OVER FOR		
of starting any proposed w proposed completion or recompletion or recompletion or recompletion or recompletion or recompletion or recompletion of recompletion	ork). SEE RULE 19.15.7.1 completion. S. BEFORE MIRU. E. POT 25SX OF CLASS "C" LF AND TEST CASING. C" CEMENT FROM 2800' C" CEMENT FROM 1306' C" CEMENT FROM 450'- NCHORS 3' BELOW SUI	14 NMAC. For Multiple Cor "CEMENT FROM 3600'-33 '-2468'. WOC&TAG. (YAT) '-1156'. WOC&TAG. (T.SA SURFACE. VERIFY CEME RFACE AND INSTALL DR	mpletions: Attach wellbore diagram of 350'. (PERFS) ES/B.SALT) LT) ENT TO SURFACE. (FW/SHOE/SURFACE). YHOLE MARKER. TURN OVER FOR		
of starting any proposed w proposed completion or recompletion or recompletion or recompletion or recompletion or recompletion or recompletion of recompletion	ork). SEE RULE 19.15.7.1 completion. S. BEFORE MIRU. E. POT 25SX OF CLASS "C" LF AND TEST CASING. C" CEMENT FROM 2800' C" CEMENT FROM 1306' C" CEMENT FROM 450'- NCHORS 3' BELOW SUI	14 NMAC. For Multiple Cor "CEMENT FROM 3600'-33 '-2468'. WOC&TAG. (YAT) '-1156'. WOC&TAG. (T.SA SURFACE. VERIFY CEME RFACE AND INSTALL DR	mpletions: Attach wellbore diagram of 350'. (PERFS) ES/B.SALT) LT) ENT TO SURFACE. (FW/SHOE/SURFACE). YHOLE MARKER. TURN OVER FOR		
of starting any proposed w proposed completion or recompletion	ork). SEE RULE 19.15.7.1 completion. S. BEFORE MIRU. E. POT 25SX OF CLASS "C" LF AND TEST CASING. C" CEMENT FROM 2800' C" CEMENT FROM 1306' C" CEMENT FROM 450'- NCHORS 3' BELOW SUI	14 NMAC. For Multiple Cor "CEMENT FROM 3600'-33 '-2468'. WOC&TAG. (YAT) '-1156'. WOC&TAG. (T.SA SURFACE. VERIFY CEME RFACE AND INSTALL DR	npletions: Attach wellbore diagram of 350'. (PERFS) ES/B.SALT) LT) ENT TO SURFACE. (FW/SHOE/SURFACE). YHOLE MARKER. TURN OVER FOR		
of starting any proposed w proposed completion or recompletion of recompletion	ork). SEE RULE 19.15.7.1 completion. S. BEFORE MIRU. E. POT 25SX OF CLASS "C' LF AND TEST CASING. C" CEMENT FROM 2800' C" CEMENT FROM 1306' C" CEMENT FROM 450'- NCHORS 3' BELOW SUI NMENT SYSTEM WILL Rig Ro	"CEMENT FROM 3600'-33 "-2468'. WOC&TAG. (YAT) "-1156'. WOC&TAG. (T.SA) SURFACE. VERIFY CEME RFACE AND INSTALL DR BE USED FOR FLUIDS.	mpletions: Attach wellbore diagram of 350'. (PERFS) ES/B.SALT) LT) ENT TO SURFACE. (FW/SHOE/SURFACE). YHOLE MARKER. TURN OVER FOR See Attached Conditions of Approval		
of starting any proposed w proposed completion or recompletion	ork). SEE RULE 19.15.7.1 completion. S. BEFORE MIRU. E. POT 25SX OF CLASS "C' LF AND TEST CASING. C" CEMENT FROM 2800' C" CEMENT FROM 1306' C" CEMENT FROM 450'- NCHORS 3' BELOW SUI NMENT SYSTEM WILL Rig Ro	"CEMENT FROM 3600'-33 "-2468'. WOC&TAG. (YAT) "-1156'. WOC&TAG. (T.SA) SURFACE. VERIFY CEME RFACE AND INSTALL DR BE USED FOR FLUIDS.	mpletions: Attach wellbore diagram of 350'. (PERFS) ES/B.SALT) LT) ENT TO SURFACE. (FW/SHOE/SURFACE). YHOLE MARKER. TURN OVER FOR See Attached Conditions of Approval		
of starting any proposed w proposed completion or recompletion of recompletion	ork). SEE RULE 19.15.7.1 completion. S. BEFORE MIRU. E. POT 25SX OF CLASS "C' LF AND TEST CASING. C" CEMENT FROM 2800' C" CEMENT FROM 1306' C" CEMENT FROM 450'- NCHORS 3' BELOW SUI NMENT SYSTEM WILL Rig Ro	"CEMENT FROM 3600'-33 "-2468'. WOC&TAG. (YAT) "-1156'. WOC&TAG. (T.SA) SURFACE. VERIFY CEME RFACE AND INSTALL DR BE USED FOR FLUIDS.	mpletions: Attach wellbore diagram of 350'. (PERFS) ES/B.SALT) LT) ENT TO SURFACE. (FW/SHOE/SURFACE). YHOLE MARKER. TURN OVER FOR See Attached Conditions of Approval		
of starting any proposed w proposed completion or recompletion of recompletion	ork). SEE RULE 19.15.7.1 completion. S. BEFORE MIRU. E. POT 25SX OF CLASS "C" LF AND TEST CASING. C" CEMENT FROM 2800' C" CEMENT FROM 1306' C" CEMENT FROM 450'- NCHORS 3' BELOW SUI NMENT SYSTEM WILL Rig Ro above is true and complete	"CEMENT FROM 3600'-33' '-2468'. WOC&TAG. (YAT) '-1156'. WOC&TAG. (T.SA) SURFACE. VERIFY CEME RFACE AND INSTALL DR BE USED FOR FLUIDS. elease Date:	mpletions: Attach wellbore diagram of 350'. (PERFS) ES/B.SALT) LT) ENT TO SURFACE. (FW/SHOE/SURFACE). YHOLE MARKER. TURN OVER FOR See Attached Conditions of Approval		
of starting any proposed w proposed completion or recompletion of the proposed	ork). SEE RULE 19.15.7.1 completion. S. BEFORE MIRU. E. POT 25SX OF CLASS "C" LF AND TEST CASING. C" CEMENT FROM 2800' C" CEMENT FROM 1306' C" CEMENT FROM 450'- NCHORS 3' BELOW SUI NMENT SYSTEM WILL Rig Ro above is true and complete	"CEMENT FROM 3600'-33 "-2468'. WOC&TAG. (YATT '-1156'. WOC&TAG. (T.SA SURFACE. VERIFY CEME RFACE AND INSTALL DR BE USED FOR FLUIDS. elease Date: to the best of my knowledge to the best of my knowledge	mpletions: Attach wellbore diagram of 350°. (PERFS) ES/B.SALT) LT) ENT TO SURFACE. (FW/SHOE/SURFACE). YHOLE MARKER. TURN OVER FOR Conditions of Approval e and belief. AGERDATE08/26/19		
of starting any proposed w proposed completion or recompletion	ork). SEE RULE 19.15.7.1 completion. S. BEFORE MIRU. E. POT 25SX OF CLASS "C" LF AND TEST CASING. C" CEMENT FROM 2800' C" CEMENT FROM 1306' C" CEMENT FROM 450'- NCHORS 3' BELOW SUI NMENT SYSTEM WILL Rig Re above is true and complete TITLE TTERSON E-mail address	"CEMENT FROM 3600'-33 "-2468'. WOC&TAG. (YAT) '-1156'. WOC&TAG. (T.SA) SURFACE. VERIFY CEME RFACE AND INSTALL DR BE USED FOR FLUIDS. elease Date: to the best of my knowledge EOPERATIONS MANA s: _MPATTERSON@RAM	mpletions: Attach wellbore diagram of 350'. (PERFS) ES/B.SALT) LT) ENT TO SURFACE. (FW/SHOE/SURFACE). YHOLE MARKER. TURN OVER FOR See Attached Conditions of Approval e and belief.		
of starting any proposed w proposed completion or recompletion	ork). SEE RULE 19.15.7.1 completion. S. BEFORE MIRU. E. POT 25SX OF CLASS "C" LF AND TEST CASING. C" CEMENT FROM 2800' C" CEMENT FROM 1306' C" CEMENT FROM 450'- NCHORS 3' BELOW SUI NMENT SYSTEM WILL Rig Re above is true and complete TITLE TTERSON E-mail address	"CEMENT FROM 3600'-33 "-2468'. WOC&TAG. (YAT) '-1156'. WOC&TAG. (T.SA) SURFACE. VERIFY CEME RFACE AND INSTALL DR BE USED FOR FLUIDS. elease Date: to the best of my knowledge EOPERATIONS MANA s: _MPATTERSON@RAM	and belief. AGERDATE08/26/19_ ENERGY.NET PHONE: _(918)947-6301_		
of starting any proposed w proposed completion or recompletion	ork). SEE RULE 19.15.7.1 completion. S. BEFORE MIRU. E. POT 25SX OF CLASS "C" LF AND TEST CASING. C" CEMENT FROM 2800' C" CEMENT FROM 1306' C" CEMENT FROM 450'- NCHORS 3' BELOW SUI NMENT SYSTEM WILL Rig Ro above is true and complete	"CEMENT FROM 3600'-33 "-2468'. WOC&TAG. (YAT) '-1156'. WOC&TAG. (T.SA) SURFACE. VERIFY CEME RFACE AND INSTALL DR BE USED FOR FLUIDS. elease Date: to the best of my knowledge EOPERATIONS MANA s: _MPATTERSON@RAM	mpletions: Attach wellbore diagram of 350°. (PERFS) ES/B.SALT) LT) ENT TO SURFACE. (FW/SHOE/SURFACE). YHOLE MARKER. TURN OVER FOR Conditions of Approval e and belief. AGERDATE08/26/19		

WELLBORE DIAGRAM WEST DOLLARHIDE QUEEN SAND UNIT #82 CURRENT

Created: Updated: Lease: Field: Surf. Loc.: Bot. Loc.: County: Status:	Ql	By: LEE R. By: DE QUEEN SAND UN JEEN & 1150' FWL	<u>π</u> (Well #: API Jnit Ltr.: FSHP/Rng: Pool Code: Directions:	82 D	30-025-30006 Sec 24S-T38E OGRID:	32
Surface Cas Size: Wt., Grd.: Depth: Sxs Cmt: Circulate: TOC: Hole Size:	8-5/8" 24# 400' 250 YES SURFACE 12-1/4"						
FORMATION T.Salt B. Salt	TOPS 1256' 2568'						
Intermediate Size: Wt., Grd.: Depth: Sxs Cmt: Circulate: TOC: Hole Size:	5-1/2" 15.5#/17# 3940' 1000 YES SURFACE 7-7/8"			Quee	en: 3666	'-3711'(OA)	

WELLBORE DIAGRAM WEST DOLLARHIDE QUEEN SAND UNIT #82 CURRENT

Created:	08/26/19	By: LEE R.	Well #:	82		
Updated:		By:	API	30	-025-30006	
Lease:	WEST DOOLARH	IDE QUEEN SAND UNIT	Unit Ltr.:	D	Sec. 32	
Field:	Q	UEEN	TSHP/Rng:	2	24S-T38E	
Surf. Loc.:	330' FNL	. & 1150' FWL	Pool Code:	•	OGRID: 3097	77
Bot. Loc.:			_			
County:	LEA	St.: NM	Directions:		<u>.</u>	
Status:						
Surface Cas Size: Wt., Grd.: Depth: Sxs Cmt: Circulate: TOC: Hole Size:	8-5/8" 24# 400' 250 YES SURFACE 12-1/4"		VERI		MT FROM 450'-SU DE/SURFACE)	IRFACE.
FORMATION	· · · · · · · · · · · · · · · · · · ·		000000000000000000000000000000000000000	T 25SX OF (C&TAG. (T.S	CMT FROM 1300 (ALT)	5'-1156'.
T.Salt B. Salt	1256' 2568'		TS	TANCVALA	CMT FROM 2800	1 3/861
D. Sait	2000		MI - 10000001 I		JMI FROM 2000 TES/B.SALT)	/ -2400 .
					' AND SPOT 25	SY ON TOP
Intermediate	Casina	(\$ \$2\$ \$9 \$9 \$9 \$9 \$2\$ \$2\$ \$2\$ \$2\$ \$2\$ \$2	_		SA UN TUP
	•	\ \	I PRO	M 3600'-335	v .(FERF3)	
Size:	5-1/2"			00001	=44KO * `	
Wt., Grd.:	15.5#/17#		Que	en: 3666'-3	711'(OA)	
Depth:	3940'				•	
Sxs Cmt:	1000	(
Circulate: TOC:	YES	<u> </u> _				
	SURFACE		1858			
Hole Size:	7-7/8"					

GENERAL CONDITIONS OF APPROVAL:

- 1) Insure all bradenheads have been exposed, identified, and valves are operational prior to rigging up on well.
- 2) Contact the appropriate NMOCD District Office no later than 24 hours prior to moving in and rigging up.
- 3) A copy of the approved C103 intent to P&A should be distributed to the onsite company and plugging representatives. Approved procedures are good for a period of one year from approved date, unless otherwise specified on the C103 intent. Approvals past this date will require the submission and approval of a new C103 intent.
- 4) A company representative is required to be present to witness all operations including setting CIBP's, circulation of mud laden fluids, perforating, squeezing or spotting cement plugs, tags, or any other operations approved on the C103 intent to P&A. Company representative should contact the NMOCD and report all operations.
- 5) Any changes that may be required during plugging operations should be approved by the NMOCD before proceeding.
- 6) A closed loop system is to be used for all plugging operations. Contents of the steel pits to be hauled to a NMOCD permitted disposal facility.
- 7) Mud laden fluids must be placed between all cement plugs mixed at 25 sacks of salt gel per 100 barrels of brine.
- 8) All cement plugs will be 100' or 25 sacks cement, whichever is greater. Class 'C' cement will be used above 7500' and Class 'H' below 7500'. Plugs should be no more than 3000' apart
- 9) Site remediation due within one year of well plugging completion.