| Submit 1 Copy To Appropriate District | State of New Me | exico | | Form C-103 |
|--|---------------------------|--------------------------------|--|-----------------------------------|
| Office Energy Minerpla and Natural Resources | | | Revised July 18, 2013 | |
| 1625 N. French Dr., Hobbs, NM 88240 | | | WELL API | |
| District II - (575) 748-1283 | | | 30-025-33696 5. Indicate Type of Lease | |
| 811 S. First St., Artesia, NM 88210 District III (505) 324 6178 | | | | |
| District III - (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410 | | | STATE FEE 🗸 | |
| District IV – (505) 476-3460 | | | 6. State Oil | & Gas Lease No. |
| 1220 S. St. Francis Dr., Santa Fe, NM 87505 | | 212015 | 302375 | |
| SUNDRY NOTICES AND REPO | ORTS ON WEELS | | 7. Lease Na | me or Unit Agreement Name |
| SUNDRY NOTICES AND REPO (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OF DIFFERENT RESERVOIR, USE "APPLICATION FOR PERM | R TO DEEPEN OR PL | UGBACINE | WAWEIR | |
| | 4IT" (FORM C-101) | E CUCH. | | |
| PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other | | | 8. Well Number 13 | |
| 2. Name of Operator | | | 9. OGRID | Number |
| Apache Corporation | | | 873 | |
| 3. Address of Operator | | | 10. Pool na | me or Wildcat |
| 303 Veterans Airpark Lane, Suite 1000 Midland, TX | 79705 | | MONUMENT | -ABO |
| 4. Well Location | | | | |
| | from the N | line and 165 | 0 fe | et from the W line |
| | | inc and ange 36E | NMPM | County LEA |
| | A | , RKB, RT, GR, etc., | - | County LEA |
| 11. Elevation | (Show whether DK) 3639 | , KKD , KI , GK , $eic.$ | ' | |
| · · · · · · · · · · · · · · · · · · · | 3039 | | L | |
| | | | | |
| 12. Check Appropriate Be | ox to Indicate N | ature of Notice, | Report or U | ther Data |
| NOTICE OF INTENTION T | ∩ ∙ | | SEOLIENT | REPORT OF: |
| PERFORM REMEDIAL WORK PLUG AND A | | REMEDIAL WOR | | |
| | | COMMENCE DRI | | |
| PULL OR ALTER CASING MULTIPLE CO | | CASING/CEMEN | | |
| DOWNHOLE COMMINGLE | | | 1 308 | |
| | | | | |
| OTHER: plug back instead of P&A | | OTHER: | | П |
| 13. Describe proposed or completed operations. | | | l give pertiner | t dates, including estimated date |
| of starting any proposed work). SEE RULE | 19.15.7.14 NMA | C. For Multiple Cor | npletions: At | tach wellbore diagram of |
| proposed completion or recompletion. | | • | • | C |
| Apache is requesting change from P&A to plug back. A | Attached are plug b | ack procedures for v | our approval | |
| Apalite is requesting shange norm at the plug back. | allocitod dro piog bi | | our approvail | |
| | | | | |
| C-101 and C-102 to plug back and recomplete to NMC | 3SAU (filed 8/19/20 |)19) online | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| j | | | | |
| Spud Date: 11/26/2019 | Rig Release Da | ate. | | |
| Spud Date: 11/26/2019 | Rig Release De | nc. | | |
| | | | | |
| | | | | |
| I hereby certify that the information above is true and | I complete to the b | est of my knowledg | e and belief. | |
| | | | | |
| SIGNIATION Aliana Indiana | TITLE Sr. Sta | ff Reg Analyst | | DATE 8/19/2019 |
| SIGNATURE alicia fulton | | n rieg / naryot | | DATE |
| Type or print name Alicia Fulton | E-mail address | s: alicia.fulton@apach | necorp.com | PHONE: (432) 818-1062 |
| For State Use Only | | | | |
| | ^ . | ↑ | | a l in |
| APPROVED BY: Xerry Junner TITLE C. O. A DATE 9-6-19 | | | | |
| Conditions of Approval (if any): | | • • | | |
| ······································ | | | | |
| | | | | |

August 12th, 2019

| WA Weir #13 | | |
|--------------------|--------|-------|
| API # 30-025-33696 | | |
| Lea County, NM | | |
| Production Casing: | 5-1/2" | 15.5# |
| Surface Casing: | 8-5/8" | 24# |

<u>Objective</u>: Plug back from Abo to Grayburg, shoot perfs and squeeze cement to surface to stop small flow up surface casing, recomplete to Grayburg and acidize

Procedure:

AFE 11-19-0382

- 1. RU WL, set CIBP @ 5,400', dump bail 35' cement (3 sxs)
- 2. PUH, set CIBP @ 4,300', dump bail 35' cement (3 sxs)
- 3. Run CBL from 4,200' to surface, RD WL
- 4. MIRU WO Unit, circulate wellbore with 10# brine
- 5. RU WL, shoot perfs @ 20' above TOC per CBL, RD WL
- 6. RIH and set packer at 100' above squeeze holes, establish circulation to surface
- 7. If full returns established pump dye and measure annular volume
- 8. Pump 5 bbls FW, squeeze casing annulus w/ 30% excess cement, flush FW, WOC
- 9. POOH with tubing and packer
 - a. If cement not circulated to surface, SI under pressure, WOC, open backside and observe
 - i. If flow is dead, continue with step 11
 - ii. If flow is not dead, run CBL to find TOC, repeat steps 5-9, contact Midland
- 10. RIH and DO cement
- 11. Pressure test squeeze to 500 PSI
- 12. Complete cleanout run to TOC @ ~4,265'
- 13. POOH

AFE 11-19-0744

- 1. RU WL and perf the following intervals @ 2 SPF with 3 1/8" TAG w/ SDP Charges
 - a. 4,054' 4,061'; 4,065' 4,098'; 4,105' 4,130'
- 2. RD WL, RIH and set packer at ~4,000'
- 3. Acidize Grayburg with 5,000 gals 15% HCL and 150 ball sealers
- 4. Swab test Grayburg for pumping unit sizing
- 5. Release packer, POOH, LD workstring
- 6. RIH with tubing, RIH with rods and pump, RD WO Unit
- 7. Set pumping unit, POP



