UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

OCD Hobbs

FORM APPROVED OMB NO. 1004-0137


Expires: January 31, 2018 5. Lease Serial No.

S	UNDRY	NOTICI	ES AND	REPOR	RTS ON	WELLS	
o ne	ot use th	is form t	or prop	osals to	drill or to	re-enter ar	7
						h proposal	

SUNDRY	INMINIZETE								
Do not use thi abandoned wei	6. If Indian, Allottee	or Tribe Name							
SUBMIT IN		7. If Unit or CA/Agreement, Name and/or No. NMNM111771							
1. Type of Well Oil Well Gas Well Oth		8. Well Name and No. MINIS 2 FEDERAL COM 04							
Name of Operator COG OPERATING LLC	Contact: ABI E-Mail: abbym@bcmar	GAIL ANDERSON CONTROL OF CONTROL	9. API Well No. 30-025-36290-	9. API Well No. 30-025-36290-00-S1					
3a. Address ONE CONCHO CENTER 60 MIDLAND, TX 79701-4287	0 W ILLINOIS AVENUE PH	. Phone No. 11 11 area code) n: 432-581-7161	10. Field and Pool of HAT MESA	10. Field and Pool or Exploratory Area HAT MESA					
4. Location of Well (Footage, Sec., T	., R., M., or Survey Description)		11. County or Parish	11. County or Parish, State					
Sec 2 T21S R32E SENE Lot 8	3 1944FNL 660FEL		LEA COUNTY	LEA COUNTY, NM					
12. CHECK THE A	PROPRIATE BOX(ES) TO	INDICATE NATURE OF	F NOTICE, REPORT, OR OT	HER DATA					
TYPE OF SUBMISSION	. •	TYPE OF	TYPE OF ACTION						
Notice of Intent	☐ Acidize	□ Deepen	☐ Production (Start/Resume)	■ Water Shut-Off					
_	☐ Alter Casing	☐ Hydraulic Fracturing	□ Reclamation	■ Well Integrity					
☐ Subsequent Report	☐ Casing Repair	■ New Construction	☐ Recomplete	☐ Other					
☐ Final Abandonment Notice	☐ Change Plans	Plug and Abandon	□ Temporarily Abandon						
	☐ Convert to Injection	□ Plug Back	■ Water Disposal						
If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation resultiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection. 1. Set 5 1/2" CIBP @ 13,601'. Circ hole w/ MLF. Pressure test csg. Spot 25 sx cmt @ 13,601-13,400'. 2. Spot 25 sx cmt @ 12908-12678'. (Strawn) 3. Spot 25 sx cmt @ 14,659-11,460'. (Wolfcamp) 4. Spot 25 sx cmt @ 8750-8550'. (Bone Spring) 5. Spot 25 sx cmt @ 5456-5300'. WOC & Tag (T/Delaware & 8 5/8" Shoe) 6. Perf & Sqz 350 sx cmt @ 3194-1500'. WOC & Tag (11 3/4" Shoe, R-111-P Potash Area, 16" Shoe) 7. Perf & Sqz 25 sx cmt @ 60' to surface. 9. Cut off well head, verify cmt to surface, weld on Below Ground Dry Hole Marker.									
			SEE ATTACHED	FOR					
			CONDITIONS OF						
14. I hereby certify that the foregoing is	Electronic Submission #4744	147 verified by the BLM Well	Information System						
Con	nmitted to AFMSS for processi	RATING LLC, sent to the H	07/22/2019 (19PP2596SE)						
Name (Printed/Typed) ABIGAIL /	ANDERSON	Title AGENT							
Signature (Electronic S	Submission)	Date 07/22/20	019						
	THIS SPACE FOR	FEDERAL OR STATE (OFFICE USE						
Approved By James	a. amos_	Title 5%	167	7.28-19 Date					
Conditions of approval, if any, are attached certify that the applicant holds legal or equivalent to conduct the applicant the applicant to conduct the applicant to the applicant the applicant to the	uitable title to those rights in the sub	warrant or ject lease	7						

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2) ** BLM REVISED ** BLM REVIS X7 NMOCD 9-6-19 M



LSE#: 012928 WELL NAME Minis 2 Fed Com #4 FIELD: Hat Mesa STATE: NM LOCATION: N/2 SE NE 2-21S-32E **COUNTY:** Lea API NO: 30-025-36290 SPUD DATE: 6/30/2003 FORMATION: Morrow TD: 14400' **PBTD: 14270' ELEVATION: 3659' GL** 7. Perf & Sqz 25 sx cmt @ 60' to Surface. 16" @ 1556' 6. Perf & Sqz 350 sx cmt @ 3194-1500". WOC & Tag (11 3/4" Shoe, R-111-P Potash Area, 16" Shoe) 11 3/4" @ 3144' 5 1/2" TOC @ 5036' 8 5/8" @ 5350' 5. Spot 25 sx cmt @ 5455-5300'. WOC & Tag (T/Delaware & 8 5/8" Shoe) 4. Spot 25 sx cmt @ 8750-8550' (Bone Spring) 3. Spot 25 sx cmt @ 11,650-11,450' (Wolfcamp) MJ @ 12410' 2. Spot 25 sx cmt @ 12,908-12,678'. (Strawn) 1. Set 5 1/2" CIBP @ 13,601'. Circ hole w/ MLF. Pressure test csg. Spot 25 sx cmt @ 13,601-13,400' 13651-60' 13672-78' Morrow 13868-77' 13914-18' Morrow 14064-67' 14104-107' 14159-62' 14190-94' Morrow Tagged @ 14210' (4/19/05) FC @ 14312' FS @ 14398' 5 1/2" @ 14.398' TD:14400"

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Permanent Abandonment of Federal Wells Conditions of Approval (LPC Habitat)

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement</u>: Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of brine water Minimum nine (9) pounds per gallon.
- 5 <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. Before pumping or bailing cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. Below Ground Level Cap (Lesser Prairie-Chicken Habitat): All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10th day, the BLM is to be contacted with justification to receive an extension for completing the cut off. Upon the plugging and subsequent abandonment of wells that are located in lesser prairie-chicken habitat, the casings shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The well bore shall then be covered with a metal plate at least ¼ inch thick and welded in place. A weep hole shall be left in the plate and/or casing.

NMOCD also requires the operator to notify NMOCD when this type of dry hole marker is used. This can be done on the subsequent report of abandonment which is submitted to the BLM after the well is plugged. State that a below ground cap was installed as required in the COA's from the BLM.

- 7. Subsequent Plugging Reporting: Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. Show date well was plugged.
- 8. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation objectives.

<u>Timing Limitation Stipulation/ Condition of Approval for Lesser Prairie-Chicken:</u>
From March 1st through June 15th annually, abandonment activities will be allowed except between the hours from 3 00 am and 9 00 am. Normal vehicle use on existing roads will not be restricted