BL SUNDRY I Do not use this	UNITED STATES PARTMENT OF THE IN JREAU OF LAND MANA NOTICES AND REPO IS form for proposals to I. Use form 3160-3 (API	TERIOR GEMENT RTS ON WELI drill or to re-en	ter an	obbs	OMB NO	APPROVED D. 1004-0137 nuary 31, 2018
SUBMIT IN T	RIPLICATE - Other inst	tructions on pa	HORB	3 OCE	7. If Unit or CA/Agree	ment, Name and/or No.
1. Type of Well Dil Well 🛛 Gas Well 🗖 Oth	er		SEP 2	3 2019	8. Well Name and No. NEW MEXICO B	FEDERAL 3
2. Name of Operator COG OPERATING LLC	Contact: E-Mail: abbym@bo	ABIGAIL ANDE mandassociates.		IVED	9. API Well No. 30-025-38293-0	0-S1
3a. Address ONE CONCHO CENTER 600 MIDLAND, TX 79701-4287	W ILLINOIS AVENUE	3b. Phone No. (ir Ph: 432-580-7			10. Field and Pool or E HAT MESA	Exploratory Area
4. Location of Well (Footage, Sec., T.	•)			11. County or Parish, S	
Sec 3 T21S R32E NESE 3300 32.509680 N Lat, 103.656182					LEA COUNTY, I	NM
12. CHECK THE AP	PROPRIATE BOX(ES)	TO INDICATE	NATURE O	F NOTICE,	REPORT, OR OTH	IER DATA
TYPE OF SUBMISSION	•		TYPE OF	ACTION		
Notice of Intent	C Acidize	Deeper		—	ion (Start/Resume)	□ Water Shut-Off
Subsequent Report	Alter Casing Casing Repair		lic Fracturing	□ Reclam □ Recomp		Well Integrity Other
Final Abandonment Notice	Change Plans	. —	d Abandon		arily Abandon	
	Convert to Injection	🗖 Plug Ba	ack	🗖 Water I	Disposal	
testing has been completed. Final Ab determined that the site is ready for fit 1. Set 5 1/2" CIBP @ 13,700'. 13,700-13,500.' 13479 (2 2. Spot 25 sx cmt @ 12,865-14 3. Spot 25 sx cmt @ 12,865-14 4. Spot 25 sx cmt @ $0720-052$ 5. Spot 29 sx cmt @ $0720-052$ 5. Spot 29 sx cmt @ $5410-515$ 6. Ferf & Sez 400 sx cmt @ 94 7. Ferf & Sez 400 sx cmt @ 94 5. Cut off well head, verify cmt Records in direct At <u>Belan graund</u> leve	Circulate hole w/ MLF. P 30' $7005'$. $12 \times 3 \in \mathbb{C}^{2}$ $1540'$. $10740 \to 10$ $10'$ $8722 \to 853$ 7'. WOC & Tag (95/8" S 400-1435'. WOC & Tag (1 to surface. to surface, weld on Belo 1 = 1000 Casings Casi	ressure test csg 530 (210 530 (210 540 (210)	. Spot 25 sx c 7/BS 5/LLO Area & 13 3/4 tole Marker. 1 1 1 1 1 1 1 1	rmt@ SIS7 ("Shoe) 3 Ver:{; wi. [e.]	Solid Ali (Del.) 592 (inchu @ cut/o	Lalt Section
Commi	# Electronic Submission For COG tted to AFMSS for process	OPERATING LLC	, sent to the H	lobbs	-	
Name (Printed/Typed) ABIGAIL A	•		itle AGENT			
Signature (Electronic S	ubmission)	D	ate 08/23/2	019		
	THIS SPACE FO	OR FEDERAL	OR STATE	OFFICE U	SE	
Approved By Lames	Limon _		Fitle St	Ét		9-15-19 Date
Conditions of approval, if any, are attached certify that the applicant holds legal or equivient which would entitle the applicant to condu-	itable title to those rights in the	e subject lease	Office 1Fe	9		
Title 18 U.S.Q. Section 1001 and Title 43 1 States any false, fictitious or fraudulent s				willfully to m	ake to any department or	agency of the United
(Instructions on page 2) ** BLM REVI	SED ** BLM REVISED 2 N/M D C			A REVISE	FOR RECO	RD ONLY

K.Z.	WELL N		N M Federal 6	3 #3	-		Hat Mesa			039735	0.005.005			
	STATE:		New Mexico 30-025-38293	•		OUNTY:	Lea 7/24/2007				S-32E 330	0' FSL.& 66	0' FEL	
	TD:		30-025-38293 14353'	•	5901		14267'		RMATION: EVATION:					
	10:		14333		ECORD	PBID.	14207	EL	EVATION:		& HOLE			
	CSG	OD	GRADE	THD	WT/FT	TOP	BTM	# JTS	BIT SIZE		SX	WT.	тос	
13.375" @1485 7	Surf	13.375"-	J-55	1	54.50#	0'	14857	35	17.500" •		1460		Surf	
1404		9.625"	НСК-55		40.00#	0'	5368'	121	12.250"	-	1080		4404	
•	Prod	5.500"	P110	LT&C	20.00#	0'	14353'	333	8.750"	-	2585		5150	
	Tbg	2,375"	L-80			0'	13798	423						
:	1		14080'-14241') nole.	Frac w/4	8753# of 20)/40 Bau	xite, 595 bbls	fluid and	CAPACITI TBG: 2.37 CSG: 9.62	75 in. #	(bbl/ft)	(ft/bbl)	(cf/ft)	
	10/19/20		13893'-13978')	Frac w/4	8539# of 20)/40 Bau	xite, 490 bbis	fluid and						
· M. MARMARKET	02/24/20	007: First Sa 010: Perf tbg	A 13740' 13	750'					VOLUME TBGxCSG			(ft/bbl)	(cf/ft)	
9.625 @ 5368	An	hey .	1500						TBGxCSG CSGxHOL					
	Yes	tos .	3350						TBGxHOL					
	C	Andry 1500 Yetas 3350 Capitan 3542-4850 Del Selo DEE												
		1	Sin		-				1		70115	STATUS		
	De							DATE 10/16/2007	TOP 14239'	BTM 14241'	ZONE		SPF 2	
								10/16/2007	14220	14227	Lwr Mrrw		2	
	BS		8672					10/16/2007	14080	14086	Lwr Mrrw	1	2	
	-							10/18/2007	13973	13978	Upr Mrrw		2	
	400		>640					10/18/2007	13961'	13967'	Upr Mrrw	Active	2	
	54		12 814	•				10/18/2007	13917	13919	Upr Mrrw	Active	2	
								10/18/2007	13903	13908'	Upr Mrrw	Active	2	
	At		/z 160					10/18/2007	13893'	13896'	Upr Mrrw	Active	2	
	MR	Tubing Detai	3590 As of 08/17/09:][-						
		423 JTS 2 3/8 T O/O TOOL W/ 1X 10 # PKR 8' C 2.385" SUE	1.87 X NIPPLE J	13,787' 13,788' 3,790'	SRC WI% LOGS:								i 1	
		1.87 XN NIPPLE	E E	3,798	LANDMA	N:		GEOLOGIST						
Tbg@13798		2 3/8 PUMP OI	UT PLUG 1	3,799'			<u>. n</u>	JBULAR GO	ID ID		NCE Collapse	Burst*	Tensil	
-bg@13730		 			Material				(in)	(in)	(psi)	(psi)	(lbs)	
MJ @ 12131'					13.375" J 9.625" H									
-					2.375" L-									
MJ @ 13154']	
1X 10K PKR @ 13,790' E	OT @ 1379	8						•						
13749'- 13750' 7 13893'- 13978' 7					 Safety F 	actor No	t Included	·····,	L	l	I	<u>[</u>		
14080'-14241'														
:5.5' @14353' PBTD:" @14267'					PREPA	RED BY:				OFFICE:				
U						DATE:				FAX:				
					1	Indatod								

Updated:

To draw a packer, click on tools, macro, macros and select packer To draw a triangle, click on tools, macro, macros and select triangle.

¢

32.5096779 -103.6561737

STATE: New Mexico COUNTY: Lea LOCATION: Sec 3-21S-32E 3300' FSL & 660' FEL API NO: 30-025-38293 SPUD DATE: 7/24/2007 FORMATION: Morrow Image: Constraint of the sec sec sec sec sec sec sec sec sec se	STATE: New Mexico COUNTY: Lea LOCATION: Sec 3-215-32E 3300' FSL & 660' FEL API NO: 30-025-38283 SPUD DATE: 1/2/2/200' FORMATION: Morrow	STATE:				FIELD:		Hat Mesa	i	.SE#:	039735			
API NO: 30-025-38283 SPUD DATE: 17/24/2007 FUND MATTON: Moreow Image: Content of the state o	API NO: 30-025-38283 SPUD DATE: 7/24/2007 FORMATION: Morrow TD: 14353' PBTD: 14207 ELEVATION: 3727 1 CSG OD GRADE THD WT/FT TOP BTM 9.JTS BIT SIZE DEPTH SX WT. Surf 13.375' J-55 54.50# 0' 1485' 35' 17.500' 1480' 15' 100' 1480' 1480' 1480' 15' 100' 1480' 1480' 15' 15' 10' 10' 10' 10'		i New	Mexico		COUNTY:		Lea	LO	CATION:	Sec 3-21S-32	E 3300' FS	L & 660' FEL	
To: 14253' PRTD: 14287 ELEVATION: 3727 Image: Construction of the construction of	TD: 14353' PBTD: 14267' ELEVATION: 3727' Image: Comparison of the compa		E											
OSG OD GRADE PIPE RECORD CEMENT & HOLE DATA Surf 13.375" J-55 54.505 TOP BTM 9.175 BTM 9.175 BTM SX WT Surf 13.375" J-55 40.006 0 53.86' 121 12.250" 1080 Introduction Prod 5.500" P110 LT&C 20.006 0 14353' 333 8.750" 2585 Introduction Tog 2.375" L-80 0 13798' 423 Introduction Introd	CSG OD GRADE THD WT/FT TOP BTM # JTS BIT SIZE DEPTH SX WT. Surf 13.375* J.55 54.504 0* 1485* 35 17.500* 1486 121 12.250* 1480 1 Intrmed 9.625* HCK-55 40.00# 0* 14353* 333 8.750* 2585 1 Prod 5.500* P110 LT&C 20.00# 0* 14353* 333 8.750* 2585 1 Tbg 2.375* L-80 0* 13798* 423 1													
CSG OD GRADE TND WT/FT YOP BTM #JTS BIT SIZE DEPTH SX WT. Surf 13.375* J-55 54.508 0' 1485* 35' 1486* 11 12.507 1486 1486* 11 12.507 1486 11 12.507 1080 10 1080 10 1080 10 1080 10 1080 10 1080 10 10 12.507 1080 10 <td>CSG OD GRADE THD WT/FT TOP BTM # JTS BIT SIZE DEPTH SX WT. Surf 13.375* J-55 54.50# 0' 1485* 35 17.500* 1460 1 Intimed 9.625* HCK-55 40.00# 0' 5388* 121 12.250* 1080 1 Prod 5.500* P110 LT&C 20.00# 0' 14353' 333 8.750* 2585 1 Tbg 2.375* L-80 0' 13798* 423 1 <</td> <td></td> <td></td> <td>·</td> <td>PIPE RECO</td> <td>L</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td><u>م</u></td> <td></td>	CSG OD GRADE THD WT/FT TOP BTM # JTS BIT SIZE DEPTH SX WT. Surf 13.375* J-55 54.50# 0' 1485* 35 17.500* 1460 1 Intimed 9.625* HCK-55 40.00# 0' 5388* 121 12.250* 1080 1 Prod 5.500* P110 LT&C 20.00# 0' 14353' 333 8.750* 2585 1 Tbg 2.375* L-80 0' 13798* 423 1 <			·	PIPE RECO	L							<u>م</u>	
Surt 13.375' J-55 54.508 0' 1485' 35 17.500' 1480 1 Intrmed 9.622' HCK-55 40.008 0' 5386' 121 12.250' 1080 1 Prod 5.500' P110 LT&C 20.00# 0' 14353' 333 8.750' 2585 1 1 Tob 2.375' L40 0' 14353' 333 8.750' 2585 1 1 Tbg 2.375' L40 0' 13798' 423 1	Surt 13.375° J-55 54.50# 0° 1465° 35 17.500° 1460 1 Intrmed 9.825° HCK-55 40.00# 0° 5368° 121 12.250° 1080 1 Prod 5.500° P110 LT&C 20.00# 0° 14353' 333 8.750° 2585 1 Tbg 2.375° L-80 0' 13788' 423 1	CSG	OD	GRADE		WT/FT	TOP	BTM	#JTS	BIT SIZE				тс
Intrmed 9.625° HCK-55 40.00# 0' 5368' 121 12.250' 1080 1080 Prod 5.500° P110 LT&C 20.00# 0' 14353' 333 8.750° 2585 1 Tbg 2.375° L-80 0' 13798' 423 0 0' 13798' 423 7. Perf & Sqz 25 sx cmt @ 60' to surface. 13.375' @1485' 0' 0' 13798' 423 0 0' 0' 13798' 423 0 0'	Intrmed 9.625° HCK-55 40.00# 0' 5388' 121 12.250° 1080 1 Prod 5.500° P110 LT&C 20.00# 0' 14353' 333 8.750° 2585 1 Tbg 2.375° L-80 0' 13798' 423 0' 0' 13798' 423 0' 0													S
Prod 5.500" P110 LT&C 20.00# 0 14353 333 8.750" 2585 1 Tbg 2.375" L-80 0' 13798' 423 1	Prod 5.500" P110 LT&C 20.00# 0 14353 333 8.750" 2585 1 Tbg 2.375" L-80 0 13798 423 1													
Tbg 2.375" L-80 0" 13798" 423 7. Perf & Sqz 25 sx cmt @ 60' to surface. 13.375" @1485" 0" 13798" 423 C @1404' 6. Perf & Sqz 400 sx cmt @ 3400-1435". WOC & Tag (R-111-P Potash Area & 13 3/4" Shoe) DV Tool @ 5207" 9.625 @ 3388"	Tbg 2.375" L-80 0" 13798" 423 7. Perf & Sqz 25 sx cmt @ 60' to surface. 13.375" @1485" 0" 0" 13798" 423 C @1404" 6. Perf & Sqz 400 sx cmt @ 3400-1435". WOC & Tag (R-111-P Potash Area & 13 3/4" Shoe) DV Tool @ 5207" 9.625 @ 3388"	Intrmed	9.625"	HCK-55		40.00#	0°	5368'	121	12.250"		1080		14
Tbg 2.375° L-80 0° 13798° 423 7. Perf & Sqz 25 sx cmt @ 60' to surface. 13.375° @1485° 0° 13798° 423 0° 13798° 423 0° 0° 13.375° @1485° 0° 13798° 423 0° 13.375° @1485° 0° 0° 13798° 423 0° 0° 13798° 423 0° 0° 13798° 423 0° 13.375° @1485° 0° 0° 13798° 423 0° 0° 0° 0° 13798° 423 0° 13798° 423 0° 0° 13.375° @1485° 0° 0° 13798° 423 0° 0° 0° 13.04° 0° 0° 13798° 423 0° 0° 0° 13.04° 0° 13.375° 0° 0° 13798° 1379° 0° 13.04° 0° 14.04° 0° 13.34° 13.34° 13.34° 13.34° 0° 10° 10° 10°	Tbg 2.375° L-80 0° 13798° 423 7. Perf & Sqz 25 sx cmt @ 60' to surface. 13.375° @1485° 0° 13798° 423 0° 13798° 423 0° 0° 13.375° @1485° 0° 13798° 423 0° 13.375° @1485° 0° 0° 13798° 423 0° 13798° 423 0° 0° 13.375° @1485° 0° 0° 13798° 423 0° 13798° 423 0° 0° 0° 13798° 423 0° 0° 13.375° @1485° 0° 0° 13798° 423 0° 1404° 0° 0° 0° 6. Perf & Sqz 400 sx cmt @ 3400-1435°. WOC & Tag (R-111-P Potash Area & 13 3/4° Shoe) 0° DV Tool @ 5207° 9.825 @ 3588° 0° 0°													
 7. Perf & Sqz 25 sx cmt @ 60' to surface. 13.375" @1485" 0C @1404' 6. Perf & Sqz 400 sx cmt @ 3400-1435'. WOC & Tag (R-111-P Potash Area & 13 3/4" Shoe) 	 7. Perf & Sqz 25 sx cmt @ 60' to surface. 13.375" @1485" 0C @1404' 6. Perf & Sqz 400 sx cmt @ 3400-1435'. WOC & Tag (R-111-P Potash Area & 13 3/4" Shoe) 	Prod	5.500"	P110	LT&C	20.00#	0'	14353'	333	8.750"		2585		5
 7. Perf & Sqz 25 sx cmt @ 60' to surface. 13.375" @1485" 0C @1404' 6. Perf & Sqz 400 sx cmt @ 3400-1435'. WOC & Tag (R-111-P Potash Area & 13 3/4" Shoe) 	 7. Perf & Sqz 25 sx cmt @ 60' to surface. 13.375" @1485" 0C @1404' 6. Perf & Sqz 400 sx cmt @ 3400-1435'. WOC & Tag (R-111-P Potash Area & 13 3/4" Shoe) 													
7. Perf & Sqz 25 sx cmt @ 60' to surface. 13.375" @1485' CC @1404' 6. Perf & Sqz 400 sx cmt @ 3400-1435'. WOC & Tag (R-111-P Potash Area & 13 3/4" Shoe) DV Tool @ 5207' 9.625 @ 5368'	7. Perf & Sqz 25 sx cmt @ 60' to surface. 13.375" @1485' CC @1404' 6. Perf & Sqz 400 sx cmt @ 3400-1435'. WOC & Tag (R-111-P Potash Area & 13 3/4" Shoe) DV Tool @ 5207' 9.625 @ 5368'													
7. Perf & Sqz 25 sx cmt @ 60' to surface. 13.375° @1485' CC @1404' 6. Perf & Sqz 400 sx cmt @ 3400-1435'. WOC & Tag (R-111-P Potash Area & 13 3/4" Shoe) DV Tool @ 5207' 9.625 @ 5368'	 7. Perf & Sqz 25 sx cmt @ 60' to surface. 13.375" @1485' CC @1404' 6. Perf & Sqz 400 sx cmt @ 3400-1435'. WOC & Tag (R-111-P Potash Area & 13 3/4" Shoe) DV Tool @ 5207' 9.625 @ 5368'	Tbg	2.375"	L-80	1		0'	13798'	423					
		1 ⁷ 00 @1404'		@ 3400-1435'	. WOC & T	ag (R-111-P Pot	ash Are	ea & 13 3/4	" Shoe)				
4. Spot 25 sx cmt @ 8720-8520'.		9.625 @ 5368' 5. Spot 25 sx o	nt @ 8720-8	3520' .	& Tag (9 5/	/8" Shoe & DV T	ool)							
 4. Spot 25 sx cmt @ 8720-8520'. 3. Spot 25 sx cmt @ 11.760-11.540'. 	3. Spot 25 sx cmt @ 11.760-11.540'.	9.625 @ 5368' 5. Spot 25 sx o	nt @ 8720-8	3520' .	& Tag (9 5/	/8" Shoe & DV T	ool)							
3. Spot 25 sx cmt @ 11.760-11.540'.		9.625 @ 5368' 5. Spot 25 sx of 4. Spot 25 sx of 3. Spot 25 sx of	nt @ 8720-8	3520' .	& Tag (9 5/	/8" Shoe & DV T	ool)							
3. Spot 25 sx cmt @ 11.760-11.540'. MJ @ 12131'	MJ @ 12131'	9.625 @ 5368' 5. Spot 25 sx of 4. Spot 25 sx or 3. Spot 25 sx or MJ @ 12131'	et @ 8720-8 ot @ 11.760	3520'. 9-11.540'.	& Tag (9 5/	/8" Shoe & DV T	ool)							
3. Spot 25 sx cmt @ 11.760-11.540'. MJ @ 12131'	MJ @ 12131'	9.625 @ 5368' 5. Spot 25 sx of 4. Spot 25 sx or 3. Spot 25 sx or MJ @ 12131'	et @ 8720-8 ot @ 11.760	3520'. 9-11.540'.	& Tag (9 5/	/8" Shoe & DV T	ool)							
3. Spot 25 sx cmt @ 11.760-11.540'. MJ @ 12131' 2. Spot 25 sx cmt @ 12,865-12,665'.	MJ @ 12131' 2. Spot 25 sx cmt @ 12,865-12,665'.	9.625 @ 5368' 5. Spot 25 sx cm 4. Spot 25 sx cm 3. Spot 25 sx cm MJ @ 12131' 2. Spot 25 sx cm	et @ 8720-8 ot @ 11.760	3520'. 9-11.540'.	& Tag (9 5/	/8" Shoe & DV T	ool)							
3. Spot 25 sx cmt @ 11.760-11.540'. MJ @ 12131'	MJ @ 12131' 2. Spot 25 sx cmt @ 12,865-12,665'.	9.625 @ 5368' 5. Spot 25 sx cm 4. Spot 25 sx cm 3. Spot 25 sx cm MJ @ 12131' 2. Spot 25 sx cm	et @ 8720-8 ot @ 11.760	3520'. 9-11.540'.	& Tag (9 5/	/8" Shoe & DV T	ool)							
 3. Spot 25 sx cmt @ 11.760-11.540'. MJ @ 12131' 2. Spot 25 sx cmt @ 12,865-12,665'. MJ @ 13154' 	MJ @ 12131' 2. Spot 25 sx cmt @ 12,865-12,665'. MJ @ 13154'	9.625 @ 5368' 5. Spot 25 sx cm 4. Spot 25 sx cm 3. Spot 25 sx cm MJ @ 12131' 2. Spot 25 sx cm MJ @ 13154'	nt @ 8720-8 nt @ 11.760 nt @ 12,865	9520'. 1-11.540'. 5-12,665'.				ot 25 sx cr	nt @ 13	3 700-13 50	10 '			
3. Spot 25 sx cmt @ 11.760-11.540'. ^{MJ} @ 12131' 2. Spot 25 sx cmt @ 12,865-12,665'. ^{MJ} @ 13154' 1. Set 5 1/2" CIBP @ 13,700'. Circulate hole w/ MLF. Pressure test csg. Spot 25 sx cmt @ 13,700-13,500.'	MJ @ 12131' 2. Spot 25 sx cmt @ 12,865-12,665'. MJ @ 13154' 1. Set 5 1/2'' CIBP @ 13,700'. Circulate hole w/ MLF. Pressure test csg. Spot 25 sx cmt @ 13,700-13,500.'	9.625 @ 5368' 5. Spot 25 sx cm 3. Spot 25 sx cm MJ @ 12131' 2. Spot 25 sx cm MJ @ 13154' 1. Set 5 1/2'' CIB	nt @ 8720-8 nt @ 11.760 nt @ 12,865	9520'. 1-11.540'. 5-12,665'.				ot 25 sx cr	nt @ 13	3,700-13,50	10.'			
 3. Spot 25 sx cmt @ 11.760-11.540'. MJ @ 12131' 2. Spot 25 sx cmt @ 12,865-12,665'. MJ @ 13154' 1. Set 5 1/2" CIBP @ 13,700'. Circulate hole w/ MLF. Pressure test csg. Spot 25 sx cmt @ 13,700-13,500.' 13749'-13750' 	MJ @ 12131' 2. Spot 25 sx cmt @ 12,865-12,665'. MJ @ 13154' 1. Set 5 1/2'' CIBP @ 13,700'. Circulate hole w/ MLF. Pressure test csg. Spot 25 sx cmt @ 13,700-13,500.' 13749'-13750'	 9.625 @ 5368' 5. Spot 25 sx cm 3. Spot 25 sx cm MJ @ 12131' 2. Spot 25 sx cm MJ @ 13154' 1. Set 5 1/2" CIB 13749'-13750' 	nt @ 8720-8 nt @ 11.760 nt @ 12,865	9520'. 1-11.540'. 5-12,665'.				ot 25 sx cr	nt @ 13	3,700-13,50	10.4			
 3. Spot 25 sx cmt @ 11.760-11.540'. MJ @ 12131' 2. Spot 25 sx cmt @ 12,865-12,665'. MJ @ 13154' 1. Set 5 1/2" CIBP @ 13,700'. Circulate hole w/ MLF. Pressure test csg. Spot 25 sx cmt @ 13,700-13,500.' 13749-13750' 13893'-13978' 	MJ @ 12131' 2. Spot 25 sx cmt @ 12,865-12,665'. MJ @ 13154' 1. Set 5 1/2'' CIBP @ 13,700'. Circulate hole w/ MLF. Pressure test csg. Spot 25 sx cmt @ 13,700-13,500.' 13749-13750' 13893'-13978'	 9.625 @ 5368' 5. Spot 25 sx cm 3. Spot 25 sx cm MJ @ 12131' 2. Spot 25 sx cm MJ @ 13154' 1. Set 5 1/2" CIB 13749'-13750' 13893'-13978' 	nt @ 8720-8 nt @ 11.760 nt @ 12,865	9520'. 1-11.540'. 5-12,665'.				ot 25 sx cr	nt @ 13	3,700-13,50	10.'			
 3. Spot 25 sx cmt @ 11.760-11.540'. MJ @ 12131' 2. Spot 25 sx cmt @ 12,865-12,665'. MJ @ 13154' 1. Set 5 1/2'' CIBP @ 13,700'. Circulate hole w/ MLF. Pressure test csg. Spot 25 sx cmt @ 13,700-13,500.' 13749'-13750' 	MJ @ 12131' 2. Spot 25 sx cmt @ 12,865-12,665'. MJ @ 13154' 1. Set 5 1/2'' CIBP @ 13,700'. Circulate hole w/ MLF. Pressure test csg. Spot 25 sx cmt @ 13,700-13,500.' 13749'-13750' 13893'-13978'	 9.625 @ 5368' 5. Spot 25 sx cm 3. Spot 25 sx cm MJ @ 12131' 2. Spot 25 sx cm MJ @ 13154' 1. Set 5 1/2" CIB 13749'-13750' 13893'-13978' 	nt @ 8720-8 nt @ 11.760 nt @ 12,865	9520'. 1-11.540'. 5-12,665'.				ot 25 sx cr	nt @ 13	5,700-13,50	10.1			
 3. Spot 25 sx cmt @ 11.760-11.540'. MJ @ 12131' 2. Spot 25 sx cmt @ 12,865-12,665'. MJ @ 13154' 1. Set 5 1/2" CIBP @ 13,700'. Circulate hole w/ MLF. Pressure test csg. Spot 25 sx cmt @ 13,700-13,500.' 13749'-13750' 13893'-13978' 	MJ @ 12131' 2. Spot 25 sx cmt @ 12,865-12,665'. MJ @ 13154' 1. Set 5 1/2'' CIBP @ 13,700'. Circulate hole w/ MLF. Pressure test csg. Spot 25 sx cmt @ 13,700-13,500.' 13749'-13750' 13893'-13978' 14080'-14241'	 9.625 @ 5368' 5. Spot 25 sx cm 3. Spot 25 sx cm MJ @ 12131' 2. Spot 25 sx cm MJ @ 13154' 1. Set 5 1/2" CIB 13749'-13750' 13893'-13978' 14080'-14241' 	nt @ 8720-8 nt @ 11.760 nt @ 12,865	9520'. 1-11.540'. 5-12,665'.				ot 25 sx cr	nt @ 13	3,700-13,50	10.'			

Ì

. .

. . . .

•

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Permanent Abandonment of Federal Wells Conditions of Approval (LPC Habitat)

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>minety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

2. <u>Notification</u>: Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.

3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.

4. <u>Mud Requirement</u>: Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of brine water. Minimum nine (9) pounds per gallon.

5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. Before pumping or bailing cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. <u>Below Ground Level Cap (Lesser Prairie-Chicken Habitat)</u>: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10th day, the BLM is to be contacted with justification to receive an extension for completing the cut off. Upon the plugging and subsequent abandonment of wells that are located in lesser prairie-chicken habitat, the casings shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The well bore shall then be covered with a metal plate at least ¼ inch thick and welded in place. A weep hole shall be left in the plate and/or casing.

NMOCD also requires the operator to notify NMOCD when this type of dry hole marker is used. This can be done on the subsequent report of abandonment which is submitted to the BLM after the well is plugged. State that a below ground cap was installed as required in the COA's from the BLM.

7. <u>Subsequent Plugging Reporting</u>: Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. <u>Show date well was plugged</u>.

8. <u>Trash</u>: All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation objectives.

<u>Timing Limitation Stipulation/Condition of Approval for Lesser Prairie-Chicken:</u> From March 1st through June 15th annually, abandonment activities will be allowed except between the hours from 3:00 am and 9:00 am. Normal vehicle use on existing roads will not be restricted