Office	State of New Mexico	Form C-103
District I - (575) 393-6161	Energy, Minerals and Natural Resource	Revised August 1, 2011
1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1283		WELL API NO. 30-025-44960
811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION	5. Indicate Type of Lease
<u>District III</u> - (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.	STATE X FEE
District IV - (505) 476-3460	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505		
SUNDRY NOTIC	CES AND REPORTS ON WELLS D	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOS	SALS TO DRILL OR TO DEFENSE ON PLUG BACK TO A CATION FOR PER CONTROL OF THE PROPERTY OF THE PR	_
PROPOSALS.)	A 2019	STATE 25
1. Type of Well: Oil Well X	Gas Well Other CT 0 4 2019	8. Well Number 001Y
2. Name of Operator	CEIVED	9. OGRID Number
CIMAREX ENERGY CO. OF COI	LORADO RECEIVED	162683
3. Address of Operator 600 N. MARIENFELD, SUITE 600		10. Pool name or Wildcat KEMNITZ; CISCO, SOUTH
4. Well Location	, WILDERTO, 111/4/10 17/101	REWINTE, CISCO, SOUTH
Unit Letter I : 23	20 feet from the SOUTH line and 380 fee	et from the EAST line
Section 25	Township 16S Range	33E NMPM LEA County
20000000	11. Elevation (Show whether DR, RKB, RT, GR	
	4,148' – GR	
Approved for Plugging of	well bore only. Liability under :e of Not	ice, Report or Other Data
bond is retained pending i	estoration and completion of	LIBSEOUENT DEDORT OF
the C-103. Specific for Su	bsequent Report of well	SUBSEQUENT REPORT OF: VORK
plugging, which may be for	und on the OCD wob noce	VORK
'- under torms.	J	MENT JOB PNR
PL Restoration Due by: 9	-30-20	٨,
		σ
OTHER:		LL PLUGGED AND ABANDONED 09/30/19.
13. Describe proposed or compl	eted operations. (Clearly state all pertinent detail	s, and give pertinent dates, including estimated date
13. Describe proposed or compl	eted operations. (Clearly state all pertinent detail rk). SEE RULE 19.15.7.14 NMAC. For Multipl	s, and give pertinent dates, including estimated date
13. Describe proposed or compl of starting any proposed wo proposed completion or reco	eted operations. (Clearly state all pertinent detail rk). SEE RULE 19.15.7.14 NMAC. For Multiplompletion.	s, and give pertinent dates, including estimated date e Completions: Attach wellbore diagram of
13. Describe proposed or complor of starting any proposed wo proposed completion or reco	eted operations. (Clearly state all pertinent detail rk). SEE RULE 19.15.7.14 NMAC. For Multiple ompletion. 0,800'; CIRC. WELL W/ M.L.F.; PRES. TEST 5	s, and give pertinent dates, including estimated date
13. Describe proposed or complete of starting any proposed wo proposed completion or recomplete of the starting any proposed wo proposed completion or recomplete of the starting and proposed complete of the starting and starti	eted operations. (Clearly state all pertinent detail rk). SEE RULE 19.15.7.14 NMAC. For Multiple ompletion. 0,800'; CIRC. WELL W/ M.L.F.; PRES. TEST 500'.	s, and give pertinent dates, including estimated date e Completions: Attach wellbore diagram of -1/2" CSG. TO 750# - HELD OK; PUMP 25 SXS.
13. Describe proposed or complor of starting any proposed wo proposed completion or recompletion of the completion of th	eted operations. (Clearly state all pertinent detail rk). SEE RULE 19.15.7.14 NMAC. For Multiple ompletion. 0,800'; CIRC. WELL W/ M.L.F.; PRES. TEST 500'. 0,750' – NOT FREE; ATTEMPT TO EST. INJ. F	s, and give pertinent dates, including estimated date completions: Attach wellbore diagram of -1/2" CSG. TO 750# - HELD OK; PUMP 25 SXS. ATE - PRES. UP TO 2,000# X HOLD.
13. Describe proposed or complor of starting any proposed wo proposed completion or recompletion of the completion of th	eted operations. (Clearly state all pertinent detail rk). SEE RULE 19.15.7.14 NMAC. For Multiple ompletion. 0,800'; CIRC. WELL W/ M.L.F.; PRES. TEST 500'. 0,750' – NOT FREE; ATTEMPT TO EST. INJ. F. (@ 9,840') (PER OCD); WOC X TAG CMT. (@ 9.840')	s, and give pertinent dates, including estimated date e Completions: Attach wellbore diagram of -1/2" CSG. TO 750# - HELD OK; PUMP 25 SXS. ATE - PRES. UP TO 2,000# X HOLD. 2,435' (OK'D BY OCD).
13. Describe proposed or complete of starting any proposed wo proposed completion or recomplete of the proposed completion or recomplete of the proposed completion or recomplete of the proposed complete of the proposed complete of the proposed or complete of the proposed or complete of the proposed or complete or proposed or complete or proposed or complete or proposed or	eted operations. (Clearly state all pertinent detail rk). SEE RULE 19.15.7.14 NMAC. For Multiple ompletion. 0,800'; CIRC. WELL W/ M.L.F.; PRES. TEST 500'. 0,750' – NOT FREE; ATTEMPT TO EST. INJ. F. @ 9,840' (PER OCD); WOC X TAG CMT. @ 9,8,000' – NOT FREE; ATTEMPT TO EST. INJ. F. 8,820' (PER OCD).	s, and give pertinent dates, including estimated date completions: Attach wellbore diagram of -1/2" CSG. TO 750# - HELD OK; PUMP 25 SXS. ATE - PRES. UP TO 2,000# X HOLD.
13. Describe proposed or complete of starting any proposed wo proposed completion or recomplete of the proposed completion or recomplete of the proposed completion or recomplete of the proposed complete of the proposed co	eted operations. (Clearly state all pertinent detail rk). SEE RULE 19.15.7.14 NMAC. For Multiple ompletion. 0,800'; CIRC. WELL W/ M.L.F.; PRES. TEST 500'. 0,750' – NOT FREE; ATTEMPT TO EST. INJ. F. (@ 9,840' (PER OCD); WOC X TAG CMT. (@ 9,800' – NOT FREE; ATTEMPT TO EST. INJ. F. (8,820' (PER OCD)). 8,820' (PER OCD). CSG. (@ 6,090'.	s, and give pertinent dates, including estimated date e Completions: Attach wellbore diagram of -1/2" CSG. TO 750# - HELD OK; PUMP 25 SXS. ATE - PRES. UP TO 2,000# X HOLD. 2,435' (OK'D BY OCD). ATE - PRES. UP TO 1,800# X HOLD; PUMP 40
13. Describe proposed or complete of starting any proposed wo proposed completion or recomplete of the proposed complete	eted operations. (Clearly state all pertinent detail rk). SEE RULE 19.15.7.14 NMAC. For Multiple ompletion. 0,800'; CIRC. WELL W/ M.L.F.; PRES. TEST 500'. 0,750' – NOT FREE; ATTEMPT TO EST. INJ. F. (29,840') (PER OCD); WOC X TAG CMT. (29,8090') – NOT FREE; ATTEMPT TO EST. INJ. F. (8,820') (PER OCD). CSG. (20,6090'). (20,6140'; WOC X TAG CMT. (20,5,896') (OK').	s, and give pertinent dates, including estimated date e Completions: Attach wellbore diagram of -1/2" CSG. TO 750# - HELD OK; PUMP 25 SXS. ATE - PRES. UP TO 2,000# X HOLD. 2,435' (OK'D BY OCD). ATE - PRES. UP TO 1,800# X HOLD; PUMP 40 BY OCD).
13. Describe proposed or complete of starting any proposed wo proposed completion or recomplete of the proposed complete of the proposed of the p	eted operations. (Clearly state all pertinent detail rk). SEE RULE 19.15.7.14 NMAC. For Multiple ompletion. 0,800'; CIRC. WELL W/ M.L.F.; PRES. TEST 500'. 0,750' – NOT FREE; ATTEMPT TO EST. INJ. F. (29.840') (PER OCD); WOC X TAG CMT. (29.840') (PER OCD). 8,820' (PER OCD). CSG. (20.6090'). (20.6140'; WOC X TAG CMT. (20.8896') (OK'). (30.6140'; WOC X TAG CMT. (30.8896') (OK'). (30.6140'; WOC X TAG CMT. (30.8896') (OK').	s, and give pertinent dates, including estimated date e Completions: Attach wellbore diagram of -1/2" CSG. TO 750# - HELD OK; PUMP 25 SXS. ATE - PRES. UP TO 2,000# X HOLD. 1,435' (OK'D BY OCD). ATE - PRES. UP TO 1,800# X HOLD; PUMP 40 D BY OCD). O BY OCD). O'; WOC.
13. Describe proposed or complete of starting any proposed wo proposed completion or recomplete of the proposed complete	eted operations. (Clearly state all pertinent detail rk). SEE RULE 19.15.7.14 NMAC. For Multiple ompletion. 0,800'; CIRC. WELL W/ M.L.F.; PRES. TEST 5.00'. 0,750' – NOT FREE; ATTEMPT TO EST. INJ. F. (2000) (PER OCD); WOC X TAG CMT. (2000) (PER OCD). CSG. (2000) (PER OCD). CSG. (2000) (CSG. (2000) (C	s, and give pertinent dates, including estimated date e Completions: Attach wellbore diagram of -1/2" CSG. TO 750# - HELD OK; PUMP 25 SXS. ATE - PRES. UP TO 2,000# X HOLD. 4,435' (OK'D BY OCD). ATE - PRES. UP TO 1,800# X HOLD; PUMP 40 BY OCD). BY OCD). O'; WOC. JMP 75 SXS. CMT. @ 1,680'; WOC X TAG
13. Describe proposed or complete of starting any proposed wo proposed completion or recomplete of the proposed complete	eted operations. (Clearly state all pertinent detail rk). SEE RULE 19.15.7.14 NMAC. For Multiple ompletion. 0,800'; CIRC. WELL W/ M.L.F.; PRES. TEST 500'. 0,750' – NOT FREE; ATTEMPT TO EST. INJ. F. (20) (10) (20) (20) (20) (20) (20) (20) (20) (2	s, and give pertinent dates, including estimated date e Completions: Attach wellbore diagram of -1/2" CSG. TO 750# - HELD OK; PUMP 25 SXS. ATE - PRES. UP TO 2,000# X HOLD. 4,435' (OK'D BY OCD). ATE - PRES. UP TO 1,800# X HOLD; PUMP 40 BY OCD). BY OCD). O'; WOC. JMP 75 SXS. CMT. @ 1,680'; WOC X TAG
13. Describe proposed or complete of starting any proposed wo proposed completion or recomplete of the proposed complete	eted operations. (Clearly state all pertinent detail rk). SEE RULE 19.15.7.14 NMAC. For Multiple ompletion. 0,800'; CIRC. WELL W/ M.L.F.; PRES. TEST 5.00'. 0,750' – NOT FREE; ATTEMPT TO EST. INJ. F. @ 9,840' (PER OCD); WOC X TAG CMT. @ 9.8,090' – NOT FREE; ATTEMPT TO EST. INJ. F. 8,820' (PER OCD). CSG. @ 6,090'. @ 6,140'; WOC X TAG CMT. @ 5,896' (OK'E. @ 4,620'-4,480'; PUMP 55 SXS. CMT. @ 2,855. PUMP 25 SXS. CMT. @ 2,804' (PER OCD); PLO BY OCD); MIX X CIRC. TO SURF. 25 SXS. F. WELLHEAD 3' B.G.L.; WELD ON STEEL P.	s, and give pertinent dates, including estimated date e Completions: Attach wellbore diagram of -1/2" CSG. TO 750# - HELD OK; PUMP 25 SXS. ATE - PRES. UP TO 2,000# X HOLD. 2,435' (OK'D BY OCD). ATE - PRES. UP TO 1,800# X HOLD; PUMP 40 BY OCD). O'; WOC. JMP 75 SXS. CMT. @ 1,680'; WOC X TAG CMT. @ 63'-3'.
13. Describe proposed or complete of starting any proposed wo proposed completion or recomplete of the proposed completion or recomplete of the proposed completion or recomplete of the proposed complete of the proposed co	eted operations. (Clearly state all pertinent detail rk). SEE RULE 19.15.7.14 NMAC. For Multiple ompletion. 0,800'; CIRC. WELL W/ M.L.F.; PRES. TEST 5.00'. 0,750' – NOT FREE; ATTEMPT TO EST. INJ. F. @ 9,840' (PER OCD); WOC X TAG CMT. @ 9.8,090' – NOT FREE; ATTEMPT TO EST. INJ. F. 8,820' (PER OCD). CSG. @ 6,090'. @ 6,140'; WOC X TAG CMT. @ 5,896' (OK'E. @ 4,620'-4,480'; PUMP 55 SXS. CMT. @ 2,855. PUMP 25 SXS. CMT. @ 2,804' (PER OCD); PLO BY OCD); MIX X CIRC. TO SURF. 25 SXS. F. WELLHEAD 3' B.G.L.; WELD ON STEEL P.	s, and give pertinent dates, including estimated date e Completions: Attach wellbore diagram of -1/2" CSG. TO 750# - HELD OK; PUMP 25 SXS. ATE - PRES. UP TO 2,000# X HOLD. 2,435' (OK'D BY OCD). ATE - PRES. UP TO 1,800# X HOLD; PUMP 40 BY OCD). O'; WOC. JMP 75 SXS. CMT. @ 1,680'; WOC X TAG CMT. @ 63'-3'.
13. Describe proposed or complete of starting any proposed wo proposed completion or recomplete of the proposed completion or recomplete of the proposed completion or recomplete of the proposed complete of the proposed co	eted operations. (Clearly state all pertinent detail rk). SEE RULE 19.15.7.14 NMAC. For Multiple ompletion. 0,800'; CIRC. WELL W/ M.L.F.; PRES. TEST 500'. 0,750' – NOT FREE; ATTEMPT TO EST. INJ. F. @ 9,840' (PER OCD); WOC X TAG CMT. @ 98,090' – NOT FREE; ATTEMPT TO EST. INJ. F. 8,820' (PER OCD). CSG. @ 6,090'. @ 6,140'; WOC X TAG CMT. @ 5,896' (OK'E @ 4,620'-4,480'; PUMP 55 SXS. CMT. @ 2,85. PUMP 25 SXS. CMT. @ 2,804' (PER OCD); PLO BY OCD); MIX X CIRC. TO SURF. 25 SXS. F. WELLHEAD 3' B.G.L.; WELD ON STEEL PLR.	s, and give pertinent dates, including estimated date e Completions: Attach wellbore diagram of -1/2" CSG. TO 750# - HELD OK; PUMP 25 SXS. ATE - PRES. UP TO 2,000# X HOLD. 2,435' (OK'D BY OCD). ATE - PRES. UP TO 1,800# X HOLD; PUMP 40 BY OCD). O'; WOC. JMP 75 SXS. CMT. @ 1,680'; WOC X TAG CMT. @ 63'-3'.
13. Describe proposed or complete of starting any proposed wo proposed completion or recomplete of the proposed completion or recomplete of the proposed completion or recomplete of the proposed complete of the proposed co	eted operations. (Clearly state all pertinent detail rk). SEE RULE 19.15.7.14 NMAC. For Multiple ompletion. 0,800'; CIRC. WELL W/ M.L.F.; PRES. TEST 500'. 0,750' – NOT FREE; ATTEMPT TO EST. INJ. F. @ 9,840' (PER OCD); WOC X TAG CMT. @ 98,090' – NOT FREE; ATTEMPT TO EST. INJ. F. 8,820' (PER OCD). CSG. @ 6,090'. @ 6,140'; WOC X TAG CMT. @ 5,896' (OK'E @ 4,620'-4,480'; PUMP 55 SXS. CMT. @ 2,85. PUMP 25 SXS. CMT. @ 2,804' (PER OCD); PLO BY OCD); MIX X CIRC. TO SURF. 25 SXS. F. WELLHEAD 3' B.G.L.; WELD ON STEEL PLR.	s, and give pertinent dates, including estimated date e Completions: Attach wellbore diagram of -1/2" CSG. TO 750# - HELD OK; PUMP 25 SXS. ATE – PRES. UP TO 2,000# X HOLD. 2,435' (OK'D BY OCD). ATE – PRES. UP TO 1,800# X HOLD; PUMP 40 BY OCD). O'; WOC. JMP 75 SXS. CMT. @ 1,680'; WOC X TAG CMT. @ 63'-3'. ATE TO CSG. X INSTALL ABOVE GROUND
13. Describe proposed or complete of starting any proposed wo proposed completion or recomplete of starting any proposed wo proposed completion or recomplete of the proposed complete of the propos	eted operations. (Clearly state all pertinent detail rk). SEE RULE 19.15.7.14 NMAC. For Multiple ompletion. 0,800'; CIRC. WELL W/ M.L.F.; PRES. TEST 500'. 0,750' – NOT FREE; ATTEMPT TO EST. INJ. F. @ 9,840' (PER OCD); WOC X TAG CMT. @ 98,090' – NOT FREE; ATTEMPT TO EST. INJ. F. 8,820' (PER OCD). CSG. @ 6,090'. @ 6,140'; WOC X TAG CMT. @ 5,896' (OK'E @ 4,620'-4,480'; PUMP 55 SXS. CMT. @ 2,85. PUMP 25 SXS. CMT. @ 2,804' (PER OCD); PLO BY OCD); MIX X CIRC. TO SURF. 25 SXS. F. WELLHEAD 3' B.G.L.; WELD ON STEEL PLR.	s, and give pertinent dates, including estimated date e Completions: Attach wellbore diagram of -1/2" CSG. TO 750# - HELD OK; PUMP 25 SXS. ATE - PRES. UP TO 2,000# X HOLD. 435' (OK'D BY OCD). ATE - PRES. UP TO 1,800# X HOLD; PUMP 40 BY OCD). O'; WOC. JMP 75 SXS. CMT. @ 1,680'; WOC X TAG CMT. @ 63'-3'. LATE TO CSG. X INSTALL ABOVE GROUND PXA EQUIP. 09/30/19
13. Describe proposed or complete of starting any proposed wo proposed completion or recomplete of starting any proposed wo proposed completion or recomplete of the proposed complete of the propos	eted operations. (Clearly state all pertinent detail rk). SEE RULE 19.15.7.14 NMAC. For Multiple ompletion. 0,800'; CIRC. WELL W/ M.L.F.; PRES. TEST 500'. 0,750' – NOT FREE; ATTEMPT TO EST. INJ. F. @ 9,840' (PER OCD); WOC X TAG CMT. @ 98,090' – NOT FREE; ATTEMPT TO EST. INJ. F. 8,820' (PER OCD). CSG. @ 6,090'. @ 6,140'; WOC X TAG CMT. @ 5,896' (OK'I. @ 4,620'-4,480'; PUMP 55 SXS. CMT. @ 2,856'. PUMP 25 SXS. CMT. @ 2,804' (PER OCD); Plot of the process of the pro	s, and give pertinent dates, including estimated date e Completions: Attach wellbore diagram of -1/2" CSG. TO 750# - HELD OK; PUMP 25 SXS. ATE - PRES. UP TO 2,000# X HOLD. 435' (OK'D BY OCD). ATE - PRES. UP TO 1,800# X HOLD; PUMP 40 BY OCD). O'; WOC. JMP 75 SXS. CMT. @ 1,680'; WOC X TAG CMT. @ 63'-3'. LATE TO CSG. X INSTALL ABOVE GROUND PXA EQUIP. 09/30/19
13. Describe proposed or complete of starting any proposed wo proposed completion or recomplete of the proposed completion or recomplete of the proposed completion or recomplete of the proposed complete of the proposed co	eted operations. (Clearly state all pertinent detail rk). SEE RULE 19.15.7.14 NMAC. For Multiple ompletion. 0,800'; CIRC. WELL W/ M.L.F.; PRES. TEST 5.00'. 0,750' – NOT FREE; ATTEMPT TO EST. INJ. F. (2000). (2000	s, and give pertinent dates, including estimated date e Completions: Attach wellbore diagram of -1/2" CSG. TO 750# - HELD OK; PUMP 25 SXS. ATE – PRES. UP TO 2,000# X HOLD. 9,435' (OK'D BY OCD). ATE – PRES. UP TO 1,800# X HOLD; PUMP 40 O BY OCD). O'; WOC. JMP 75 SXS. CMT. @ 1,680'; WOC X TAG CMT. @ 63'-3'. ATE TO CSG. X INSTALL ABOVE GROUND PXA EQUIP. 09/30/19
13. Describe proposed or complete of starting any proposed wo proposed completion or recomplete of starting any proposed wo proposed completion or recomplete of the proposed complete of the propos	eted operations. (Clearly state all pertinent detail rk). SEE RULE 19.15.7.14 NMAC. For Multiple ompletion. 0,800'; CIRC. WELL W/ M.L.F.; PRES. TEST 500'. 0,750' – NOT FREE; ATTEMPT TO EST. INJ. F. @ 9,840' (PER OCD); WOC X TAG CMT. @ 98,090' – NOT FREE; ATTEMPT TO EST. INJ. F. 8,820' (PER OCD). CSG. @ 6,090'. @ 6,140'; WOC X TAG CMT. @ 5,896' (OK'I. @ 4,620'-4,480'; PUMP 55 SXS. CMT. @ 2,856'. PUMP 25 SXS. CMT. @ 2,804' (PER OCD); Plot of the process of the pro	s, and give pertinent dates, including estimated date e Completions: Attach wellbore diagram of -1/2" CSG. TO 750# - HELD OK; PUMP 25 SXS. ATE - PRES. UP TO 2,000# X HOLD. 435' (OK'D BY OCD). ATE - PRES. UP TO 1,800# X HOLD; PUMP 40 BY OCD). O'; WOC. JMP 75 SXS. CMT. @ 1,680'; WOC X TAG CMT. @ 63'-3'. LATE TO CSG. X INSTALL ABOVE GROUND PXA EQUIP. 09/30/19
13. Describe proposed or complete of starting any proposed wo proposed completion or recomplete of starting any proposed wo proposed completion or recomplete of the proposed complete of the propos	eted operations. (Clearly state all pertinent detail rk). SEE RULE 19.15.7.14 NMAC. For Multiple ompletion. 0,800'; CIRC. WELL W/ M.L.F.; PRES. TEST 500'. 0,750' – NOT FREE; ATTEMPT TO EST. INJ. F. @ 9,840' (PER OCD); WOC X TAG CMT. @ 98,090' – NOT FREE; ATTEMPT TO EST. INJ. F. 8,820' (PER OCD). CSG. @ 6,090'. @ 6,140'; WOC X TAG CMT. @ 5,896' (OK'D. @ 4,620'-4,480'; PUMP 55 SXS. CMT. @ 2,850. PUMP 25 SXS. CMT. @ 2,804' (PER OCD); PO BY OCD); MIX X CIRC. TO SURF. 25 SXS. F. WELLHEAD 3' B.G.L.; WELD ON STEEL POR. O9/18/19 RDMO TITLE: AGENT	s, and give pertinent dates, including estimated date e Completions: Attach wellbore diagram of -1/2" CSG. TO 750# - HELD OK; PUMP 25 SXS. ATE – PRES. UP TO 2,000# X HOLD. 9,435' (OK'D BY OCD). ATE – PRES. UP TO 1,800# X HOLD; PUMP 40 O BY OCD). O'; WOC. JMP 75 SXS. CMT. @ 1,680'; WOC X TAG CMT. @ 63'-3'. ATE TO CSG. X INSTALL ABOVE GROUND PXA EQUIP. 09/30/19
13. Describe proposed or complete of starting any proposed wo proposed completion or recomplete of the proposed completion or recomplete of the proposed completion or recomplete of the proposed complete of the proposed co	eted operations. (Clearly state all pertinent detail rk). SEE RULE 19.15.7.14 NMAC. For Multiple ompletion. 0,800'; CIRC. WELL W/ M.L.F.; PRES. TEST 5.00'. 0,750' – NOT FREE; ATTEMPT TO EST. INJ. F. @ 9,840' (PER OCD); WOC X TAG CMT. @ 9.8,090' – NOT FREE; ATTEMPT TO EST. INJ. F. 8,820' (PER OCD). CSG. @ 6,090'. @ 6,140'; WOC X TAG CMT. @ 5,896' (OK'E. @ 4,620'-4,480'; PUMP 55 SXS. CMT. @ 2,855. PUMP 25 SXS. CMT. @ 2,804' (PER OCD); P.D. BY OCD); MIX X CIRC. TO SURF. 25 SXS. F. WELLHEAD 3' B.G.L.; WELD ON STEEL P.R. 109/18/19 RDMO Above is true and complete to the best of my known above	s, and give pertinent dates, including estimated date e Completions: Attach wellbore diagram of -1/2" CSG. TO 750# - HELD OK; PUMP 25 SXS. ATE - PRES. UP TO 2,000# X HOLD. (435' (OK'D BY OCD). ATE - PRES. UP TO 1,800# X HOLD; PUMP 40 BY OCD). (2) BY OCD). (3) WOC. (4) JMP 75 SXS. CMT. @ 1,680'; WOC X TAG (5) CMT. @ 63'-3'. (6) ATE TO CSG. X INSTALL ABOVE GROUND PXA EQUIP. 09/30/19 Pledge and belief. DATE: 10/01/19 (AGRO-RES.COM PHONE: 432.687.3033)
13. Describe proposed or complete of starting any proposed wo proposed completion or recomplete of starting any proposed wo proposed completion or recomplete of the proposed complete of the propos	eted operations. (Clearly state all pertinent detail rk). SEE RULE 19.15.7.14 NMAC. For Multiple ompletion. 0,800'; CIRC. WELL W/ M.L.F.; PRES. TEST 500'. 0,750' – NOT FREE; ATTEMPT TO EST. INJ. F. @ 9,840' (PER OCD); WOC X TAG CMT. @ 98,090' – NOT FREE; ATTEMPT TO EST. INJ. F. 8,820' (PER OCD). CSG. @ 6,090'. @ 6,140'; WOC X TAG CMT. @ 5,896' (OK'D. @ 4,620'-4,480'; PUMP 55 SXS. CMT. @ 2,850. PUMP 25 SXS. CMT. @ 2,804' (PER OCD); PO BY OCD); MIX X CIRC. TO SURF. 25 SXS. F. WELLHEAD 3' B.G.L.; WELD ON STEEL POR. O9/18/19 RDMO TITLE: AGENT	s, and give pertinent dates, including estimated date e Completions: Attach wellbore diagram of -1/2" CSG. TO 750# - HELD OK; PUMP 25 SXS. ATE – PRES. UP TO 2,000# X HOLD. 2,435' (OK'D BY OCD). ATE – PRES. UP TO 1,800# X HOLD; PUMP 40 BY OCD). O'; WOC. JMP 75 SXS. CMT. @ 1,680'; WOC X TAG CMT. @ 63'-3'. ATE TO CSG. X INSTALL ABOVE GROUND PXA EQUIP. 09/30/19 Pledge and belief. DATE: 10/01/19