

Submit 1 Copy To Appropriate District State of New Mexico	Form C-103
District I – (575) 393-6161 Energy, Minerals and Natural Resources	Revised August 1, 2011 WELL API NO.
District II – (575) 748-1283 811 S. First St., Artesia, NM 88210 OIL CONSERVATORDIVISION	30-025-30305
District III – (505) 334-6178 1220 South St. Francis DOCA	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NHA 876360 District IV - (505) 476-3460 Santa Fe, NHA 87635 1220 S. St. Francis Dr., Santa Fe, NM	6. State Oil & Gas Lease No. B-9311
87505 RE-	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUCHER TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	7. Lease Name or Unit Agreement Name WEST DOLLARHIDE QUEEN SAND UNIT
1. Type of Well: Oil Well Gas Well Other INJECTOR	8. Well Number 148
2. Name of Operator	9. OGRID Number 309777
RAM ENERGY LLC 3. Address of Operator	10. Pool name or Wildcat
2100 S. UTICA AVE., SUITE 175, TULSA, OK 74114	DOLLARHIDE QUEEN (018810)
4. Well Location	
Unit Letter V 2 700 feet from the SOUTH line and 550	
Section 32 Township 24S Range 38E 11. Elevation (Show whether DR, RKB, RT, GR, etc.	NMPM LEA County
11. Elevation (Snow whether DR, RKB, R1, GR, etc. 3135' GL	
0.1	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: 🛩 SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK 🔲 PLUG AND ABANDON 🛛 🖛 REMEDIAL WORK 🔲 ALTERING CASING 🗌	
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEI DOWNHOLE COMMINGLE	ІТ ЈОВ 📋
OTHER: OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of	
proposed completion or recompletion.	
1 NOTIEV NMOCD 24 LIDS DEEODE MIDLI	
 NOTIFY NMOCD 24 HRS. BEFORE MIRU. MIRU. ND WH, NU BOPE. 	
3. SET CIBP@3500'. SPOT 25SX OF CLASS "C" CEMENT FROM 3500'-3250'.	
 CIRCULATE 9.5 PPG MLF AND TEST CASING. SPOT 35SX OF CLASS "C" CEMENT FROM 2725'-2405'. WOC&TAG. (YATES/B.SALT) 	
 SPOT 35SX OF CLASS "C" CEMENT FROM 2725'-2405'. WOC&TAG. (YATES/B.SALT) SPOT 25SX OF CLASS "C" CEMENT FROM 1250'-1100'. WOC&TAG. (T.SALT) 	
7. SPOT 55SX OF CLASS "C" CEMENT FROM 462'-SURFACE. VERIFY CEMENT TO SURFACE. (FW/SHOE/SURFACE).	
8. CUTOFF WELLHEAD, ANCHORS 3' BELOW SURFACE AND INSTALL D RECLAMATION.	RYHOLE MARKER. TURN OVER FOR
RECLAMATION.	
CLOSED LOOP CONTAINMENT SYSTEM WILL BE USED FOR FLUIDS.	
	See Attached
Spud Date: Rig Release Date:	Conditions of Approval
I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
SIGNATURE	
Type or print name MATTHEW PATTERSON_E-mail address: <u>MPATTERSON@RAMENERGY.NET</u> PHONE: (918)947-6301_ For State Use Only	
APPROVED BY: Kenny father TITLE C. 6 A DATE 12-11-19	
Conditions of Approval (if any):	

/

WELLBORE DIAGRAM WEST DOLLARHIDE QUEEN SAND UNIT #148



WELLBORE DIAGRAM WEST DOLLARHIDE QUEEN SAND UNIT #148



CONDITIONS FOR PLUGGING AND ABANDONMENT

OCD - Southern District

The following is a guide or checklist in preparation of a plugging program, this is not all inclusive and care must be exercised in establishing special plugging programs in unique and unusual cases, Notify NMOCD District Office I (Hobbs) at (575)-399-3221 at least 24 hours before beginning work. After MIRU rig will remain on well until it is plugged to surface. OCD is to be notified before rig down. Company representative will be on location during plugging procedures.

- 1. A notice of intent to plug and abandon a wellbore is required to be approved before plugging operations are conducted. A cement evaluation tool is required in order to ensure isolation of producing formations, protection of water and correlative rights. A cement bond log or other accepted cement evaluation tool is to be provided to the division for evaluation if one has not been previously run or if the well did not have cement circulated to surface during the original casing cementing job or subsequent cementing jobs. Insure all bradenheads have been exposed, identified and valves are operational prior to rig up.
- 2. Closed loop system is to be used for entire plugging operation. Upon completion, contents of steel pits are to be hauled to a permitted disposal location.
- 3. Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator as well as the contractor, to verify that this permit is in place prior to performing work. Drivers shall be able to produce a copy upon request of an NMOCD Field inspector.
- 4. Filing a subsequent C-103 will serve as notification that the well has been plugged.
- 5. A final C-103 shall be filed (and a site inspection by NMOCD Inspector to determine if the location is satisfactorily cleaned, all equipment, electric poles and trash has been removed to Meet NMOCD standards) before bonding can be released.
- 6. If work has not begun within 1 Year of the approval of this procedure, an extension request must be file stating the reason the well has not been plugged.
- 7. Squeeze pressures are not to exceed 500 psi, unless approval is given by NMOCD.
- 8. Produced water will not be used during any part of the plugging operation.
- 9. Mud laden fluids must be placed between all cement plugs mixed at 25 sacks per 100 bbis of water.
- 10. All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater. 50' of calculated cement excess required for inside casing plugs and 100% calculated cement excess required on outside casing plugs.
- 11. Class 'C' cement will be used above 7500 feet.
- 12. Class 'H' cement will be used below 7500 feet.
- 13. A cement plug is required to be set 50' above and 50' below, casing stubs, DV tools, attempted casing cut offs, cement tops outside casing, salt sections and anywhere the casing is perforated, these plugs require a 4 hour WOC and then will be tagged
- 14. All Casing Shoes Will Be Perforated 50' below shoe depth and Attempted to be Squeezed, cement needs to be 50' above and 50' Below Casing Shoe inside the Production Casing.