

Submit I Copy To Appropriate District Office	State of New Mexico			Form C-103	
<u>District I</u> – (575) 393-6161	Energy, Minerals and Natural Resources			Revised July 18, 2013	
1625 N. French Dr., Hobbs, NM 88240				WELL API NO.	
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION			<u>30-025-04</u>	
District III - (505) 334-6178	1220 South St. Francis Dr.			5. Indicate Type STATE	
1000 Rio Brazos Rd., Aztec, NM 87410 District IV – (505) 476-3460	Santa Fe, NM 87505			6. State Oil &	
1220 S. St. Empreis Dr. Sente En NM	,			030435	
87505		AD	as ocu		
87505 SUNDRY NOTICES AND REPORTS ON BBBS OCD (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A				7. Lease Name State AC	e or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR & USE "APPLICATION FOR PERMIT"					
		-		8. Well Numbe	er I
1. Type of Well: Oil Well	Gas Well 🛛 Other		CEIVED		
2. Name of Operator Burgundy Oil & Gas of New Me	vico Inc	RE	CENT	9. OGRID Nur 003044	nber
3. Address of Operator				10. Pool name	or Wildcat
505 N. Big Spring St., Suite 603	Midland, TX 79701				s-7Rvrs-Queen (Pro Gas)
4. Well Location	,				
Unit Letter B :	1910 feet from the	N	line and 19	RA faat from	the <u>E</u> line
Section 2					
Section 2					unty Lea
	11. Elevation (Show whether DR, RKB, RT, GR, etc. 3517' GL				
NOTICE OF INTENTION TO: Y SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK □ PLUG AND ABANDON □ REMEDIAL WORK □ ALTERING CASING □ TEMPORARILY ABANDON □ CHANGE PLANS □ COMMENCE DRILLING OPNS.□ P AND A □ PULL OR ALTER CASING □ MULTIPLE COMPL □ CASING/CEMENT JOB □ □ DOWNHOLE COMMINGLE □ □ CASING/CEMENT JOB □ □ OTHER: □ OTHER: □ 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 1. Set 5 ½" CIBP @ 2625'. Circ hole w/ MLF. Pressure test csg. Spot 25 sx cmt @ 2625-2450'. WOC & Tag (B/Salt) 2. Perf & Sqz 60 sx cmt @ 1340-1070'. WOC & Tag (8 5/8" Shoe, T/Salt) 3. Perf & Sqz 25-sx cmt @ 56' to Surface. Cift C I50'					
				See A Conditions	ttached of Approval
Spud Date:	Rig Rel	ease Da	te:		
I hereby certify that the information above is true and complete to the best of my knowledge and belief.					
SIGNATURE Indy K. amplel TITLE_Production AccountantDATE12/20/2019					
Type or print nameCindy K. Campbell E-mail address:ccampbell@burgundy-oil.com _ PHONE: _432-684-4033 For State Use Only					
APPROVED BY: <u>Yuny</u> Jun Conditions of Approval (i G any):	terTITLE_	<u>c (</u>		<u>/</u>	DATE 1-7-20

1

.

(





CONDITIONS FOR PLUGGING AND ABANDONMENT

OCD - Southern District

The following is a guide or checklist in preparation of a plugging program, this is not all inclusive and care must be exercised in establishing special plugging programs in unique and unusual cases, Notify NMOCD District Office I (Hobbs) at (575)-399-3221 at least 24 hours before beginning work. After MIRU rig will remain on well until it is plugged to surface. OCD is to be notified before rig down. Company representative will be on location during plugging procedures.

- 1. A notice of intent to plug and abandon a wellbore is required to be approved before plugging operations are conducted. A cement evaluation tool is required in order to ensure isolation of producing formations, protection of water and correlative rights. A cement bond log or other accepted cement evaluation tool is to be provided to the division for evaluation if one has not been previously run or if the well did not have cement circulated to surface during the original casing cementing job or subsequent cementing jobs. Insure all bradenheads have been exposed, identified and valves are operational prior to rig up.
- 2. Closed loop system is to be used for entire plugging operation. Upon completion, contents of steel pits are to be hauled to a permitted disposal location.
- 3. Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator as well as the contractor, to verify that this permit is in place prior to performing work. Drivers shall be able to produce a copy upon request of an NMOCD Field inspector.
- 4. Filing a subsequent C-103 will serve as notification that the well has been plugged.
- 5. A final C-103 shall be filed (and a site inspection by NMOCD Inspector to determine if the location is satisfactorily cleaned, all equipment, electric poles and trash has been removed to Meet NMOCD standards) before bonding can be released.
- 6. If work has not begun within 1 Year of the approval of this procedure, an extension request must be file stating the reason the well has not been plugged.
- 7. Squeeze pressures are not to exceed 500 psi, unless approval is given by NMOCD.
- 8. Produced water will not be used during any part of the plugging operation.
- 9. Mud laden fluids must be placed between all cement plugs mixed at 25 sacks per 100 bbis of water.
- 10. All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater. 50' of calculated cement excess required for inside casing plugs and 100% calculated cement excess required on outside casing plugs.
- 11. Class 'C' cement will be used above 7500 feet.
- 12. Class 'H' cement will be used below 7500 feet.
- 13. A cement plug is required to be set 50' above and 50' below, casing stubs, DV tools, attempted casing cut offs, cement tops outside casing, salt sections and anywhere the casing is perforated, these plugs require a 4 hour WOC and then will be tagged
- 14. All Casing Shoes Will Be Perforated 50' below shoe depth and Attempted to be Squeezed, cement needs to be 50' above and 50' Below Casing Shoe inside the Production Casing.