Submit I Copy To Appropriate District State of New Mexico	Form C-103
Office	Revised July 18, 2013
District 1 – (575) 393-6161 Energy, Minerals and Natural Resources 1625 N. French Dr., Hobbs, NM 88240	WELL API NO.
District II (575) 748-1283	30-025-33280
811 S. First St., Artesia, NM 88210 OIL CONSERVATION DIVISION	5. Indicate Type of Lease
<u>District III</u> – (505) 334-6178 1220 South St. Francis Dr.	STATE STATE
1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM	State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM	Botale of a Gas Lease No.
87505	
SUNDRY NOTICES AND REPORTS ON WELLS FEB 2 4 2020	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	
PROPOSALS.)	ALASKA COOPER
1. Type of Well: Oil Well 🔲 Gas Well 🛛 Other	8. Well Number 9
2. Name of Operator	9. OGRID Number
LEGACY RESERVES OPERATING LP	240974
3. Address of Operator	10. Pool name or Wildcat
PO BOX 10848, MIDLAND, TX 79702	Eumont; Yates-7 Rvrs-Queen (Gas)
4. Well Location	I
Unit Letter <u>P</u> : <u>760</u> feet from the <u>SOUTH</u> line and <u>60</u>	<u>50</u> feet from the <u>EAST</u> line
	NMPM County LEA
11. Elevation (Show whether DR, RKB, RT, GR, etc.,	
3547' GL	<u>.</u>
12. Check Appropriate Box to Indicate Nature of Notice,	Report or Other Data
	SEQUENT REPORT OF:
TEMPORARILY ABANDON 🛛 CHANGE PLANS 🔲 COMMENCE DRI	
PULL OR ALTER CASING DIMULTIPLE COMPL CASING/CEMEN	ГЈОВ 🗌
13. Describe proposed or completed operations. (Clearly state all pertinent details, an	a nortinent dates including estimated date
of starting and managed words) SEE DULE 10.15.7.14 MMAG. For Makinle Co.	
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Con	
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Conproposed completion or recompletion.	
proposed completion or recompletion.	npletions: Attach wellbore diagram of
proposed completion or recompletion. Legacy Reserves requests permission to temporarily abandon (TA) the Alaska Cod	npletions: Attach wellbore diagram of
proposed completion or recompletion.	npletions: Attach wellbore diagram of
proposed completion or recompletion. Legacy Reserves requests permission to temporarily abandon (TA) the Alaska Complace the wellbore in TA status for future utilization of the well.	npletions: Attach wellbore diagram of
proposed completion or recompletion. Legacy Reserves requests permission to temporarily abandon (TA) the Alaska Complace the wellbore in TA status for future utilization of the well. TA Procedure:	npletions: Attach wellbore diagram of
proposed completion or recompletion. Legacy Reserves requests permission to temporarily abandon (TA) the Alaska Complace the wellbore in TA status for future utilization of the well. TA Procedure: A) Displace hole w/packer fluid.	npletions: Attach wellbore diagram of oper #9 for 5 years. Legacy would like to
proposed completion or recompletion. Legacy Reserves requests permission to temporarily abandon (TA) the Alaska Complace the wellbore in TA status for future utilization of the well. TA Procedure: A) Displace hole w/packer fluid. B) Set CIBP @ ~2,700'.	npletions: Attach wellbore diagram of
proposed completion or recompletion. Legacy Reserves requests permission to temporarily abandon (TA) the Alaska Complace the wellbore in TA status for future utilization of the well. TA Procedure: A) Displace hole w/packer fluid. B) Set CIBP @ ~2,700'. C) Set 50' cmt plug (class C cmt) on top of CIBP.	npletions: Attach wellbore diagram of oper #9 for 5 years. Legacy would like to
proposed completion or recompletion. Legacy Reserves requests permission to temporarily abandon (TA) the Alaska Complace the wellbore in TA status for future utilization of the well. TA Procedure: A) Displace hole w/packer fluid. B) Set CIBP @ ~2,700'. C) Set 50' cmt plug (class C cmt) on top of CIBP. D) Pressure test and chart casing. TA well. <b>Conditional</b>	npletions: Attach wellbore diagram of oper #9 for 5 years. Legacy would like to on of Approval: no. Hobbs office 24 hours
proposed completion or recompletion. Legacy Reserves requests permission to temporarily abandon (TA) the Alaska Complace the wellbore in TA status for future utilization of the well. TA Procedure: A) Displace hole w/packer fluid. B) Set CIBP @ ~2,700'. C) Set 50' cmt plug (class C cmt) on top of CIBP. D) Pressure test and chart casing. TA well. <b>Conditional</b>	npletions: Attach wellbore diagram of oper #9 for 5 years. Legacy would like to on of Approval: nc.
proposed completion or recompletion. Legacy Reserves requests permission to temporarily abandon (TA) the Alaska Complace the wellbore in TA status for future utilization of the well. TA Procedure: A) Displace hole w/packer fluid. B) Set CIBP @ ~2,700'. C) Set 50' cmt plug (class C cmt) on top of CIBP. D) Pressure test and chart casing. TA well. <b>Conditional</b>	npletions: Attach wellbore diagram of oper #9 for 5 years. Legacy would like to on of Approval: no. Hobbs office 24 hours
proposed completion or recompletion. Legacy Reserves requests permission to temporarily abandon (TA) the Alaska Complace the wellbore in TA status for future utilization of the well. TA Procedure: A) Displace hole w/packer fluid. B) Set CIBP @ ~2,700'. C) Set 50' cmt plug (class C cmt) on top of CIBP. D) Pressure test and chart casing. TA well. <b>Conditional</b>	npletions: Attach wellbore diagram of oper #9 for 5 years. Legacy would like to on of Approval: no. Hobbs office 24 hours
proposed completion or recompletion. Legacy Reserves requests permission to temporarily abandon (TA) the Alaska Complace the wellbore in TA status for future utilization of the well. TA Procedure: A) Displace hole w/packer fluid. B) Set CIBP @ ~2,700'. C) Set 50' cmt plug (class C cmt) on top of CIBP. D) Pressure test and chart casing. TA well. OCD I prior of ru	npletions: Attach wellbore diagram of oper #9 for 5 years. Legacy would like to on of Approval: no. Hobbs office 24 hours
proposed completion or recompletion. Legacy Reserves requests permission to temporarily abandon (TA) the Alaska Complace the wellbore in TA status for future utilization of the well. TA Procedure: A) Displace hole w/packer fluid. B) Set CIBP @ ~2,700'. C) Set 50' cmt plug (class C cmt) on top of CIBP. D) Pressure test and chart casing. TA well. <b>Conditional</b>	npletions: Attach wellbore diagram of oper #9 for 5 years. Legacy would like to on of Approval: no. Hobbs office 24 hours
proposed completion or recompletion. Legacy Reserves requests permission to temporarily abandon (TA) the Alaska Complace the wellbore in TA status for future utilization of the well. TA Procedure: A) Displace hole w/packer fluid. B) Set CIBP @ ~2,700'. C) Set 50' cmt plug (class C cmt) on top of CIBP. D) Pressure test and chart casing. TA well. OCD I prior of ru	npletions: Attach wellbore diagram of oper #9 for 5 years. Legacy would like to on of Approval: no. Hobbs office 24 hours
proposed completion or recompletion. Legacy Reserves requests permission to temporarily abandon (TA) the Alaska Complace the wellbore in TA status for future utilization of the well. TA Procedure: A) Displace hole w/packer fluid. B) Set CIBP @ ~2,700'. C) Set 50' cmt plug (class C cmt) on top of CIBP. D) Pressure test and chart casing. TA well. OCD I prior of ru	npletions: Attach wellbore diagram of oper #9 for 5 years. Legacy would like to on of Approval: no. Hobbs office 24 hours
proposed completion or recompletion. Legacy Reserves requests permission to temporarily abandon (TA) the Alaska Complace the wellbore in TA status for future utilization of the well. TA Procedure: A) Displace hole w/packer fluid. B) Set CIBP @ ~2,700'. C) Set 50' cmt plug (class C cmt) on top of CIBP. D) Pressure test and chart casing. TA well. OCD I prior of ru Spud Date: Spud Date:	npletions: Attach wellbore diagram of oper #9 for 5 years. Legacy would like to on of Approval: no. Hobbs office 24 hours Inning MIT Test & Chart
proposed completion or recompletion. Legacy Reserves requests permission to temporarily abandon (TA) the Alaska Complace the wellbore in TA status for future utilization of the well. TA Procedure: A) Displace hole w/packer fluid. B) Set CIBP @ ~2,700'. C) Set 50' cmt plug (class C cmt) on top of CIBP. D) Pressure test and chart casing. TA well. OCD I prior of ru	npletions: Attach wellbore diagram of oper #9 for 5 years. Legacy would like to on of Approval: no. Hobbs office 24 hours Inning MIT Test & Chart
proposed completion or recompletion. Legacy Reserves requests permission to temporarily abandon (TA) the Alaska Complace the wellbore in TA status for future utilization of the well. TA Procedure: A) Displace hole w/packer fluid. B) Set CIBP @ ~2,700'. C) Set 50' cmt plug (class C cmt) on top of CIBP. D) Pressure test and chart casing. TA well. OCD I prior of ru Spud Date: Spud Date:	npletions: Attach wellbore diagram of oper #9 for 5 years. Legacy would like to on of Approval: no. Hobbs office 24 hours Inning MIT Test & Chart
proposed completion or recompletion. Legacy Reserves requests permission to temporarily abandon (TA) the Alaska Complace the wellbore in TA status for future utilization of the well. TA Procedure: A) Displace hole w/packer fluid. B) Set CIBP @ ~2,700'. C) Set 50' cmt plug (class C cmt) on top of CIBP. D) Pressure test and chart casing. TA well. OCD I prior of ru Spud Date: Spud Date:	npletions: Attach wellbore diagram of oper #9 for 5 years. Legacy would like to on of Approval: no. Hobbs office 24 hours nning MIT Test & Chart e and belief.
proposed completion or recompletion.  Legacy Reserves requests permission to temporarily abandon (TA) the Alaska Complace the wellbore in TA status for future utilization of the well.  TA Procedure: A) Displace hole w/packer fluid. B) Set CIBP @ ~2,700'. C) Set 50' cmt plug (class C cmt) on top of CIBP. D) Pressure test and chart casing. TA well.  Spud Date:  I hereby certify that the information above is true and complete to the best of my knowledg	npletions: Attach wellbore diagram of oper #9 for 5 years. Legacy would like to on of Approval: no. Hobbs office 24 hours anning MIT Test & Chart e and belief.
proposed completion or recompletion.  Legacy Reserves requests permission to temporarily abandon (TA) the Alaska Complace the wellbore in TA status for future utilization of the well.  TA Procedure: A) Displace hole w/packer fluid. B) Set CIBP @ ~2,700'. C) Set 50' cmt plug (class C cmt) on top of CIBP. D) Pressure test and chart casing. TA well.  Spud Date:  I hereby certify that the information above is true and complete to the best of my knowledg	npletions: Attach wellbore diagram of oper #9 for 5 years. Legacy would like to on of Approval: nc. Hobbs office 24 hours anning MIT Test & Chart e and belief.
proposed completion or recompletion.  Legacy Reserves requests permission to temporarily abandon (TA) the Alaska Complace the wellbore in TA status for future utilization of the well.  TA Procedure: A) Displace hole w/packer fluid. B) Set CIBP @ ~2,700'. C) Set 50' cmt plug (class C cmt) on top of CIBP. D) Pressure test and chart casing. TA well.  Spud Date: Rig Release Date: I hereby certify that the information above is true and complete to the best of my knowledg  SIGNATURE	npletions: Attach wellbore diagram of oper #9 for 5 years. Legacy would like to on of Approval: nc. Hobbs office 24 hours anning MIT Test & Chart e and belief.
proposed completion or recompletion.  Legacy Reserves requests permission to temporarily abandon (TA) the Alaska Cooplace the wellbore in TA status for future utilization of the well.  TA Procedure: A) Displace hole w/packer fluid. B) Set CIBP @ ~2,700'. Condition Condition Condition Condition D) Pressure test and chart casing. TA well.  Spud Date:  Thereby certify that the information above is true and complete to the best of my knowledg SIGNATURE	npletions: Attach wellbore diagram of oper #9 for 5 years. Legacy would like to on of Approval: nc. Hobbs office 24 hours anning MIT Test & Chart e and belief. orDATE_02/19/2020 comPHONE: _432-689-5200
proposed completion or recompletion.  Legacy Reserves requests permission to temporarily abandon (TA) the Alaska Complace the wellbore in TA status for future utilization of the well.  TA Procedure: A) Displace hole w/packer fluid. B) Set CIBP @ ~2,700'. C) Set 50' cmt plug (class C cmt) on top of CIBP. D) Pressure test and chart casing. TA well.  Spud Date:  Thereby certify that the information above is true and complete to the best of my knowledg  SIGNATURE	npletions: Attach wellbore diagram of oper #9 for 5 years. Legacy would like to on of Approval: no. Hobbs office 24 hours anning MIT Test & Chart e and belief.