

FLARE INSPECTION 2- Batteries on

| Centènial Resources | location |
|--|------------------------|
| LEASE OR FACILITY NAME: Tour Bus 23 57 | |
| WELL# #502 API#30-025 - | 42735 |
| U.L_DSEC_23T_225R34E | <u> </u> |
| FOOTAGE 250 (NS 330 E) | $\widehat{\mathbb{W}}$ |
| IS A FLARE STACK PRESENT? YES NO | |
| IS FLARE ACTIVE? YES NO | |
| IS GAS TO FLARE METERED? YES NO | • |
| AREA AROUND FLARE CLEARED? YES NO | |
| COMMENTS: Frod. 9AS 90ing to 3 | SALES |
| | |
| | |
| IS VRU PRESENT? YES NO | |
| IS VRU ACTIVE? YES NO | , |
| COMMENTS: TANK UMPOR GRE 901 | ng to |
| flare | <i></i> |
| | |
| | |
| | |
| INSPECTOR Java Palman | DATE 3-20-20 |