

Submit I Copy To Appropriate District	State of New Mexico	Form C-103
Office	Energy, Minerals and Natural Resour	-
<u>District 1</u> - (575) 393-6161 1625 N. French Dr., Hobbs. NM 88240	Energy, white als and Natural Resour	WELL API NO.
<u>District II</u> - (575) 748-1283	OIL CONSERVATION DIVISIO)N <u>30-025-02916</u>
811 S. First St., Artesia, NM 88210 <u>District III</u> – (505) 334-6178	1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 District IV - (505) 476-3460		6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM	Santa Fe, NM 87505 CES AND REPORTS ON WEOBS SALS TO DRILL OR TO DEEPEN OR PLUG BACK TO CATION FOR PERMIT" (FORM C-101) FOR SUCH	B-2498
87505	CES AND REPORTS ON WAR	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOS	SALS TO DRILL OR TO DEEPEN OR PLUG BACK TO	East Vacuum GB-SA Unit Tr 2864
DIFFERENT RESERVOIR. USE *APPLIC	SALS TO DRILL OR TO DEEPEN OR PLUG BACK TO CATION FOR PERMIT" (FORM C-101) FOR SUCH	8. Well Number
1. Type of Well: Oil Well	Gas Well 🔲 Other	NED 013
2. Name of Operator	DECE	9. OGRID Number
	ocoPhillips Company	217817
3. Address of Operator 925 N. Eldrid	dge Pkwy Houston, TX 77079	10. Pool name or Wildcat Vacuum GB/SA
4. Well Location		
	660 feet from the North line and	660 feet from the West line
Section 28 Township 17-S Range 35-E NMPM County Lea		
	11. Elevation (Show whether DR, RKB, RT,	
	,	
12. Check A	Appropriate Box to Indicate Nature of N	Notice, Report or Other Data
NOTICE OF IN		SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK		
PULL OR ALTER CASING		CEMENT JOB
CLOSED-LOOP SYSTEM		п
		tails, and give pertinent dates, including estimated date
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of		
proposed completion or rec	ompletion.	
MIRU	ND WH, NU BOP. POOH Prod Equipment	
Set CIBP @ 4160' – Circ hole w/ MLF. Pressure test casing. Spot 25sx cmt @ 4160' – 4060'. WOC-Tag		
Spot 25sx cmt @ 3724' – 3604'		
Spot 70sx cmt @ 3165' - 2795'. WOC-Tag		
Spot 25sx cmt @ 1714' – 1594'. WOC-Tag Perf/Circ 120sx cmt @ 300' – 3'		
POOH. Fill wellbore. Verify cmt @ surface in all annuli		
	WH & anchors. Install DH marker	
		See Attached
		Conditions of Approval
A closed-loop system w	vill be used for all fluids from this wellbore and d	lisposed of required by OCD Rule 19.15.17
	[
Spud Date:	Rig Release Date:	
<u></u>		
I hereby certify that the information	above is true and complete to the best of my ki	nowledge and belief.
SIGNATURE	TITLE Agent – Basic Er	nergy Services DATE 7/9/20
Type or print nameGreg Brya	ant E-mail address:	PHONE:432-563-3355
For State Use Only		
APPROVED BY:	The TITLE CO	H DATE 7-14-20
Conditions of Approval (if any):		

WELLBORE SKETCH ConocoPhillips Company - Permian Basin Business Unit



TD @ 4695

WELLBORE SKETCH ConocoPhillips Company -- Permian Basin Business Unit



CONDITIONS OF APPROVAL FOR PLUGGING AND ABANDONMENT OCD - Southern District

The following is a guide or checklist in preparation of a plugging program, this is not all inclusive and care must be exercised in establishing special plugging programs in unique and unusual cases, Notify NMOCD District Office I (Hobbs) at (575)-263-6633 at least 24 hours before beginning work. After MIRU rig will remain on well until it is plugged to surface. OCD is to be notified before rig down.

Company representative will be on location during plugging procedures.

1. A notice of intent to plug and abandon a wellbore is required to be approved before plugging operations are conducted. A cement evaluation tool is required in order to ensure isolation of producing formations, protection of water and correlative rights. A cement bond log or other accepted cement evaluation tool is to be provided to the division for evaluation if one has not been previously run or if the well did not have cement circulated to surface during the original casing cementing job or subsequent cementing jobs. Insure all bradenheads have been exposed, identified and valves are operational prior to rig up.

2. Closed loop system is to be used for entire plugging operation. Upon completion, contents of steel pits are to be hauled to a permitted disposal location.

3. Trucking companies being used to haul oilfield waste fluids to a disposal - commercial or private- shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator as well as the contractor, to verify that this permit is in place prior to performing work. Drivers shall be able to produce a copy upon request of an NMOCD Field inspector.

4. Filing a subsequent C-103 will serve as notification that the well has been plugged.

5. A final C-103 shall be filed (and a site inspection by NMOCD Inspector to determine if the location is satisfactorily cleaned, all equipment, electric poles and trash has been removed to Meet NMOCD standards) before bonding can be released.

6. If work has not begun within 1 Year of the approval of this procedure, an extension request must be file stating the reason the well has not been plugged.

7. Squeeze pressures are not to exceed 500 psi, unless approval is given by NMOCD.

8. Produced water will not be used during any part of the plugging operation.

9. Mud laden fluids must be placed between all cement plugs mixed at 25 sacks per 100 bbls of water.

10. All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater. 50' of calculated cement excess required for inside casing plugs and 100% calculated cement excess required on outside casing plugs.

11. Class 'C' cement will be used above 7500 feet.

12. Class 'H' cement will be used below 7500 feet.

13. A cement plug is required to be set 50' above and 50' below, casing stubs, DV tools, attempted casing cut offs, cement tops outside casing, salt sections and anywhere the casing is perforated, these plugs require a 4 hour WOC and then will be tagged

14. All Casing Shoes Will Be Perforated 50' below shoe depth and Attempted to be Squeezed, cement needs to be 50' above and 50' Below Casing Shoe inside the Production Casing.

16. When setting the top out cement plug in production, intermediate and surface casing, wellbores should remain full at least 30 minutes after plugs are set

17. A CIBP is to be set within 100' of production perforations, capped with 100' of cement, WOC 4 hours and tag.

18. A CIBP with 35' of cement may be used in lieu of the 100' plug if set with a bailer. This plug will be placed within 100' of the top perforation, (WOC 4 hrs and tag).

19. No more than 3000' is allowed between cement plugs in cased hole and 2000' in open hole.

20. Some of the Formations to be isolated with cement plugs are: These plugs to be set to isolate formation tops

- A) Fusselman
- B) Devonian
- C) Morrow
- D) Wolfcamp
- E) Bone Springs
- F) Delaware
- G) Any salt sections
- H) Abo
- I) Glorieta
- J) Yates.

K) Potash----(In the R-111-P Area (Potash Mine Area),

A solid cement plug must be set across the salt section. Fluid used to mix the cement shall be saturated with the salts that are common to the section penetrated and in suitable proportions, not more than 3% calcium chloride (by weight of cement) will be considered the desired mixture whenever possible, woe 4 hours and tag, this plug will be SO' below the bottom and 50' above the top of the Formation.

21. If cement does not exist behind casing strings at recommended formation depths, the casing can be cut and pulled with plugs set at recommended depths. If casing is not pulled, perforations will be shot and cement squeezed behind casing, woe and tagged. These plugs will be set SO' below formation bottom to 50' above formation top inside the casing

DRY HOLE MARKER REQ.UIRMENTS

The operator shall mark the exact location of the plugged and abandoned well with a steel marker not less than four inches in diameter, 3' below ground level with a plate of at least¹/₄" welded to the top of the casing and the dry hole marker welded on the plate with the following information welded on the dry hole marker:

- 1. Operator name
- 2. Lease and Well Number
- 3. API Number
- 4. Unit letter
- 5. Quarter Section (feet from the North, South, East or West)
- 6. Section, Township and Range
- 7. Plugging Date
- 8. County

SPECIAL CASES -----AGRICULTURE OR PRARIE CHICKEN BREEDING AREAS

In these areas, a below ground marker is required with all pertinent information mentioned above on a plate, set 3' below ground level, a picture of the plate will be supplied to NMOCD for record, the exact location of the marker (longitude and latitude by GPS) will be provided to NMOCD (We typically require a current survey to verify the GPS)

SITE REMEDIATION DUE WITHIN ONE YEAR OF WELL PLUGGING COMPLETION