

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

HOBBS OFFICE D. C. C.

NEW MEXICO OIL CONSERVATION COMMISSION
 DEC 8 8 15 AM '65

Form C-103
 Supersedes Old
 C-102 and C-103
 Effective 1-1-65

5a. Indicate Type of Lease
 State Fee

5. State Oil & Gas Lease No.
K 3935

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Sunray Oil Company	8. Farm or Lease Name New Mexico State "AZ"
3. Address of Operator P. O. Box 1116, Roswell, New Mexico	9. Well No. 13
4. Location of Well UNIT LETTER A 660 FEET FROM THE N LINE AND 660 FEET FROM THE E LINE, SECTION 34 TOWNSHIP 78 RANGE 33E NMPM.	10. Field and Pool, or Wildcat Cherokee San Andres
15. Elevation (Show whether DF, RT, GR, etc.) Furnish Later	12. County Roosevelt


16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOB <input checked="" type="checkbox"/> OTHER Commence drlg operations <input checked="" type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- Spud well 11-30-65. Drill 12 1/4" hole to 360' TD. Ran 11 jts 8 5/8", 2 1/2", J-55, csg to csg pt 358'.
- Cut w/200 sx neat cut w/2% Gell. Circ 10 sx to surface. WOC 18 hrs., Pressure test to 1000 psig for 30 min - OK.
- Now drlg ahead.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED  **E. F. Brawley** TITLE **District Engineer** DATE **12-2-65**

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: