

OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease  
State  Fee

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Wolfson Oil Company	8. Farm or Lease Name Marshall
3. Address of Operator 3206 Republic Bank Tower Dallas, Texas 75201	9. Well No. 2
4. Location of Well UNIT LETTER <u>G</u> <u>1650</u> FEET FROM THE <u>East</u> LINE AND <u>2310</u> FEET FROM THE <u>North</u> LINE, SECTION <u>6</u> TOWNSHIP <u>9-S</u> RANGE <u>30-E</u> N.M.P.M.	10. Field and Pool, or Wildcat <u>Gato (San Andres)</u>
15. Elevation (Show whether DF, RT, GR, etc.) <u>1131 DF</u>	12. County <u>Chaves</u>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Set 25 sx plug in 1 1/2" casing across perfs at 3285-3351.
2. Circulated hole with mud-laden fluid.
3. Cut 1 1/2" casing at 2075'. Pulled 2075' of casing.
4. Set 25 sx plug at 2075'.
5. Set 30 sx plug at surface pipe at 1033.
6. Set 10 sx plug at surface
7. Set appropriate marker and cut anchors. 1-20-78

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED: H. B. Freedman TITLE: Prod. Engr. DATE: 1-25-78

APPROVED BY: Eddie Seay TITLE: OIL & GAS INSPECTOR DATE: 30

CONDITIONS OF APPROVAL, IF ANY: