

NEW MEXICO OIL CONSERVATION COMMISSION

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

5a. Indicate Type of Lease  
State  Fee   
5. State Oil & Gas Lease No.  
**E-1233**

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL  GAS WELL  OTHER-  
2. Name of Operator  
**Amoco Production Company**  
3. Address of Operator  
**BOX 68, HOBBS, N. M. 88240**  
4. Location of Well  
UNIT LETTER **J** **1980** FEET FROM THE **SOUTH** LINE AND **1980** FEET FROM  
THE **EAST** LINE, SECTION **34** TOWNSHIP **12-S** RANGE **34-E** NMPM.  
19. Field and Pool, or Wildcat  
**RANGER LAKE-LEA**  
15. Elevation (Show whether DF, RT, GR, etc.)  
**4166' R. D. B.**  
12. County  
**LEA**

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	
		OTHER _____	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

*Well no longer capable of oil or gas production and no further use as a salt water injection anticipated. No recompletion possibilities. Propose to Plug and abandon as follows.*

*Spot 5000 cement plug across pups (10,280-10346) back to appx. 10,000*

*Shoot & pull 5 1/2" CPQ from appx 4500 to 5500:*

*Spot 30 st - In & out of 5 1/2" CPQ Shut*

*8 7/8" CPQ Shoe @ 4270'*

*Shoot & pull 8 7/8" CPQ from appx 800-1100:*

*Spot 50 st plug in & out of 8 7/8" Shut*

*13 3/4" Shoe @ 405'*

*10 st @ surface; erect P.A. marker*

*Fill all intervals w/ heavy mud laden fluid.*

*Make final cleanup & restore ground to contour.*

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED \_\_\_\_\_ TITLE **AREA SUPERINTENDENT** DATE **APR 23 1973**

APPROVED BY *Fresh A. Clement* TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY:  
*1-RR4 206 NOTICE - DRILL TO SETTING BTM. PLUG*