

UNITED STATES DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE
(Other instructions on reverse side)

Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL GAS WELL OTHER

2. NAME OF OPERATOR
Conoco Inc.

3. ADDRESS OF OPERATOR
P.O. Box 460 - Hobbs, NM 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)
At surface
G-1/W + 1980/20
Unit Letter C

14. PERMIT NO. 30-025-1270100

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

5. LEASE DESIGNATION AND SERIAL NO.
LC-058697B

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME
MCA Unit

8. FARM OR LEASE NAME
MCA Unit *Sty 4*

9. WELL NO.
No. 134

10. FIELD AND POOL, OR WILDCAT
Maljamar G-SA

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 30, T17S, R33E

12. COUNTY OR PARISH 13. STATE

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input checked="" type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

- MIRU. ND wellhead NU BOP.
- Abandon open hole from 4167'-4315'. Set cement retainer @ 4100'. Pump 50 sx cement through retainer. Sting out and spot 25 sx of cement on top of retainer from 3814' to 4100'. Circ. hole w/65 bbls of mud.
- Set top plug. Pump 20 sx cement from surface to ~~200'~~ ^{1250' as per H. David.} inside 4-1/2" csg. SJS
- Cut casing string 3' below ground level. Erect a permanent abandonment marker.

RECEIVED

For further technical information contact Henry David at 397-5894.


18. I hereby certify that the foregoing is true and correct
SIGNED W.W. Baker W.W. Baker TITLE Administrative Supervisor DATE July 22, 1989

(This space for Federal or State office use)
APPROVED BY _____ TITLE PETROLEUM ENGINEER DATE 8-25-89
CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

MCA UNIT No. 134 Proposed Wellbore

10' x 4" marker



Conoco Inc
Calculation Sheet

Job No.

3

Blgd

Date

RECEIVED

AUG 28 1989

**OCD
HOBBS OFFICE**