

UNITED STATES DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
HOBBS, NEW MEXICO

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. UNIT AGREEMENT NAME	
2. NAME OF OPERATOR Conoco Inc.		8. FARM OR LEASE NAME Warren Unit Blinbery	
3. ADDRESS OF OPERATOR P.O. Box 460 - Hobbs, New Mexico 88240		9. WELL NO. 9	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1980' FNL & 660' FWL - Unit Letter E		10. FIELD AND POOL, OR FUTURE Warren Blinbery Oil & Gas	
14. PERMIT NO. 30-025-07841		15. ELEVATIONS (Show whether DF, RT, GR, etc.)	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 27-20S-38E	
		12. COUNTY OR PARISH Lea	
		13. STATE NM	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input checked="" type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <u>Re complete to Blinbery</u>	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Work started 2/3/88. MURU. Set CIBP at 6344' w/one sx cement on top to isolate Dunkard & Tubb perms. Perf Blinbery 6005'-6321'. Acidize w/30 bbls HCL acid. Sand frac. Swab well. Set RBP at 5997'. Perf upper Blinbery 5871'-5965'. Acidize w/30 bbls HCL acid. Sand frac. Swab well. POOH w/RBP to commingle Blinbery perms. Run producing equipment & place on production.

I hereby certify that the foregoing is true and correct
SIGNED DF Finney TITLE Administrative Supervisor DATE May 18, 1988

ACCEPTED FOR RECORD
DATE MAY 31 1988

*See instructions on Reverse Side

SJS
CARLSBAD, NEW MEXICO

BLM-Carlsbad (6) File ZA Warren Tubb & Warren Drkl