
15:27

SHARP #1



BOP STACK

3000 PSI WORKING PRESSURE

BOP ARRANGEMENT