

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Department
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-147
Revised April 3, 2017

Recycling Facility and/or Recycling Containment

Type of Facility: ☒ Recycling Facility ☒ Recycling Containment*

Type of action: ☒ Permit ☐ Registration
☐ Modification ☒ Extension
☐ Closure ☒ Other (explain) Annual extension from 06/26/2026 to 06/26/2027

*** At the time C-147 is submitted to the division for a Recycling Containment, a copy shall be provided to the surface owner.**

Be advised that approval of this request does not relieve the operator of liability should operations result in pollution of surface water, ground water or the environment. Nor does approval relieve the operator of its responsibility to comply with any other applicable governmental authority's rules, regulations or ordinances.

1.
Operator: OWL SWD Operating, LLC (For multiple operators attach page with information) OGRID #: 308339
Address: 20 Greenway Plaza, Suite 500 Houston, TX 77046
Facility or well name (include API# if associated with a well): OWL Fulfer Recycling Facility and Containment
OCD Permit Number: 1RF-23 (For new facilities the permit number will be assigned by the district office)
U/L or Qtr/Qtr Section 25 Township 25S Range 36E County: Lea
Surface Owner: ☐ Federal ☐ State ☒ Private ☐ Tribal Trust or Indian Allotment

2.
☒ **Recycling Facility:**
Location of recycling facility (if applicable): Latitude 32.097730 Longitude -103.219018 NAD83
Proposed Use: ☒ Drilling* ☒ Completion* ☒ Production* ☒ Plugging *
***The re-use of produced water may NOT be used until fresh water zones are cased and cemented**
☐ Other, **requires permit for other uses. Describe use, process, testing, volume of produced water and ensure there will be no adverse impact on groundwater or surface water.**
☒ Fluid Storage
☐ Above ground tanks ☒ Recycling containment ☐ Activity permitted under 19.15.17 NMAC explain type _____
☐ Activity permitted under 19.15.36 NMAC explain type: _____ ☐ Other explain _____
☐ For multiple or additional recycling containments, attach design and location information of each containment
☐ **Closure Report (required within 60 days of closure completion):** ☐ Recycling Facility Closure Completion Date: _____

3.
☒ **Recycling Containment:**
☐ Annual Extension after initial 5 years (attach summary of monthly leak detection inspections for previous year)
Center of Recycling Containment (if applicable): Latitude 32.097730 Longitude -103.219018 NAD83
☐ For multiple or additional recycling containments, attach design and location information of each containment
☒ Lined ☐ Liner type: Thickness _____ mil ☒ LLDPE ☒ HDPE ☐ PVC ☐ Other _____
☐ String-Reinforced 40 mil (secondary)
60 mil (primary)
Liner Seams: ☒ Welded ☒ Factory ☒ Other Field Welds Volume: 500,000 bbl Dimensions: L 625 x W 400 x D 18
☐ Recycling Containment Closure Completion Date: _____

4.

Bonding:

- ☒ Covered under bonding pursuant to 19.15.8 NMAC per 19.15.34.15(A)(2) NMAC (These containments are limited to only the wells owned or operated by the owners of the containment.)
- ☐ Bonding in accordance with 19.15.34.15(A)(1). Amount of bond \$ _____ (work on these facilities cannot commence until bonding amounts are approved)
- ☐ Attach closure cost estimate and documentation on how the closure cost was calculated.

5.

Fencing:

- ☐ Four foot height, four strands of barbed wire evenly spaced between one and four feet
- ☒ Alternate. Please specify _____ Chain Link Game Fence _____

6.

Signs:

- ☒ 12"x 24", 2" lettering, providing Operator's name, site location, and emergency telephone numbers
- ☐ Signed in compliance with 19.15.16.8 NMAC

7.

Variances:

Justifications and/or demonstrations that the proposed variance will afford reasonable protection against contamination of fresh water, human health, and the environment.

Check the below box only if a variance is requested:

☒ Variance(s): Requests must be submitted to the appropriate division district for consideration of approval. If a Variance is requested, include the variance information on a separate page and attach it to the C-147 as part of the application.

If a Variance is requested, it must be approved prior to implementation.

8.

Siting Criteria for Recycling Containment

Instructions: The applicant must provide attachments that demonstrate compliance for each siting criteria below as part of the application. Potential examples of the siting attachment source material are provided below under each criteria.

General siting**Ground water is less than 50 feet below the bottom of the Recycling Containment.**

NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells

☐ Yes ☒ No
☐ NA

Within incorporated municipal boundaries or within a defined municipal fresh water well field covered under a municipal ordinance adopted pursuant to NMSA 1978, Section 3-27-3, as amended.

☐ Yes ☒ No
☐ NA

- Written confirmation or verification from the municipality; written approval obtained from the municipality

Within the area overlying a subsurface mine.

☐ Yes ☒ No

- Written confirmation or verification or map from the NM EMNRD-Mining and Minerals Division

Within an unstable area.

☐ Yes ☒ No

- Engineering measures incorporated into the design; NM Bureau of Geology & Mineral Resources; USGS; NM Geological Society; topographic map

Within a 100-year floodplain. FEMA map

☐ Yes ☒ No

Within 300 feet of a continuously flowing watercourse, or 200 feet of any other significant watercourse, or lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark).

☐ Yes ☒ No

- Topographic map; visual inspection (certification) of the proposed site

Within 1000 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application.

☐ Yes ☒ No

- Visual inspection (certification) of the proposed site; aerial photo; satellite image

Within 500 horizontal feet of a spring or a fresh water well used for domestic or stock watering purposes, in existence at the time of initial application.

☐ Yes ☒ No

- NM Office of the State Engineer - iWATERS database search; visual inspection (certification) of the proposed site

Within 500 feet of a wetland.

☐ Yes ☒ No

- US Fish and Wildlife Wetland Identification map; topographic map; visual inspection (certification) of the proposed site

9.

Recycling Facility and/or Containment Checklist:

Instructions: Each of the following items must be attached to the application. Indicate, by a check mark in the box, that the documents are attached.

- ☒ Design Plan - based upon the appropriate requirements.
- ☒ Operating and Maintenance Plan - based upon the appropriate requirements.
- ☒ Closure Plan - based upon the appropriate requirements.
- ☒ Site Specific Groundwater Data -
- ☒ Siting Criteria Compliance Demonstrations –
- ☒ Certify that notice of the C-147 (only) has been sent to the surface owner(s)

10.

Operator Application Certification:

I hereby certify that the information and attachments submitted with this application are true, accurate and complete to the best of my knowledge and belief.

Name (Print): Shelly Cowden Title: Director Regulatory and Compliance
Signature: Shelly Cowden Date: 06.21.2026
e-mail address: Shelly.Cowden@pilotwater.com Telephone: 505-692-0354

11.

OCD Representative Signature: Senior Environmental Scientist Approval Date: 07/01/2026

Title: Victoria Venegas OCD Permit Number: 1RF-23

- ☒ OCD Conditions _____
- ☐ Additional OCD Conditions on Attachment _____



New Mexico Recycling Facility Monthly Inspection

Submitted By

[Mario Nevarez](#)

Surrogate

[Mario Nevarez](#)

Started On February 26 2025, 1:19pm

Submitted On June 6 2025, 9:22am (3 months)

Weather 73°, clear

Version V1 (latest)

Updated June 6 2025, 9:22am

Report No. 60215492

Location



New Mexico Recycling Facility Monthly Inspection

GENERAL DETAILS

Date June 6th 2025 8:20 AM MDT

Area [New Mexico](#)Recycle Facility [FULFER RECYCLE FACILITY](#)

INLET AST

Is there fluid in the leak detection system? No

Any migratory birds or wildlife discovered in the AST? N/A

Is bird netting in good condition? N/A

Is there any evidence of cracking or subsidence of the pad around the AST? N/A

Is there oil to be skimmed? N/A

EFFLUENT AST

Is there fluid in the leak detection system? N/A

Any migratory birds or wildlife discovered in the AST? N/A

Is there any evidence of cracking or subsidence of the pad around the AST? N/A

SOUTH POND

Is there fluid in the leak detection system? No

Are pond level markers visible? Yes

Is pond level sensor working?	Yes
Is there any visible damage to the pond liner?	No
Any migratory birds or wildlife discovered in the pond?	No
Is bird deterrent working?	Yes
Is there any evidence of cracking or subsidence around the pond berm?	No
Is there any erosion on the outside of the berm?	No
Is life vest and related pond safety equipment in working condition?	Yes
Is pond aeration system functional?	Yes

TREATMENT FACILITY

Is fencing and cattleguard in good condition?	Yes
Is there any evidence of spills or soil staining that have not been cleaned up?	No
Any migratory birds or wildlife discovered in the facility?	No
Are there any holes found in the containment liner?	No
Any evidence of erosion on the outside slope of the facility?	No

SUMMARY

# of Action Item(s)	0
Inspector	None

Signature



Generated Friday, June 6th 2025, 1:40pm CDT.

powered by  KPA



New Mexico Recycling Facility Monthly Inspection

Submitted By

[Mario Nevarez](#)

Surrogate

[Mario Nevarez](#)

Started On July 8 2025, 7:15am

Submitted On July 8 2025, 7:17am (a minute)


Weather 72°, cloudy

Version V1 (latest)

Updated July 8 2025, 7:17am

Report No. 61956229

Location



New Mexico Recycling Facility Monthly Inspection

GENERAL DETAILS

Date July 8th 2025 7:16 AM CDT

Area [New Mexico](#)Recycle Facility [FULFER RECYCLE FACILITY](#)

INLET AST

Is there fluid in the leak detection system? No

Any migratory birds or wildlife discovered in the AST? No

Is bird netting in good condition? Yes

Is there any evidence of cracking or subsidence of the pad around the AST? No

Is there oil to be skimmed? No

EFFLUENT AST

Is there fluid in the leak detection system? No

Any migratory birds or wildlife discovered in the AST? No

Is there any evidence of cracking or subsidence of the pad around the AST? No

SOUTH POND

Is there fluid in the leak detection system? No

Are pond level markers visible? Yes

Is pond level sensor working?	Yes
Is there any visible damage to the pond liner?	No
Any migratory birds or wildlife discovered in the pond?	No
Is bird deterrent working?	Yes
Is there any evidence of cracking or subsidence around the pond berm?	No
Is there any erosion on the outside of the berm?	No
Is life vest and related pond safety equipment in working condition?	Yes
Is pond aeration system functional?	Yes


TREATMENT FACILITY

Is fencing and cattleguard in good condition?	Yes
Is there any evidence of spills or soil staining that have not been cleaned up?	No
Any migratory birds or wildlife discovered in the facility?	No
Are there any holes found in the containment liner?	No
Any evidence of erosion on the outside slope of the facility?	No

SUMMARY

# of Action Item(s)	0
Inspector	Mario Nevarez

Signature



Generated Thursday, July 17th 2025, 12:01pm CDT.

powered by  KPA



New Mexico Recycling Facility Monthly Inspection

Submitted By

[Mario Nevarez](#)

Surrogate

[Mario Nevarez](#)

Started On July 28 2025, 9:31am

Submitted On July 28 2025, 9:33am (2 minutes)


Weather 75°, clear

Version V1 (latest)

Updated July 28 2025, 9:33am

Report No. 63126451

Location



New Mexico Recycling Facility Monthly Inspection

GENERAL DETAILS

Date July 28th 2025 8:31 AM MDT

Area [New Mexico](#)Recycle Facility [FULFER RECYCLE FACILITY](#)

INLET AST

Is there fluid in the leak detection system? N/A

Any migratory birds or wildlife discovered in the AST? N/A

Is bird netting in good condition? N/A

Is there any evidence of cracking or subsidence of the pad around the AST? N/A

Is there oil to be skimmed? N/A

EFFLUENT AST

Is there fluid in the leak detection system? N/A

Any migratory birds or wildlife discovered in the AST? N/A

Is there any evidence of cracking or subsidence of the pad around the AST? N/A

SOUTH POND

Is there fluid in the leak detection system? No

Are pond level markers visible? Yes

Is pond level sensor working?	Yes
Is there any visible damage to the pond liner?	No
Any migratory birds or wildlife discovered in the pond?	No
Is bird deterrent working?	Yes
Is there any evidence of cracking or subsidence around the pond berm?	No
Is there any erosion on the outside of the berm?	No
Is life vest and related pond safety equipment in working condition?	Yes
Is pond aeration system functional?	Yes


TREATMENT FACILITY

Is fencing and cattleguard in good condition?	Yes
Is there any evidence of spills or soil staining that have not been cleaned up?	No
Any migratory birds or wildlife discovered in the facility?	No
Are there any holes found in the containment liner?	No
Any evidence of erosion on the outside slope of the facility?	No

SUMMARY

# of Action Item(s)	0
Inspector	Mario Nevarez

Signature



Generated Monday, July 28th 2025, 9:44am CDT.

powered by  KPA



New Mexico Recycling Facility Monthly Inspection

Submitted By

[Mario Nevarez](#)

Surrogate

[Mario Nevarez](#)

Started On August 26 2025, 10:31am

Submitted On August 26 2025, 10:32am (2 minutes)


Weather 81°, clear

Version V1 (latest)

Updated August 26 2025, 10:32am

Report No. 65040170

Location



New Mexico Recycling Facility Monthly Inspection

GENERAL DETAILS

Date August 26th 2025 10:31 AM

Area [New Mexico](#)Recycle Facility [FULFER RECYCLE FACILITY](#)

INLET AST

Is there fluid in the leak detection system? N/A

Any migratory birds or wildlife discovered in the AST? N/A

Is bird netting in good condition? N/A

Is there any evidence of cracking or subsidence of the pad around the AST? N/A

Is there oil to be skimmed? N/A

EFFLUENT AST

Is there fluid in the leak detection system? N/A

Any migratory birds or wildlife discovered in the AST? N/A

Is there any evidence of cracking or subsidence of the pad around the AST? N/A

SOUTH POND

Is there fluid in the leak detection system? No

Are pond level markers visible? Yes

Is pond level sensor working?	Yes
Is there any visible damage to the pond liner?	No
Any migratory birds or wildlife discovered in the pond?	No
Is bird deterrent working?	Yes
Is there any evidence of cracking or subsidence around the pond berm?	No
Is there any erosion on the outside of the berm?	No
Is life vest and related pond safety equipment in working condition?	Yes
Is pond aeration system functional?	Yes


TREATMENT FACILITY

Is fencing and cattleguard in good condition?	Yes
Is there any evidence of spills or soil staining that have not been cleaned up?	No
Any migratory birds or wildlife discovered in the facility?	No
Are there any holes found in the containment liner?	No
Any evidence of erosion on the outside slope of the facility?	None

SUMMARY

# of Action Item(s)	0
Inspector	Mario Nevarez

Signature





New Mexico Recycling Facility Monthly Inspection

Submitted By

[Mario Nevarez](#)

Surrogate

[Mario Nevarez](#)

Started On October 1 2025, 12:11pm

Submitted On October 1 2025, 12:12pm (a minute)

Weather NaN°,

Version V1 (latest)

Updated October 1 2025, 12:12pm

Report No. 67223449

Location



New Mexico Recycling Facility Monthly Inspection

GENERAL DETAILS

Date October 1st 2025 12:11 PM

Area [New Mexico](#)Recycle Facility [FULFER RECYCLE FACILITY](#)

INLET AST

Is there fluid in the leak detection system? N/A

Any migratory birds or wildlife discovered in the AST? N/A

Is bird netting in good condition? N/A

Is there any evidence of cracking or subsidence of the pad around the AST? N/A

Is there oil to be skimmed? N/A

EFFLUENT AST

Is there fluid in the leak detection system? N/A

Any migratory birds or wildlife discovered in the AST? N/A

Is there any evidence of cracking or subsidence of the pad around the AST? N/A

SOUTH POND

Is there fluid in the leak detection system? No

Are pond level markers visible? Yes

Is pond level sensor working?	Yes
Is there any visible damage to the pond liner?	No
Any migratory birds or wildlife discovered in the pond?	No
Is bird deterrent working?	Yes
Is there any evidence of cracking or subsidence around the pond berm?	No
Is there any erosion on the outside of the berm?	No
Is life vest and related pond safety equipment in working condition?	Yes
Is pond aeration system functional?	Yes


TREATMENT FACILITY

Is fencing and cattleguard in good condition?	Yes
Is there any evidence of spills or soil staining that have not been cleaned up?	No
Any migratory birds or wildlife discovered in the facility?	No
Are there any holes found in the containment liner?	No
Any evidence of erosion on the outside slope of the facility?	No

SUMMARY

# of Action Item(s)	0
Inspector	Mario Nevarez

Signature



Generated Friday, October 3rd 2025, 12:24pm CDT.

powered by  KPA



New Mexico Recycling Facility Monthly Inspection		Location
Submitted By	 Mario Nevarez	
Surrogate	 Mario Nevarez	
Started On	October 27 2025, 8:38am	
Submitted On	October 27 2025, 8:39am (a minute)	
Weather	45°, clear	
Version	V1 (latest)	
Updated	October 27 2025, 8:39am	
Report No.	68772164	

New Mexico Recycling Facility Monthly Inspection

GENERAL DETAILS

Date	October 27th 2025 8:38 AM CDT
Area	New Mexico
Recycle Facility	FULFER RECYCLE FACILITY

INLET AST

Is there fluid in the leak detection system?	N/A
Any migratory birds or wildlife discovered in the AST?	N/A
Is bird netting in good condition?	N/A
Is there any evidence of cracking or subsidence of the pad around the AST?	N/A
Is there oil to be skimmed?	N/A

EFFLUENT AST

Is there fluid in the leak detection system?	N/A
Any migratory birds or wildlife discovered in the AST?	N/A
Is there any evidence of cracking or subsidence of the pad around the AST?	N/A

SOUTH POND

Is there fluid in the leak detection system?	No
Are pond level markers visible?	Yes

Is pond level sensor working?	Yes
Is there any visible damage to the pond liner?	No
Any migratory birds or wildlife discovered in the pond?	No
Is bird deterrent working?	Yes
Is there any evidence of cracking or subsidence around the pond berm?	No
Is there any erosion on the outside of the berm?	No
Is life vest and related pond safety equipment in working condition?	Yes
Is pond aeration system functional?	Yes

TREATMENT FACILITY

Is fencing and cattleguard in good condition?	Yes
Is there any evidence of spills or soil staining that have not been cleaned up?	No
Any migratory birds or wildlife discovered in the facility?	No
Are there any holes found in the containment liner?	No
Any evidence of erosion on the outside slope of the facility?	No

SUMMARY

# of Action Item(s)	0
Inspector	Mario Nevarez

Signature



Generated Tuesday, November 4th 2025, 11:05am CST.

powered by  KPA



New Mexico Recycling Facility Monthly Inspection

Submitted By

[Mario Nevarez](#)

Surrogate

[Mario Nevarez](#)

Started On

November 26 2025, 3:32pm

Submitted On

November 26 2025, 3:33pm (a minute)

Weather

57°, cloudy

Version

V1 (latest)


Updated

November 26 2025, 3:33pm

Report No.

70730337

Location



New Mexico Recycling Facility Monthly Inspection

GENERAL DETAILS

Date	November 26th 2025 3:32 PM CST
Area	New Mexico
Recycle Facility	FULFER RECYCLE FACILITY

INLET AST

Is there fluid in the leak detection system?	N/A
Any migratory birds or wildlife discovered in the AST?	N/A
Is bird netting in good condition?	N/A
Is there any evidence of cracking or subsidence of the pad around the AST?	N/A
Is there oil to be skimmed?	N/A

EFFLUENT AST

Is there fluid in the leak detection system?	N/A
Any migratory birds or wildlife discovered in the AST?	N/A
Is there any evidence of cracking or subsidence of the pad around the AST?	N/A

SOUTH POND

Is there fluid in the leak detection system?	No
Are pond level markers visible?	Yes

Is pond level sensor working?	Yes
Is there any visible damage to the pond liner?	No
Any migratory birds or wildlife discovered in the pond?	No
Is bird deterrent working?	Yes
Is there any evidence of cracking or subsidence around the pond berm?	No
Is there any erosion on the outside of the berm?	No
Is life vest and related pond safety equipment in working condition?	Yes
Is pond aeration system functional?	Yes


TREATMENT FACILITY

Is fencing and cattleguard in good condition?	Yes
Is there any evidence of spills or soil staining that have not been cleaned up?	No
Any migratory birds or wildlife discovered in the facility?	No
Are there any holes found in the containment liner?	No
Any evidence of erosion on the outside slope of the facility?	No

SUMMARY

# of Action Item(s)	0
Inspector	Mario Nevarez

Signature





New Mexico Recycling Facility Monthly Inspection

Submitted By

[Mario Nevarez](#)

Surrogate

[Mario Nevarez](#)

Started On December 31 2025, 8:16am

Submitted On December 31 2025, 8:17am (a minute)


Weather 30°, cloudy

Version V1 (latest)

Updated December 31 2025, 8:17am

Report No. 72453183

Location



New Mexico Recycling Facility Monthly Inspection

GENERAL DETAILS

Date December 31st 2025 8:16 AM CST

Area [New Mexico](#)Recycle Facility [FULFER RECYCLE FACILITY](#)

INLET AST

Is there fluid in the leak detection system? N/A

Any migratory birds or wildlife discovered in the AST? N/A

Is bird netting in good condition? N/A

Is there any evidence of cracking or subsidence of the pad around the AST? N/A

Is there oil to be skimmed? N/A

EFFLUENT AST

Is there fluid in the leak detection system? N/A

Any migratory birds or wildlife discovered in the AST? N/A

Is there any evidence of cracking or subsidence of the pad around the AST? N/A

SOUTH POND

Is there fluid in the leak detection system? No

Are pond level markers visible? Yes

Is pond level sensor working?	Yes
Is there any visible damage to the pond liner?	No
Any migratory birds or wildlife discovered in the pond?	No
Is bird deterrent working?	Yes
Is there any evidence of cracking or subsidence around the pond berm?	No
Is there any erosion on the outside of the berm?	No
Is life vest and related pond safety equipment in working condition?	Yes
Is pond aeration system functional?	None


TREATMENT FACILITY

Is fencing and cattleguard in good condition?	None
Is there any evidence of spills or soil staining that have not been cleaned up?	None
Any migratory birds or wildlife discovered in the facility?	No
Are there any holes found in the containment liner?	No
Any evidence of erosion on the outside slope of the facility?	No

SUMMARY

# of Action Item(s)	0
Inspector	Mario Nevarez

Signature



Generated Monday, January 5th 2026, 10:38am CST.

powered by  KPA



New Mexico Recycling Facility Monthly Inspection

Submitted By

[Mario Nevarez](#)

Surrogate

[Mario Nevarez](#)

Started On January 27 2026, 2:05pm

Submitted On January 27 2026, 2:06pm (a minute)

Weather 40°, cloudy

Version V1 (latest)

Updated January 27 2026, 2:06pm

Report No. 73974435

Location



New Mexico Recycling Facility Monthly Inspection

GENERAL DETAILS

Date January 27th 2026 2:05 PM CST

Area [New Mexico](#)Recycle Facility [FULFER RECYCLE FACILITY](#)

INLET AST

Is there fluid in the leak detection system? N/A

Any migratory birds or wildlife discovered in the AST? N/A

Is bird netting in good condition? N/A

Is there any evidence of cracking or subsidence of the pad around the AST? N/A

Is there oil to be skimmed? N/A

EFFLUENT AST

Is there fluid in the leak detection system? N/A

Any migratory birds or wildlife discovered in the AST? N/A

Is there any evidence of cracking or subsidence of the pad around the AST? N/A

SOUTH POND

Is there fluid in the leak detection system? No

Are pond level markers visible? Yes

Is pond level sensor working?	Yes
Is there any visible damage to the pond liner?	No
Any migratory birds or wildlife discovered in the pond?	No
Is bird deterrent working?	Yes
Is there any evidence of cracking or subsidence around the pond berm?	No
Is there any erosion on the outside of the berm?	No
Is life vest and related pond safety equipment in working condition?	Yes
Is pond aeration system functional?	Yes


TREATMENT FACILITY

Is fencing and cattleguard in good condition?	N/A
Is there any evidence of spills or soil staining that have not been cleaned up?	N/A
Any migratory birds or wildlife discovered in the facility?	N/A
Are there any holes found in the containment liner?	N/A
Any evidence of erosion on the outside slope of the facility?	N/A

SUMMARY

# of Action Item(s)	0
Inspector	Mario Nevarez

Signature



Generated Wednesday, January 28th 2026, 8:50am CST.

powered by  KPA



New Mexico Recycling Facility Monthly Inspection

Submitted By

[Mario Nevarez](#)

Surrogate

[Mario Nevarez](#)

Started On February 25 2026, 2:21pm

Submitted On February 25 2026, 2:32pm (12 minutes)


Weather 88°, clear

Version V1 (latest)

Updated February 25 2026, 2:32pm

Report No. 75917561

Location



New Mexico Recycling Facility Monthly Inspection

GENERAL DETAILS

Date February 25th 2026 2:31 PM CST

Area [New Mexico](#)Recycle Facility [FULFER RECYCLE FACILITY](#)

INLET AST

Is there fluid in the leak detection system? N/A

Any migratory birds or wildlife discovered in the AST? N/A

Is bird netting in good condition? N/A

Is there any evidence of cracking or subsidence of the pad around the AST? N/A

Is there oil to be skimmed? N/A

EFFLUENT AST

Is there fluid in the leak detection system? N/A

Any migratory birds or wildlife discovered in the AST? N/A

Is there any evidence of cracking or subsidence of the pad around the AST? N/A

SOUTH POND

Is there fluid in the leak detection system? No

Are pond level markers visible? Yes

Is pond level sensor working?	Yes
Is there any visible damage to the pond liner?	No
Any migratory birds or wildlife discovered in the pond?	No
Is bird deterrent working?	Yes
Is there any evidence of cracking or subsidence around the pond berm?	No
Is there any erosion on the outside of the berm?	No
Is life vest and related pond safety equipment in working condition?	Yes
Is pond aeration system functional?	Yes


TREATMENT FACILITY

Is fencing and cattleguard in good condition?	Yes
Is there any evidence of spills or soil staining that have not been cleaned up?	No
Any migratory birds or wildlife discovered in the facility?	No
Are there any holes found in the containment liner?	No
Any evidence of erosion on the outside slope of the facility?	No

SUMMARY

# of Action Item(s)	0
Inspector	Mario Nevarez

Signature



Generated Friday, February 27th 2026, 11:42am CST.

powered by  KPA



New Mexico Recycling Facility Monthly Inspection

Submitted By

[Mario Nevarez](#)

Surrogate

[Mario Nevarez](#)

Started On April 6 2026, 11:14am

Submitted On April 6 2026, 11:15am (a minute)


Weather 61°, clear

Version V1 (latest)

Updated April 6 2026, 11:15am

Report No. 78634908

Location



New Mexico Recycling Facility Monthly Inspection

GENERAL DETAILS

Date April 6th 2026 11:14 AM CDT

Area [New Mexico](#)Recycle Facility [FULFER RECYCLE FACILITY](#)

INLET AST

Is there fluid in the leak detection system? N/A

Any migratory birds or wildlife discovered in the AST? N/A

Is bird netting in good condition? N/A

Is there any evidence of cracking or subsidence of the pad around the AST? N/A

Is there oil to be skimmed? N/A

EFFLUENT AST

Is there fluid in the leak detection system? N/A

Any migratory birds or wildlife discovered in the AST? N/A

Is there any evidence of cracking or subsidence of the pad around the AST? N/A

SOUTH POND

Is there fluid in the leak detection system? No

Are pond level markers visible? Yes

Is pond level sensor working?	Yes
Is there any visible damage to the pond liner?	No
Any migratory birds or wildlife discovered in the pond?	No
Is bird deterrent working?	Yes
Is there any evidence of cracking or subsidence around the pond berm?	No
Is there any erosion on the outside of the berm?	No
Is life vest and related pond safety equipment in working condition?	Yes
Is pond aeration system functional?	Yes


TREATMENT FACILITY

Is fencing and cattleguard in good condition?	N/A
Is there any evidence of spills or soil staining that have not been cleaned up?	N/A
Any migratory birds or wildlife discovered in the facility?	N/A
Are there any holes found in the containment liner?	N/A
Any evidence of erosion on the outside slope of the facility?	N/A

SUMMARY

# of Action Item(s)	0
Inspector	Mario Nevarez

Signature





New Mexico Recycling Facility Monthly Inspection

Submitted By

[Mario Nevarez](#)

Surrogate

[Mario Nevarez](#)

Started On April 28 2026, 10:58am

Submitted On April 28 2026, 10:59am (a minute)


Weather 80°, clear

Version V1 (latest)

Updated April 28 2026, 10:59am

Report No. 80207348

Location



New Mexico Recycling Facility Monthly Inspection

GENERAL DETAILS

Date April 28th 2026 10:58 AM CDT

Area [New Mexico](#)Recycle Facility [FULFER RECYCLE FACILITY](#)

INLET AST

Is there fluid in the leak detection system? N/A

Any migratory birds or wildlife discovered in the AST? N/A

Is bird netting in good condition? N/A

Is there any evidence of cracking or subsidence of the pad around the AST? N/A

Is there oil to be skimmed? N/A

EFFLUENT AST

Is there fluid in the leak detection system? N/A

Any migratory birds or wildlife discovered in the AST? N/A

Is there any evidence of cracking or subsidence of the pad around the AST? N/A

SOUTH POND

Is there fluid in the leak detection system? No

Are pond level markers visible? Yes

Is pond level sensor working?	Yes
Is there any visible damage to the pond liner?	No
Any migratory birds or wildlife discovered in the pond?	No
Is bird deterrent working?	Yes
Is there any evidence of cracking or subsidence around the pond berm?	No
Is there any erosion on the outside of the berm?	No
Is life vest and related pond safety equipment in working condition?	Yes
Is pond aeration system functional?	Yes


TREATMENT FACILITY

Is fencing and cattleguard in good condition?	N/A
Is there any evidence of spills or soil staining that have not been cleaned up?	N/A
Any migratory birds or wildlife discovered in the facility?	N/A
Are there any holes found in the containment liner?	N/A
Any evidence of erosion on the outside slope of the facility?	N/A

SUMMARY

# of Action Item(s)	0
Inspector	Mario Nevarez

Signature





New Mexico Recycling Facility Monthly Inspection

Submitted By

[Mario Nevarez](#)

Surrogate

[Mario Nevarez](#)

Started On May 26 2026, 12:55pm

Submitted On May 26 2026, 12:56pm (57 seconds)


Weather 62°, rain

Version V1 (latest)

Updated May 26 2026, 12:56pm

Report No. 82081094

Location



New Mexico Recycling Facility Monthly Inspection

GENERAL DETAILS

Date May 26th 2026 12:55 PM

Area [New Mexico](#)Recycle Facility [FULFER RECYCLE FACILITY](#)

INLET AST

Is there fluid in the leak detection system? N/A

Any migratory birds or wildlife discovered in the AST? N/A

Is bird netting in good condition? N/A

Is there any evidence of cracking or subsidence of the pad around the AST? N/A

Is there oil to be skimmed? N/A

EFFLUENT AST

Is there fluid in the leak detection system? N/A

Any migratory birds or wildlife discovered in the AST? N/A

Is there any evidence of cracking or subsidence of the pad around the AST? N/A

SOUTH POND

Is there fluid in the leak detection system? No

Are pond level markers visible? Yes

Is pond level sensor working?	Yes
Is there any visible damage to the pond liner?	No
Any migratory birds or wildlife discovered in the pond?	No
Is bird deterrent working?	Yes
Is there any evidence of cracking or subsidence around the pond berm?	No
Is there any erosion on the outside of the berm?	No
Is life vest and related pond safety equipment in working condition?	Yes
Is pond aeration system functional?	Yes


TREATMENT FACILITY

Is fencing and cattleguard in good condition?	N/A
Is there any evidence of spills or soil staining that have not been cleaned up?	N/A
Any migratory birds or wildlife discovered in the facility?	N/A
Are there any holes found in the containment liner?	N/A
Any evidence of erosion on the outside slope of the facility?	N/A

SUMMARY

# of Action Item(s)	0
Inspector	Mario Nevarez

Signature



Generated Thursday, May 28th 2026, 12:15pm CDT.

powered by  KPA

**New Mexico Recycling Facility Weekly Inspection****Location**

Submitted By

[Steven Anderson](#)*Location was not collected for this report.*

Surrogate

[Steven Anderson](#)

Started On June 5 2025, 11:38am

Submitted On June 5 2025, 11:39am (46 seconds)

Weather NaN°,

Version V1 (latest)

Updated June 5 2025, 11:39am

Report No. 60158657

New Mexico Recycling Facility Weekly Inspection**GENERAL DETAILS**

Date June 5th 2025

Area [New Mexico](#)Recycle Facility [FULFER RECYCLE FACILITY](#)**WEEKLY INSPECTION**

Read and record the fluid height of staff gauges 11.5"

Does the pond surface show visible oil? No

Visually inspect containments liner Good

Check leak detection system for any evidence of a loss of integrity of the primary liner Good

SUMMARY

of Action Item(s) 0

Inspector [Steven Anderson](#)

Signature

A handwritten signature in blue ink, appearing to be "S. Anderson", written over a horizontal line.

Generated Friday, June 6th 2025, 1:38pm CDT.

powered by KPA



New Mexico Recycling Facility Weekly Inspection

Location

Submitted By

[Mario Nevarez](#)

Surrogate

[Mario Nevarez](#)

Started On June 30 2025, 1:33pm


Submitted On June 30 2025, 1:33pm (28 seconds)

Weather 87°, cloudy

Version V1 (latest)

Updated June 30 2025, 1:34pm

Report No. 61555323



New Mexico Recycling Facility Weekly Inspection

GENERAL DETAILS

Date June 30th 2025

Area [New Mexico](#)Recycle Facility [FULFER RECYCLE FACILITY](#)

WEEKLY INSPECTION

Read and record the fluid height of staff gauges Yes

Does the pond surface show visible oil? No

Visually inspect containments liner Yes

Check leak detection system for any evidence of a loss of integrity of the primary liner Yes

SUMMARY

of Action Item(s) 0

Inspector [Mario Nevarez](#)

Signature



New Mexico Recycling Facility Weekly Inspection

Location

Submitted By

[Mario Nevarez](#)

Surrogate

[Mario Nevarez](#)

Started On

July 7 2025, 9:38am

Submitted On

July 7 2025, 9:39am (33 seconds)

Weather

76°, clear

Version


V1 (latest)

Updated

July 7 2025, 9:39am

Report No.

61898628



New Mexico Recycling Facility Weekly Inspection

GENERAL DETAILS

Date

July 7th 2025

Area

[New Mexico](#)

Recycle Facility

[FULFER RECYCLE FACILITY](#)

WEEKLY INSPECTION

Read and record the fluid height of staff gauges

Yes

Does the pond surface show visible oil?

No

Visually inspect containments liner

Yes

Check leak detection system for any evidence of a loss of integrity of the primary liner

Yes

SUMMARY

of Action Item(s)

0

Inspector

[Mario Nevarez](#)

Signature



New Mexico Recycling Facility Weekly Inspection

Submitted By

[Fernando Sanchez](#)

Surrogate

[Fernando Sanchez](#)

Started On July 9 2025, 9:21am

Submitted On July 9 2025, 9:26am (5 minutes)


Weather 75°, clear

Version V1 (latest)

Updated July 9 2025, 9:26am

Report No. 62043249

Location



New Mexico Recycling Facility Weekly Inspection

GENERAL DETAILS

Date July 9th 2025

Area [New Mexico](#)Recycle Facility [FULFER RECYCLE FACILITY](#)

NOTES

Signs of erosion on walls around the pond

WEEKLY INSPECTION

Read and record the fluid height of staff gauges 13ft

Does the pond surface show visible oil? No

Visually inspect containments liner Liner looks to be in operational condition

Check leak detection system for any evidence of a loss of integrity of the primary liner No evidence of loss of integrity

SUMMARY

of Action Item(s) 0

Inspector [Fernando Sanchez](#)

Signature



New Mexico Recycling Facility Weekly Inspection

Submitted By

[Fernando Sanchez](#)

Surrogate

[Fernando Sanchez](#)

Started On July 16 2025, 12:42pm

Submitted On July 16 2025, 12:50pm (7 minutes)


Weather 86°, clear

Version V1 (latest)

Updated July 16 2025, 12:50pm

Report No. 62466917

Location



New Mexico Recycling Facility Weekly Inspection

GENERAL DETAILS

Date July 16th 2025

Area [New Mexico](#)Recycle Facility [FULFER RECYCLE FACILITY](#)

WEEKLY INSPECTION

Read and record the fluid height of staff gauges 13ft 2in

NOTES

Soil in some areas is washed out

Does the pond surface show visible oil? No

Visually inspect containments liner Liner looks to be in working condition

Check leak detection system for any evidence of a loss of integrity of the primary liner No evidence of integrity loss

SUMMARY

of Action Item(s) 0

Inspector [Fernando Sanchez](#)

Signature



New Mexico Recycling Facility Weekly Inspection

Submitted By

[Mario Nevarez](#)

Surrogate

[Mario Nevarez](#)

Started On July 21 2025, 9:22am

Submitted On July 21 2025, 9:23am (30 seconds)


Weather 79°, cloudy

Version V1 (latest)

Updated July 21 2025, 9:23am

Report No. 62705101

Location



New Mexico Recycling Facility Weekly Inspection

GENERAL DETAILS

Date July 21st 2025

Area [New Mexico](#)Recycle Facility [FULFER RECYCLE FACILITY](#)

WEEKLY INSPECTION

Read and record the fluid height of staff gauges Yes

Does the pond surface show visible oil? No

Visually inspect containments liner Yes

Check leak detection system for any evidence of a loss of integrity of the primary liner Yes

SUMMARY

of Action Item(s) 0

Inspector [Mario Nevarez](#)

Signature



New Mexico Recycling Facility Weekly Inspection

Submitted By  [Fernando Sanchez](#)

Surrogate  [Fernando Sanchez](#)

Started On July 23 2025, 9:59am

Submitted On July 23 2025, 10:10am (11 minutes)


Weather 79°, cloudy

Version V1 (latest)

Updated July 23 2025, 10:10am

Report No. 62852468

Location



New Mexico Recycling Facility Weekly Inspection

GENERAL DETAILS

Date July 23rd 2025

Area [New Mexico](#)

Recycle Facility [FULFER RECYCLE FACILITY](#)

WEEKLY INSPECTION

Read and record the fluid height of staff gauges 13ft 6in

Does the pond surface show visible oil? No

Visually inspect containments liner Liner looks to be in working condition

Check leak detection system for any evidence of a loss of integrity of the primary liner No evidence of integrity loss

NOTES

Aerator pump not wanting to kick on. Going to contact electrician

SUMMARY

of Action Item(s) 0

Inspector [Fernando Sanchez](#)

Signature

A handwritten signature in blue ink, consisting of several stylized, overlapping loops and lines, positioned above a horizontal line.

Generated Wednesday, July 23rd 2025, 10:52am CDT.

powered by  KPA



New Mexico Recycling Facility Weekly Inspection

Submitted By

[Mario Nevarez](#)

Surrogate

[Mario Nevarez](#)

Started On July 28 2025, 9:33am

Submitted On July 28 2025, 9:34am (36 seconds)


Weather 75°, cloudy

Version V1 (latest)

Updated July 28 2025, 9:34am

Report No. 63126515

Location



New Mexico Recycling Facility Weekly Inspection

GENERAL DETAILS

Date July 28th 2025

Area [New Mexico](#)Recycle Facility [FULFER RECYCLE FACILITY](#)

WEEKLY INSPECTION

Read and record the fluid height of staff gauges Yes

Does the pond surface show visible oil? No

Visually inspect containments liner Yes

Check leak detection system for any evidence of a loss of integrity of the primary liner Yes

SUMMARY

of Action Item(s) 0

Inspector [Mario Nevarez](#)

Signature

Generated Monday, July 28th 2025, 9:38am CDT.

powered by  KPA



New Mexico Recycling Facility Weekly Inspection

Submitted By

[Fernando Sanchez](#)

Surrogate

[Fernando Sanchez](#)

Started On July 31 2025, 5:48pm

Submitted On July 31 2025, 5:49pm (a minute)


Weather 90°, cloudy

Version V1 (latest)

Updated July 31 2025, 5:49pm

Report No. 63425167

Location



New Mexico Recycling Facility Weekly Inspection

GENERAL DETAILS

Date July 31st 2025

Area [New Mexico](#)Recycle Facility [FULFER RECYCLE FACILITY](#)

WEEKLY INSPECTION

Read and record the fluid height of staff gauges 13ft 6in

Does the pond surface show visible oil? No

Visually inspect containments liner Liner looks to be in good condition

Check leak detection system for any evidence of a loss of integrity of the primary liner No evidence of integrity loss

SUMMARY

of Action Item(s) 0

Inspector [Fernando Sanchez](#)

Signature

**New Mexico Recycling Facility Weekly Inspection****Location**

Submitted By

[Steven Anderson](#)*Location was not collected for this report.*

Surrogate

[Steven Anderson](#)

Started On

August 4 2025, 2:42pm

Submitted On

August 4 2025, 2:43pm (53 seconds)

Weather

NaN°,

Version

V1 (latest)

Updated

August 4 2025, 2:43pm

Report No.

63624826

New Mexico Recycling Facility Weekly Inspection**GENERAL DETAILS**

Date

August 4th 2025

Area

[New Mexico](#)

Recycle Facility

[FULFER RECYCLE FACILITY](#)**WEEKLY INSPECTION**

Read and record the fluid height of staff gauges

13.8"

Does the pond surface show visible oil?

No

Visually inspect containments liner

Good

Check leak detection system for any evidence of a loss of integrity of the primary liner

Good

SUMMARY

of Action Item(s)

0

Inspector

[Steven Anderson](#)

Signature

A handwritten signature in blue ink, appearing to be "SE", written over a horizontal line.

Generated Monday, August 4th 2025, 2:45pm CDT.

powered by KPA



New Mexico Recycling Facility Weekly Inspection

Submitted By

[Mario Nevarez](#)

Surrogate

[Mario Nevarez](#)

Started On August 11 2025, 11:18am

Submitted On August 11 2025, 11:18am (26 seconds)


Weather 84°, clear

Version V1 (latest)

Updated August 11 2025, 11:18am

Report No. 64081980

Location



New Mexico Recycling Facility Weekly Inspection

GENERAL DETAILS

Date August 11th 2025

Area [New Mexico](#)Recycle Facility [FULFER RECYCLE FACILITY](#)

WEEKLY INSPECTION

Read and record the fluid height of staff gauges Yes

Does the pond surface show visible oil? No

Visually inspect containments liner Yes

Check leak detection system for any evidence of a loss of integrity of the primary liner Yes

SUMMARY

of Action Item(s) 0

Inspector [Mario Nevarez](#)

Signature

**New Mexico Recycling Facility Weekly Inspection****Location**

Submitted By

[Steven Anderson](#)*Location was not collected for this report.*

Surrogate

[Steven Anderson](#)

Started On August 14 2025, 9:23am

Submitted On August 14 2025, 9:24am (a minute)

Weather NaN°,

Version V1 (latest)

Updated August 14 2025, 9:24am

Report No. 64309941

New Mexico Recycling Facility Weekly Inspection**GENERAL DETAILS**

Date August 14th 2025

Area [New Mexico](#)Recycle Facility [FULFER RECYCLE FACILITY](#)**WEEKLY INSPECTION**

Read and record the fluid height of staff gauges 10'

Does the pond surface show visible oil? No

Visually inspect containments liner Good

Check leak detection system for any evidence of a loss of integrity of the primary liner Everything is good

SUMMARY

of Action Item(s) 0

Inspector [Steven Anderson](#)

Signature

A handwritten signature in blue ink, appearing to be "S. Anderson", written over a horizontal line.

Generated Tuesday, August 19th 2025, 10:18am CDT.

powered by KPA



New Mexico Recycling Facility Weekly Inspection

Location

Submitted By

[Mario Nevarez](#)

Surrogate

[Mario Nevarez](#)

Started On August 20 2025, 10:16am


Submitted On August 20 2025, 10:16am (23 seconds)

Weather 80°, clear

Version V1 (latest)

Updated August 20 2025, 10:16am

Report No. 64669839



New Mexico Recycling Facility Weekly Inspection

GENERAL DETAILS

Date August 20th 2025

Area [New Mexico](#)Recycle Facility [FULFER RECYCLE FACILITY](#)

WEEKLY INSPECTION

Read and record the fluid height of staff gauges Yes

Does the pond surface show visible oil? No

Visually inspect containments liner Yes

Check leak detection system for any evidence of a loss of integrity of the primary liner Yes

SUMMARY

of Action Item(s) 0

Inspector [Mario Nevarez](#)

Signature



New Mexico Recycling Facility Weekly Inspection

Submitted By

[Mario Nevarez](#)

Surrogate

[Mario Nevarez](#)

Started On August 26 2025, 10:32am

Submitted On August 26 2025, 10:33am (40 seconds)


Weather 81°, clear

Version V1 (latest)

Updated August 26 2025, 10:33am

Report No. 65040239

Location



New Mexico Recycling Facility Weekly Inspection

GENERAL DETAILS

Date August 26th 2025

Area [New Mexico](#)Recycle Facility [FULFER RECYCLE FACILITY](#)

WEEKLY INSPECTION

Read and record the fluid height of staff gauges Yes

Does the pond surface show visible oil? No

Visually inspect containments liner Yes


Check leak detection system for any evidence of a loss of integrity of the primary liner Yes

SUMMARY

of Action Item(s) 0

Inspector [Mario Nevarez](#)

Signature

A handwritten signature in blue ink, consisting of several overlapping loops and a long horizontal stroke at the bottom.

Generated Tuesday, August 26th 2025, 10:35am CDT.

powered by  KPA

**New Mexico Recycling Facility Weekly Inspection****Location**

Submitted By

[Mario Nevarez](#)

Surrogate

[Mario Nevarez](#)

Started On

September 2 2025, 8:39am

Submitted On

September 2 2025, 8:40am (24 seconds)

Weather

69°, clear

Version


V1 (latest)

Updated

September 2 2025, 8:40am

Report No.

65393869

**New Mexico Recycling Facility Weekly Inspection****GENERAL DETAILS**

Date

September 2nd 2025

Area

[New Mexico](#)

Recycle Facility

[FULFER RECYCLE FACILITY](#)**WEEKLY INSPECTION**

Read and record the fluid height of staff gauges

Yes

Does the pond surface show visible oil?

No

Visually inspect containments liner

Yes

Check leak detection system for any evidence of a loss of integrity of the primary liner

Yes

SUMMARY

of Action Item(s)

0

Inspector

[Mario Nevarez](#)

Signature

A handwritten signature in blue ink, consisting of a stylized 'M' followed by a series of loops and a long horizontal stroke at the bottom.

Generated Tuesday, September 2nd 2025, 8:46am CDT.

powered by  KPA



New Mexico Recycling Facility Weekly Inspection

Submitted By  [Fernando Sanchez](#)Surrogate  [Fernando Sanchez](#)

Started On September 3 2025, 12:22pm

Submitted On September 3 2025, 12:35pm (13 minutes)


Weather 82°, clear

Version V1 (latest)

Updated September 3 2025, 12:35pm

Report No. 65502181

Location



New Mexico Recycling Facility Weekly Inspection

GENERAL DETAILS

Date September 3rd 2025

Area [New Mexico](#)Recycle Facility [FULFER RECYCLE FACILITY](#)

WEEKLY INSPECTION

Read and record the fluid height of staff gauges 11ft 8in

NOTES

Erosion around pond soil

Does the pond surface show visible oil? No

Visually inspect containments liner Liner looks to be in good condition

Check leak detection system for any evidence of a loss of integrity of the primary liner No evidence of integrity loss

SUMMARY

of Action Item(s) 0

Inspector [Fernando Sanchez](#)

Signature

Generated Wednesday, September 3rd 2025, 12:58pm CDT.

powered by  KPA



New Mexico Recycling Facility Weekly Inspection

Submitted By

[Mario Nevarez](#)

Surrogate

[Mario Nevarez](#)

Started On September 8 2025, 4:37pm

Submitted On September 8 2025, 4:37pm (20 seconds)


Weather 87°, clear

Version V1 (latest)

Updated September 8 2025, 4:37pm

Report No. 65797519

Location



New Mexico Recycling Facility Weekly Inspection

GENERAL DETAILS

Date September 8th 2025

Area [New Mexico](#)Recycle Facility [FULFER RECYCLE FACILITY](#)

WEEKLY INSPECTION

Read and record the fluid height of staff gauges Yes

Does the pond surface show visible oil? No

Visually inspect containments liner Yes

Check leak detection system for any evidence of a loss of integrity of the primary liner Yes

SUMMARY

of Action Item(s) 0

Inspector [Mario Nevarez](#)

Signature



New Mexico Recycling Facility Weekly Inspection

Submitted By

[Fernando Sanchez](#)

Surrogate

[Fernando Sanchez](#)

Started On September 11 2025, 2:04pm

Submitted On September 11 2025, 2:05pm (2 minutes)


Weather 88°, clear

Version V1 (latest)

Updated September 11 2025, 2:05pm

Report No. 66014527

Location



New Mexico Recycling Facility Weekly Inspection

GENERAL DETAILS

Date September 11th 2025

Area [New Mexico](#)Recycle Facility [FULFER RECYCLE FACILITY](#)

WEEKLY INSPECTION

Read and record the fluid height of staff gauges 12ft 7in

Does the pond surface show visible oil? No

Visually inspect containments liner Liner looks go be in good condition

Check leak detection system for any evidence of a loss of integrity of the primary liner No evidence of integrity loss

SUMMARY

of Action Item(s) 0

Inspector [Fernando Sanchez](#)

Signature



New Mexico Recycling Facility Weekly Inspection

Location

Submitted By

[Mario Nevarez](#)

Surrogate

[Mario Nevarez](#)

Started On

September 15 2025, 3:39pm

Submitted On

September 15 2025, 3:39pm (29 seconds)

Weather

88°, clear

Version


V1 (latest)

Updated

September 15 2025, 3:39pm

Report No.

66213178



New Mexico Recycling Facility Weekly Inspection

GENERAL DETAILS

Date

September 15th 2025

Area

[New Mexico](#)

Recycle Facility

[FULFER RECYCLE FACILITY](#)

WEEKLY INSPECTION

Read and record the fluid height of staff gauges

Yes

Does the pond surface show visible oil?

No

Visually inspect containments liner

Yes

Check leak detection system for any evidence of a loss of integrity of the primary liner

Yes

SUMMARY

of Action Item(s)

0

Inspector

[Mario Nevarez](#)

Signature



New Mexico Recycling Facility Weekly Inspection

Submitted By

[Fernando Sanchez](#)

Surrogate

[Fernando Sanchez](#)

Started On September 20 2025, 3:13pm

Submitted On September 20 2025, 3:17pm (4 minutes)


Weather 87°, clear

Version V1 (latest)

Updated September 20 2025, 3:17pm

Report No. 66528856

Location



New Mexico Recycling Facility Weekly Inspection

GENERAL DETAILS

Date September 20th 2025

Area [New Mexico](#)Recycle Facility [FULFER RECYCLE FACILITY](#)

WEEKLY INSPECTION

Read and record the fluid height of staff gauges 14'2"

Does the pond surface show visible oil? No

Visually inspect containments liner Liner looks to be in good condition

Check leak detection system for any evidence of a loss of integrity of the primary liner No evidence of loss of integrity

SUMMARY

of Action Item(s) 0

Inspector [Fernando Sanchez](#)

Signature None

Generated Tuesday, September 23rd 2025, 3:25pm CDT.

powered by KPA



New Mexico Recycling Facility Weekly Inspection

Submitted By

[Mario Nevarez](#)

Surrogate

[Mario Nevarez](#)

Started On September 22 2025, 10:20am

Submitted On September 22 2025, 10:21am (37 seconds)


Weather 80°, clear

Version V1 (latest)

Updated September 22 2025, 10:21am

Report No. 66601293

Location



New Mexico Recycling Facility Weekly Inspection

GENERAL DETAILS

Date September 22nd 2025

Area [New Mexico](#)Recycle Facility [FULFER RECYCLE FACILITY](#)

WEEKLY INSPECTION

Read and record the fluid height of staff gauges Yes

Does the pond surface show visible oil? No

Visually inspect containments liner Yes

Check leak detection system for any evidence of a loss of integrity of the primary liner Yes

SUMMARY

of Action Item(s) 0

Inspector [Mario Nevarez](#)

Signature

Generated Tuesday, September 23rd 2025, 3:29pm CDT.

powered by  KPA



New Mexico Recycling Facility Weekly Inspection

Submitted By

[Fernando Sanchez](#)

Surrogate

[Fernando Sanchez](#)

Started On September 27 2025, 2:30pm

Submitted On September 27 2025, 2:31pm (a minute)

Weather 86°, clear

Version V1 (latest)

Updated September 27 2025, 2:31pm

Report No. 66962155

Location



New Mexico Recycling Facility Weekly Inspection

GENERAL DETAILS

Date September 27th 2025

Area [New Mexico](#)Recycle Facility [FULFER RECYCLE FACILITY](#)

WEEKLY INSPECTION

Read and record the fluid height of staff gauges 14'2"

Does the pond surface show visible oil? No

Visually inspect containments liner Liner looks to be in good condition

Check leak detection system for any evidence of a loss of integrity of the primary liner No evidence of loss of integrity

SUMMARY

of Action Item(s) 0

Inspector [Fernando Sanchez](#)

Signature



New Mexico Recycling Facility Weekly Inspection

Location

Submitted By

[Mario Nevarez](#)

Surrogate

[Mario Nevarez](#)

Started On

September 29 2025, 10:42am

Submitted On

September 29 2025, 10:42am (22 seconds)

Weather

67°, cloudy

Version


V1 (latest)

Updated

September 29 2025, 10:42am

Report No.

67042266



New Mexico Recycling Facility Weekly Inspection

GENERAL DETAILS

Date

September 29th 2025

Area

[New Mexico](#)

Recycle Facility

[FULFER RECYCLE FACILITY](#)

WEEKLY INSPECTION

Read and record the fluid height of staff gauges

Yes

Does the pond surface show visible oil?

No

Visually inspect containments liner

Yes

Check leak detection system for any evidence of a loss of integrity of the primary liner

Yes

SUMMARY

of Action Item(s)

0

Inspector

[Mario Nevarez](#)

Signature



New Mexico Recycling Facility Weekly Inspection

Submitted By

[Mario Nevarez](#)

Surrogate

[Mario Nevarez](#)

Started On October 8 2025, 12:55pm

Submitted On October 8 2025, 12:56pm (37 seconds)


Weather 74°, cloudy

Version V1 (latest)

Updated October 8 2025, 12:56pm

Report No. 67669618

Location



New Mexico Recycling Facility Weekly Inspection

GENERAL DETAILS

Date October 8th 2025

Area [New Mexico](#)Recycle Facility [FULFER RECYCLE FACILITY](#)

WEEKLY INSPECTION

Read and record the fluid height of staff gauges Yes

Does the pond surface show visible oil? No

Visually inspect containments liner Yes

Check leak detection system for any evidence of a loss of integrity of the primary liner Yes

SUMMARY

of Action Item(s) 0

Inspector [Mario Nevarez](#)

Signature

**New Mexico Recycling Facility Weekly Inspection****Location**

Submitted By

[Steven Anderson](#)*Location was not collected for this report.*

Surrogate

[Steven Anderson](#)

Started On October 9 2025, 12:27pm

Submitted On October 9 2025, 12:28pm (a minute)

Weather NaN°,

Version V1 (latest)

Updated October 9 2025, 12:28pm

Report No. 67747234

New Mexico Recycling Facility Weekly Inspection**GENERAL DETAILS**

Date October 9th 2025

Area [New Mexico](#)Recycle Facility [FULFER RECYCLE FACILITY](#)**WEEKLY INSPECTION**

Read and record the fluid height of staff gauges 13'

Does the pond surface show visible oil? No

Visually inspect containments liner Looks good

Check leak detection system for any evidence of a loss of integrity of the primary liner No signs of leaks

SUMMARY

of Action Item(s) 0

Inspector [Steven Anderson](#)

Signature

A handwritten signature in blue ink, consisting of several overlapping loops and strokes, positioned above a horizontal line.

Generated Wednesday, October 22nd 2025, 9:45am CDT.

powered by KPA

**New Mexico Recycling Facility Weekly Inspection****Location**

Submitted By

[Steven Anderson](#)*Location was not collected for this report.*

Surrogate

[Steven Anderson](#)

Started On October 13 2025, 2:44pm

Submitted On October 13 2025, 2:45pm (a minute)

Weather NaN°,

Version V1 (latest)

Updated October 13 2025, 2:45pm

Report No. 67942217

New Mexico Recycling Facility Weekly Inspection**GENERAL DETAILS**

Date October 13th 2025

Area [New Mexico](#)Recycle Facility [FULFER RECYCLE FACILITY](#)**WEEKLY INSPECTION**

Read and record the fluid height of staff gauges 12'

Does the pond surface show visible oil? No

Visually inspect containments liner Everything looks good

Check leak detection system for any evidence of a loss of integrity of the primary liner No signs of leaks

SUMMARY

of Action Item(s) 0

Inspector [Steven Anderson](#)

Signature

A handwritten signature in blue ink, appearing to be "S. Anderson", written over a horizontal line.

Generated Wednesday, October 22nd 2025, 10:24am CDT.

powered by KPA



New Mexico Recycling Facility Weekly Inspection

Submitted By

[Mario Nevarez](#)

Surrogate

[Mario Nevarez](#)

Started On October 20 2025, 1:24pm

Submitted On October 20 2025, 1:25pm (26 seconds)


Weather 89°, clear

Version V1 (latest)

Updated October 20 2025, 1:25pm

Report No. 68367260

Location



New Mexico Recycling Facility Weekly Inspection

GENERAL DETAILS

Date October 20th 2025

Area [New Mexico](#)Recycle Facility [FULFER RECYCLE FACILITY](#)

WEEKLY INSPECTION

Read and record the fluid height of staff gauges Yes

Does the pond surface show visible oil? No

Visually inspect containments liner Yes

Check leak detection system for any evidence of a loss of integrity of the primary liner Yes

SUMMARY

of Action Item(s) 0

Inspector [Mario Nevarez](#)

Signature



New Mexico Recycling Facility Weekly Inspection

Location

Submitted By

[Steven Anderson](#)

Location was not collected for this report.

Surrogate

[Steven Anderson](#)

Started On October 22 2025, 11:23am

Submitted On October 22 2025, 11:24am (a minute)

Weather NaN°,

Version V1 (latest)

Updated October 22 2025, 11:24am

Report No. 68517398

New Mexico Recycling Facility Weekly Inspection

GENERAL DETAILS

Date October 22nd 2025

Area [New Mexico](#)Recycle Facility [FULFER RECYCLE FACILITY](#)

WEEKLY INSPECTION

Read and record the fluid height of staff gauges 14.5'

Does the pond surface show visible oil? No

Visually inspect containments liner Everything looks good

Check leak detection system for any evidence of a loss of integrity of the primary liner No signs of leaks

SUMMARY

of Action Item(s) 0

Inspector [Steven Anderson](#)

Signature

Generated Wednesday, October 22nd 2025, 11:27am CDT.

powered by KPA

**New Mexico Recycling Facility Weekly Inspection****Location**

Submitted By

[Mario Nevarez](#)*Location was not collected for this report.*

Surrogate

[Mario Nevarez](#)

Started On October 27 2025, 8:37am

Submitted On October 27 2025, 8:38am (44 seconds)

Weather NaN°,

Version V1 (latest)

Updated October 27 2025, 8:38am

Report No. 68771991

New Mexico Recycling Facility Weekly Inspection**GENERAL DETAILS**

Date October 27th 2025

Area [New Mexico](#)Recycle Facility [FULFER RECYCLE FACILITY](#)**WEEKLY INSPECTION**

Read and record the fluid height of staff gauges Yes

Does the pond surface show visible oil? No

Visually inspect containments liner Yes

Check leak detection system for any evidence of a loss of integrity of the primary liner Yes

SUMMARY

of Action Item(s) 0

Inspector [Mario Nevarez](#)

Signature

A handwritten signature in blue ink, consisting of a stylized 'X' shape with a horizontal line at the bottom.

**New Mexico Recycling Facility Weekly Inspection****Location**

Submitted By

[Mario Nevarez](#)*Location was not collected for this report.*

Surrogate

[Mario Nevarez](#)

Started On

November 4 2025, 11:35am

Submitted On

November 4 2025, 11:35am (20 seconds)

Weather

NaN°,

Version

V1 (latest)

Updated

November 4 2025, 11:35am

Report No.

69321418

New Mexico Recycling Facility Weekly Inspection**GENERAL DETAILS**

Date

November 4th 2025

Area

[New Mexico](#)

Recycle Facility

[FULFER RECYCLE FACILITY](#)**WEEKLY INSPECTION**

Read and record the fluid height of staff gauges

Yes

Does the pond surface show visible oil?

No

Visually inspect containments liner

Yes

Check leak detection system for any evidence of a loss of integrity of the primary liner

Yes

SUMMARY


of Action Item(s)

0

Inspector

[Mario Nevarez](#)

Signature

A handwritten signature in blue ink, consisting of a stylized 'X' shape with a horizontal line crossing it.

Generated Tuesday, November 4th 2025, 1:54pm CST.

powered by  KPA



New Mexico Recycling Facility Weekly Inspection

Submitted By

[Mario Nevarez](#)

Surrogate

[Mario Nevarez](#)

Started On November 10 2025, 1:16pm

Submitted On November 10 2025, 1:16pm (26 seconds)


Weather 58°, clear

Version V1 (latest)

Updated November 10 2025, 1:16pm

Report No. 69695367

Location



New Mexico Recycling Facility Weekly Inspection

GENERAL DETAILS

Date November 10th 2025

Area [West Texas](#)Recycle Facility [FULFER RECYCLE FACILITY](#)

WEEKLY INSPECTION

Read and record the fluid height of staff gauges Yes

Does the pond surface show visible oil? No

Visually inspect containments liner Yes

Check leak detection system for any evidence of a loss of integrity of the primary liner Yes

SUMMARY

of Action Item(s) 0

Inspector [Mario Nevarez](#)

Signature

**New Mexico Recycling Facility Weekly Inspection****Location**

Submitted By

[William Waldron](#)*Location was not collected for this report.*

Surrogate

[William Waldron](#)

Started On

November 5 2025, 2:27pm

Submitted On

November 13 2025, 10:08am (8 days)

Weather

NaN°

Version

V1 (latest)

Updated

November 13 2025, 10:08am

Report No.

69912058

New Mexico Recycling Facility Weekly Inspection**GENERAL DETAILS**

Date

November 13th 2025

Area

[New Mexico](#)

Recycle Facility

[FULFER RECYCLE FACILITY](#)**WEEKLY INSPECTION**

Read and record the fluid height of staff gauges

11 1/2 ft

Does the pond surface show visible oil?

No

Visually inspect containments liner

Good condition

Check leak detection system for any evidence of a loss of integrity of the primary liner

No evidence of loss of integrity

SUMMARY

of Action Item(s)

0

Inspector

[William Waldron](#)

Signature

A handwritten signature in blue ink, consisting of stylized, overlapping letters that appear to be "W" and "L".

**New Mexico Recycling Facility Weekly Inspection****Location**

Submitted By

[Mario Nevarez](#)

Surrogate

[Mario Nevarez](#)

Started On

November 17 2025, 9:17am

Submitted On

November 17 2025, 9:17am (31 seconds)

Weather

65°, clear

Version


V1 (latest)

Updated

November 17 2025, 9:17am

Report No.

70111052

**New Mexico Recycling Facility Weekly Inspection****GENERAL DETAILS**

Date

November 17th 2025

Area

[New Mexico](#)

Recycle Facility

[FULFER RECYCLE FACILITY](#)**WEEKLY INSPECTION**

Read and record the fluid height of staff gauges

Yes

Does the pond surface show visible oil?

No

Visually inspect containments liner

Yes

Check leak detection system for any evidence of a loss of integrity of the primary liner

Yes

SUMMARY

of Action Item(s)

0

Inspector

[Mario Nevarez](#)

Signature

A handwritten signature in blue ink, appearing to be "Mario Nevarez", written over a horizontal line.

Generated Monday, November 17th 2025, 9:23am CST.

powered by  KPA



New Mexico Recycling Facility Weekly Inspection

Submitted By

[William Waldron](#)

Surrogate

[William Waldron](#)

Started On November 19 2025, 10:49am

Submitted On November 19 2025, 10:49am (44 seconds)


Weather 61°, cloudy

Version V1 (latest)

Updated November 19 2025, 10:50am

Report No. 70287376

Location



New Mexico Recycling Facility Weekly Inspection

GENERAL DETAILS

Date November 19th 2025

Area [New Mexico](#)Recycle Facility [FULFER RECYCLE FACILITY](#)

WEEKLY INSPECTION

Read and record the fluid height of staff gauges 11ft

Does the pond surface show visible oil? No

Visually inspect containments liner Good

Check leak detection system for any evidence of a loss of integrity of the primary liner No loss of integrity

SUMMARY

of Action Item(s) 0

Inspector [William Waldron](#)

Signature

Generated Wednesday, November 19th 2025, 3:40pm CST.

powered by KPA



New Mexico Recycling Facility Weekly Inspection

Submitted By

[Mario Nevarez](#)

Surrogate

[Mario Nevarez](#)

Started On

November 26 2025, 3:34pm

Submitted On

November 26 2025, 3:35pm (28 seconds)

Weather

57°, cloudy

Version

V1 (latest)


Updated

November 26 2025, 3:35pm

Report No.

70730432

Location



New Mexico Recycling Facility Weekly Inspection

GENERAL DETAILS

Date

November 26th 2025

Area

[New Mexico](#)

Recycle Facility

[FULFER RECYCLE FACILITY](#)

WEEKLY INSPECTION

Read and record the fluid height of staff gauges

Yes

Does the pond surface show visible oil?

No

Visually inspect containments liner

Yes

Check leak detection system for any evidence of a loss of integrity of the primary liner

Yes

SUMMARY


of Action Item(s)

0

Inspector

[Mario Nevarez](#)

Signature

A handwritten signature in blue ink, consisting of several overlapping loops and a long, sweeping tail that extends downwards and to the right.

Generated Wednesday, December 3rd 2025, 8:52am CST.

powered by  KPA



New Mexico Recycling Facility Weekly Inspection

Submitted By  [William Waldron](#)Surrogate  [William Waldron](#)

Started On November 19 2025, 12:09pm

Submitted On November 28 2025, 11:07am (9 days)


Weather 54°, cloudy

Version V1 (latest)

Updated November 28 2025, 11:07am

Report No. 70773989

Location



New Mexico Recycling Facility Weekly Inspection

GENERAL DETAILS

Date November 28th 2025

Area [New Mexico](#)Recycle Facility [FULFER RECYCLE FACILITY](#)

WEEKLY INSPECTION

Read and record the fluid height of staff gauges 11ft 6 inches

Does the pond surface show visible oil? No

Visually inspect containments liner No visible tears

Check leak detection system for any evidence of a loss of integrity of the primary liner No loss of integrity

SUMMARY

of Action Item(s) 0

Inspector [William Waldron](#)Signature 

Generated Wednesday, December 3rd 2025, 8:51am CST.

powered by  KPA

**New Mexico Recycling Facility Weekly Inspection****Location**

Submitted By

[Mario Nevarez](#)

Surrogate

[Mario Nevarez](#)

Started On

December 1 2025, 10:17am

Submitted On

December 1 2025, 10:17am (21 seconds)

Weather

37°, clear

Version


V1 (latest)

Updated

December 1 2025, 10:19am

Report No.

70871966

**New Mexico Recycling Facility Weekly Inspection****GENERAL DETAILS**

Date

December 1st 2025

Area

[New Mexico](#)

Recycle Facility

[FULFER RECYCLE FACILITY](#)**WEEKLY INSPECTION**

Read and record the fluid height of staff gauges

Yes

Does the pond surface show visible oil?

No

Visually inspect containments liner

Yes

Check leak detection system for any evidence of a loss of integrity of the primary liner

Yes

SUMMARY

of Action Item(s)

0

Inspector

[Mario Nevarez](#)

Signature

A handwritten signature in blue ink, consisting of a stylized 'M' and 'N' combined, written over a horizontal line.

Generated Wednesday, December 3rd 2025, 8:49am CST.

powered by  KPA



New Mexico Recycling Facility Weekly Inspection

Submitted By

[Mario Nevarez](#)

Surrogate

[Mario Nevarez](#)

Started On December 8 2025, 7:41am

Submitted On December 8 2025, 7:41am (29 seconds)

Weather 39°, clear

Version V1 (latest)

Updated December 8 2025, 7:41am

Report No. 71281878

Location



New Mexico Recycling Facility Weekly Inspection

GENERAL DETAILS

Date December 8th 2025

Area [New Mexico](#)Recycle Facility [FULFER RECYCLE FACILITY](#)

WEEKLY INSPECTION

Read and record the fluid height of staff gauges Yes

Does the pond surface show visible oil? No

Visually inspect containments liner Yes

Check leak detection system for any evidence of a loss of integrity of the primary liner Yes

SUMMARY

of Action Item(s) 0

Inspector [Mario Nevarez](#)

Signature

**New Mexico Recycling Facility Weekly Inspection****Location**

Submitted By

[Steven Anderson](#)*Location was not collected for this report.*

Surrogate

[Steven Anderson](#)

Started On

October 22 2025, 12:17pm

Submitted On

December 17 2025, 10:35am (2 months)

Weather

NaN°,

Version

V1 (latest)

Updated

December 17 2025, 10:35am

Report No.

71866063

New Mexico Recycling Facility Weekly Inspection**GENERAL DETAILS**

Date

December 17th 2025

Area

[New Mexico](#)

Recycle Facility

[FULFER RECYCLE FACILITY](#)**WEEKLY INSPECTION**

Read and record the fluid height of staff gauges

11.5"

Does the pond surface show visible oil?

No

Visually inspect containments liner

Everything looks good

Check leak detection system for any evidence of a loss of integrity of the primary liner

Everything is good

SUMMARY

of Action Item(s)

0

Inspector

[Steven Anderson](#)

Signature

A handwritten signature in blue ink, appearing to be "S. Anderson", written over a horizontal line.

Generated Wednesday, December 17th 2025, 10:36am CST.

powered by KPA

**New Mexico Recycling Facility Weekly Inspection****Location**

Submitted By

[Mario Nevarez](#)

Surrogate

[Mario Nevarez](#)

Started On

December 22 2025, 9:10am

Submitted On

December 22 2025, 12:20pm (3 hours)

Weather

64°, clear

Version


V1 (latest)

Updated

December 22 2025, 12:20pm

Report No.

72124647

**New Mexico Recycling Facility Weekly Inspection****GENERAL DETAILS**

Date

December 22nd 2025

Area

[New Mexico](#)

Recycle Facility

[FULFER RECYCLE FACILITY](#)**WEEKLY INSPECTION**

Read and record the fluid height of staff gauges

Yes

Does the pond surface show visible oil?

No

Visually inspect containments liner

Yes

Check leak detection system for any evidence of a loss of integrity of the primary liner

Yes

SUMMARY

of Action Item(s)

0

Inspector

[Mario Nevarez](#)

Signature

A handwritten signature in blue ink, consisting of a stylized, angular shape with a horizontal line extending to the right.

Generated Friday, December 26th 2025, 11:47am CST.

powered by  KPA



New Mexico Recycling Facility Weekly Inspection

Location

Submitted By

[Mario Nevarez](#)

Surrogate

[Mario Nevarez](#)

Started On

December 31 2025, 8:17am

Submitted On

December 31 2025, 8:18am (22 seconds)

Weather

30°, cloudy

Version


V1 (latest)

Updated

December 31 2025, 8:18am

Report No.

72453210



New Mexico Recycling Facility Weekly Inspection

GENERAL DETAILS

Date

December 31st 2025

Area

[New Mexico](#)

Recycle Facility

[FULFER RECYCLE FACILITY](#)

WEEKLY INSPECTION

Read and record the fluid height of staff gauges

Yes

Does the pond surface show visible oil?

No

Visually inspect containments liner

Yes

Check leak detection system for any evidence of a loss of integrity of the primary liner

Yes

SUMMARY

of Action Item(s)

0

Inspector

[Mario Nevarez](#)

Signature

Generated Monday, January 5th 2026, 10:40am CST.

powered by  KPA



New Mexico Recycling Facility Weekly Inspection

Submitted By

[Mario Nevarez](#)

Surrogate

[Mario Nevarez](#)

Started On January 5 2026, 12:17pm

Submitted On January 5 2026, 12:17pm (22 seconds)


Weather 69°, clear

Version V1 (latest)

Updated January 5 2026, 12:17pm

Report No. 72652911

Location



New Mexico Recycling Facility Weekly Inspection

GENERAL DETAILS

Date January 5th 2026

Area [New Mexico](#)Recycle Facility [FULFER RECYCLE FACILITY](#)

WEEKLY INSPECTION

Read and record the fluid height of staff gauges Yes

Does the pond surface show visible oil? No

Visually inspect containments liner Yes


Check leak detection system for any evidence of a loss of integrity of the primary liner Yes

SUMMARY

of Action Item(s) 0

Inspector [Mario Nevarez](#)

Signature

A handwritten signature in blue ink, consisting of several overlapping loops and a long, sweeping tail that extends downwards and to the right.

Generated Monday, January 5th 2026, 12:30pm CST.

powered by  KPA



New Mexico Recycling Facility Weekly Inspection

Submitted By

[Mario Nevarez](#)

Surrogate

[Mario Nevarez](#)

Started On January 12 2026, 12:51pm

Submitted On January 12 2026, 12:52pm (20 seconds)


Weather 48°, clear

Version V1 (latest)

Updated January 12 2026, 12:52pm

Report No. 73104975

Location



New Mexico Recycling Facility Weekly Inspection

GENERAL DETAILS

Date January 12th 2026

Area [New Mexico](#)Recycle Facility [FULFER RECYCLE FACILITY](#)

WEEKLY INSPECTION

Read and record the fluid height of staff gauges Yes

Does the pond surface show visible oil? No

Visually inspect containments liner Yes

Check leak detection system for any evidence of a loss of integrity of the primary liner Yes

SUMMARY

of Action Item(s) 0

Inspector [Mario Nevarez](#)

Signature



New Mexico Recycling Facility Weekly Inspection

Submitted By

[Mario Nevarez](#)

Surrogate

[Mario Nevarez](#)

Started On January 20 2026, 6:55am

Submitted On January 20 2026, 6:55am (22 seconds)

Weather 32°, clear

Version V1 (latest)

Updated January 20 2026, 6:55am

Report No. 73569124

Location



New Mexico Recycling Facility Weekly Inspection

GENERAL DETAILS

Date January 20th 2026

Area [New Mexico](#)Recycle Facility [FULFER RECYCLE FACILITY](#)

WEEKLY INSPECTION

Read and record the fluid height of staff gauges Yes

Does the pond surface show visible oil? No

Visually inspect containments liner Yes

Check leak detection system for any evidence of a loss of integrity of the primary liner Yes

SUMMARY

of Action Item(s) 0

Inspector [Mario Nevarez](#)

Signature

Generated Tuesday, January 20th 2026, 9:28am CST.

powered by KPA



New Mexico Recycling Facility Weekly Inspection

Submitted By

[Mario Nevarez](#)

Surrogate

[Mario Nevarez](#)

Started On January 26 2026, 12:54pm

Submitted On January 26 2026, 12:54pm (26 seconds)


Weather 19°, snow

Version V1 (latest)

Updated January 26 2026, 12:54pm

Report No. 73897396

Location



New Mexico Recycling Facility Weekly Inspection

GENERAL DETAILS

Date January 26th 2026

Area [New Mexico](#)Recycle Facility [FULFER RECYCLE FACILITY](#)

WEEKLY INSPECTION

Read and record the fluid height of staff gauges Yes

Does the pond surface show visible oil? No

Visually inspect containments liner Yes

Check leak detection system for any evidence of a loss of integrity of the primary liner Yes

SUMMARY

of Action Item(s) 0

Inspector [Mario Nevarez](#)

Signature

Generated Tuesday, January 27th 2026, 8:07am CST.

powered by  KPA



New Mexico Recycling Facility Weekly Inspection

Submitted By

[Mario Nevarez](#)

Surrogate

[Mario Nevarez](#)

Started On February 2 2026, 2:26pm

Submitted On February 2 2026, 2:26pm (36 seconds)


Weather 62°, cloudy

Version V1 (latest)

Updated February 2 2026, 2:26pm

Report No. 74352853

Location



New Mexico Recycling Facility Weekly Inspection

GENERAL DETAILS

Date February 2nd 2026

Area [New Mexico](#)Recycle Facility [FULFER RECYCLE FACILITY](#)

WEEKLY INSPECTION

Read and record the fluid height of staff gauges Yes

Does the pond surface show visible oil? No

Visually inspect containments liner Yes


Check leak detection system for any evidence of a loss of integrity of the primary liner Yes

SUMMARY

of Action Item(s) 0

Inspector [Mario Nevarez](#)

Signature

A handwritten signature in blue ink, consisting of several overlapping loops and a long horizontal stroke at the bottom.

Generated Monday, February 2nd 2026, 2:27pm CST.

powered by  KPA



New Mexico Recycling Facility Weekly Inspection

Location

Submitted By

[Mario Nevarez](#)

Surrogate

[Mario Nevarez](#)

Started On

February 8 2026, 9:33am

Submitted On

February 8 2026, 9:33am (21 seconds)

Weather

53°, clear

Version


V1 (latest)

Updated

February 8 2026, 9:33am

Report No.

74748900



New Mexico Recycling Facility Weekly Inspection

GENERAL DETAILS

Date

February 8th 2026

Area

[New Mexico](#)

Recycle Facility

[FULFER RECYCLE FACILITY](#)

WEEKLY INSPECTION

Read and record the fluid height of staff gauges

Yes

Does the pond surface show visible oil?

No

Visually inspect containments liner

Yes

Check leak detection system for any evidence of a loss of integrity of the primary liner

Yes

SUMMARY

of Action Item(s)

0

Inspector

[Mario Nevarez](#)

Signature



New Mexico Recycling Facility Weekly Inspection

Location

Submitted By

[Mario Nevarez](#)

Surrogate

[Mario Nevarez](#)

Started On

February 17 2026, 9:50am

Submitted On

February 17 2026, 9:51am (18 seconds)

Weather

47°, clear

Version


V1 (latest)

Updated

February 17 2026, 9:51am

Report No.

75346252



New Mexico Recycling Facility Weekly Inspection

GENERAL DETAILS

Date

February 17th 2026

Area

[New Mexico](#)

Recycle Facility

[FULFER RECYCLE FACILITY](#)

WEEKLY INSPECTION

Read and record the fluid height of staff gauges

Yes

Does the pond surface show visible oil?

No

Visually inspect containments liner

Yes

Check leak detection system for any evidence of a loss of integrity of the primary liner

Yes

SUMMARY

of Action Item(s)

0

Inspector

[Mario Nevarez](#)

Signature



New Mexico Recycling Facility Weekly Inspection

Submitted By

[Mario Nevarez](#)

Surrogate

[Mario Nevarez](#)

Started On February 25 2026, 7:42am

Submitted On February 25 2026, 7:42am (18 seconds)


Weather 56°, clear

Version V1 (latest)

Updated February 25 2026, 7:42am

Report No. 75876550

Location



New Mexico Recycling Facility Weekly Inspection

GENERAL DETAILS

Date February 25th 2026

Area [New Mexico](#)Recycle Facility [FULFER RECYCLE FACILITY](#)

WEEKLY INSPECTION

Read and record the fluid height of staff gauges Yes

Does the pond surface show visible oil? No

Visually inspect containments liner Yes


Check leak detection system for any evidence of a loss of integrity of the primary liner Yes

SUMMARY

of Action Item(s) 0

Inspector [Mario Nevarez](#)

Signature

A handwritten signature in blue ink, consisting of several overlapping loops and a long, sweeping tail that extends downwards and to the right. The signature is positioned above a horizontal grey line.

Generated Wednesday, February 25th 2026, 9:27am CST.

powered by  KPA



New Mexico Recycling Facility Weekly Inspection

Submitted By

[Mario Nevarez](#)

Surrogate

[Mario Nevarez](#)

Started On March 2 2026, 8:53am

Submitted On March 2 2026, 8:53am (20 seconds)


Weather 52°, clear

Version V1 (latest)

Updated March 2 2026, 8:53am

Report No. 76196849

Location



New Mexico Recycling Facility Weekly Inspection

GENERAL DETAILS

Date March 2nd 2026

Area [New Mexico](#)Recycle Facility [FULFER RECYCLE FACILITY](#)

WEEKLY INSPECTION

Read and record the fluid height of staff gauges Yes

Does the pond surface show visible oil? No

Visually inspect containments liner Yes

Check leak detection system for any evidence of a loss of integrity of the primary liner Yes

SUMMARY

of Action Item(s) 0

Inspector [Mario Nevarez](#)

Signature

Generated Tuesday, March 3rd 2026, 3:58pm CST.

powered by  KPA



New Mexico Recycling Facility Weekly Inspection

Submitted By

[Mario Nevarez](#)

Surrogate

[Mario Nevarez](#)

Started On March 10 2026, 10:45am

Submitted On March 10 2026, 10:46am (22 seconds)


Weather 66°, clear

Version V1 (latest)

Updated March 10 2026, 10:46am

Report No. 76792665

Location



New Mexico Recycling Facility Weekly Inspection

GENERAL DETAILS

Date March 10th 2026

Area [New Mexico](#)Recycle Facility [FULFER RECYCLE FACILITY](#)

WEEKLY INSPECTION

Read and record the fluid height of staff gauges Yes

Does the pond surface show visible oil? No

Visually inspect containments liner Yes

Check leak detection system for any evidence of a loss of integrity of the primary liner Yes

SUMMARY

of Action Item(s) 0

Inspector [Mario Nevarez](#)

Signature



New Mexico Recycling Facility Weekly Inspection

Submitted By

[Mario Nevarez](#)

Surrogate

[Mario Nevarez](#)

Started On March 16 2026, 11:42am

Submitted On March 16 2026, 11:42am (20 seconds)


Weather 38°, clear

Version V1 (latest)

Updated March 16 2026, 11:42am

Report No. 77196285

Location



New Mexico Recycling Facility Weekly Inspection

GENERAL DETAILS

Date March 16th 2026

Area [New Mexico](#)Recycle Facility [FULFER RECYCLE FACILITY](#)

WEEKLY INSPECTION

Read and record the fluid height of staff gauges Yes

Does the pond surface show visible oil? No

Visually inspect containments liner Yes


Check leak detection system for any evidence of a loss of integrity of the primary liner Yes

SUMMARY

of Action Item(s) 0

Inspector [Mario Nevarez](#)

Signature

A handwritten signature in blue ink, consisting of a stylized 'K' or 'R' shape, positioned above a horizontal line.

Generated Tuesday, March 17th 2026, 11:10am CDT.

powered by  KPA



New Mexico Recycling Facility Weekly Inspection

Location

Submitted By

[Mario Nevarez](#)

Surrogate

[Mario Nevarez](#)

Started On

March 23 2026, 9:42am

Submitted On

March 23 2026, 9:42am (20 seconds)

Weather

51°, clear

Version


V1 (latest)

Updated

March 23 2026, 9:42am

Report No.

77659877



New Mexico Recycling Facility Weekly Inspection

GENERAL DETAILS

Date

March 23rd 2026

Area

[New Mexico](#)

Recycle Facility

[FULFER RECYCLE FACILITY](#)

WEEKLY INSPECTION

Read and record the fluid height of staff gauges

Yes

Does the pond surface show visible oil?

No

Visually inspect containments liner

Yes

Check leak detection system for any evidence of a loss of integrity of the primary liner

Yes

SUMMARY

of Action Item(s)

0

Inspector

[Mario Nevarez](#)

Signature

Generated Monday, March 23rd 2026, 11:29am CDT.

powered by  KPA

**New Mexico Recycling Facility Weekly Inspection****Location**

Submitted By

[Mario Nevarez](#)

Surrogate

[Mario Nevarez](#)

Started On

March 30 2026, 10:33am

Submitted On

March 30 2026, 10:33am (24 seconds)

Weather

65°, clear

Version


V1 (latest)

Updated

March 30 2026, 10:33am

Report No.

78151867

**New Mexico Recycling Facility Weekly Inspection****GENERAL DETAILS**

Date

March 30th 2026

Area

[New Mexico](#)

Recycle Facility

[FULFER RECYCLE FACILITY](#)**WEEKLY INSPECTION**

Read and record the fluid height of staff gauges

Yes

Does the pond surface show visible oil?

No

Visually inspect containments liner

Yes

Check leak detection system for any evidence of a loss of integrity of the primary liner

Yes

SUMMARY

of Action Item(s)

0

Inspector

[Mario Nevarez](#)

Signature

A handwritten signature in blue ink, appearing to be "Mario Nevarez", written over a horizontal line.

Generated Wednesday, April 1st 2026, 12:53pm CDT.

powered by  KPA



New Mexico Recycling Facility Weekly Inspection

Location

Submitted By

[Mario Nevarez](#)

Surrogate

[Mario Nevarez](#)

Started On

April 2 2026, 7:07am

Submitted On

April 2 2026, 7:07am (39 seconds)

Weather

59°, clear

Version


V1 (latest)

Updated

April 2 2026, 7:07am

Report No.

78399850



New Mexico Recycling Facility Weekly Inspection

GENERAL DETAILS

Date

April 2nd 2026

Area

[New Mexico](#)

Recycle Facility

[FULFER RECYCLE FACILITY](#)

WEEKLY INSPECTION

Read and record the fluid height of staff gauges

Yes

Does the pond surface show visible oil?

No

Visually inspect containments liner

Yes

Check leak detection system for any evidence of a loss of integrity of the primary liner

Yes

SUMMARY

of Action Item(s)

0

Inspector

[Mario Nevarez](#)

Signature

Generated Thursday, April 2nd 2026, 12:14pm CDT.

powered by  KPA



New Mexico Recycling Facility Weekly Inspection

Location

Submitted By

[Mario Nevarez](#)

Surrogate

[Mario Nevarez](#)

Started On

April 6 2026, 11:13am

Submitted On

April 6 2026, 11:14am (19 seconds)

Weather

61°, clear

Version


V1 (latest)

Updated

April 6 2026, 11:14am

Report No.

78634816



New Mexico Recycling Facility Weekly Inspection

GENERAL DETAILS

Date

April 6th 2026

Area

[New Mexico](#)

Recycle Facility

[FULFER RECYCLE FACILITY](#)

WEEKLY INSPECTION

Read and record the fluid height of staff gauges

Yes

Does the pond surface show visible oil?

No

Visually inspect containments liner

Yes

Check leak detection system for any evidence of a loss of integrity of the primary liner

Yes

SUMMARY

of Action Item(s)

0

Inspector

[Mario Nevarez](#)

Signature

Generated Tuesday, April 7th 2026, 10:03am CDT.

powered by  KPA



New Mexico Recycling Facility Weekly Inspection

Submitted By

[Mario Nevarez](#)

Surrogate

[Mario Nevarez](#)

Started On April 14 2026, 8:17am

Submitted On April 14 2026, 8:17am (19 seconds)


Weather 66°, cloudy

Version V1 (latest)

Updated April 14 2026, 8:17am

Report No. 79219542

Location



New Mexico Recycling Facility Weekly Inspection

GENERAL DETAILS

Date April 14th 2026

Area [New Mexico](#)Recycle Facility [FULFER RECYCLE FACILITY](#)

WEEKLY INSPECTION

Read and record the fluid height of staff gauges Yes

Does the pond surface show visible oil? No

Visually inspect containments liner Yes


Check leak detection system for any evidence of a loss of integrity of the primary liner Yes

SUMMARY

of Action Item(s) 0

Inspector [Mario Nevarez](#)

Signature

A handwritten signature in blue ink, consisting of several overlapping loops and a long, sweeping tail that extends downwards and to the right. The signature is positioned above a horizontal line.

Generated Tuesday, April 14th 2026, 9:21am CDT.

powered by  KPA



New Mexico Recycling Facility Weekly Inspection

Submitted By

[Mario Nevarez](#)

Surrogate

[Mario Nevarez](#)

Started On April 28 2026, 10:56am

Submitted On April 28 2026, 10:56am (19 seconds)


Weather 80°, clear

Version V1 (latest)

Updated April 28 2026, 10:57am

Report No. 80207140

Location



New Mexico Recycling Facility Weekly Inspection

GENERAL DETAILS

Date April 28th 2026

Area [New Mexico](#)Recycle Facility [FULFER RECYCLE FACILITY](#)

WEEKLY INSPECTION

Read and record the fluid height of staff gauges Yes

Does the pond surface show visible oil? No

Visually inspect containments liner Yes


Check leak detection system for any evidence of a loss of integrity of the primary liner Yes

SUMMARY

of Action Item(s) 0

Inspector [Mario Nevarez](#)

Signature

A handwritten signature in blue ink, consisting of several overlapping loops and a long vertical stroke extending downwards from the right side.

Generated Tuesday, April 28th 2026, 12:08pm CDT.

powered by  KPA



New Mexico Recycling Facility Weekly Inspection

Submitted By

[Mario Nevarez](#)

Surrogate

[Mario Nevarez](#)

Started On May 5 2026, 12:48pm

Submitted On May 5 2026, 12:48pm (18 seconds)


Weather 83°, clear

Version V1 (latest)

Updated May 5 2026, 12:48pm

Report No. 80706599

Location



New Mexico Recycling Facility Weekly Inspection

GENERAL DETAILS

Date May 5th 2026

Area [New Mexico](#)Recycle Facility [FULFER RECYCLE FACILITY](#)

WEEKLY INSPECTION

Read and record the fluid height of staff gauges Yes

Does the pond surface show visible oil? No

Visually inspect containments liner Yes

Check leak detection system for any evidence of a loss of integrity of the primary liner Yes

SUMMARY

of Action Item(s) 0

Inspector [Mario Nevarez](#)

Signature

Generated Tuesday, May 5th 2026, 1:01pm CDT.

powered by  KPA



New Mexico Recycling Facility Weekly Inspection

Submitted By

[Mario Nevarez](#)

Surrogate

[Mario Nevarez](#)

Started On May 11 2026, 10:00am

Submitted On May 11 2026, 11:04am (an hour)


Weather 69°, cloudy

Version V1 (latest)

Updated May 11 2026, 11:04am

Report No. 81099887

Location



New Mexico Recycling Facility Weekly Inspection

GENERAL DETAILS

Date May 11th 2026

Area [New Mexico](#)Recycle Facility [FULFER RECYCLE FACILITY](#)

WEEKLY INSPECTION

Read and record the fluid height of staff gauges Yes

Does the pond surface show visible oil? No

Visually inspect containments liner Yes


Check leak detection system for any evidence of a loss of integrity of the primary liner Yes

SUMMARY

of Action Item(s) 0

Inspector [Mario Nevarez](#)

Signature

A handwritten signature in blue ink, consisting of several overlapping loops and a long, sweeping tail that extends downwards and to the right.

Generated Monday, May 18th 2026, 8:10am CDT.

powered by  KPA



New Mexico Recycling Facility Weekly Inspection

Submitted By

[Mario Nevarez](#)

Surrogate

[Mario Nevarez](#)

Started On May 19 2026, 7:19am

Submitted On May 19 2026, 7:19am (19 seconds)


Weather 72°, clear

Version V1 (latest)

Updated May 19 2026, 7:19am

Report No. 81633785

Location



New Mexico Recycling Facility Weekly Inspection

GENERAL DETAILS

Date May 19th 2026

Area [New Mexico](#)Recycle Facility [FULFER RECYCLE FACILITY](#)

WEEKLY INSPECTION

Read and record the fluid height of staff gauges Yes

Does the pond surface show visible oil? No

Visually inspect containments liner Yes

Check leak detection system for any evidence of a loss of integrity of the primary liner Yes

SUMMARY

of Action Item(s) 0

Inspector [Mario Nevarez](#)

Signature



New Mexico Recycling Facility Weekly Inspection

Submitted By

[Mario Nevarez](#)

Surrogate

[Mario Nevarez](#)

Started On May 26 2026, 12:54pm

Submitted On May 26 2026, 12:54pm (18 seconds)


Weather 62°, rain

Version V1 (latest)

Updated May 26 2026, 12:54pm

Report No. 82081000

Location



New Mexico Recycling Facility Weekly Inspection

GENERAL DETAILS

Date May 26th 2026

Area [New Mexico](#)Recycle Facility [FULFER RECYCLE FACILITY](#)

WEEKLY INSPECTION

Read and record the fluid height of staff gauges Yes

Does the pond surface show visible oil? No

Visually inspect containments liner Yes


Check leak detection system for any evidence of a loss of integrity of the primary liner Yes

SUMMARY

of Action Item(s) 0

Inspector [Mario Nevarez](#)

Signature

A handwritten signature in blue ink, consisting of several overlapping loops and a long horizontal stroke at the bottom.

Generated Thursday, May 28th 2026, 12:16pm CDT.

powered by  KPA

Venegas, Victoria, EMNRD

From: Venegas, Victoria, EMNRD
Sent: Wednesday, July 1, 2026 11:15 AM
To: Shelly Cowden
Subject: 1RF-23 – OWL FULFER RECYCLING FACILITY AND CONTAINMENT [fOY1728349023]
Attachments: C-147 1RF-23 – OWL FULFER RECYCLING FACILITY AND CONTAINMENT [fOY1728349023] 07.01.2026.pdf

1RF-23 – OWL FULFER RECYCLING FACILITY AND CONTAINMENT [fOY1728349023]

Good morning Ms. Cowden.

The NMOCD has reviewed the registration/permit annual extension request for 1RF-23 – OWL FULFER RECYCLING FACILITY AND CONTAINMENT [fOY1728349023] received from [308339] OWL SWD OPERATING, LLC on 06/25/2026 Application ID **599578**. The registration/permit annual extension request is approved with the following conditions of approval:

- 1RF-23 – OWL FULFER RECYCLING FACILITY AND CONTAINMENT [fOY1728349023] is approved for one (1) year of operation from the date of the previous registration/permit expiration date of June 26, 2026. The new registration/permit expiration date is June 26, 2027.
- [308339] OWL SWD OPERATING, LLC will continue to operate, maintain, and close the 1RF-23 - OWL Fulfer Recycling Facility and Containment, ID [fOY1728349023] in compliance with 19.15.34 NMAC, to include but not limited to the performance of weekly inspections regardless of fluid levels in the containment; recording of detailed inspection reports; removal of debris, foreign objects and oil from the containment; and monthly reporting of recycling and reuse of produced water, drilling fluids, and liquid oil field waste via from C-148.
- [308339] OWL SWD OPERATING, LLC will maintain a liquid level in the containment that is at least equal to the weight of the liner plus 20%. [308339] OWL SWD OPERATING, LLC may maintain a higher liquid level if they choose.
- If less than 20% of the total fluid capacity is utilized every consecutive six months, operation of the facility is considered ceased and notification of cessation of operations should be sent electronically form through the OCD Online. An extension to extend the cessation of operations, not to exceed six months, may be submitted using a C-147 form via OCD Online.
- The recycling containment is bonded pursuant to 19.15.8 NMAC per 19.15.34.15(A)(2) NMAC. Water reuse and recycling from 1RF-23 – OWL FULFER RECYCLING FACILITY AND CONTAINMENT [fOY1728349023] is limited to wells owned or operated by [308339] OWL SWD OPERATING, LLC.
- A minimum of 3-feet freeboard must be maintained in the recycling containment at all times.
- [308339] OWL SWD OPERATING, LLC will comply with 19.15.29 NMAC Releases in the event of any release of produced water or other oil field wastes at 1RF-23 – OWL FULFER RECYCLING FACILITY AND CONTAINMENT [fOY1728349023]. [308339] OWL SWD OPERATING, LLC will comply with all other OCD rules.
- [308339] OWL SWD OPERATING, LLC must perform weekly inspections of the containment and leak detection system.
- If [308339] OWL SWD OPERATING, LLC, wishes to extend the registration/permit past June 26, 2027, a registration/permit extension request must be submitted to OCD. Extension requests are reviewed on a case-by-case basis and evaluated on their merit and are considered for a maximum length of one year.
- Additional requests must be submitted to OCD through the OCD Online system on Form C-147 as an Extension request and should include a formal extension request letter, a summary of the prior registration/permit period inspection reports, and the copies of the detailed inspection records for the prior permit period. The extension request should be submitted no later than May 26, 2027.

Please let me know if you have any questions.
Best regards,

Victoria Venegas • Senior Environmental Scientist
EMNRD - Oil Conservation Division
506 W. Texas Ave. Artesia, NM 88210
575.909.0269 | Victoria.Venegas@emnrd.nm.gov

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 599578

CONDITIONS

Operator: OWL SWD OPERATING, LLC 20 Greenway Plaza Houston, TX 77046	OGRID: 308339
	Action Number: 599578
	Action Type: [C-147] Water Recycle Long (C-147L)

CONDITIONS

Created By	Condition	Condition Date
vvenegas	1RF-23 – OWL FULFER RECYCLING FACILITY AND CONTAINMENT [fOY1728349023] is approved for one (1) year of operation from the date of the previous registration/permit expiration date of June 26, 2026. The new registration/permit expiration date is June 26, 2027. If [308339] OWL SWD OPERATING, LLC, wishes to extend the registration/permit past June 26, 2027, a registration/permit extension request must be submitted to OCD no later than May 26, 2027.	7/1/2026