

Pima Environmental Services 5614 N. Lovington Highway Hobbs, NM 88240 575-964-7740

June 24, 2022

NMOCD District 2 811 S. First Street Artesia, NM 88210

Bureau of Land Management 620 East Green Street Carlsbad, NM 88220

RE: Liner Inspection and Closure Report

Thistle Unit 22 CTB 2

API No. N/A

GPS: Latitude 32.295341 Longitude -103.554565 UL- A, Section 22, Township 23S, Range 33E NMOCD Reference No. NAPP2130051391

Devon Energy Production Company (Devon) has contracted Pima Environmental Services, LLC (Pima) to perform a liner inspection and prepare this closure report for a produced water release that happened at the Thistle Unit 22 CTB 2 (Thistle). An initial C-141 was submitted on October 27, 2021, and can be found in Appendix B. This incident was assigned Incident ID NAPP2130051391, by the New Mexico Oil Conservation Division (NMOCD).

Site Information and Site Characterization

The Thistle is located approximately twenty-five (25) miles West of Eunice, NM. This spill site is in Unit A, Section 22, Township 23S, Range 33E, Latitude 32.295341 Longitude -103.554565, Lea County, NM. A Location Map can be found in Figure 1.

Based upon New Mexico Office of the State Engineer well water data, depth to the nearest groundwater in this area is 225 feet below grade surface (BGS). According to the United States Geological Survey well water data, depth to the nearest groundwater in this area is greater than 146 feet BGS. See Appendix A for referenced water surveys. The Thistle is in a low karst area (Figure 3). A Topographic Map can be found in Figure 2.

Release Information

NAPP2130051391: On October 18, 2021, A Water transfer pump seal leaked and produced water leaked into lined containment. Approximately 11.7 barrels (bbls) of produced water was released. A vacuum truck was dispatched and recovered all 11.7 bbls of fluid from the lined SPCC containment ring. Once fluids were removed, the liner was visually inspected by Devon field staff for any pinholes or punctures, and none were found. Based on this inspection there is no evidence that the spilled fluids left containment.

A Site Map can be found in Figure 4.

Site Assessment and Liner Inspection

On June 17, 2022, after sending the 48-hour notification via email, Pima Environmental conducted a liner inspection at this location. We concluded that this liner and containment maintained its integrity and was able to retain the fluids. The liner inspection form and photographic documentation can be found in Appendix C.

Closure Request

After careful review, Pima requests that this incident, NAPP2130051391 be closed. Devon has complied with the applicable closure requirements.

Should you have any questions or need additional information, please feel free to contact Tom Bynum at 575-964-7740 or tom@pimaoil.com.

Respectfully,

Tom Bynum

Tom Bynum Project Manager
Pima Environmental Services, LLC

Attachments

Figures:

- 1- Location Map
- 2- Topographic Map
- 3- Karst Map
- 4- Site Map

Appendices:

Appendix A- Referenced Water Surveys


Appendix B- C-141 Form & 48 Hour Notification


Appendix C- Liner Inspection Form & Photographic Documentation





Figures:

- 1 Location Map
- 2 Topographic Map
 - 3 Karst Map
 - 4 Site Map











Appendix A

Water Surveys:

OSE

USGS



New Mexico Office of the State Engineer

Water Column/Average Depth to Water

(A CLW##### in the POD suffix indicates the POD has been replaced & no longer serves a water right file.) (R=POD has been replaced, O=orphaned, C=the file is closed)

(quarters are 1=NW 2=NE 3=SW 4=SE)

(quarters are smallest to largest) (NAD83 UTM in meters)

(In feet)

		POD													
		Sub-		Q	Q	Q								,	Water
POD Number	Code	basin	County	64	16	4	Sec	Tws	Rng	X	Y	DistanceDep	othWellDep	thWater C	Column
<u>C 03582 POD1</u>		C	LE	4	1	1	14	23S	33E	636583	3575666	1650	590		
<u>C 02283</u>		CUB	LE	4	2	2	26	23S	33E	637896	3572431*	2447	325	225	100
<u>C 02282</u>		CUB	LE	3	1	1	25	23S	33E	638098	3572436*	2596	325	225	100
<u>C 02278</u>		CUB	LE	3	4	2	28	23S	33E	634484	3571989*	2648	650	400	250
<u>C 02280</u>		CUB	LE	3	2	4	28	23S	33E	634489	3571586*	2975	650	400	250
<u>C 02284</u>		CUB	LE	4	2	4	26	23S	33E	637907	3571626*	3057	325	225	100
<u>C 02281</u>		CUB	LE	3	4	4	28	23S	33E	634495	3571183*	3318	545	400	145
C 04353 POD1		CUB	ED	4	2	2	24	23S	33E	639474	3574098	3377	603	330	273
<u>C 02277</u>		CUB	LE	2	3	4	20	23S	33E	632663	3572970*	3611	550	400	150
<u>C 02279</u>		CUB	LE	3	4	3	28	23S	33E	633691	3571173*	3780	650	400	250
C 04595 POD1		CUB	LE	4	3	3	34	23S	33E	635150	3569564	4622	55		

Average Depth to Water:

333 feet

Minimum Depth:

225 feet

Maximum Depth: 400 feet

Record Count: 11

UTMNAD83 Radius Search (in meters):

Easting (X): 636096.72 **Northing (Y):** 3574089.51 **Radius:** 5000

*UTM location was derived from PLSS - see Help

The data is furnished by the NMOSE/ISC and is accepted by the recipient with the expressed understanding that the OSE/ISC make no warranties, expressed or implied, concerning the accuracy, completeness, reliability, usability, or suitability for any particular purpose of the data.

6/10/22 2:26 PM

WATER COLUMN/ AVERAGE DEPTH TO WATER



USGS Home Contact USGS Search USGS

National Water Information System: Web Interface

USGS Water Resources

Data Category:		Geographic Area:		
Groundwater	~	United States	~	GO

Click to hideNews Bulletins

- Explore the NEW <u>USGS National Water Dashboard</u> interactive map to access realtime water <u>data</u> from over 13,500 stations nationwide.
- Full News

Groundwater levels for the Nation

Important: <u>Next Generation Monitoring Location Page</u>

Search Results -- 1 sites found

site_no list =

321609103321701

Minimum number of levels = 1

Save file of selected sites to local disk for future upload

USGS 321609103321701 23S.33E.26.421342


Available data for this site Groundwater: Field measurements GO

Lea County, New Mexico
Hydrologic Unit Code 13070007
Latitude 32°16'09", Longitude 103°32'17" NAD27
Land-surface elevation 3,648 feet above NAVD88
The depth of the well is 173 feet below land surface.
This well is completed in the Other aquifers (N99990THER) national aquifer.
This well is completed in the Chinle Formation (231CHNL) local aquifer.

Output formats

Table of data	
Tab-separated data	
Graph of data	
Reselect period	

USGS 321609103321701 235.33E.26.421342



Breaks in the plot represent a gap of at least one year between field measurements. Download a presentation-quality graph

Questions about sites/data? Feedback on this web site Automated retrievals <u>Help</u> **Data Tips Explanation of terms** Subscribe for system changes **News**

Accessibility

FOIA

Privacy

Policies and Notices

U.S. Department of the Interior | U.S. Geological Survey

Title: Groundwater for USA: Water Levels

URL: https://nwis.waterdata.usgs.gov/nwis/gwlevels?

Page Contact Information: <u>USGS Water Data Support Team</u>

Page Last Modified: 2022-06-10 16:57:26 EDT

0.58 0.49 nadww02





Appendix B

C-141 Form

48-Hour Notification

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised August 24, 2018 Submit to appropriate OCD District office

Incident ID	
District RP	
Facility ID	
Application ID	

Release Notification

Responsible Party

Responsible Party				OGRID	OGRID		
Contact Name				Contact To	Contact Telephone		
Contact email				Incident #	Incident # (assigned by OCD)		
Contact mail	ing address						
			Location	of Release So	ource		
Latitude				Longitude			
			(NAD 83 in dec	cimal degrees to 5 decir	nal places)		
Site Name				Site Type			
Date Release	Discovered			API# (if app	olicable)		
Unit Letter	Section	Township	Range	Cour	nts.	1	
Omit Letter	Section	Township	Range	Cour	ity		
Surface Owner	r: State	☐ Federal ☐ Tr	ibal Private (A	Name:)	
			Natura and	d Volume of 1	Ralaasa		
Crude Oil		(s) Released (Select al Volume Release		calculations or specific	Volume Reco	volumes provided below) vered (bbls)	
Produced		Volume Release	` '		Volume Recovered (bbls)		
Troduced			ion of total dissol	ved solids (TDS)	Yes No		
		in the produced	water >10,000 mg				
Condensa	te	Volume Release	d (bbls)		Volume Reco	vered (bbls)	
Natural G	as	Volume Release	d (Mcf)		Volume Recovered (Mcf)		
Other (des	scribe)	Volume/Weight	Released (provide	e units)	Volume/Weight Recovered (provide units)		
Cause of Rele	ease						

Received by OCD: 8/26/202211:35:58 PM1 State of New Mexico
Page 2 Oil Conservation Division

Pag	e d	4	24
			İ

Incident ID	
District RP	
Facility ID	
Application ID	

Was this a major	If YES, for what reason(s) does the respon	nsible party consider this a major release?
release as defined by 19.15.29.7(A) NMAC?		
☐ Yes ☐ No		
If YES, was immediate no	otice given to the OCD? By whom? To wh	nom? When and by what means (phone, email, etc)?
	Initial R	esponse
The responsible p	party must undertake the following actions immediate	y unless they could create a safety hazard that would result in injury
☐ The source of the rele	ease has been stopped.	
☐ The impacted area ha	s been secured to protect human health and	the environment.
Released materials ha	ave been contained via the use of berms or o	likes, absorbent pads, or other containment devices.
☐ All free liquids and re	ecoverable materials have been removed an	d managed appropriately.
If all the actions described	d above have <u>not</u> been undertaken, explain	why:
has begun, please attach	a narrative of actions to date. If remedial	emediation immediately after discovery of a release. If remediation efforts have been successfully completed or if the release occurred blease attach all information needed for closure evaluation.
		best of my knowledge and understand that pursuant to OCD rules and
		fications and perform corrective actions for releases which may endanger OCD does not relieve the operator of liability should their operations have
failed to adequately investig	ate and remediate contamination that pose a thre	at to groundwater, surface water, human health or the environment. In
addition, OCD acceptance of and/or regulations.	f a C-141 report does not relieve the operator of	responsibility for compliance with any other federal, state, or local laws
_		mul.
Printed Name:	0 //	Title:
Signature: Nendra	De Hoyos	Date:
		Telephone:
OCD Only		
Received by: Ramona M	arcus	Date: 11/1/2021

NAPP2130051391

Spills In Lined Co	ontainment
Measurements Of S	tanding Fluid
Length(Ft)	71
Width(Ft)	71
Depth(in.)	0.25
Total Capacity without tank displacements (bbls)	18.70
No. of 500 bbl Tanks In Standing Fluid No. of Other Tanks In	10
OD Of Other Tanks In Standing Fluid(feet)	
Total Volume of standing fluid accounting for tank displacement.	11.71

	Page 16 of	24
+ ID	NADD2130051301	1

Incident ID	NAPP2130051391
District RP	
Facility ID	
Application ID	

Site Assessment/Characterization

This information must be provided to the appropriate district office no later than 90 days after the release discovery date.

What is the shallowest depth to groundwater beneath the area affected by the release?	146 (ft bgs)					
Did this release impact groundwater or surface water?						
Are the lateral extents of the release within 300 feet of a continuously flowing watercourse or any other significant watercourse?						
Are the lateral extents of the release within 200 feet of any lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark)?						
Are the lateral extents of the release within 300 feet of an occupied permanent residence, school, hospital, institution, or church?	☐ Yes 🏻 No					
Are the lateral extents of the release within 500 horizontal feet of a spring or a private domestic fresh water well used by less than five households for domestic or stock watering purposes?	☐ Yes 🏻 No					
Are the lateral extents of the release within 1000 feet of any other fresh water well or spring?	☐ Yes ☒ No					
Are the lateral extents of the release within incorporated municipal boundaries or within a defined municipal fresh water well field?	☐ Yes ☒ No					
Are the lateral extents of the release within 300 feet of a wetland?	☐ Yes 🛛 No					
Are the lateral extents of the release overlying a subsurface mine?	☐ Yes ☒ No					
Are the lateral extents of the release overlying an unstable area such as karst geology?						
Are the lateral extents of the release within a 100-year floodplain?	☐ Yes ☒ No					
Did the release impact areas not on an exploration, development, production, or storage site?						
Attach a comprehensive report (electronic submittals in .pdf format are preferred) demonstrating the lateral and vertical extents of soil contamination associated with the release have been determined. Refer to 19.15.29.11 NMAC for specifics.						
Characterization Report Checklist: Each of the following items must be included in the report.						
Scaled site map showing impacted area, surface features, subsurface features, delineation points, and monitoring well Field data Data table of soil contaminant concentration data Depth to water determination Determination of water sources and significant watercourses within ½-mile of the lateral extents of the release Boring or excavation logs Photographs including date and GIS information Topographic/Aerial maps Laboratory data including chain of custody	s.					

If the site characterization report does not include completed efforts at remediation of the release, the report must include a proposed remediation plan. That plan must include the estimated volume of material to be remediated, the proposed remediation technique, proposed sampling plan and methods, anticipated timelines for beginning and completing the remediation. The closure criteria for a release are contained in Table 1 of 19.15.29.12 NMAC, however, use of the table is modified by site- and release-specific parameters.

Received by OCD: 8/26/2022 1:35:58 PM Form C-141 State of New Mexico Page 4 Oil Conservation Division

	rage 17 of 2
Incident ID	NAPP2130051391
District RP	
Facility ID	
Application ID	

I hereby certify that the information given above is true and complete to the regulations all operators are required to report and/or file certain release not public health or the environment. The acceptance of a C-141 report by the failed to adequately investigate and remediate contamination that pose a thr addition, OCD acceptance of a C-141 report does not relieve the operator of and/or regulations.	ifications and perform corrective actions for releases which may endanger OCD does not relieve the operator of liability should their operations have eat to groundwater, surface water, human health or the environment. In
Printed Name: Wes Mathews	Title: EHS Professional
Signature: Wesley Mathews	Date: 6/24/2022
email: wesley.mathews@dvn.com	Telephone: <u>575-513-8608</u>
OCD Only	
Received by: Jocelyn Harimon	Date:08/26/2022

Page 18 of 24

Incident ID	NAPP2130051391
District RP	
Facility ID	
Application ID	

Closure

The responsible party must attach information demonstrating they have complied with all applicable closure requirements and any conditions or directives of the OCD. This demonstration should be in the form of a comprehensive report (electronic submittals in .pdf format are preferred) including a scaled site map, sampling diagrams, relevant field notes, photographs of any excavation prior to backfilling, laboratory data including chain of custody documents of final sampling, and a narrative of the remedial activities. Refer to 19.15.29.12 NMAC.

Closure Report Attachment Checklist: Each of the following	items must be included in the closure report.		
A scaled site and sampling diagram as described in 19.15.29.	11 NMAC		
Note: appropriate OCD District office must be notified 2 days prior to liner inspection)			
Laboratory analyses of final sampling (Note: appropriate OD	C District office must be notified 2 days prior to final sampling)		
Description of remediation activities			
and regulations all operators are required to report and/or file certa may endanger public health or the environment. The acceptance of should their operations have failed to adequately investigate and rehuman health or the environment. In addition, OCD acceptance of compliance with any other federal, state, or local laws and/or regularestore, reclaim, and re-vegetate the impacted surface area to the coaccordance with 19.15.29.13 NMAC including notification with 19.15.29.	ations. The responsible party acknowledges they must substantially onditions that existed prior to the release or their final land use in OCD when reclamation and re-vegetation are complete.		
	_{Title:} EHS Professional		
Signature: Wesley Mathews	Date: 6/24/2022		
email: wesley.mathews@dvn.com	Telephone: 575-513-8608		
OCD Only			
Received by: _Jocelyn Harimon	Date:08/26/2022		
	of liability should their operations have failed to adequately investigate and water, human health, or the environment nor does not relieve the responsible /or regulations.		
Closure Approved by:	Date: 09/01/2022		
Printed Name: Jennifer Nobui	Title:Environmental Specialist A		



Gio PimaOil <gio@pimaoil.com>

Thistle 22 CTB 2 Notice of Inspection

1 message

Gio PimaOil <gio@pimaoil.com>

Wed, Jun 15, 2022 at 9:03 AM

To: ocdonline@state.nm.us, Tom Pima Oil <tom@pimaoil.com>

Good Morning,

Pima Environmental would like to notify you that we will be conducting a liner Inspection at the Thistle Unit 22 CTB 2 for incident NAPP2130051391. Pima personnel are scheduled to be on site for this Inspection event at approximately 9:00 a.m. On Friday, June 17, 2022. If you have any questions or concerns, please let me know. Thank you.

Gio Gomez Environmental Project Manager cell-806-782-1151 Office- 575-964-7740 Pima Environmental Services, LLC.



Appendix C

Liner Inspection Form

Photographic Documentation



Liner Inspection Form

Company Name:	Devon E	Energy			
Site:Thist	tle Unit	22 CT	<u>B</u>		
Lat/Long: <u>32.29</u>	95341,	-103.5	54565		
NMOCD Incident ID & Incident Date:	NA	.PP213	0051391	10/18/2021	
2-Day Notification Sent: =	_via E	mail by	y Gio Gomez	6/15/2022	
Inspection Date:	6/17	/2022_			
Liner Type: E	Earthen	w/line	r	Earthen no liner	Polystar
S	steel w/	poly li	ner	Steel w/spray epoxy	No Liner
Other: _					
Visualization	Yes	No		Comments	
Is there a tear in the liner?		X			
Are there holes in the liner?		X			
Is the liner retaining any fluids?	X		Rainwater		
Does the liner have integrity to contain a leak?	X				
Comments:					
Inspector Name: <u>Ned</u>	l Roger	<u>s</u>	Insp	ector Signature: _ <i>Nat Ra</i>	ogers











District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone: (575) 748-1283 Fax: (575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 138554

CONDITIONS

Operator:	OGRID:
DEVON ENERGY PRODUCTION COMPANY, LP	6137
333 West Sheridan Ave.	Action Number:
Oklahoma City, OK 73102	138554
	Action Type:
	[C-141] Release Corrective Action (C-141)

CONDITIONS

Created By	Condition	Condition Date
jnobui	Closure Approved.	9/1/2022