2135 S. Loop 250 W. Midland, Texas 79703 United States ghd.com

Our ref.: 12670290-NMOCD-1

September 29, 2025

New Mexico Oil Conservation Division 506 W. Texas Avenue Artesia, New Mexico 88210

Closure Report
Devon Energy Production Company, LP
Jayhawk 6 CTB 2
Unit Letter C, Section 06, T26S, R34E
GPS: 32.07629704, -103.51193
Lea County, New Mexico

1. Introduction

GHD Services Inc. (GHD), on behalf of Devon Energy Production Company, LP (Devon Energy), has prepared this *Closure Report* to document site assessment activities at Jayhawk 6 CTB 2 (Site). The purpose of the assessment was to determine the presence or absence of impacts to soil following a release of produced water within a lined containment at the Site. Based on field observations, Devon Energy is submitting this *Closure Report*, describing Site assessment activities that have occurred and requesting closure for Incident Number nAPP2512561032.


2. Site Description and Release Summary

The Site is located in Unit C, Section 06, Township 26 South, Range 34 East, in Lea County, New Mexico (32.07629704° N, 103.51193° W) and is associated with oil and gas exploration and production operations on Federal Land managed by the Bureau of Land Management (BLM).

On May 5, 2025, approximately 25 barrels (bbls) of produced water was released into the lined secondary containment due to the failure of an air eliminator on a booster pump. A vacuum truck was dispatched to the Site to recover free-standing fluids; all 25 bbls of released produced water were recovered from within the lined containment. The release was reported to the New Mexico Oil Conservation Division (NMOCD) on May 8, 2025, and was subsequently assigned Incident Number nAPP2512561032.

3. Site Characterization and Closure Criteria

The Site was characterized to assess applicability of Table I, Closure Criteria for Soils Impacted by a Release, of Title 19, Chapter 15, Part 29 (NMAC 19.15.29) of the New Mexico Administrative Code (NMAC). Results from the characterization desktop review are summarized below and a Site Map is presented on **Figure 1**.



According to the soil survey provided by the United States Department of Agriculture National Resources Conservation Services, the soils located within the Site consists of Pyote and Maljamar fine sands. Per the New Mexico Bureau of Geology and Mineral Resources, the shallow geology consists of interlayered eolian sands and piedmont slope deposits, Holocene to middle Pleistocene in age. The Site is located within an area of low karst potential.

Depth to groundwater at the Site is estimated to be greater than 100 feet below ground surface (ft bgs) based on the nearest groundwater well data. Groundwater was determined utilizing the New Mexico Office of the State Engineers (NMOSE) database for registered water wells. The nearest permitted groundwater well with depth to groundwater data is NMOSE Well Pod C-03441 located approximately 0.34 miles northeast of the Site. The well was drilled on May 3, 2010 and completed to a depth of 250 ft bgs. The water bearing strata is identified from 128-189 ft bgs in a sandy red clay. A copy of the referenced well record is included in **Attachment A**.

The Site is greater than 200 feet from a lakebed, sinkhole, or playa lake and greater than 300 feet from an occupied residence, school, hospital, institution, church, or wetland. The Site is greater than 1,000 feet to a freshwater well or spring and is not within a 100-year floodplain or overlying a subsurface mine. The nearest fresh water well for livestock watering purposes is located approximately 0.35 miles northeast of the Site. The Site is not underlain by unstable geology (low potential karst designation area). The location of the Site is depicted on **Figure 1**. A detailed map of the Site is provided on **Figure 2**. The Site Characterization Documentation is included in **Attachment B**.

Based on the results of the Site Characterization desktop review and having confirmed depth to groundwater within 0.5 miles of the Site, the following NMOCD Table I Closure Criteria (Closure Criteria) apply.

Table 3.1 Closure Criteria for Soils Impacted by a Release (NMAC 19.15.29.12)

Regulatory Standard	Benzene (mg/kg)	BTEX (mg/kg)	TPH (GRO+DRO) (mg/kg)	TPH (GRO+DRO+MRO) (mg/kg)	Chloride (mg/kg)
19.15.29.12 NMAC Table I Closure Criteria for Soils Impacted by a Release.	10	50		2,500	20,000

Notes:

--- = not defined.

mg/kg = milligrams per kilogram.

TPH = total petroleum hydrocarbons.

GRO+DRO+MRO = Gasoline Range Organics + Diesel Range Organics + Motor Oil/Lube Range Organics.

BTEX = benzene, toluene, ethylbenzene, and xylene.

4. Site Assessment Activities

The liner inspection notice was provided on August 21, 2025. A liner integrity inspection was performed on August 27, 2025. The liner was visually inspected and no rips, tears, holes, or damages in the liner were observed. The liner was determined to be intact with no integrity issues. Photographic documentation of the liner inspection is presented in **Attachment C**.

5. Closure Request

Based on the liner inspection and assessment activities at the Site, Devon Energy respectfully requests that no further actions be required and requests the closure of Incident Number nAPP2512561032 be granted.

Should you have any questions or require further information regarding this report, please do not hesitate to contact the undersigned.

Regards,

Kayla Taylor

Senior Project Manager

+1 432 210-5443

kayla.taylor@ghd.com

Jessica Wright

Project Director

+1 713 337-5419

jessica.wright@ghd.com

KT/jlf/1

Encl.:


Figure 1 - Site Location Map


Figure 2 - Site Details Map

Attachment A - Referenced Well Records

Attachment B - Site Characterization Documentation

Attachment C - Photographic Documentation







DEVON ENERGY PRODUCTION COMPANY, LP LEA COUNTY, NEW MEXICO JAYHAWK 6 CTB 2 INCIDENT No. naPP2512561032


SITE LOCATION MAP

Date September 2025

FIGURE 1

Received by OCD: 10/13/2025 12:51:22 PM







DEVON ENERGY PRODUCTION COMPANY, LP LEA COUNTY, NEW MEXICO JAYHAWK 6 CTB 2 INCIDENT No. naPP2512561032

SITE DETAILS MAP

Project No. 12670290
Date September 2025

FIGURE 2

Attachment A


Referenced Well Records

Ros II.	
TOO ME NOW THE OWNER OF	
17 15/20	

	<u></u>					·		 -		3		
ON	POD NUMB	ER (WE	LL NU	(MBER)	3 4 41-P	001		OSE FILE NUN C 03441	IBER(S)	11.	2000	·•••
ОСАТІ	well own Dinwiddi				7		<u></u>	PHONE (OPTIO	ONAL)		,	
GENERAL AND WELL LOCATION	WELL OWN PO Box		LING	ADDRESS	······································			спу Capitan		STATE NM	88	ZIP 316
N QN	WELL				DEGREES	MINUTES SE	CONDS	40,224				
LA	LOCATIO	ı	LAT	ITUDE	N32	04	-41.0 N	1	REQUIRED: ONE TEN	•	_	
ERA	(FROM G	PS)	LON	GITUDE	W103	30	-80.9 W	* DATUM REC	QUIRED: WGS 84	OSE G	43)	
1. GEN	DESCRIPTI	ION REL	ATIN	G WELL LOCATION	TO STREET ADDRE	SS AND COMMON LAN	IDMARKS	- 22.867				
	(2.5 ACR	(E)		(10 ACRE)	(40 ACRE)	(160 ACRE)	SECTION		TOWNSHIP		RANGE	
١٢	NW >	4	5	En	NW 4	NE %		6	26	NORTH SOUTH	34	Ø EAST ☐ WEST
OPTIONAL	SUBDIVISI	ON NAM	1E	- \- 	7.7.4		LOT NUM	IBER	BLOCK NUMBER		UNIT/TRA	
	HYDROGR.	APHICS	IIRVE	···					MAP NUMBER	 -	TRACT NU	MRER
4	n rokook	Arme s	OKT						MAI NOMBER		TRACTNO	MBEK
	LICENSE N	имвек 1044		NAME OF LICENS Alan Eades	SED DRILLER				NAME OF WELL DI Eades Drilling			
z.	DRILLING STARTED DRILLING ENDED DEPTH OF COMPLETED WELL (FT) BORE I 05-03-10 250							LE DEPTH (FT) 250				
BRILLING INFORMATION	COMPLETED WELL IS: ARTESIAN DRY HOLE SHALLOW (UNCONFINED)						STATIC WATER LEVEL IN COMPLETED WELL (FT)			L (FT)		
FOR	DRILLING	ғылр:		AIR	✓ MUD	ADDITIVES -	SPECIFY:					
NI 5	DRILLING		D;	✓ ROTARY	HAMMER	CABLE TOOL	ОТН	ER - SPECIFY:				
	DEPT	H (FT)		BORE HOLE				NECTION	INSIDE DIA.	CASING	3 WALL	SLOT
DR.	FROM	TC)	DIA. (IN)	<u> </u>		TYPE	(CASING)	CASING (IN)		IESS (IN)	SIZE (IN)
m	0	20		11	 	PVC		ip joint	6.166		55	
	20 190	19 25		9.75 9.75	BV	PVC C - screen		ip joint ip joint	6.166 6.166		55 55	.035
	190	20		9.75	- FV	C - SCIEGII	311	p Jone	0.100	·	.55	.033
	L	H (FT)	-	m1 11 CH 2 17 20 0		ORMATION DESCR	PIPTION OF S	DEINCIDAL W	ATED DEADING	TDATA		MELD
⊴	FROM	T(F1)		THICKNESS (FT)	ľ	•	•		R FRACTURE ZOI			YIELD (GPM)
STRATA	128	18		· 61			sand	ly red clay				
CS												
R. N.												
HE H	ļ	ļ								- ·		
E		<u> </u>		<u> </u>								
4. WATER BEARING	METHOD	USED TO) ESTI	MATE YIELD OF W	ATER-BEARING STR	ATA			TOTAL ESTIMATE	D WELL YIEI	.D (GPM)	
				<u> </u>			<u></u>					
	FOR OSE INTERNAL USE FILE NUMBER C-3941 POD NUMBER POD_1 TRN NUMBER PAGE 1 OF 2						/9/08)					
	LOCATI	ON) [24 6 21	41122	TODION			1101 HOIVIB		PAGE I	OF 2

			☑ SUBMER	RSIBLE	☐ JET	☐ NO PUMP – WELL NOT EQUIPPED				
₽	TYPE O	FPUMP:	TURBIN		CYLINDER	. OTHER-SPECIFY:				
D P U		=======	DEPTH	I (FT)	BORE HOLE	AAATERIAL TYPE AND CITE	AMOUNT	МЕТН	OD OF	
NA.	ANNULAR SEAL AND GRAVEL PACK		FROM	то	DIA. (IN)	MATERIAL TYPE AND SIZE	(CUBIC FT)		MENT	
EAL			0	20	11	bentonite chips - hydrated	9	gravi	ty fed	
S.S	ORAVE	LFACK	20	250	9.75	gravel	84	gravi	ty fed	
			<u> </u>	<u>L</u>	<u> </u>		<u>l</u>	<u> </u>		
	DEPTI	H (FT)	тніск	NESS		COLOR AND TYPE OF MATERIAL ENCOUNT	ERED	WA	TER	
	FROM	то	(F	r) 	(INCLI	JDE WATER-BEARING CAVITIES OR FRACT	URE ZONES)	BEAF	BEARING?	
".	0	1	1			top soil		☐ YES	□ NO	
	1	25	24			sandy clay		☐ YES	□ио	
	25	37	12			caliche & sand		☐ YES	□ NO	
	37	85	48	В		sand & sandstone stringers		☐ YES	□ NO	
3	85	108	23	3	<u> </u>	red sandstone with red clay strea	ks	☐ YES	□ио	
6. GEOLOGIC LOG OF WELL	108	128	20	0		sandstone with yellow clay streat	(S	☐ YES	□ NO	
OF	128	189	6	1		sandy red clay		☐ YES	□ NO	
9	189	249	6	0		white sandstone with red clay stream	aks	☐ YES	□ NO	
Sic	249	250	1			red clay		☐ YES	□ NO	
0								☐ YES	□ NO	
1 23								YES	□ NO	
قت								☐ YES	□ NO	
								☐ YES	□ NO	
					<u></u>			☐ YES	□ NO	
1					<u> </u>			☐ YES	□ NO	
					<u></u>			☐ YES	□ NO	
								☐ YES	Ои	
l	ATTACH ADDITIONAL PAGES AS NEEDED TO FULLY DESCRIBE THE GEOLOGIC LOG OF THE WELL									
	METHOD: DAILER DUMP AIR LIFT OTHER - SPECIFY:									
INFO	WELL	. TEST	TEST RESU	JLTS - ATTA	ACH A COPY OF I	DATA COLLECTED DURING WELL TESTING,	INCLUDING START	TIME, END T	IME,	
Į į			AND A TAI	BLE SHOWI	NG DISCHARGE	AND DRAWDOWN OVER THE TESTING PER	IOD.	RS .		
& ADDITTONAL	ADDITIO	NAL STATE	MENTS OR EXPL	.2NOITANA				SEE -		
							MAY	T2		
¥								. <u> </u>		
7. TEST							æΠ uE			
7. T	}							χ. πΩ		
-						COT OF THE OR LESS KNOWN FROM AND REL	SE THE PODECONIO	< 1 1000 mu = 1		
35	CORRE	CT RECOI	RD OF THE AL	BOVE DESC	RIBED HOLE AN	EST OF HIS OR HER KNOWLEDGE AND BELI D THAT HE OR SHE WILL FILE THIS WELL F	ECORD WITH THE ST	ATE ENGIN	EER AND	
ATL	THE PE	RMIT HOI	DER WITHIN	120 DAYS A	AFTER COMPLETI 1	ON OF WELL DRILLING:		-:		
SIGNATURE		/x	Lan)	Yad	16 DX	May 14, 2010				
oci										
										

FOR OSE INTERNAL USE	FOR OSE INTERNAL USE					
FILE NUMBER C-3341	POD NUMBER POD.	TRN NUMBER				
LOCATION 26.34.6.24.32			PAGE 2 OF 2			
Released to Imaging: 10/17/2025 3:25:33 PM						



Locator Tool Report

General Information:

Application ID:29

Date: 02-01-2011

Time: 11:32:20

WR File Number: C-03441-STK

Purpose: POINT OF DIVERSION

Applicant First Name: DINWIDDIE CATTLE CO

Applicant Last Name: NEW STOCK WELL (OSE FIELD GPS)

GW Basin: CARLSBAD

County: LEA

Critical Management Area Name(s): NONE Special Condition Area Name(s): NONE

Land Grant Name: NON GRANT

PLSS Description (New Mexico Principal Meridian):

NW 1/4 of SE 1/4 of NW 1/4 of NE 1/4 of Section 06, Township 26S, Range 34E.

Coordinate System Details:

Geographic Coordinates:

Latitude:

32 Degrees 4 Minutes 40.2 Seconds N

Longitude:

103 Degrees 30 Minutes 22.9 Seconds W

Universal Transverse Mercator Zone: 13N

 NAD 1983(92) (Meters)
 N: 3,550,040
 E: 640,971

 NAD 1983(92) (Survey Feet)
 N: 11,647,089
 E: 2,102,918

 NAD 1927 (Meters)
 N: 3,549,839
 E: 641,018

 NAD 1927 (Survey Feet)
 N: 11,646,429
 E: 2,103,073

State Plane Coordinate System Zone: New Mexico East

 NAD 1983(92) (Meters)
 N: 119,798
 E: 243,072


 NAD 1983(92) (Survey Feet)
 N: 393,037
 E: 797,479

 NAD 1927 (Meters)
 N: 119,780
 E: 230,518

 NAD 1927 (Survey Feet)
 N: 392,980
 E: 756,292

NEW MEXICO OFFICE OF STATE ENGINEER

Locator Tool Report





WR File Number: C-03441-STK Scale: 1:77,058

Northing/Easting: UTM83(92) (Meter): N: 3,550,040 E: 640,971

Northing/Easting: SPCS83(92) (Feet): N: 393,037 E: 797,479

GW Basin: Carlsbad

Page 2 of 2 Print Date: 02/01/2011

Attachment B

Site Characterization Documentation



Soil Map—Lea County, New Mexico (Jayhawk 6 CTB 2)

MAP LEGEND

â

0

Δ

Water Features

Transportation

Background

Spoil Area

Stony Spot

Wet Spot

Other

Rails

US Routes

Major Roads

Local Roads

Very Stony Spot

Special Line Features

Streams and Canals

Interstate Highways

Aerial Photography

Area of Interest (AOI)

Area of Interest (AOI)

Soils

Soil Map Unit Polygons



Soil Map Unit Points

Special Point Features

Blowout

Borrow Pit

Clay Spot

Closed Depression

Gravel Pit

Gravelly Spot

Candfill

Lava Flow

Marsh or swamp

Mine or Quarry

Miscellaneous Water

Perennial Water

Saline Spot

Sandy Spot

Severely Eroded Spot

Sinkhole

Slide or Slip

Sodic Spot

MAP INFORMATION

The soil surveys that comprise your AOI were mapped at 1:20.000.

Warning: Soil Map may not be valid at this scale.

Enlargement of maps beyond the scale of mapping can cause misunderstanding of the detail of mapping and accuracy of soil line placement. The maps do not show the small areas of contrasting soils that could have been shown at a more detailed scale

Please rely on the bar scale on each map sheet for map measurements.

Source of Map: Natural Resources Conservation Service Web Soil Survey URL:

Coordinate System: Web Mercator (EPSG:3857)

Maps from the Web Soil Survey are based on the Web Mercator projection, which preserves direction and shape but distorts distance and area. A projection that preserves area, such as the Albers equal-area conic projection, should be used if more accurate calculations of distance or area are required.

This product is generated from the USDA-NRCS certified data as of the version date(s) listed below.

Soil Survey Area: Lea County, New Mexico Survey Area Data: Version 21, Sep 3, 2024

Soil map units are labeled (as space allows) for map scales 1:50,000 or larger.

Date(s) aerial images were photographed: Feb 7, 2020—May 12, 2020

The orthophoto or other base map on which the soil lines were compiled and digitized probably differs from the background imagery displayed on these maps. As a result, some minor shifting of map unit boundaries may be evident.

Jayhawk 6 CTB 2

Map Unit Legend

Map Unit Symbol	Map Unit Name	Acres in AOI	Percent of AOI
PU	Pyote and Maljamar fine sands	5.9	100.0%
Totals for Area of Interest		5.9	100.0%

Lea County, New Mexico

PU—Pyote and Maljamar fine sands

Map Unit Setting

National map unit symbol: dmqq Elevation: 3,000 to 3,900 feet

Mean annual precipitation: 10 to 12 inches Mean annual air temperature: 60 to 62 degrees F

Frost-free period: 190 to 205 days

Farmland classification: Not prime farmland

Map Unit Composition

Pyote and similar soils: 46 percent Maljamar and similar soils: 44 percent

Minor components: 10 percent

Estimates are based on observations, descriptions, and transects of

the mapunit.

Description of Pyote

Setting

Landform: Plains

Landform position (three-dimensional): Rise

Down-slope shape: Linear Across-slope shape: Linear

Parent material: Sandy eolian deposits derived from sedimentary

rock

Typical profile

A - 0 to 30 inches: fine sand

Bt - 30 to 60 inches: fine sandy loam

Properties and qualities

Slope: 0 to 3 percent

Depth to restrictive feature: More than 80 inches

Drainage class: Well drained Runoff class: Negligible

Capacity of the most limiting layer to transmit water (Ksat): High

(2.00 to 6.00 in/hr)

Depth to water table: More than 80 inches

Frequency of flooding: None Frequency of ponding: None

Calcium carbonate, maximum content: 5 percent

Gypsum, maximum content: 1 percent

Maximum salinity: Nonsaline to very slightly saline (0.0 to 2.0


mmhos/cm)

Sodium adsorption ratio, maximum: 2.0

Available water supply, 0 to 60 inches: Low (about 5.1 inches)

Interpretive groups

Land capability classification (irrigated): 6e



Land capability classification (nonirrigated): 7s

Hydrologic Soil Group: A

Ecological site: R070BD003NM - Loamy Sand

Hydric soil rating: No

Description of Maljamar

Setting

Landform: Plains

Landform position (three-dimensional): Rise

Down-slope shape: Linear Across-slope shape: Linear

Parent material: Sandy eolian deposits derived from sedimentary

rock

Typical profile

A - 0 to 24 inches: fine sand

Bt - 24 to 50 inches: sandy clay loam
Bkm - 50 to 60 inches: cemented material

Properties and qualities

Slope: 0 to 3 percent

Depth to restrictive feature: 40 to 60 inches to petrocalcic

Drainage class: Well drained Runoff class: Very low

Capacity of the most limiting layer to transmit water (Ksat): Very low

to moderately low (0.00 to 0.06 in/hr) Depth to water table: More than 80 inches

Frequency of flooding: None Frequency of ponding: None

Calcium carbonate, maximum content: 5 percent

Gypsum, maximum content: 1 percent

Maximum salinity: Nonsaline to very slightly saline (0.0 to 2.0

mmhos/cm)

Sodium adsorption ratio, maximum: 2.0

Available water supply, 0 to 60 inches: Low (about 5.6 inches)

Interpretive groups

Land capability classification (irrigated): 6e Land capability classification (nonirrigated): 7e

Hydrologic Soil Group: B

Ecological site: R070BD003NM - Loamy Sand


Hydric soil rating: No

Minor Components

Kermit

Percent of map unit: 10 percent

Ecological site: R070BC022NM - Sandhills



Map Unit Description: Pyote and Maljamar fine sands---Lea County, New Mexico

Jayhawk 6 CTB 2

Hydric soil rating: No

Data Source Information

Soil Survey Area: Lea County, New Mexico Survey Area Data: Version 21, Sep 3, 2024


Karst Potential Map



10/3/2025, 9:15:18 AM

Karst Occurrence Potential Lov

Medium





Jayhawk 6 CTB 2



August 28, 2025

Wetlands

Estuarine and Marine Deepwater

Estuarine and Marine Wetland

Freshwater Emergent Wetland

Freshwater Pond

Freshwater Forested/Shrub Wetland

Lake

Other

Riverine

This map is for general reference only. The US Fish and Wildlife Service is not responsible for the accuracy or currentness of the base data shown on this map. All wetlands related data should be used in accordance with the layer metadata found on the Wetlands Mapper web site.

National Flood Hazard Layer FIRMette





SEE FIS REPORT FOR DETAILED LEGEND AND INDEX MAP FOR FIRM PANEL LAYOUT Without Base Flood Elevation (BFE) With BFE or Depth Zone AE, AO, AH, VE, AR SPECIAL FLOOD HAZARD AREAS Regulatory Floodway 0.2% Annual Chance Flood Hazard, Areas of 1% annual chance flood with average depth less than one foot or with drainage areas of less than one square mile Zone X **Future Conditions 1% Annual** Chance Flood Hazard Zone X Area with Reduced Flood Risk due to Levee. See Notes. Zone X OTHER AREAS OF Area with Flood Risk due to Levee Zone D FLOOD HAZARD NO SCREEN Area of Minimal Flood Hazard Zone X Effective LOMRs OTHER AREAS Area of Undetermined Flood Hazard Zone D - - - Channel, Culvert, or Storm Sewer **GENERAL** STRUCTURES | LILLIL Levee, Dike, or Floodwall 20.2 Cross Sections with 1% Annual Chance 17.5 Water Surface Elevation **Coastal Transect** ---- 513---- Base Flood Elevation Line (BFE) Limit of Study Jurisdiction Boundary — --- Coastal Transect Baseline OTHER **Profile Baseline FEATURES** Hydrographic Feature Digital Data Available No Digital Data Available MAP PANELS Unmapped The pin displayed on the map is an approximate point selected by the user and does not represent an authoritative property location.

This map complies with FEMA's standards for the use of digital flood maps if it is not void as described below. The basemap shown complies with FEMA's basemap accuracy standards

The flood hazard information is derived directly from the authoritative NFHL web services provided by FEMA. This map was exported on 8/28/2025 at 2:44 PM and does not reflect changes or amendments subsequent to this date and time. The NFHL and effective information may change or become superseded by new data over time.

This map image is void if the one or more of the following map elements do not appear: basemap imagery, flood zone labels, legend, scale bar, map creation date, community identifiers, FIRM panel number, and FIRM effective date. Map images for unmapped and unmodernized areas cannot be used for regulatory purposes.



2,000

Attachment C

Photographic Documentation

Devon Energy Production Company, LP Jayhawk 6 CTB 2 Incident No. nAPP2512561032 Lea County, New Mexico





Photo 1 Image of Site signage.



Photo 2 View of western portion of secondary containment facing north.




Photo 3 View of southern portion of secondary containment facing southeast.



Photo 4 View of northeast corner of secondary containment.

Devon Energy Production Company, LP Jayhawk 6 CTB 2 Incident No. nAPP2512561032 Lea County, New Mexico






Photo 5 View of eastern portion of secondary containment towards south.




Photo 6 View of southern portion of secondary containment facing west.




Photo 7 View towards central portion of secondary containment.




Photo 8 View of eastern portion of secondary containment facing north.

Devon Energy Production Company, LP Jayhawk 6 CTB 2 Incident No. nAPP2512561032 Lea County, New Mexico










Photo 10 View of central portion of secondary containment facing east.

Sante Fe Main Office Phone: (505) 476-3441 General Information

Phone: (505) 629-6116
Online Phone Directory
https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

QUESTIONS

Action 514497

QUESTIONS

Operator:	OGRID:
DEVON ENERGY PRODUCTION COMPANY, LP	6137
333 West Sheridan Ave.	Action Number:
Oklahoma City, OK 73102	514497
	Action Type:
	[C-141] Remediation Closure Request C-141 (C-141-v-Closure)

QUESTIONS

Prerequisites				
Incident ID (n#)	nAPP2512561032			
Incident Name	NAPP2512561032 JAYHAWK 6 CTB 2 @ FAPP2130256531			
Incident Type	Produced Water Release			
Incident Status	Remediation Closure Report Received			
Incident Facility	[fAPP2130256531] JAYHAWK 6 CTB 2			

Location of Release Source				
Please answer all the questions in this group.				
Site Name	JAYHAWK 6 CTB 2			
Date Release Discovered	05/05/2025			
Surface Owner	Federal			

Incident Details				
Please answer all the questions in this group.				
Incident Type	Produced Water Release			
Did this release result in a fire or is the result of a fire	No			
Did this release result in any injuries	No			
Has this release reached or does it have a reasonable probability of reaching a watercourse	No			
Has this release endangered or does it have a reasonable probability of endangering public health	No			
Has this release substantially damaged or will it substantially damage property or the environment	No			
Is this release of a volume that is or may with reasonable probability be detrimental to fresh water	No			

Nature and Volume of Release					
Material(s) released, please answer all that apply below. Any calculations or specific justifications for the volumes provided should be attached to the follow-up C-141 submission.					
Crude Oil Released (bbls) Details	Not answered.				
Produced Water Released (bbls) Details	Cause: Equipment Failure Pump Produced Water Released: 25 BBL Recovered: 25 BBL Lost: 0 BBL.				
Is the concentration of chloride in the produced water >10,000 mg/l	Yes				
Condensate Released (bbls) Details	Not answered.				
Natural Gas Vented (Mcf) Details	Not answered.				
Natural Gas Flared (Mcf) Details	Not answered.				
Other Released Details	Not answered.				
Are there additional details for the questions above (i.e. any answer containing Other, Specify, Unknown, and/or Fire, or any negative lost amounts)	Air eliminator on booster pump failed. Allowing release of produced water to lined secondary containment. Fluids fully recovered.				

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

QUESTIONS, Page 2

Action 514497

QUESTI	ONS (continued)		
Operator: DEVON ENERGY PRODUCTION COMPANY, LP 333 West Sheridan Ave. Oklahoma City, OK 73102	OGRID: 6137 Action Number: 514497		
Gitanolia Giy, Git 10102	Action Type: [C-141] Remediation Closure Request C-141 (C-141-v-Closure)		
QUESTIONS			
Nature and Volume of Release (continued)			
Is this a gas only submission (i.e. only significant Mcf values reported)	No, according to supplied volumes this does not appear to be a "gas only" report.		
Was this a major release as defined by Subsection A of 19.15.29.7 NMAC	Yes		
Reasons why this would be considered a submission for a notification of a major release	From paragraph A. "Major release" determine using: (1) an unauthorized release of a volume, excluding gases, of 25 barrels or more.		
With the implementation of the 19.15.27 NMAC (05/25/2021), venting and/or flaring of natural gas (i.e.	e. gas only) are to be submitted on the C-129 form.		
Initial Response The responsible party must undertake the following actions immediately unless they could create a s	afety hazard that would result in injury.		
The source of the release has been stopped	True		
The impacted area has been secured to protect human health and the environment	True		
Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices	True		
All free liquids and recoverable materials have been removed and managed appropriately	True		
If all the actions described above have not been undertaken, explain why	Not answered.		
	ation immediately after discovery of a release. If remediation has begun, please prepare and attach a narrative ted or if the release occurred within a lined containment area (see Subparagraph (a) of Paragraph (5) of valuation in the follow-up C-141 submission.		
to report and/or file certain release notifications and perform corrective actions for releathe OCD does not relieve the operator of liability should their operations have failed to a	knowledge and understand that pursuant to OCD rules and regulations all operators are require asses which may endanger public health or the environment. The acceptance of a C-141 report by adequately investigate and remediate contamination that pose a threat to groundwater, surface t does not relieve the operator of responsibility for compliance with any other federal, state, or		
I hereby agree and sign off to the above statement	Name: James Raley Title: EHS Professional Email: jim.raley@dvn.com Date: 10/13/2025		

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

QUESTIONS, Page 3

Action 514497

QUESTIONS (continued)

Operator:	OGRID:
DEVON ENERGY PRODUCTION COMPANY, LP	6137
333 West Sheridan Ave.	Action Number:
Oklahoma City, OK 73102	514497
	Action Type:
	[C-141] Remediation Closure Request C-141 (C-141-v-Closure)

Site Characterization

A 100-year floodplain

storage site

Did the release impact areas not on an exploration, development, production, or

QUESTIONS

o ontarestorization		
Please answer all the questions in this group (only required when seeking remediation plan approval and beyond). This information must be provided to the appropriate district office no later than 90 days after the release discovery date.		
What is the shallowest depth to groundwater beneath the area affected by the release in feet below ground surface (ft bgs)	Between 100 and 500 (ft.)	
What method was used to determine the depth to ground water	NM OSE iWaters Database Search	
Did this release impact groundwater or surface water	No	
What is the minimum distance, between the closest lateral extents of the release and the following surface areas:		
A continuously flowing watercourse or any other significant watercourse	Between 1 and 5 (mi.)	
Any lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark)	Between 1 and 5 (mi.)	
An occupied permanent residence, school, hospital, institution, or church	Between 1 and 5 (mi.)	
A spring or a private domestic fresh water well used by less than five households for domestic or stock watering purposes	Between 1000 (ft.) and ½ (mi.)	
Any other fresh water well or spring	Between 1000 (ft.) and ½ (mi.)	
Incorporated municipal boundaries or a defined municipal fresh water well field	Greater than 5 (mi.)	
A wetland	Between ½ and 1 (mi.)	
A subsurface mine	Greater than 5 (mi.)	
An (non-karst) unstable area	Greater than 5 (mi.)	
Categorize the risk of this well / site being in a karst geology	Low	

Greater than 5 (mi.)

Remediation Plan		
Please answer all the questions that apply or are indicated. This information must be provided to the appropriate district office no later than 90 days after the release discovery date.		
Requesting a remediation plan approval with this submission	Yes	
Attach a comprehensive report demonstrating the lateral and vertical extents of soil contamination associated with the release have been determined, pursuant to 19.15.29.11 NMAC and 19.15.29.13 NMAC.		
Have the lateral and vertical extents of contamination been fully delineated	Yes	
Was this release entirely contained within a lined containment area	Yes	
Per Subsection B of 19.15.29.11 NMAC unless the site characterization report includes complete which includes the anticipated timelines for beginning and completing the remediation.	ed efforts at remediation, the report must include a proposed remediation plan in accordance with 19.15.29.12 NMAC,	
On what estimated date will the remediation commence	08/25/2025	
On what date will (or did) the final sampling or liner inspection occur	08/27/2025	
On what date will (or was) the remediation complete(d)	08/27/2025	
What is the estimated surface area (in square feet) that will be remediated	6900	
What is the estimated volume (in cubic yards) that will be remediated	0	
These estimated dates and measurements are recognized to be the best guess or calculation at t	he time of submission and may (be) change(d) over time as more remediation efforts are completed.	

No

The SCD recognizes that proposed remediation measures may have to be minimally adjusted in accordance with the physical realities encountered during remediation. If the responsible party has any need to significantly deviate from the remediation plan proposed, then it should consult with the division to determine if another remediation plan submission is required.

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

QUESTIONS, Page 4

Action 514497

QUESTIONS (continued)

ı	Operator:	OGRID:
ı	DEVON ENERGY PRODUCTION COMPANY, LP	6137
ı	333 West Sheridan Ave.	Action Number:
ı	Oklahoma City, OK 73102	514497
ı		Action Type:
ı		[C-141] Remediation Closure Request C-141 (C-141-v-Closure)

QUESTIONS

Remediation Plan (continued)		
Please answer all the questions that apply or are indicated. This information must be provided to the appropriate district office no later than 90 days after the release discovery date.		
This remediation will (or is expected to) utilize the following processes to remediate / reduce contaminants:		
(Select all answers below that apply.)		
Is (or was) there affected material present needing to be removed	Yes	
Is (or was) there a power wash of the lined containment area (to be) performed	Yes	
OTHER (Non-listed remedial process)	Not answered.	
Per Subsection B of 19.15.29.11 NMAC unless the site characterization report includes completed efforts at remediation, the report must include a proposed remediation plan in accordance with 19.15.29.12 NMAC,		

Per Subsection B of 19.15.29.11 NMAC unless the site characterization report includes completed efforts at remediation, the report must include a proposed remediation plan in accordance with 19.15.29.12 NMAC which includes the anticipated timelines for beginning and completing the remediation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

I hereby agree and sign off to the above statement

Name: James Raley Title: EHS Professional Email: jim.raley@dvn.com Date: 10/13/2025

The OCD recognizes that proposed remediation measures may have to be minimally adjusted in accordance with the physical realities encountered during remediation. If the responsible party has any need to significantly deviate from the remediation plan proposed, then it should consult with the division to determine if another remediation plan submission is required.

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe. NM 87505

QUESTIONS, Page 6

Action 514497

Santa Fe, NM 87505				
QUESTIONS (continued)				
Operator: DEVON ENERGY PRODUCTION COMPANY, LP 333 West Sheridan Ave. Oklahoma City, OK 73102	ORS (CONTINUED) OGRID: 6137 Action Number: 514497 Action Type: [C-141] Remediation Closure Request C-141 (C-141-v-Closure)			
QUESTIONS				
Liner Inspection Information				
Last liner inspection notification (C-141L) recorded	498076			
Liner inspection date pursuant to Subparagraph (a) of Paragraph (5) of Subsection A of 19.15.29.11 NMAC	08/27/2025			
Was all the impacted materials removed from the liner	Yes			
What was the liner inspection surface area in square feet	6900			
Remediation Closure Request Only answer the questions in this group if seeking remediation closure for this release because all re Requesting a remediation closure approval with this submission	emediation steps have been completed. Yes			
Have the lateral and vertical extents of contamination been fully delineated	Yes			
Was this release entirely contained within a lined containment area	Yes			
What was the total surface area (in square feet) remediated	6900			
What was the total volume (cubic yards) remediated	0			
Summarize any additional remediation activities not included by answers (above)	Liner inspected			
	closure requirements and any conditions or directives of the OCD. This demonstration should be in the form of a notes, photographs of any excavation prior to backfilling, laboratory data including chain of custody documents			
to report and/or file certain release notifications and perform corrective actions for release the OCD does not relieve the operator of liability should their operations have failed to a water, human health or the environment. In addition, OCD acceptance of a C-141 report	knowledge and understand that pursuant to OCD rules and regulations all operators are required ses which may endanger public health or the environment. The acceptance of a C-141 report by adequately investigate and remediate contamination that pose a threat to groundwater, surface t does not relieve the operator of responsibility for compliance with any other federal, state, or ally restore, reclaim, and re-vegetate the impacted surface area to the conditions that existed no notification to the OCD when reclamation and re-vegetation are complete.			
I hereby agree and sign off to the above statement	Name: James Raley Title: EHS Professional Email: jim.raley@dvn.com Date: 10/13/2025			

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 514497

CONDITIONS

Operator:	OGRID:
DEVON ENERGY PRODUCTION COMPANY, LP	6137
333 West Sheridan Ave.	Action Number:
Oklahoma City, OK 73102	514497
	Action Type:
	[C-141] Remediation Closure Request C-141 (C-141-v-Closure)

CONDITIONS

Created By	Condition	Condition Date
scott.rodgers	App ID 514497 Liner Inspection approved	10/17/2025