Submit 1 Copy To Appropriate District	et Office	State of No	ew Mexico				Е	Form C-103
<u>District I</u> - (575) 393-6161	Energy,		nd Natural Ro	esources	TYPE Y A	N.N.O		d July 18,2013
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> - (575) 748-1283	0				WELL AI	30.015	5.22657	
811 S. First St., Artesia, NM 88210			ATION DIVI		5. Indicate	Type of Le	ase	
<u>Disrtict III - (</u> 505) 334-6178 1000 Rio Brazos Rd. Aztec, NM 8741	.0	1220 South S	St. Francis Dr.	•		ATE 🗸		FEE
<u>District IV - (505) 476-3460</u> 1220 S. St. Francis Dr., Santa Fe, NM	87505	Santa Fe,	NM 87505		6. State O	il & Gas Lea	ise No.	
	RY NOTICES AND REPO	RTS ON WEI	LS		7. Lease N	Name or Uni	Agreeme	ent Name
(DO NOT USE THIS FORM FOR PR	OPOSALS TO DRILL OR DEE	PEN OR PLUG B	ACK TO A DIFFE	ERENT		mpire Abo	Ü	
RESERVIOR. USE "APPLICATION	FOR PERMIT" (FORM C-101)	FOR SUCH PRO	POSALS.)		8. Well N	•	(00)	,
1. Type of Well: Oil Well	Gas Well Other				9. OGRID		93	
2. Name of Operator	Apache Corporat	ion			9. UGRIL		73	
3. Address of Operator					10. Pool Name or Wildcat			
4. Well Location	Airpark Lane, Ste. 300	00, Midland,	TX 79705		Emire: Abo (22040)			
Unit Letter	J : 2490	feet from the	S 1i	ine and	2200	feet from t	E	line
Section	1 Township	18S	Range	27 E	NMPM		County	EDDY
	11. Elevation (S		DR, RKB,RT, G 642' GR	GR, etc.)				
1′	2. Check Appropriate B			Notice Re	nort or O	ther Data		
	** *	ox 10 maica	ic ivaluic of i	•			05	
PERFORM REMEDIAL WORK	OF INTENTION TO:	ANDON 🗸	REMEDIAL W		SEQUENI	REPORT ALTERIN		а П
TEMPORARILY ABANDON	CHANGE PLAN	=	COMMENCE		OPNS.	PANDA	0 0/10/11	
PULL OR ALTER CASING		MPL	CASING/CEM	I <u>ENT JOB</u>		1		
DOWNHOLE COMMINGLE				Notify C	OCD 24 hrs	s. prior to a	ny work	
CLOSED-LOOP SYSTEM			OTUED:	done				
OTHER:	ompleted operations ((Tlearly state a	OTHER:	etails and	give perti	inant dates	includin	g actimated
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work.) SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram or								
proposed completion or reco).13./.1 \ 1\I\	110. 101 1110	itipie con	ipietions.	Tittuell we	noore un	igruin or
proposed compression of rec								
	. 50.4 (
Apache Corporation pro	-		-		-			ystem will
be used for all	I fluids from this wellb	ore and disp	osea or requ	iirea by O	CD Rule	19.15.17.14	NWAC.	
	QEI	CHANGES	TO PROCEI	DURE				
	OLL	CHANGES	TO FROCE	DUKL				
Spud Date:			Rig Release	Date:				
****SEE ATTAC	HED COA's****		MUST	r RF PI	LIGGE	D BY 13	2/29/20	121
****SEE ATTACHED COA's**** MUST BE PLUGGED BY 12/29/2021 I hereby certify that the information above is true and complete to the best of my knowledge and belief.								
		r		,				
SIGNATURE	Guínn Burks	TITLE	Sr. Recla	mation Fo	oreman	DATE	12	/20/20
						- 		
Type or print name	Guinn Burks	E-mail add.	guinn.burks	@apache	corp.com	PHONE:	432-5	556-9143
For State Use Only			S	17.1			10/00	/2020
APPROVED BY:		> TITLE	Staff	Mana	<i>iger</i>	DATE	12/29	/2020
Conditions of Approval (if any) :		ω		V			



LEASE NAME	Empire Abo Unit
WELL#	#193
API#	30.015.22657
COUNTY	EDDY, NM

DEPTH SX/CMT

	WELL BORE INFO.	
0		
v		
259		
519		
778	11" Hole 8 5/8" 24# @ 1006'	
1038	w/ 700 sx CIRC surf	
1297		
1556		
1816		
2075		
2334		
2594		
2853		
3113		
3372		
3631		
3891	DVT @ 4014' w/ 900 to surf	
4150	5V1 @ 4014 W/ 300 to 3u11	
4409		
4669		
4928		
5188		
5447	CIBP @ 5626' w/ 35' cmt	
5706		WEWAWA
5966		
6225	7 7/8" Hole 5 1/2" 15.5# @ 6225' w/ 400 sx to 4014' DVT	PBTD @ 5626'
		TD @ 6225'

Abo perfs @ 5676'-6030'



 LEASE NAME
 Empire Abo Unit

 WELL #
 #193

 API #
 30.015.22657

 COUNTY
 EDDY, NM

DEPTH SX/CMT

PROPOSED PROCEDURE

SURF

130 sx

PUH & SPOT CLASS "C" CMT TO SURF/ FILL UP.

QUEEN, SURF SHOE. WATER BOARD, & SURF PLUG

Perf @ 1056' & attempt to circulate cement to surface

1250'

1900'

25 sx 2100' PUH & SPOT CLASS "C" CMT, WOC/TAG

SAN ANDRES

3100'

100 sx

PUH & SPOT CLASS "C" CMT, WOC/TAG

DVT & GLORIETA

4064'

5426' 5626' 25 sx

MIRU P&A RIG. RIH W/TBG & VERIFY CIBP, CIRC W/MLF, & SPOT CLASS "C" CMT.

ABO Perfs

Abo perfs @ 5676'-6030'

CIBP @ 6140'

TD @ 6225'

Perfs @ 6150'-6160'

	WELL BODE INFO			
	WELL BORE INFO.	7777	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	200
•				
0				
259				
E40				
519				
778				
	11" Hole 8 5/8" 24# @ 1006'			
1038	w/ 700 sx CIRC surf			
1030	W/ 700 3X OIITO SUIT			
1297				
1556				
4040				
1816				
2075				
2334				
2004				
2594				
2853				
0440				
3113				
3372				
3631				
0001				
3891				
	DVT @ 4014' w/ 900 to surf			
4150	2			
4409				
4403				
4669				
4928				
F400				
5188				
5447				
	CIBP @ 5626' w/ 35' cmt			
5706				
2.30				
5966				
	7 7/8" Hole			
6225	5 1/2" 15.5# @ 6225'		><	W
	w/ 400 sx to 4014' DVT	PE	STD @ 56	26'
		7	ロコ の ドンフ	•

CONDITIONS FOR PLUGGING AND ABANDONMENT

OCD - Southern District

The following is a guide or checklist in preparation of a plugging program, this is not all inclusive and care must be exercised in establishing special plugging programs in unique and unusual cases, Notify NMOCD District Office II at (575)-748-1283 at least 24 hours before beginning work. After MIRU rig will remain on well until it is plugged to surface. OCD is to be notified before rig down. Company representative will be on location during plugging procedures.

- A notice of intent to plug and abandon a wellbore is required to be approved before plugging
 operations are conducted. A cement evaluation tool is required in order to ensure isolation of
 producing formations, protection of water and correlative rights. A cement bond log or other
 accepted cement evaluation tool is to be provided to the division for evaluation if one has not
 been previously run or if the well did not have cement circulated to surface during the original
 casing cementing job or subsequent cementing jobs. Insure all bradenheads have been
 exposed, identified and valves are operational prior to rig up.
- 2. Closed loop system is to be used for entire plugging operation. Upon completion, contents of steel pits are to be hauled to a permitted disposal location.
- 3. Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator as well as the contractor, to verify that this permit is in place prior to performing work. Drivers shall be able to produce a copy upon request of an NMOCD Field inspector.
- 4. Filing a subsequent C-103 will serve as notification that the well has been plugged.
- 5. A final C-103 shall be filed (and a site inspection by NMOCD Inspector to determine if the location is satisfactorily cleaned, all equipment, electric poles and trash has been removed to Meet NMOCD standards) before bonding can be released.
- 6. If work has not begun within 1 Year of the approval of this procedure, an extension request must be file stating the reason the well has not been plugged.
- 7. Squeeze pressures are not to exceed 500 psi, unless approval is given by NMOCD.
- 8. Produced water will not be used during any part of the plugging operation.
- 9. Mud laden fluids must be placed between all cement plugs mixed at 25 sacks per 100 bbls of water.
- 10. All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater. 50' of calculated cement excess required for inside casing plugs and 100% calculated cement excess required on outside casing plugs.
- 11. Class 'C' cement will be used above 7500 feet.
- 12. Class 'H' cement will be used below 7500 feet.
- 13. A cement plug is required to be set 50' above and 50' below, casing stubs, DV tools, attempted casing cut offs, cement tops outside casing, salt sections and anywhere the casing is perforated, these plugs require a 4 hour WOC and then will be tagged
- 14. All Casing Shoes Will Be Perforated 50' below shoe depth and Attempted to be Squeezed, cement needs to be 50' above and 50' Below Casing Shoe inside the Production Casing.

- 16. When setting the top out cement plug in production, intermediate and surface casing, wellbores should remain full at least 30 minutes after plugs are set
- 17. A CIBP is to be set within 100' of production perforations, capped with 100' of cement, WOC 4 hours and tag.
- 18. A CIBP with 35' of cement may be used in lieu of the 100' plug if set with a bailer. This plug will be placed within 100' of the top perforation, (WOC 4 hrs and tag).
- 19. No more than 3000' is allowed between cement plugs in cased hole and 2000' in open hole.
- 20. Some of the Formations to be isolated with cement plugs are: These plugs to be set to isolate formation tops
 - A) Fusselman
 - B) Devonian
 - C) Morrow
 - D) Wolfcamp
 - E)Bone Springs
 - F) Delaware
 - G) Any salt sections
 - H) Abo
 - I) Glorieta
 - J) Yates.
 - K) Potash--- (In the R-111-P Area (Potash Mine Area), a solid cement plug must be set across the salt section. Fluid used to mix the cement shall be saturated with the salts that are common to the section penetrated and in suitable proportions, not more than 3% calcium chloride (by weight of cement) will be considered the desired mixture whenever possible, WOC 4 hours and tag, this plug will be 50' below the bottom and 50' above the top of the Formation.
- 21. If cement does not exist behind casing strings at recommended formation depths, the casing can be cut and pulled with plugs set at recommended depths. If casing is not pulled, perforations will be shot and cement squeezed behind casing, WOC and tagged. These plugs will be set 50' below formation bottom to 50' above formation top inside the casing

DRY HOLE MARKER REQUIRMENTS

The operator shall mark the exact location of the plugged and abandoned well with a steel marker not less than four inches in diameter, 3' below ground level with a plate of at least ¼" welded to the top of the casing and the dry hole marker welded on the plate with the following information welded on the dry hole marker:

1. Operator name 2. Lease and Well Number 3.API Number 4. Unit Letter 5. Quarter Section (feet from the North, South, East or West) 6. Section, Township and Range 7. Plugging Date 8. County (SPECIAL CASES)------AGRICULTURE OR PRARIE CHICKEN BREEDING AREAS

In these areas, a below ground marker is required with all pertinent information mentioned above on a plate, set 3' below ground level, a picture of the plate will be supplied to NMOCD for record, the exact location of the marker (longitude and latitude by GPS) will be provided to NMOCD (We typically require a current survey to verify the GPS)

SITE REMEDIATION DUE WITHIN ONE YEAR OF WELL PLUGGING COMPLETION

<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III
1000 Rio Brazos Rd., Aztec, NM 87410

Phone:(505) 334-6178 Fax:(505) 334-6170 1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 12763

CONDITIONS OF APPROVAL

Operator	r:		OGRID:	Action Number:	Action Type:
	APACHE CORPORATION	303 Veterans Airpark Ln	873	12763	C-103P
#1000	Midland, TX79705				

OCD Reviewer	Condition
gcordero	COA's attached to file