Received by Och; Appropriate Fisher 8	AM State of New M	[exico		Form C-103 ¹ of 6
<u>District I</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Nat	tural Resources	WELL ADINO	Revised July 18, 2013
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION	N DIVISION	5. Indicate Type of Lea	015-31550
<u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Fra		STATE	FEE
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM	Santa Fe, NM 8	3/303	6. State Oil & Gas Leas	
87505 SUNDRY NOT	TICES AND REPORTS ON WELL	.S	7. Lease Name or Unit	
(DO NOT USE THIS FORM FOR PROPO	OSALS TO DRILL OR TO DEEPEN OR P. ICATION FOR PERMIT" (FORM C-101) I	LUG BACK TO A	GERONIMO 34	
PROPOSALS.) 1. Type of Well: Oil Well	Gas Well Other		8. Well Number	002
2. Name of Operator	WPX Energy Permian,	LLC	9. OGRID Number	246289
3. Address of Operator _{3500 ONE W} TULSA, OK	/ILLIAMS CENTER MD 35 74172		10. Pool name or Wildo EMPIRE; PE	
4. Well Location	1650 feet from the NOF	RTH 1:	1140 feet from the	EAST line
Unit Letter :: Section 34	leet from the	line and Range 28E	NMPM EDDY Cou	nne
	11. Elevation (Show whether D			
	3,0	57 1		
12. Check	Appropriate Box to Indicate 1	Nature of Notice,	Report or Other Data	
	NTENTION TO:		SEQUENT REPOR	
PERFORM REMEDIAL WORK ☐ TEMPORARILY ABANDON ☐	PLUG AND ABANDON CHANGE PLANS	REMEDIAL WOR	_	ERING CASING ID A
PULL OR ALTER CASING		CASING/CEMEN		
DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM			Notify OCD 24 hrs. prior t	o any work
OTHER:		OTHER:	done	11
of starting any proposed w	pleted operations. (Clearly state all ork). SEE RULE 19.15.7.14 NMA			
proposed completion or rec WPX ENERGY PERMIAN, LLC requests to	±	low procedure:		
1) SET 5-1/2" CIBP@ 10,400'; PUMP 25 SX	•	•		
2) PUMP 25 SXS. CMT.@ 9,901 '-9,711' (T/ 3) PUMP 25 SXS. CMT.@ 9,506'-9,316' (T/S	ATOKA)			
4) PUMP 25 SXS. CMT.@ 7,127'-6,957' (T/\ 5) PUMP 25 SXS. CMT.@ 5,805'-5,655' (T/\				
6) PUMP 25 sxs. CMT.@ 5,091 '-4,941' (5-1 7) PUMP 25 SXS. CMT.@ 3,457'-3,327' (T/0				
8) PUMP 25 SXS. CMT. @2,765'-2,645' (9-59) PERF. X ATTEMPT TO SQZ. 110 SXS. 0		3-3/8" CSG. SHOE) ; wo	e X TAG.	
10) PERF. X CIRC. TO SURF., FILLING AL 11) DIG OUT X CUT OFF WELLHEAD 3' B.				
DURING THIS PROCEDURE WE PLAN TO OCD RULE 19.15.17.	USE THE CLOSED-LOOP SYSTEM W/	A STEEL TANK AND H	AUL CONTENTS TO THE RE	QUIRED DISPOSAL, PER
Spud Date: 02/03/2	Rig Release I	Date: 03/	15/2001	
****SEE ATTACHE	<u></u>		PLUGGED BY	3/1/2022
I hereby certify that the information				0/1/2022
1-15	1 Was		5 ()	0.104.10004
SIGNATURE MILLON			e Professional _{DATE} 0	13/01/2021
Type or print name Caitlin O'		🧓 caitlin.ohair	(a)dyn com	530-573-3527
For State Use Only	Hair E-mail addre	ss:	@avn.com PHONE:	
	Hair E-mail addre	ss: <u>Cartini.orian</u>	PHONE:	3/1/2021

CONDITIONS FOR PLUGGING AND ABANDONMENT

OCD - Southern District

The following is a guide or checklist in preparation of a plugging program, this is not all inclusive and care must be exercised in establishing special plugging programs in unique and unusual cases, Notify NMOCD District Office II at (575)-748-1283 at least 24 hours before beginning work. After MIRU rig will remain on well until it is plugged to surface. OCD is to be notified before rig down. Company representative will be on location during plugging procedures.

- 1. A notice of intent to plug and abandon a wellbore is required to be approved before plugging operations are conducted. A cement evaluation tool is required in order to ensure isolation of producing formations, protection of water and correlative rights. A cement bond log or other accepted cement evaluation tool is to be provided to the division for evaluation if one has not been previously run or if the well did not have cement circulated to surface during the original casing cementing job or subsequent cementing jobs. Insure all bradenheads have been exposed, identified and valves are operational prior to rig up.
- 2. Closed loop system is to be used for entire plugging operation. Upon completion, contents of steel pits are to be hauled to a permitted disposal location.
- 3. Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator as well as the contractor, to verify that this permit is in place prior to performing work. Drivers shall be able to produce a copy upon request of an NMOCD Field inspector.
- 4. Filing a subsequent C-103 will serve as notification that the well has been plugged.
- 5. A final C-103 shall be filed (and a site inspection by NMOCD Inspector to determine if the location is satisfactorily cleaned, all equipment, electric poles and trash has been removed to Meet NMOCD standards) before bonding can be released.
- 6. If work has not begun within 1 Year of the approval of this procedure, an extension request must be file stating the reason the well has not been plugged.
- 7. Squeeze pressures are not to exceed 500 psi, unless approval is given by NMOCD.
- 8. Produced water will not be used during any part of the plugging operation.
- 9. Mud laden fluids must be placed between all cement plugs mixed at 25 sacks per 100 bbls of water.
- 10. All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater. 50' of calculated cement excess required for inside casing plugs and 100% calculated cement excess required on outside casing plugs.
- 11. Class 'C' cement will be used above 7500 feet.
- 12. Class 'H' cement will be used below 7500 feet.
- 13. A cement plug is required to be set 50' above and 50' below, casing stubs, DV tools, attempted casing cut offs, cement tops outside casing, salt sections and anywhere the casing is perforated, these plugs require a 4 hour WOC and then will be tagged
- 14. All Casing Shoes Will Be Perforated 50' below shoe depth and Attempted to be Squeezed, cement needs to be 50' above and 50' Below Casing Shoe inside the Production Casing.

- 16. When setting the top out cement plug in production, intermediate and surface casing, wellbores should remain full at least 30 minutes after plugs are set
- 17. A CIBP is to be set within 100' of production perforations, capped with 100' of cement, WOC 4 hours and tag.
- 18. A CIBP with 35' of cement may be used in lieu of the 100' plug if set with a bailer. This plug will be placed within 100' of the top perforation, (WOC 4 hrs and tag).
- 19. No more than 3000' is allowed between cement plugs in cased hole and 2000' in open hole.
- 20. Some of the Formations to be isolated with cement plugs are: These plugs to be set to isolate formation tops
 - A) Fusselman
 - B) Devonian
 - C) Morrow
 - D) Wolfcamp
 - E)Bone Springs
 - F) Delaware
 - G) Any salt sections
 - H) Abo
 - I) Glorieta
 - J) Yates.
 - K) Potash--- (In the R-111-P Area (Potash Mine Area), a solid cement plug must be set across the salt section. Fluid used to mix the cement shall be saturated with the salts that are common to the section penetrated and in suitable proportions, not more than 3% calcium chloride (by weight of cement) will be considered the desired mixture whenever possible, WOC 4 hours and tag, this plug will be 50' below the bottom and 50' above the top of the Formation.
- 21. If cement does not exist behind casing strings at recommended formation depths, the casing can be cut and pulled with plugs set at recommended depths. If casing is not pulled, perforations will be shot and cement squeezed behind casing, WOC and tagged. These plugs will be set 50' below formation bottom to 50' above formation top inside the casing

DRY HOLE MARKER REQUIRMENTS

The operator shall mark the exact location of the plugged and abandoned well with a steel marker not less than four inches in diameter, 3' below ground level with a plate of at least ¼" welded to the top of the casing and the dry hole marker welded on the plate with the following information welded on the dry hole marker:

1. Operator name 2. Lease and Well Number 3.API Number 4. Unit Letter 5. Quarter Section (feet from the North, South, East or West) 6. Section, Township and Range 7. Plugging Date 8. County (SPECIAL CASES)------AGRICULTURE OR PRARIE CHICKEN BREEDING AREAS

In these areas, a below ground marker is required with all pertinent information mentioned above on a plate, set 3' below ground level, a picture of the plate will be supplied to NMOCD for record, the exact location of the marker (longitude and latitude by GPS) will be provided to NMOCD (We typically require a current survey to verify the GPS)

SITE REMEDIATION DUE WITHIN ONE YEAR OF WELL PLUGGING COMPLETION

Imaging: 3/1/2021 10:14:56 AM

WELLBORE DIAGRAM

WELL: GERONIMO 34 STATE COM 2 SPUD DATE: 2/3/2001 COUNTY: STATE: EDDY 10,600 MD (KB) TVD: PBTD: TVD (KB) 10,560 MD (KB) EU NUMBER: 62431421 KB ELEVATION: 3,689 3,671 SURFACE LAT/LONG: 32.7938814 -104.1589018

		CA	SI	N	G	R	E	C	ō	R	Ē
--	--	----	----	---	---	---	---	---	---	---	---

SII	RF	ACF	CAS	ING

O.D.	WT./FT.	GRADE	THD	TOP	втм	CMT
13.375"				0.000"	443	430 Sack

INTERMEDIATE CASING

O.D.	WT./FT.	GRADE	THD	TOP	ВТМ	CMT
9 5/8				0	2705	1000 Sack

9.625 @ 2,705' (MD) PRODUCTION LIN

13.375 @ 443' (MD)

DV Tool @ 5016'

5.5 @ 10,600' (MD)

O.D.	WT./FT.	GRADE	THD	TOP	BTM	CMT
5.500"				0.000"	10600	1810 Sac

PERFORATION RECORD

ZONE - Stage	TOP	BOTTOM	Gross Perfs	Net Perfs	Shots (60°)
	10,461	10,472			
			-		
			-		
			 		

TI	IBIN	GI	DET	ΔII	

ubing and Packer detail	No. Jts	Length (ft)	Top Depth (ft)
В		18'	
7/8"		10,334'	18'
		EOT @	10,352'

-Pump 25 5x5.@ 2,765'- 2,645'- TAG.

2705

- Pump 25 SXS. @ 3,457'-3,327'

Pump 25 SXS. @ 5,091 - 4,941 - TAG 5016 Pump 25 SXS. @ 5,805 - 5,655 Pump 25 SXS. @ 7,127 -6,957, Pump 25 SXS. @ 9,506, 9,316, fump 25 SXS. @ 9,901-9,711, - Pump 25, SXS. @ 16,400, 10,200

10,461-72 SET 51/2" CABP@ 10,400

10,600

T/ANH4. ~ 600 T/YATES ~ 722' T/5.A. ~ 2,166 T/GLOP. ~ 3,392' TIABO. ~ 5,730' T/WLCP. - 7,042' T/STWN.~ 9,411 T/ATOKA. ~ 9,806" T/MRPW. ~ 10,110'

<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III
1000 Rio Brazos Rd., Aztec, NM 87410

Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 19217

CONDITIONS OF APPROVAL

Operator:			OGRID:	Action Number:	Action Type:
WPX ENERGY PERMIAN, LLC	3500 One Williams Center	Tulsa, OK74172	246289	19217	C-103F

OCD Reviewer	Condition
gcordero	None