Submit 1 Copy To Appropriate District Office	State of New Mexico Form (
District I – (575) 393-6161	Energy, Minerals and Natural Resources	Revised August 1, 2011				
1625 N. French Dr., Hobbs, NM 88240		WELL API NO.				
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION	30-015-28849				
District III - (505) 334-6178	1220 South St. Francis Dr.	5. Indicate Type of Lease STATE X FEE				
1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> – (505) 476-3460	Santa Fe, NM 87505	6. State Oil & Gas Lease No.				
1220 S. St. Francis Dr., Santa Fe, NM		o. State On & Gas Lease 140.				
87505						
	S AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name				
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		EV STATE				
PROPOSALS.)		8. Well Number				
1. Type of Well: Oil Well Gas Well X Other		004				
2. Name of Operator	9. OGRID Number					
CHISHOLM ENERGY OPERATING.	372137					
3. Address of Operator	10. Pool name or Wildcat					
801 CHERRY ST., SUITE 1200, UNIT	Γ 20, FORT WORTH, TEXAS 76102	HAPPY VALLEY, DELAWARE				
4. Well Location						
Unit Letter A: 990	feet from the NORTH line and 1650	feet from the EAST line				
Section 32	Township 22S Range	26E NMPM EDDY County				
	1. Elevation (Show whether DR, RKB, RT, GR, et					
	3,308' – GR					
12 Check Ann	ropriate Box to Indicate Nature of Notice	Report or Other Data				
12. Check App	ropriate box to material realist of rother	e, Report of Other Data				
NOTICE OF INTE	INTION TO:	BSEQUENT REPORT OF:				
PERFORM REMEDIAL WORK PLUG AND ABANDON X REMEDIAL WORK ALTERING CASIN						
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. P AND A						
PULL OR ALTER CASING	IULTIPLE COMPL	NT JOB				
DOWNHOLE COMMINGLE		Nextific OCD 24 least region to accompany				
		Notify OCD 24 hrs. prior to any work done				
OTHER:	OTHER:					
	•	and give pertinent dates, including estimated date				
	SEE RULE 19.15.7.14 NMAC. For Multiple C	completions: Attach wellbore diagram of				
proposed completion or recomp	dietion.					
1) $TAGPRTD @ +/-2 806' \cdot 0$	CIRC WELL W/MIF					
 TAG PBTD @ +/-2,806'; CIRC. WELL W/ M.L.F. PUMP 25 SXS. CMT. @ 1,660'-1,550' (T/DLWR., 8-5/8" CSG.SHOE); WOC X TAG TOC. 						
3) PERF. X CIRC. TO SURF., FILLING ALL ANNULI, 125 SXS. CMT. @ 400'-3' (13-3/8'' CSG.SHOE).						
4) DIG OUT X CUT OFF WELLHEAD 3' B.G.L.; VERIFY CMT. TO SURF. ON ALL ANNULI; WELD ON STEEL						
PLATE TO CSGS. X INSTALL DRY HOLE MARKER.						
DURING THIS PROCEDURE WE PLAN TO USE THE CLOSED-LOOP SYSTEM W/ A STEEL TANK AND HAUL						
	WE FLAN TO USE THE CLUSED-LOOF STS	STEM W/ A STEEL TANK AND HAUL				
CONTENTS TO THE REQUII	RED DISPOSAL, PER OCD RULE 19.15.17.	STEM W/ A STEEL TANK AND HAUL				
CONTENTS TO THE REQUII		STEM W/ A STEEL TANK AND HAUL				
CONTENTS TO THE REQUIREMENTS TO THE REQUIREMENTS TO THE REQUIREMENTS.	RED DISPOSAL, PER OCD RULE 19.15.17.	BE PLUGGED BY 5/14/2022				
	RED DISPOSAL, PER OCD RULE 19.15.17.					
	RED DISPOSAL, PER OCD RULE 19.15.17.					
	RED DISPOSAL, PER OCD RULE 19.15.17.					
****SEE ATTACHED	COA's**** MUST I	BE PLUGGED BY 5/14/2022				
****SEE ATTACHED	RED DISPOSAL, PER OCD RULE 19.15.17.	BE PLUGGED BY 5/14/2022				
****SEE ATTACHED	COA's**** MUST I	BE PLUGGED BY 5/14/2022				
****SEE ATTACHED I hereby certify that the information about	RED DISPOSAL, PER OCD RULE 19.15.17. COA's**** WUST I	BE PLUGGED BY 5/14/2022 dge and belief.				
****SEE ATTACHED	COA's**** MUST I	BE PLUGGED BY 5/14/2022				
****SEE ATTACHED I hereby certify that the information about SIGNATURE	RED DISPOSAL, PER OCD RULE 19.15.17. COA's**** we is true and complete to the best of my knowled TITLE: AGENT	BE PLUGGED BY 5/14/2022 dge and belief. DATE: 05/10/21				
I hereby certify that the information about SIGNATURE Type or print name: DAVID A. EYLE	RED DISPOSAL, PER OCD RULE 19.15.17. COA's**** we is true and complete to the best of my knowled TITLE: AGENT	BE PLUGGED BY 5/14/2022 dge and belief.				
****SEE ATTACHED I hereby certify that the information about SIGNATURE	red DISPOSAL, PER OCD RULE 19.15.17. MUST I ve is true and complete to the best of my knowled TITLE: AGENT E-mail address: DEYLER@ MILA	BE PLUGGED BY 5/14/2022 dge and belief. DATE: 05/10/21 GRO-RES.COM PHONE: 432.687.3033				
I hereby certify that the information about SIGNATURE Type or print name: DAVID A. EYLE	RED DISPOSAL, PER OCD RULE 19.15.17. COA's**** we is true and complete to the best of my knowled TITLE: AGENT	BE PLUGGED BY 5/14/2022 dge and belief. DATE: 05/10/21 GRO-RES.COM PHONE: 432.687.3033				

Page 1 of 6

Received by OCD: 5/11/2021 1:25:43 PM

CONDITIONS FOR PLUGGING AND ABANDONMENT

OCD - Southern District

The following is a guide or checklist in preparation of a plugging program, this is not all inclusive and care must be exercised in establishing special plugging programs in unique and unusual cases, Notify NMOCD District Office II at (575)-748-1283 at least 24 hours before beginning work. After MIRU rig will remain on well until it is plugged to surface. OCD is to be notified before rig down. Company representative will be on location during plugging procedures.

- 1. A notice of intent to plug and abandon a wellbore is required to be approved before plugging operations are conducted. A cement evaluation tool is required in order to ensure isolation of producing formations, protection of water and correlative rights. A cement bond log or other accepted cement evaluation tool is to be provided to the division for evaluation if one has not been previously run or if the well did not have cement circulated to surface during the original casing cementing job or subsequent cementing jobs. Insure all bradenheads have been exposed, identified and valves are operational prior to rig up.
- 2. Closed loop system is to be used for entire plugging operation. Upon completion, contents of steel pits are to be hauled to a permitted disposal location.
- 3. Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator as well as the contractor, to verify that this permit is in place prior to performing work. Drivers shall be able to produce a copy upon request of an NMOCD Field inspector.
- 4. Filing a subsequent C-103 will serve as notification that the well has been plugged.
- 5. A final C-103 shall be filed (and a site inspection by NMOCD Inspector to determine if the location is satisfactorily cleaned, all equipment, electric poles and trash has been removed to Meet NMOCD standards) before bonding can be released.
- 6. If work has not begun within 1 Year of the approval of this procedure, an extension request must be file stating the reason the well has not been plugged.
- 7. Squeeze pressures are not to exceed 500 psi, unless approval is given by NMOCD.
- 8. Produced water will not be used during any part of the plugging operation.
- 9. Mud laden fluids must be placed between all cement plugs mixed at 25 sacks per 100 bbls of water.
- 10. All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater. 50' of calculated cement excess required for inside casing plugs and 100% calculated cement excess required on outside casing plugs.
- 11. Class 'C' cement will be used above 7500 feet.
- 12. Class 'H' cement will be used below 7500 feet.
- 13. A cement plug is required to be set 50' above and 50' below, casing stubs, DV tools, attempted casing cut offs, cement tops outside casing, salt sections and anywhere the casing is perforated, these plugs require a 4 hour WOC and then will be tagged
- 14. All Casing Shoes Will Be Perforated 50' below shoe depth and Attempted to be Squeezed, cement needs to be 50' above and 50' Below Casing Shoe inside the Production Casing.

- 16. When setting the top out cement plug in production, intermediate and surface casing, wellbores should remain full at least 30 minutes after plugs are set
- 17. A CIBP is to be set within 100' of production perforations, capped with 100' of cement, WOC 4 hours and tag.
- 18. A CIBP with 35' of cement may be used in lieu of the 100' plug if set with a bailer. This plug will be placed within 100' of the top perforation, (WOC 4 hrs and tag).
- 19. No more than 3000' is allowed between cement plugs in cased hole and 2000' in open hole.
- 20. Some of the Formations to be isolated with cement plugs are: These plugs to be set to isolate formation tops
 - A) Fusselman
 - B) Devonian
 - C) Morrow
 - D) Wolfcamp
 - E)Bone Springs
 - F) Delaware
 - G) Any salt sections
 - H) Abo
 - I) Glorieta
 - J) Yates.
 - K) Potash--- (In the R-111-P Area (Potash Mine Area), a solid cement plug must be set across the salt section. Fluid used to mix the cement shall be saturated with the salts that are common to the section penetrated and in suitable proportions, not more than 3% calcium chloride (by weight of cement) will be considered the desired mixture whenever possible, WOC 4 hours and tag, this plug will be 50' below the bottom and 50' above the top of the Formation.
- 21. If cement does not exist behind casing strings at recommended formation depths, the casing can be cut and pulled with plugs set at recommended depths. If casing is not pulled, perforations will be shot and cement squeezed behind casing, WOC and tagged. These plugs will be set 50' below formation bottom to 50' above formation top inside the casing

DRY HOLE MARKER REQUIRMENTS

The operator shall mark the exact location of the plugged and abandoned well with a steel marker not less than four inches in diameter, 3' below ground level with a plate of at least ¼" welded to the top of the casing and the dry hole marker welded on the plate with the following information welded on the dry hole marker:


1. Operator name 2. Lease and Well Number 3.API Number 4. Unit Letter 5. Quarter Section (feet from the North, South, East or West) 6. Section, Township and Range 7. Plugging Date 8. County (SPECIAL CASES)------AGRICULTURE OR PRARIE CHICKEN BREEDING AREAS

In these areas, a below ground marker is required with all pertinent information mentioned above on a plate, set 3' below ground level, a picture of the plate will be supplied to NMOCD for record, the exact location of the marker (longitude and latitude by GPS) will be provided to NMOCD (We typically require a current survey to verify the GPS)

SITE REMEDIATION DUE WITHIN ONE YEAR OF WELL PLUGGING COMPLETION

CURRENT WBD

Received by OCD: 5/11/2021 1:25:43 PM



Released to Imaging: 5/17/2021 3:20:05 PM

PROPOSED PA WBD CHISHOLM ENERGY MD EV STATE #004 30-015-28849 (TVD) 133/9 @ 350 PERF. X CIRC. 125 SXS. @ 400'-3' 400 800 1,200 85/9 0 1,600 1,600 Pump 25 sxs. @ 1,660'- 1,550- TAG 2,000 2,400 - TOCE 2,806', - CIBPE 2,840' 2,800 3,200 3,600 4,000

www.WellShadow.com

4,400

Released to Imaging: 5/17/2021 3:20:05 PM

Received by OCD: 5/11/2021 1:25:43 PM

<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III
1000 Rio Brazos Rd., Aztec, NM 87410

Phone:(505) 334-6178 Fax:(505) 334-6170 1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 27793

CONDITIONS OF APPROVAL

Operator:			OGRID:	Action Number:	Action Type:
CHISHOLM ENERGY OPERATING, LLC	801 Cherry Street	Fort Worth, TX76102	372137	27793	C-103F

OCD Reviewer	Condition
gcordero	None