
State of New Mexico	Form 2-103 of 10
District I – (575) 393-6161 Energy, Minerals and Natural Re	esources Revised July 18, 2013 WELL API NO.
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283 811 S. First St. Artesia, NM 88210 OIL CONSERVATION DIV	30-025-29984
811 S. First St., Artesia, NM 88210 <u>District III</u> – (505) 334-6178 1220 South St. Francis I	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 District IV – (505) 476-3460 Santa Fe, NM 87505	STATE FEE X 6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM	313857
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BAY	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUC PROPOSALS.)	<u> </u>
1. Type of Well: Oil Well X Gas Well Other	8. Well Number 75
2. Name of Operator RAM ENERGY LLC	9. OGRID Number 309777
3. Address of Operator	10. Pool name or Wildcat
2100 S UTICA AVE., SUITE 175, TULSA, OK 74114	18810
4. Well Location Unit Letter J: 1450 feet from the F.	line and 2200 feet from the S line
Unit Letter J : 1450 feet from the E Section 30 Township 24S Range 3	line and 2300 feet from the S line 8E NMPM County LEA
11. Elevation (Show whether DR, RKB)	J EEN
3177 KB	
12 Cl 1 A '	
12. Check Appropriate Box to Indicate Nature	of Notice, Report or Other Data
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
_ _	MEDIAL WORK ALTERING CASING
	MMENCE DRILLING OPNS. P AND A ING/CEMENT JOB
DOWNHOLE COMMINGLE	IIIVO/OLIVILIVI GOD
CLOSED-LOOP SYSTEM	
OTHER: OTHER: OTHER: OTHER:	
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For	
proposed completion or recompletion.	VVV 2000
MIRU P&A UNIT. POOH W/ EXISTING STRING.	
OVER EXISTING PERFS @ 3680 - 3802. PU WORK	
PLUG. SET 2ND CIBP @ 2760 & SPOT 35 FT CMT	
1320 W/ 35 FT CMT PLUG ON CIBP. PERF AT 520	
OPERATIONS TO P&A WELL WILL BEGIN IMMI	EDIATELY FOLLOWING
APPROVAL.	
	SEE ATTACHED CONDITIONS OF APPROVAL
4" diameter 4' tall Above Ground Marker	
Spud Date: Rig Release Date:	
I hereby certify that the information above is true and complete to the best of	my knowledge and belief.
SIGNATURE MRP TITLE OPERAT	TONS MANAGER DATE 8-31-21
Type or print name <u>MATTHEW PATTERSON</u> E-mail address:MPA	
For State Use Only	I LENSON@NAMENERGI.NE I PHONE: 210-747-0301
APPROVED BY: Xerry Forther TITLE Compliance	

WELLBORE DIAGRAM WEST DOLLARHIDE QUEEN SAND UNIT #075 CURRENT

		,	JU U_		
Surface of Size: Wt.: Depth: Sxs Cmt: Circulate: TOC: Hole Size:	Casing 8 5/8" 24# 416' 250 yes surface 12-1/4"				
	_				
Formatio	-				
T. Salt B. Salt	1230'				
D. Salt	<u>2522'</u>				
Production	_				
Size:	<u>5-1/2"</u>				
Wt.:	<u>15.5#</u>				
Depth: Sxs Cmt:	3950' 1025				
Circulate:	<u>1023</u> <u>yes</u>				
TOC:	<u>surface</u>				
Hole Size:	7-7/8"				
				PERFS	3680'-3802'

WELLBORE DIAGRAM WEST DOLLARHIDE QUEEN SAND UNIT #075 PROPOSED



CONDITIONS OF APPROVAL FOR PLUGGING AND ABANDONMENT OCD - Southern District

The following is a guide or checklist in preparation of a plugging program, this is not all inclusive and care must be exercised in establishing special plugging programs in unique and unusual cases, Notify NMOCD District Office I (Hobbs) at (575)-263-6633 at least 24 hours before beginning work. After MIRU rig will remain on well until it is plugged to surface. OCD is to be notified before rig down.

Company representative will be on location during plugging procedures.

- **1.** A notice of intent to plug and abandon a wellbore is required to be approved before plugging operations are conducted. A cement evaluation tool is required in order to ensure isolation of producing formations, protection of water and correlative rights. A cement bond log or other accepted cement evaluation tool is to be provided to the division for evaluation if one has not been previously run or if the well did not have cement circulated to surface during the original casing cementing job or subsequent cementing jobs. Insure all bradenheads have been exposed, identified and valves are operational prior to rig up.
- **2.** Closed loop system is to be used for entire plugging operation. Upon completion, contents of steel pits are to be hauled to a permitted disposal location.
- **3.** Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private- shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator as well as the contractor, to verify that this permit is in place prior to performing work. Drivers shall be able to produce a copy upon request of an NMOCD Field inspector.
- 4. Filing a subsequent C-103 will serve as notification that the well has been plugged.
- **5.** A final C-103 shall be filed (and a site inspection by NMOCD Inspector to determine if the location is satisfactorily cleaned, all equipment, electric poles and trash has been removed to Meet NMOCD standards) before bonding can +be released.
- **6.** If work has not begun within 1 Year of the approval of this procedure, an extension request must be file stating the reason the well has not been plugged.
- 7. Squeeze pressures are not to exceed 500 psi, unless approval is given by NMOCD.
- **8.** Produced water will not be used during any part of the plugging operation.
- 9. Mud laden fluids must be placed between all cement plugs mixed at 25 sacks per 100 bbls of water.
- **10.** All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater. 50' of calculated cement excess required for inside casing plugs and 100% calculated cement excess required on outside casing plugs.
- 11. Class 'C' cement will be used above 7500 feet.
- 12. Class 'H' cement will be used below 7500 feet.
- **13.** A cement plug is required to be set 50' above and 50' below, casing stubs, DV tools, attempted casing cut offs, cement tops outside casing, salt sections and anywhere the casing is perforated, these plugs require a 4 hour WOC and then will be tagged
- **14.** All Casing Shoes Will Be Perforated 50' below shoe depth and Attempted to be Squeezed, cement needs to be 50' above and 50' Below Casing Shoe inside the Production Casing.
- **16.** When setting the top out cement plug in production, intermediate and surface casing, wellbores should remain full at least 30 minutes after plugs are set
- 17. A CIBP is to be set within 100' of production perforations, capped with 100' of cement, WOC 4 hours and tag.
- **18.** A CIBP with 35' of cement may be used in lieu of the 100' plug if set with a bailer. This plug will be placed within 100' of the top perforation, (WOC 4 hrs and tag).

- 19. No more than 3000' is allowed between cement plugs in cased hole and 2000' in open hole.
- 20. Some of the Formations to be isolated with cement plugs are: These plugs to be set to isolate formation tops
- A) Fusselman
- B) Devonian
- C) Morrow
- D) Wolfcamp
- E) Bone Springs
- F) Delaware
- G) Any salt sections
- H) Abo
- I) Glorieta
- J) Yates.
- K) Potash---(In the R-111-P Area (Potash Mine Area),

A solid cement plug must be set across the salt section. Fluid used to mix the cement shall be saturated with the salts that are common to the section penetrated and in suitable proportions, not more than 3% calcium chloride (by weight of cement) will be considered the desired mixture whenever possible, WOC 4 hours and tag, this plug will be 50' below the bottom and 50' above the top of the Formation.

21. If cement does not exist behind casing strings at recommended formation depths, the casing can be cut and pulled with plugs set at recommended depths. If casing is not pulled, perforations will be shot and cement squeezed behind casing, WOC and tagged. These plugs will be set 50' below formation bottom to 50' above formation top inside the casing.

DRY HOLE MARKER REQ.UIRMENTS

The operator shall mark the exact location of the plugged and abandoned well with a steel marker not less than four inches in diameter, 3' below ground level with a plate of at least ¼" welded to the top of the casing and the dry hole marker welded on the plate with the following information welded on the dry hole marker:

- 1. Operator name
- 2. Lease and Well Number
- 3. API Number
- 4. Unit letter
- 5. Quarter Section (feet from the North, South, East or West)
- 6. Section, Township and Range
- 7. Plugging Date
- 8. County

SPECIAL CASES ----AGRICULTURE OR PRARIE CHICKEN BREEDING AREAS

In these areas, a below ground marker is required with all pertinent information mentioned above on a plate, set 3' below ground level, a picture of the plate will be supplied to NMOCD for record, the exact location of the marker (longitude and latitude by GPS) will be provided to NMOCD (We typically require a current survey to verify the GPS)

SITE REMEDIATION DUE WITHIN ONE YEAR OF WELL PLUGGING COMPLETION

(7-31-87) (4 HOLES)_ ₹ 3700-02' (BHOLES)____ < 37/9-23' 1 LOWER QUEEN (6 HOLES) 3750-53' (7-28-87)

(8 HOLCS) 3798-3802'

TD 3950'

9 JOINTS 2 7/8" 10V TEG. BIN'X IOV CHANGLOVER 1.10' SEATING NIPPLE - BO TOM € 3827.82 4.10' PERF. 30B 29.60' MUD JOINT - BOTTOM @ 3861.52'

2' 7/8" 508 4' 7/8" SUB 39 7/8" RODS 2' 3/4" SUB 107 3/4" RODS 107 314" RODS 10 7/8" RODS 21/2" x 2" x 16' KWBC PUMP

5/2" LTC 15.5# SET AT 3950' CMT 800 5x HALL. LITE + 200 SX CLASS C CIRC 260 SX TO PIT

LEASE NAME AND WELL NO.: WDQSU # 30-75 STATE: N.M. COUNTY: LEA BLOCK: SECTION: 30


TOWNSHIP: 24-5 RANGE: 38-E LEGAL DESCRIPTION: 2300' F5L 1450' FEL OPERATOR: Sirgo - Course Two WORKING INTEREST: ROYALTY INTEREST: TOTAL DEPTH: 3950' PBTD: — GROUND LEVEL: 3/65' KB: 3/76.5' COMPLETION: 7-29-87 QUEEN CURRENT STATUS: PRODUCING REMARKS: 7-3/-87

12-12.87

WELLBORE DIAGRAM WEST DOLLARHIDE QUEEN SAND UNIT #075 CURRENT

		 AT 1. 30-02	.5-23364	
Surface Size: Wt.: Depth: Sxs Cmt: Circulate: TOC: Hole Size:	Casing 8 5/8" 24# 416' 250 yes surface 12-1/4"			
Formation T. Salt B. Salt	on Tops <u>1230'</u> <u>2522'</u>			
Production Size: Wt.: Depth: Sxs Cmt: Circulate: TOC: Hole Size:	on Casing 5-1/2" 15.5# 3950' 1025 yes surface 7-7/8"			
			PERFS	3680'-3802

WELLBORE DIAGRAM WEST DOLLARHIDE QUEEN SAND UNIT #075 PROPOSED



District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 45855

CONDITIONS

	CODID
Operator:	OGRID:
RAM ENERGY LLC	309777
	Action Number:
Tulsa, OK 74135	45855
	Action Type:
	[C-103] NOI Plug & Abandon (C-103F)

CONDITIONS

Created By	Condition	Condition Date
kfortner	See attached conditions of approval Note changes to procedure	9/3/2021