Office	1.9:45:42 AM	State of New Mexico			Form C-103 ¹
<u>District I</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NN	C C	gy, Minerals and Natural Res	sources	WELL API NO.	rised July 18, 2013
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88	OIL	CONSERVATION DIVIS	SION	<u>30-025-</u>	-12275
<u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM		1220 South St. Francis Dr.		5. Indicate Type of Lease STATE F	EE X
District IV - (505) 476-3460		Santa Fe, NM 87505		6. State Oil & Gas Lease N	lo.
1220 S. St. Francis Dr., Santa Fe 87505				313857	
		REPORTS ON WELLS LL OR TO DEEPEN OR PLUG BACK		7. Lease Name or Unit Age	reement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH				WEST DOLLARHIDE QUEEN	I SANDS UNIT
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other INJECTION				8. Well Number 25	
2. Name of Operator RAM ENERGY LLC				9. OGRID Number 30977	7
3. Address of Operator				10. Pool name or Wildcat	<u>.</u>
2100 S UTICA AV	E., SUITE #175, T	CULSA, OK 74114		1881	10
4. Well Location					r
Unit Letter A			ine and <u>66</u>		
Section 31		Township 24SRange3tion (Show whether DR, RKB, F		NMPM County	LEA
		3154 KB	(1, 01, 01, 00)		
12.	Check Appropriat	e Box to Indicate Nature of	of Notice, R	leport or Other Data	
NOTICE	E OF INTENTION	N TO:	SUBS	EQUENT REPORT	OF:
PERFORM REMEDIAL W	VORK 🗌 🛛 PLUG AN	ID ABANDON 🛛 🛛 REME	EDIAL WORK		
TEMPORARILY ABANDO					
PULL OR ALTER CASING			NG/CEMENT	JOB 🗌	
CLOSED-LOOP SYSTEM					
OTHER:		OTHE		• .• .• .• • •	
10 D ''	1 1.1				
		ions. (Clearly state all pertinen ULE 19 15 7 14 NMAC For M			
of starting any pro		ions. (Clearly state all pertinen ULE 19.15.7.14 NMAC. For N			
of starting any pro proposed complet	pposed work). SEE R ion or recompletion.	ULE 19.15.7.14 NMAC. For M	Multiple Com	pletions: Attach wellbore d	
of starting any pro proposed complet MIRU P&A	oposed work). SEE R ion or recompletion. UNIT. POOH W/ EX	ULE 19.15.7.14 NMAC. For M	Multiple Com	pletions: Attach wellbore d	
of starting any pro proposed complet MIRU P&A OVER EXIS	oposed work). SEE R ion or recompletion. UNIT. POOH W/ EX STING PERFS @ 365:	ULE 19.15.7.14 NMAC. For M ISTING STRING. RU EWL & 5 - 3759. PU WORKSTRING &	Multiple Com SET CIBP @ & SPOT	pletions: Attach wellbore d	
of starting any pro proposed complet MIRU P&A OVER EXIS 35 FT CMT	oposed work). SEE R ion or recompletion. UNIT. POOH W/ EX STING PERFS @ 365: PLUG. SET 2ND CIE	ULE 19.15.7.14 NMAC. For M	Multiple Com SET CIBP @ & SPOT T PLUG ON	pletions: Attach wellbore d) 3555 CIBP. SET 3RD	
of starting any pro proposed complet MIRU P&A OVER EXIS 35 FT CMT CIBP @ 132 OPERATIO	oposed work). SEE R ion or recompletion. UNIT. POOH W/ EX STING PERFS @ 365: PLUG. SET 2ND CIE 0 W/ 35 FT CMT PLU NS	ULE 19.15.7.14 NMAC. For M ISTING STRING. RU EWL & 5 - 3759. PU WORKSTRING & 3P @ 2760 & SPOT 35 FT CM UG ON CIBP. PERF AT 520 &	Multiple Com SET CIBP @ & SPOT T PLUG ON CIRC CMT	pletions: Attach wellbore d) 3555 CIBP. SET 3RD TO SFC.	
of starting any pro proposed complet MIRU P&A OVER EXIS 35 FT CMT CIBP @ 132 OPERATIO	oposed work). SEE R ion or recompletion. UNIT. POOH W/ EX STING PERFS @ 365: PLUG. SET 2ND CIE 0 W/ 35 FT CMT PLU NS	ULE 19.15.7.14 NMAC. For M SISTING STRING. RU EWL & 5 - 3759. PU WORKSTRING & 3P @ 2760 & SPOT 35 FT CM	Multiple Com SET CIBP @ & SPOT T PLUG ON CIRC CMT	pletions: Attach wellbore d) 3555 CIBP. SET 3RD TO SFC.	
of starting any pro proposed complet MIRU P&A OVER EXIS 35 FT CMT CIBP @ 132 OPERATIO TO P&A WE	oposed work). SEE R tion or recompletion. UNIT. POOH W/ EX STING PERFS @ 365: PLUG. SET 2ND CIE 20 W/ 35 FT CMT PLU NS ELL WILL BEGIN IN	ULE 19.15.7.14 NMAC. For M SISTING STRING. RU EWL & 5 - 3759. PU WORKSTRING & 3P @ 2760 & SPOT 35 FT CM UG ON CIBP. PERF AT 520 & MMEDIATELY FOLLOWING	Multiple Com SET CIBP @ & SPOT T PLUG ON CIRC CMT	pletions: Attach wellbore d) 3555 CIBP. SET 3RD TO SFC.	
of starting any pro proposed complet MIRU P&A OVER EXIS 35 FT CMT CIBP @ 132 OPERATIO TO P&A WE	oposed work). SEE R ion or recompletion. UNIT. POOH W/ EX STING PERFS @ 365: PLUG. SET 2ND CIE 0 W/ 35 FT CMT PLU NS	ULE 19.15.7.14 NMAC. For M SISTING STRING. RU EWL & 5 - 3759. PU WORKSTRING & 3P @ 2760 & SPOT 35 FT CM UG ON CIBP. PERF AT 520 & MMEDIATELY FOLLOWING	Multiple Com SET CIBP @ & SPOT T PLUG ON CIRC CMT	pletions: Attach wellbore d) 3555 CIBP. SET 3RD TO SFC.	
of starting any pro proposed complet MIRU P&A OVER EXIS 35 FT CMT CIBP @ 132 OPERATIOI TO P&A WH	oposed work). SEE R tion or recompletion. UNIT. POOH W/ EX STING PERFS @ 365: PLUG. SET 2ND CIE 20 W/ 35 FT CMT PLU NS ELL WILL BEGIN IN	ULE 19.15.7.14 NMAC. For M SISTING STRING. RU EWL & 5 - 3759. PU WORKSTRING & 3P @ 2760 & SPOT 35 FT CM UG ON CIBP. PERF AT 520 & MMEDIATELY FOLLOWING	Multiple Com SET CIBP @ SPOT T PLUG ON CIRC CMT APPROVAL	pletions: Attach wellbore d) 3555 CIBP. SET 3RD TO SFC. 	
of starting any pro proposed complet MIRU P&A OVER EXIS 35 FT CMT CIBP @ 132 OPERATIO TO P&A WE	oposed work). SEE R tion or recompletion. UNIT. POOH W/ EX STING PERFS @ 365: PLUG. SET 2ND CIE 20 W/ 35 FT CMT PLU NS ELL WILL BEGIN IN	ULE 19.15.7.14 NMAC. For M SISTING STRING. RU EWL & 5 - 3759. PU WORKSTRING & 3P @ 2760 & SPOT 35 FT CM UG ON CIBP. PERF AT 520 & MMEDIATELY FOLLOWING	Multiple Com SET CIBP @ SPOT T PLUG ON CIRC CMT APPROVAL	pletions: Attach wellbore d) 3555 CIBP. SET 3RD TO SFC. 	
of starting any pro proposed complet MIRU P&A OVER EXIS 35 FT CMT CIBP @ 132 OPERATIO TO P&A WH 4" diameter 4' ta	oposed work). SEE R tion or recompletion. UNIT. POOH W/ EX STING PERFS @ 365: PLUG. SET 2ND CIE 20 W/ 35 FT CMT PLU NS ELL WILL BEGIN IN	ULE 19.15.7.14 NMAC. For M SISTING STRING. RU EWL & 5 - 3759. PU WORKSTRING & 3P @ 2760 & SPOT 35 FT CM UG ON CIBP. PERF AT 520 & MMEDIATELY FOLLOWING Marker	Multiple Com SET CIBP @ SPOT T PLUG ON CIRC CMT APPROVAL	pletions: Attach wellbore d) 3555 CIBP. SET 3RD TO SFC. 	
of starting any pro proposed complet MIRU P&A OVER EXIS 35 FT CMT CIBP @ 132 OPERATIO TO P&A WE 4" diameter 4' ta	oposed work). SEE R tion or recompletion. UNIT. POOH W/ EX STING PERFS @ 365: PLUG. SET 2ND CIE 20 W/ 35 FT CMT PLU NS ELL WILL BEGIN IN	ULE 19.15.7.14 NMAC. For M SISTING STRING. RU EWL & 5 - 3759. PU WORKSTRING & 3P @ 2760 & SPOT 35 FT CM UG ON CIBP. PERF AT 520 & MMEDIATELY FOLLOWING	Multiple Com SET CIBP @ SPOT T PLUG ON CIRC CMT APPROVAL	pletions: Attach wellbore d) 3555 CIBP. SET 3RD TO SFC. 	
of starting any pro proposed complet MIRU P&A OVER EXIS 35 FT CMT CIBP @ 132 OPERATIO TO P&A WE 4" diameter 4' ta	oposed work). SEE R tion or recompletion. UNIT. POOH W/ EX STING PERFS @ 365: PLUG. SET 2ND CIE 20 W/ 35 FT CMT PLU NS ELL WILL BEGIN IN	ULE 19.15.7.14 NMAC. For M SISTING STRING. RU EWL & 5 - 3759. PU WORKSTRING & 3P @ 2760 & SPOT 35 FT CM UG ON CIBP. PERF AT 520 & MMEDIATELY FOLLOWING Marker	Multiple Com SET CIBP @ SPOT T PLUG ON CIRC CMT APPROVAL	pletions: Attach wellbore d) 3555 CIBP. SET 3RD TO SFC. 	
of starting any proposed complet MIRU P&A OVER EXIS 35 FT CMT CIBP @ 132 OPERATION TO P&A WH 4" diameter 4' ta Spud Date:	oposed work). SEE R ion or recompletion. UNIT. POOH W/ EX STING PERFS @ 365: PLUG. SET 2ND CIE 0 W/ 35 FT CMT PLU NS ELL WILL BEGIN IN I I Above Ground I	ULE 19.15.7.14 NMAC. For M SISTING STRING. RU EWL & 5 - 3759. PU WORKSTRING & 3P @ 2760 & SPOT 35 FT CM UG ON CIBP. PERF AT 520 & MMEDIATELY FOLLOWING Marker	Multiple Com SET CIBP @ SPOT T PLUG ON CIRC CMT APPROVAL	pletions: Attach wellbore d) 3555 CIBP. SET 3RD TO SFC. CHED CONDITIONS DVAL	
of starting any proposed complet MIRU P&A OVER EXIS 35 FT CMT CIBP @ 132 OPERATION TO P&A WH 4" diameter 4' ta Spud Date:	oposed work). SEE R ion or recompletion. UNIT. POOH W/ EX STING PERFS @ 365: PLUG. SET 2ND CIE 0 W/ 35 FT CMT PLU NS ELL WILL BEGIN IN I I Above Ground I	ULE 19.15.7.14 NMAC. For M ISTING STRING. RU EWL & 5 - 3759. PU WORKSTRING & 3P @ 2760 & SPOT 35 FT CM UG ON CIBP. PERF AT 520 & MMEDIATELY FOLLOWING Marker Rig Release Date:	Multiple Com SET CIBP @ SPOT T PLUG ON CIRC CMT APPROVAL	pletions: Attach wellbore d) 3555 CIBP. SET 3RD TO SFC. CHED CONDITIONS DVAL	
of starting any proposed complet MIRU P&A OVER EXIS 35 FT CMT CIBP @ 132 OPERATION TO P&A WH 4" diameter 4' ta Spud Date:	oposed work). SEE R ion or recompletion. UNIT. POOH W/ EX STING PERFS @ 365: PLUG. SET 2ND CIE 0 W/ 35 FT CMT PLU NS ELL WILL BEGIN IN I I Above Ground I	ULE 19.15.7.14 NMAC. For M ISTING STRING. RU EWL & 5 - 3759. PU WORKSTRING & 3P @ 2760 & SPOT 35 FT CM UG ON CIBP. PERF AT 520 & MMEDIATELY FOLLOWING Marker Rig Release Date:	Multiple Com SET CIBP @ SPOT T PLUG ON CIRC CMT APPROVAL SEE ATTA OF APPRO	pletions: Attach wellbore d) 3555 CIBP. SET 3RD TO SFC. CHED CONDITIONS DVAL and belief.	
of starting any proposed complet MIRU P&A OVER EXIS 35 FT CMT CIBP @ 132 OPERATION TO P&A WH 4" diameter 4' ta Spud Date: I hereby certify that the inf SIGNATURE Type or print name MAT For State Use Only	oposed work). SEE R ion or recompletion. UNIT. POOH W/ EX STING PERFS @ 365: PLUG. SET 2ND CIE 0 W/ 35 FT CMT PLU NS ELL WILL BEGIN IN II Above Ground I	ULE 19.15.7.14 NMAC. For N CISTING STRING. RU EWL & 5 - 3759. PU WORKSTRING & 3P @ 2760 & SPOT 35 FT CM UG ON CIBP. PERF AT 520 & MMEDIATELY FOLLOWING Marker Rig Release Date: e and complete to the best of m 	Multiple Com SET CIBP @ SPOT T PLUG ON CIRC CMT APPROVAL SEE ATTA OF APPRO y knowledge DNS MANA	pletions: Attach wellbore d 3555 CIBP. SET 3RD TO SFC CHED CONDITIONS DVAL and belief. AGER DATE 9/1	2/21
of starting any proposed complet MIRU P&A OVER EXIS 35 FT CMT CIBP @ 132 OPERATION TO P&A WH 4" diameter 4' ta Spud Date: I hereby certify that the inf SIGNATURE Type or print name MAT For State Use Only	oposed work). SEE R ion or recompletion. UNIT. POOH W/ EX STING PERFS @ 365: PLUG. SET 2ND CIE 0 W/ 35 FT CMT PLU NS ELL WILL BEGIN IN II Above Ground I	ULE 19.15.7.14 NMAC. For M CISTING STRING. RU EWL & 5 - 3759. PU WORKSTRING & 3P @ 2760 & SPOT 35 FT CM UG ON CIBP. PERF AT 520 & MMEDIATELY FOLLOWING Marker Rig Release Date: e and complete to the best of m 	Multiple Com SET CIBP @ SPOT T PLUG ON CIRC CMT APPROVAL SEE ATTA OF APPRO y knowledge DNS MANA	pletions: Attach wellbore d 3555 CIBP. SET 3RD TO SFC CHED CONDITIONS DVAL and belief. AGER DATE 9/1	2/21 8-947-6301

	WELLBORE DIAGRAM WEST DOLLARHIDE QUEEN SAND UNIT #25 CURRENT API: 30-025-12275	
Surface CasingSize:9-5/8"Wt.:36#Depth:209'Sxs Cmt:175Circulate:yesTOC:surfaceHole Size:13-3/4"		
Formation Tops T. Salt <u>1230'</u> B. Salt <u>2522'</u>		
Intermediate Casing Size: <u>7"</u> Wt.: <u>20#</u> Depth: <u>3655'</u> Sxs Cmt: <u>650</u> Circulate: <u>yes</u> TOC: <u>surface</u> Hole Size: <u>8-3/4"</u>		
Production Casing Size: 4-1/2" Wt.: 10.5# Depth: 3890' Sxs Cmt: 500 Circulate: yes		2" Casing Shoe 3890' 5'-3759'

<u>surface</u>

<u>6-1/8"</u>

TOC:

WELLBORE DIAGRAM WEST DOLLARHIDE QUEEN SAND UNIT #25 PROPOSED API: 30-025-12275 Surface Casing Size: <u>9-5/8"</u> <u>36#</u> Wt.: Depth: 209' Sxs Cmt: 175 Circulate: <u>yes</u> TOC: surface Cement from 520' to surface Hole Size: <u>13-3/4"</u> 520' PERF MLF **Formation Tops** T. Salt 35' Cement Plug <u>1230'</u> CMT B. Salt 2522' 1320' CIBP MLF **Intermediate Casing** <u>7"</u> Cement Plug Size: CMT 35' Wt.: 20# 2760' CIBP 3655' Depth: Sxs Cmt: <u>650</u> Circulate: MLF yes TOC: surface Hole Size: 8-3/4" Cement Plug CMT 35' 3555' CIBP **Production Casing** Size: 4-1/2" PERFS 3655'-3759' Wt.: <u>10.5#</u> 3890' Depth: Sxs Cmt: <u>500</u> Circulate: <u>yes</u>

surface

6-1/8"

TOC:

CONDITIONS OF APPROVAL FOR PLUGGING AND ABANDONMENT OCD - Southern District

The following is a guide or checklist in preparation of a plugging program, this is not all inclusive and care must be exercised in establishing special plugging programs in unique and unusual cases, Notify NMOCD District Office I (Hobbs) at (575)-263-6633 at least 24 hours before beginning work. After MIRU rig will remain on well until it is plugged to surface. OCD is to be notified before rig down.

Company representative will be on location during plugging procedures.

1. A notice of intent to plug and abandon a wellbore is required to be approved before plugging operations are conducted. A cement evaluation tool is required in order to ensure isolation of producing formations, protection of water and correlative rights. A cement bond log or other accepted cement evaluation tool is to be provided to the division for evaluation if one has not been previously run or if the well did not have cement circulated to surface during the original casing cementing job or subsequent cementing jobs. Insure all bradenheads have been exposed, identified and valves are operational prior to rig up.

2. Closed loop system is to be used for entire plugging operation. Upon completion, contents of steel pits are to be hauled to a permitted disposal location.

3. Trucking companies being used to haul oilfield waste fluids to a disposal - commercial or private- shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator as well as the contractor, to verify that this permit is in place prior to performing work. Drivers shall be able to produce a copy upon request of an NMOCD Field inspector.

4. Filing a subsequent C-103 will serve as notification that the well has been plugged.

5. A final C-103 shall be filed (and a site inspection by NMOCD Inspector to determine if the location is satisfactorily cleaned, all equipment, electric poles and trash has been removed to Meet NMOCD standards) before bonding can +be released.

6. If work has not begun within 1 Year of the approval of this procedure, an extension request must be file stating the reason the well has not been plugged.

7. Squeeze pressures are not to exceed 500 psi, unless approval is given by NMOCD.

8. Produced water will not be used during any part of the plugging operation.

9. Mud laden fluids must be placed between all cement plugs mixed at 25 sacks per 100 bbls of water.

10. All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater. 50' of calculated cement excess required for inside casing plugs and 100% calculated cement excess required on outside casing plugs.

11. Class 'C' cement will be used above 7500 feet.

12. Class 'H' cement will be used below 7500 feet.

13. A cement plug is required to be set 50' above and 50' below, casing stubs, DV tools, attempted casing cut offs, cement tops outside casing, salt sections and anywhere the casing is perforated, these plugs require a 4 hour WOC and then will be tagged

14. All Casing Shoes Will Be Perforated 50' below shoe depth and Attempted to be Squeezed, cement needs to be 50' above and 50' Below Casing Shoe inside the Production Casing.

16. When setting the top out cement plug in production, intermediate and surface casing, wellbores should remain full at least 30 minutes after plugs are set

17. A CIBP is to be set within 100' of production perforations, capped with 100' of cement, WOC 4 hours and tag.

18. A CIBP with 35' of cement may be used in lieu of the 100' plug if set with a bailer. This plug will be placed within 100' of the top perforation, (WOC 4 hrs and tag).

19. No more than 3000' is allowed between cement plugs in cased hole and 2000' in open hole.

20. Some of the Formations to be isolated with cement plugs are: These plugs to be set to isolate formation tops

- A) Fusselman
- B) Devonian
- C) Morrow
- D) Wolfcamp
- E) Bone Springs
- F) Delaware
- G) Any salt sections
- H) Abo
- I) Glorieta
- J) Yates.

K) Potash---(In the R-111-P Area (Potash Mine Area),

A solid cement plug must be set across the salt section. Fluid used to mix the cement shall be saturated with the salts that are common to the section penetrated and in suitable proportions, not more than 3% calcium chloride (by weight of cement) will be considered the desired mixture whenever possible, WOC 4 hours and tag, this plug will be 50' below the bottom and 50' above the top of the Formation.

21. If cement does not exist behind casing strings at recommended formation depths, the casing can be cut and pulled with plugs set at recommended depths. If casing is not pulled, perforations will be shot and cement squeezed behind casing, WOC and tagged. These plugs will be set 50' below formation bottom to 50' above formation top inside the casing.

DRY HOLE MARKER REQ.UIRMENTS

The operator shall mark the exact location of the plugged and abandoned well with a steel marker not less than four inches in diameter, 3' below ground level with a plate of at least ¼" welded to the top of the casing and the dry hole marker welded on the plate with the following information welded on the dry hole marker:

- 1. Operator name
- 2. Lease and Well Number
- 3. API Number
- 4. Unit letter
- 5. Quarter Section (feet from the North, South, East or West)
- 6. Section, Township and Range
- 7. Plugging Date
- 8. County

SPECIAL CASES -----AGRICULTURE OR PRARIE CHICKEN BREEDING AREAS

In these areas, a below ground marker is required with all pertinent information mentioned above on a plate, set 3' below ground level, a picture of the plate will be supplied to NMOCD for record, the exact location of the marker (longitude and latitude by GPS) will be provided to NMOCD (We typically require a current survey to verify the GPS)

SITE REMEDIATION DUE WITHIN ONE YEAR OF WELL PLUGGING COMPLETION

eceined by Ocp : 2/13/2021 Site	State of New Me	exico		Form C-1036 of
Office <u>District I</u> – (575) 393-6161	Energy, Minerals and Natu	Iral Resources	Revis WELL API NO.	ed July 18, 2013
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283		DRUGION	WELL API NO. 30-025-1	2275
811 S. First St., Artesia, NM 88210 District III – (505) 334-6178	OIL CONSERVATION 1220 South St. Fra		5. Indicate Type of Lease	
1000 Rio Brazos Rd., Aztec, NM 8741			6. State Oil & Gas Lease No	44
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM		1303	313857	
87505 SUNDRY N	OTICES AND REPORTS ON WELLS	1	7. Lease Name or Unit Agre	ement Name
(DO NOT USE THIS FORM FOR PRO DIFFERENT RESERVOIR. USE "AF	OPOSALS TO DRILL OR TO DEEPEN OR PLI PLICATION FOR PERMIT" (FORM C-101) FO	UG BACK TO A	WEST DOLLARHIDE QUEEN	
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other INJECTION			8. Well Number 25	
2 Name of Operator	ENERGY LLC		9. OGRID Number 309777	
3. Address of Operator			10. Pool name or Wildcat	
	UITE #175, TULSA, OK 74114		18810)
4. Well Location				1.
Unit Letter A	: <u>660</u> feet from the <u>E</u> Township 24S Ra			line
Section 31	11. Elevation (Show whether DR	ange <u>38E</u> RKB RT GR etc	NMPM County	LEA
	3154			
12. Chec	ek Appropriate Box to Indicate N	lature of Notice	, Report or Other Data	
NOTICE OF	INTENTION TO:	SUE	BSEQUENT REPORT O	F:
PERFORM REMEDIAL WORK		REMEDIAL WO		
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DF	RILLING OPNS. P AND A	
PULL OR ALTER CASING		CASING/CEMEN	NT JOB	
DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM				
OTHER:		OTHER:		
	ompleted operations. (Clearly state all j			
of starting any proposed proposed completion or	work). SEE RULE 19.15.7.14 NMAG	C. For Multiple Co	ompletions: Attach wellbore dia	igram of
proposed completion of	recompletion.			
	. POOH W/ EXISTING STRING. RU		P @ 3555	
	PERFS @ 3655 - 3759. PU WORKST		NI CIDD CET 1DD	
	3. SET 2ND CIBP @ 2760 & SPOT 35 35 FT CMT PLUG ON CIBP. PERF A			
OPERATIONS			10 51 6.	
TO P&A WELL V	VILL BEGIN IMMEDIATELY FOLLO	OWING APPROV	AL.	
Spud Date:	Rig Release Da	ate:		
I hereby certify that the informat	ion above is true and complete to the b	est of my knowled	ge and belief	
Thereby certify that the informat	ion above is true and complete to the b	est of my knowled	ge and benef.	
SIGNATURE M	PP	RATIONS MAI	NAGER DATE 9/12	/21
Type or print name MATTHE For State Use Only	W PATTERSON E-mail address	s:M <u>PATTERSON@</u> F	RAMENERGY.NET PHONE: 918	-947-6301
			N	
APPROVED BY: Conditions of Approval (if any):	TITLE		DATE	
conditions of Approval (if ally).				

	WELLBORE DIAGRAM WEST DOLLARHIDE QUEEN SAND UNIT #25 CURRENT API: 30-025-12275	
Surface CasingSize:9-5/8"Wt.:36#Depth:209'Sxs Cmt:175Circulate:yesTOC:surfaceHole Size:13-3/4"		
Formation Tops T. Salt <u>1230'</u> B. Salt <u>2522'</u>		
Intermediate Casing Size: <u>7"</u> Wt.: <u>20#</u> Depth: <u>3655'</u> Sxs Cmt: <u>650</u> Circulate: <u>yes</u> TOC: <u>surface</u> Hole Size: <u>8-3/4"</u>		
Production Casing Size: 4-1/2" Wt.: 10.5# Depth: 3890' Sxs Cmt: 500 Circulate: yes		' Casing Shoe 3890' -3759'

surface

<u>6-1/8"</u>

TOC:

WELLBORE DIAGRAM WEST DOLLARHIDE QUEEN SAND UNIT #25 PROPOSED API: 30-025-12275 Surface Casing Size: <u>9-5/8"</u> Wt.: <u>36#</u> Depth: 209' Sxs Cmt: 175 Circulate: <u>yes</u> TOC: surface Cement from 520' to surface Hole Size: <u>13-3/4"</u> 520' PERF MLF **Formation Tops** T. Salt 35' Cement Plug <u>1230'</u> CMT B. Salt 2522' 1320' CIBP MLF **Intermediate Casing** <u>7"</u> Cement Plug Size: CMT 35' Wt.: 20# 2760' CIBP 3655' Depth: Sxs Cmt: <u>650</u> Circulate: MLF yes TOC: surface Hole Size: 8-3/4" Cement Plug CMT 35' 3555' CIBP **Production Casing** Size: 4-1/2" PERFS 3655'-3759' Wt.: <u>10.5#</u> 3890' Depth: Sxs Cmt: <u>500</u> Circulate: <u>yes</u>

surface

6-1/8"

TOC:

District I 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV 1220 S. St Francis Dr., Santa Fe, NM 87505 Phone: (505) 476-3470 Fax: (505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Operator:	OGRID:
RAM ENERGY LLC	309777
5100 East Skelly Drive	Action Number:
Tulsa, OK 74135	47950
	Action Type:
	[C-103] NOI Plug & Abandon (C-103F)

CONDITIONS

Created By	Condition	Condition Date
kfortner	See attached conditions of approval	9/14/2021

CONDITIONS

Page 9 of 9

Action 47950