
	State of New Mexico	Form C-103		
Office <u>District I</u> – (575) 393-6161	Energy, Minerals and Natural Resources	Revised July 18, 2013		
1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1283		WELL API NO. 30-025-29964		
811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION	5. Indicate Type of Lease		
<u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.	STATE FEE X		
<u>District IV</u> – (505) 476-3460	Santa Fe, NM 87505	6. State Oil & Gas Lease No.		
1220 S. St. Francis Dr., Santa Fe, NM 87505		313857		
SUNDRY NOTIC	CES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name		
	ALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A ATION FOR PERMIT" (FORM C-101) FOR SUCH	WEST DOLLARHIDE QUEEN SANDS UNIT		
	Gas Well Other	8. Well Number 72		
2. Name of Operator		9. OGRID Number		
RAM ENER	RGY LLC	309777		
3. Address of Operator	10. Pool name or Wildcat			
4. Well Location	E., STE #175, TULSA, OK 74114	18810		
	150feet from theE line and	150 feet from the S line		
Section 30	Township 24S Range 38E	NMPM County LEA		
Section 30	11. Elevation (Show whether DR, RKB, RT, GR, etc.	, EEH		
	3166 KB	.,		
		_		
12. Check A	ppropriate Box to Indicate Nature of Notice	, Report or Other Data		
NOTICE OF INT	ENTION TO:	DEFOLIENT DEPORT OF:		
NOTICE OF INT PERFORM REMEDIAL WORK □	PLUG AND ABANDON TO REMEDIAL WOR	BSEQUENT REPORT OF: RK □ ALTERING CASING □		
TEMPORARILY ABANDON		RILLING OPNS. P AND A		
PULL OR ALTER CASING	MULTIPLE COMPL CASING/CEMEN			
DOWNHOLE COMMINGLE				
CLOSED-LOOP SYSTEM	CTUED:			
OTUED:				
OTHER: 13 Describe proposed or complete	eted operations (Clearly state all pertinent details at	nd give pertinent dates including estimated date		
13. Describe proposed or comple	eted operations. (Clearly state all pertinent details, an			
13. Describe proposed or comple	eted operations. (Clearly state all pertinent details, at k). SEE RULE 19.15.7.14 NMAC. For Multiple Co			
13. Describe proposed or comple of starting any proposed wor proposed completion or reco	eted operations. (Clearly state all pertinent details, and k). SEE RULE 19.15.7.14 NMAC. For Multiple Completion.	ompletions: Attach wellbore diagram of		
13. Describe proposed or comple of starting any proposed wor proposed completion or reco	eted operations. (Clearly state all pertinent details, and k). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. C. POOH W/ EXISTING STRING. RU EWL & SET	ompletions: Attach wellbore diagram of Circ MLF Pressure test csg		
13. Describe proposed or comple of starting any proposed wor proposed completion or reco MIRU P&A UNIT OVER EXISTING	eted operations. (Clearly state all pertinent details, and k). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. T. POOH W/ EXISTING STRING. RU EWL & SET & PERFS @ 3618 - 3784. PU WORKSTRING & SPO	ompletions: Attach wellbore diagram of CIBP @ 3518 OT Circ MLF Pressure test csg		
13. Describe proposed or complet of starting any proposed wor proposed completion or recompletion of the completion of t	eted operations. (Clearly state all pertinent details, and k). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. C. POOH W/ EXISTING STRING. RU EWL & SET	CIBP @ 3518 Circ MLF Pressure test csg OT UG ON CIBP. SET 3RD		
13. Describe proposed or completed of starting any proposed work proposed completion or recompleted with the starting of the starting over the starting over the starting over the starting over the starting of the starting over t	eted operations. (Clearly state all pertinent details, and k). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. 7. POOH W/ EXISTING STRING. RU EWL & SET PERFS @ 3618 - 3784. PU WORKSTRING & SPOT 35 FT CMT PLUCE.	Circ MLF Pressure test csg CIBP @ 3518 OT UG ON CIBP. SET 3RD C CMT TO SFC. OPERATIONS		
13. Describe proposed or completed of starting any proposed work proposed completion or recompleted with the starting of the starting over the starting over the starting over the starting over the starting of the starting over t	eted operations. (Clearly state all pertinent details, and k). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. T. POOH W/ EXISTING STRING. RU EWL & SET BY PERFS @ 3618 - 3784. PU WORKSTRING & SPOT. SET 2ND CIBP @ 2760 & SPOT. 35 FT CMT. PLUG. SET CMT. PLUG.	Circ MLF Pressure test csg CIBP @ 3518 OT UG ON CIBP. SET 3RD C CMT TO SFC. OPERATIONS		
13. Describe proposed or complet of starting any proposed wor proposed completion or recompletion of recomplet	eted operations. (Clearly state all pertinent details, and k). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. T. POOH W/ EXISTING STRING. RU EWL & SET BY PERFS @ 3618 - 3784. PU WORKSTRING & SPOT. SET 2ND CIBP @ 2760 & SPOT. 35 FT CMT. PLUG. SET CMT. PLUG. PLUG. SET CMT. PLUG. SET CMT. PLUG. SET CMT. PLUG.	Circ MLF Pressure test csg CIBP @ 3518 OT UG ON CIBP. SET 3RD C CMT TO SFC. OPERATIONS		
13. Describe proposed or complet of starting any proposed wor proposed completion or recompletion of recomplet	eted operations. (Clearly state all pertinent details, and k). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. T. POOH W/ EXISTING STRING. RU EWL & SET & PERFS @ 3618 - 3784. PU WORKSTRING & SPOT 35 FT CMT PLUG SET 2ND CIBP @ 2760 & SPOT 35 FT CMT PLUG SET CMT PLUG ON CIBP. PERF AT 520 & CIRCUILL BEGIN IMMEDIATELY FOLLOWING APPLADOVE Ground Marker	Circ MLF Pressure test csg CIBP @ 3518 OT UG ON CIBP. SET 3RD C CMT TO SFC. OPERATIONS		
13. Describe proposed or complet of starting any proposed wor proposed completion or recompletion of recomplet	eted operations. (Clearly state all pertinent details, and k). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. 7. POOH W/ EXISTING STRING. RU EWL & SET RERFS @ 3618 - 3784. PU WORKSTRING & SPOG. SET 2ND CIBP @ 2760 & SPOT 35 FT CMT PLUG SET CMT PLUG ON CIBP. PERF AT 520 & CIREVILL BEGIN IMMEDIATELY FOLLOWING APPLADOVE Ground Marker SEE	Circ MLF Pressure test csg CIBP @ 3518 OT UG ON CIBP. SET 3RD C CMT TO SFC. OPERATIONS ROVAL.		
13. Describe proposed or complet of starting any proposed wor proposed completion or recompletion of recomplet	eted operations. (Clearly state all pertinent details, and k). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. 7. POOH W/ EXISTING STRING. RU EWL & SET RERFS @ 3618 - 3784. PU WORKSTRING & SPOG. SET 2ND CIBP @ 2760 & SPOT 35 FT CMT PLUG SET CMT PLUG ON CIBP. PERF AT 520 & CIREVILL BEGIN IMMEDIATELY FOLLOWING APPLADOVE Ground Marker SEE	Circ MLF Pressure test csg CIBP @ 3518 OT UG ON CIBP. SET 3RD C CMT TO SFC. OPERATIONS ROVAL. ATTACHED CONDITIONS		
13. Describe proposed or complet of starting any proposed wor proposed completion or recompletion of recomplet	eted operations. (Clearly state all pertinent details, and k). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. 7. POOH W/ EXISTING STRING. RU EWL & SET RERFS @ 3618 - 3784. PU WORKSTRING & SPOG. SET 2ND CIBP @ 2760 & SPOT 35 FT CMT PLUG SET CMT PLUG ON CIBP. PERF AT 520 & CIREVILL BEGIN IMMEDIATELY FOLLOWING APPLADOVE Ground Marker SEE	Circ MLF Pressure test csg CIBP @ 3518 OT UG ON CIBP. SET 3RD C CMT TO SFC. OPERATIONS ROVAL. ATTACHED CONDITIONS		
13. Describe proposed or comple of starting any proposed wor proposed completion or reco MIRU P&A UNIT OVER EXISTING 35 FT CMT PLUC CIBP @ 1320 W/ TO P&A WELL V 4" diameter 4' tall A	eted operations. (Clearly state all pertinent details, and k). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. 7. POOH W/ EXISTING STRING. RU EWL & SET RERFS @ 3618 - 3784. PU WORKSTRING & SPOG. SET 2ND CIBP @ 2760 & SPOT 35 FT CMT PLUG SET CMT PLUG ON CIBP. PERF AT 520 & CIREVILL BEGIN IMMEDIATELY FOLLOWING APPLADOVE Ground Marker SEE	Circ MLF Pressure test csg CIBP @ 3518 OT UG ON CIBP. SET 3RD C CMT TO SFC. OPERATIONS ROVAL. ATTACHED CONDITIONS		
13. Describe proposed or complet of starting any proposed wor proposed completion or recompletion of recomplet	eted operations. (Clearly state all pertinent details, and k). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. 7. POOH W/ EXISTING STRING. RU EWL & SET & PERFS @ 3618 - 3784. PU WORKSTRING & SPOG. SET 2ND CIBP @ 2760 & SPOT 35 FT CMT PLUG 35 FT CMT PLUG ON CIBP. PERF AT 520 & CIRVILL BEGIN IMMEDIATELY FOLLOWING APPLADOVE BOOK SET OF A	Circ MLF Pressure test csg CIBP @ 3518 OT UG ON CIBP. SET 3RD C CMT TO SFC. OPERATIONS ROVAL. ATTACHED CONDITIONS		
13. Describe proposed or comple of starting any proposed wor proposed completion or reco MIRU P&A UNIT OVER EXISTING 35 FT CMT PLUC CIBP @ 1320 W/TO P&A WELL V 4" diameter 4' tall A	eted operations. (Clearly state all pertinent details, at k). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. 7. POOH W/ EXISTING STRING. RU EWL & SET & PERFS @ 3618 - 3784. PU WORKSTRING & SPOG. SET 2ND CIBP @ 2760 & SPOT 35 FT CMT PLUG 35 FT CMT PLUG ON CIBP. PERF AT 520 & CIRVILL BEGIN IMMEDIATELY FOLLOWING APPLOVED BOOK OF A Rig Release Date:	CIRP @ 3518 OT UG ON CIBP. SET 3RD C CMT TO SFC. OPERATIONS ROVAL. ATTACHED CONDITIONS PPROVAL		
13. Describe proposed or comple of starting any proposed wor proposed completion or reco MIRU P&A UNIT OVER EXISTING 35 FT CMT PLUC CIBP @ 1320 W/TO P&A WELL V 4" diameter 4' tall A	eted operations. (Clearly state all pertinent details, and k). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. 7. POOH W/ EXISTING STRING. RU EWL & SET & PERFS @ 3618 - 3784. PU WORKSTRING & SPOG. SET 2ND CIBP @ 2760 & SPOT 35 FT CMT PLUG 35 FT CMT PLUG ON CIBP. PERF AT 520 & CIRVILL BEGIN IMMEDIATELY FOLLOWING APPLADOVE BOOK SET OF A	CIRP @ 3518 OT UG ON CIBP. SET 3RD C CMT TO SFC. OPERATIONS ROVAL. ATTACHED CONDITIONS PPROVAL		
13. Describe proposed or comple of starting any proposed wor proposed completion or reco MIRU P&A UNIT OVER EXISTING 35 FT CMT PLUC CIBP @ 1320 W/TO P&A WELL V 4" diameter 4' tall A	eted operations. (Clearly state all pertinent details, at k). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. 7. POOH W/ EXISTING STRING. RU EWL & SET & PERFS @ 3618 - 3784. PU WORKSTRING & SPOG. SET 2ND CIBP @ 2760 & SPOT 35 FT CMT PLUG 35 FT CMT PLUG ON CIBP. PERF AT 520 & CIRVILL BEGIN IMMEDIATELY FOLLOWING APPLOVED BOOK OF A Rig Release Date:	CIRP @ 3518 OT UG ON CIBP. SET 3RD C CMT TO SFC. OPERATIONS ROVAL. ATTACHED CONDITIONS PPROVAL		
13. Describe proposed or complete of starting any proposed wor proposed completion or recomplete of starting any proposed wor proposed completion or recomplete of starting any proposed work proposed completion or recomplete of starting any proposed work	eted operations. (Clearly state all pertinent details, at k). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. 7. POOH W/ EXISTING STRING. RU EWL & SET & PERFS @ 3618 - 3784. PU WORKSTRING & SPOG. SET 2ND CIBP @ 2760 & SPOT 35 FT CMT PLUG 35 FT CMT PLUG ON CIBP. PERF AT 520 & CIRVILL BEGIN IMMEDIATELY FOLLOWING APPLOVED BOOK OF A Rig Release Date:	Circ MLF Pressure test csg CIBP @ 3518 OT UG ON CIBP. SET 3RD C CMT TO SFC. OPERATIONS ROVAL. ATTACHED CONDITIONS PPROVAL ge and belief.		
13. Describe proposed or complete of starting any proposed wor proposed completion or recomplete of starting any proposed wor proposed completion or recomplete of starting any proposed work proposed completion or recomplete of starting any proposed work	cted operations. (Clearly state all pertinent details, and k). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. C. POOH W/ EXISTING STRING. RU EWL & SET & PERFS @ 3618 - 3784. PU WORKSTRING & SPOT 35 FT CMT PLUS ON CIBP @ 2760 & SPOT 35 FT CMT PLUS ON CIBP. PERF AT 520 & CIREVILL BEGIN IMMEDIATELY FOLLOWING APPLADOVE Ground Marker SEE OF A Rig Release Date: Dove is true and complete to the best of my knowled. TITLE OPERATIONS MAN	Circ MLF Pressure test csg CIBP @ 3518 OT UG ON CIBP. SET 3RD C CMT TO SFC. OPERATIONS ROVAL. ATTACHED CONDITIONS PPROVAL ge and belief. JAGERDATE9/12/21		
13. Describe proposed or complete of starting any proposed wor proposed completion or recomplete of starting any proposed wor proposed completion or recomplete of starting any proposed work proposed completion or recomplete of starting any proposed work proposed work proposed complete or proposed work propose	cted operations. (Clearly state all pertinent details, and k). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. C. POOH W/ EXISTING STRING. RU EWL & SET & PERFS @ 3618 - 3784. PU WORKSTRING & SPOT 35 FT CMT PLUS ON CIBP @ 2760 & SPOT 35 FT CMT PLUS ON CIBP. PERF AT 520 & CIREVILL BEGIN IMMEDIATELY FOLLOWING APPLADOVE Ground Marker SEE OF A Rig Release Date: Dove is true and complete to the best of my knowled. TITLE OPERATIONS MAN	Circ MLF Pressure test csg CIBP @ 3518 OT UG ON CIBP. SET 3RD C CMT TO SFC. OPERATIONS ROVAL. ATTACHED CONDITIONS PPROVAL ge and belief.		
13. Describe proposed or complete of starting any proposed wor proposed completion or recomplete of starting any proposed wor proposed completion or recomplete of starting any proposed work proposed completion or recomplete of starting any proposed work	eted operations. (Clearly state all pertinent details, at k). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. C. POOH W/ EXISTING STRING. RU EWL & SET & PERFS @ 3618 - 3784. PU WORKSTRING & SPOG. SET 2ND CIBP @ 2760 & SPOT 35 FT CMT PLUG ON CIBP. PERF AT 520 & CIRWILL BEGIN IMMEDIATELY FOLLOWING APPLEDOVE Ground Marker SEE OF A Rig Release Date: Dove is true and complete to the best of my knowled. TITLE OPERATIONS MAN ATTERSON E-mail address: MPATTERSON@F	Circ MLF Pressure test csg CIBP @ 3518 OT UG ON CIBP. SET 3RD C CMT TO SFC. OPERATIONS ROVAL. ATTACHED CONDITIONS PPROVAL ge and belief. JAGERDATE9/12/21		
13. Describe proposed or complete of starting any proposed wor proposed completion or recomplete of starting any proposed wor proposed completion or recomplete of starting any proposed work proposed completion or recomplete of starting any proposed work proposed work proposed complete or proposed work propose	eted operations. (Clearly state all pertinent details, at k). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. C. POOH W/ EXISTING STRING. RU EWL & SET & PERFS @ 3618 - 3784. PU WORKSTRING & SPOG. SET 2ND CIBP @ 2760 & SPOT 35 FT CMT PLUG ON CIBP. PERF AT 520 & CIRWILL BEGIN IMMEDIATELY FOLLOWING APPLEDOVE Ground Marker SEE OF A Rig Release Date: Dove is true and complete to the best of my knowled. TITLE OPERATIONS MAN ATTERSON E-mail address: MPATTERSON@F	CIRC MLF Pressure test csg CIBP @ 3518 OT UG ON CIBP. SET 3RD C CMT TO SFC. OPERATIONS ROVAL. ATTACHED CONDITIONS PPROVAL ge and belief. JAGER DATE 9/12/21 AMENERGY.NET PHONE:918-947-6301		

WELLBORE DIAGRAM WEST DOLLARHIDE QUEEN SAND UNIT #72 CURRENT

Surface (Size: Wt.: Depth: Sxs Cmt: Circulate: TOC:	8 5/8" 24# 417' 250 yes surface				
Formatio T. Salt B. Salt	<u>, ·</u>				
Production Size: Wt.: Depth: Sxs Cmt: Circulate: TOC: Hole Size:	1 Casing 5-1/2" 15.5# 3867' 1100 yes surface 7-7/8"				
			PERFS	3618'-:	3784'

WELLBORE DIAGRAM WEST DOLLARHIDE QUEEN SAND UNIT #72 PROPOSED



CONDITIONS OF APPROVAL FOR PLUGGING AND ABANDONMENT OCD - Southern District

The following is a guide or checklist in preparation of a plugging program, this is not all inclusive and care must be exercised in establishing special plugging programs in unique and unusual cases, Notify NMOCD District Office I (Hobbs) at (575)-263-6633 at least 24 hours before beginning work. After MIRU rig will remain on well until it is plugged to surface. OCD is to be notified before rig down.

Company representative will be on location during plugging procedures.

- **1.** A notice of intent to plug and abandon a wellbore is required to be approved before plugging operations are conducted. A cement evaluation tool is required in order to ensure isolation of producing formations, protection of water and correlative rights. A cement bond log or other accepted cement evaluation tool is to be provided to the division for evaluation if one has not been previously run or if the well did not have cement circulated to surface during the original casing cementing job or subsequent cementing jobs. Insure all bradenheads have been exposed, identified and valves are operational prior to rig up.
- **2.** Closed loop system is to be used for entire plugging operation. Upon completion, contents of steel pits are to be hauled to a permitted disposal location.
- **3.** Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private- shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator as well as the contractor, to verify that this permit is in place prior to performing work. Drivers shall be able to produce a copy upon request of an NMOCD Field inspector.
- 4. Filing a subsequent C-103 will serve as notification that the well has been plugged.
- **5.** A final C-103 shall be filed (and a site inspection by NMOCD Inspector to determine if the location is satisfactorily cleaned, all equipment, electric poles and trash has been removed to Meet NMOCD standards) before bonding can +be released.
- **6.** If work has not begun within 1 Year of the approval of this procedure, an extension request must be file stating the reason the well has not been plugged.
- 7. Squeeze pressures are not to exceed 500 psi, unless approval is given by NMOCD.
- **8.** Produced water will not be used during any part of the plugging operation.
- 9. Mud laden fluids must be placed between all cement plugs mixed at 25 sacks per 100 bbls of water.
- **10.** All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater. 50' of calculated cement excess required for inside casing plugs and 100% calculated cement excess required on outside casing plugs.
- 11. Class 'C' cement will be used above 7500 feet.
- 12. Class 'H' cement will be used below 7500 feet.
- **13.** A cement plug is required to be set 50' above and 50' below, casing stubs, DV tools, attempted casing cut offs, cement tops outside casing, salt sections and anywhere the casing is perforated, these plugs require a 4 hour WOC and then will be tagged
- **14.** All Casing Shoes Will Be Perforated 50' below shoe depth and Attempted to be Squeezed, cement needs to be 50' above and 50' Below Casing Shoe inside the Production Casing.
- **16.** When setting the top out cement plug in production, intermediate and surface casing, wellbores should remain full at least 30 minutes after plugs are set
- 17. A CIBP is to be set within 100' of production perforations, capped with 100' of cement, WOC 4 hours and tag.
- **18.** A CIBP with 35' of cement may be used in lieu of the 100' plug if set with a bailer. This plug will be placed within 100' of the top perforation, (WOC 4 hrs and tag).

- 19. No more than 3000' is allowed between cement plugs in cased hole and 2000' in open hole.
- 20. Some of the Formations to be isolated with cement plugs are: These plugs to be set to isolate formation tops
- A) Fusselman
- B) Devonian
- C) Morrow
- D) Wolfcamp
- E) Bone Springs
- F) Delaware
- G) Any salt sections
- H) Abo
- I) Glorieta
- J) Yates.
- K) Potash---(In the R-111-P Area (Potash Mine Area),

A solid cement plug must be set across the salt section. Fluid used to mix the cement shall be saturated with the salts that are common to the section penetrated and in suitable proportions, not more than 3% calcium chloride (by weight of cement) will be considered the desired mixture whenever possible, WOC 4 hours and tag, this plug will be 50' below the bottom and 50' above the top of the Formation.

21. If cement does not exist behind casing strings at recommended formation depths, the casing can be cut and pulled with plugs set at recommended depths. If casing is not pulled, perforations will be shot and cement squeezed behind casing, WOC and tagged. These plugs will be set 50' below formation bottom to 50' above formation top inside the casing.

DRY HOLE MARKER REQ.UIRMENTS

The operator shall mark the exact location of the plugged and abandoned well with a steel marker not less than four inches in diameter, 3' below ground level with a plate of at least ¼" welded to the top of the casing and the dry hole marker welded on the plate with the following information welded on the dry hole marker:

- 1. Operator name
- 2. Lease and Well Number
- 3. API Number
- 4. Unit letter
- 5. Quarter Section (feet from the North, South, East or West)
- 6. Section, Township and Range
- 7. Plugging Date
- 8. County

SPECIAL CASES ----AGRICULTURE OR PRARIE CHICKEN BREEDING AREAS

In these areas, a below ground marker is required with all pertinent information mentioned above on a plate, set 3' below ground level, a picture of the plate will be supplied to NMOCD for record, the exact location of the marker (longitude and latitude by GPS) will be provided to NMOCD (We typically require a current survey to verify the GPS)


SITE REMEDIATION DUE WITHIN ONE YEAR OF WELL PLUGGING COMPLETION

cceined by Och; 2/13/2021 11:46:18 AN	State of New Mexico	Form C-1036 of 9		
Office <u>District I</u> – (575) 393-6161	Energy, Minerals and Natural Resources	Revised July 18, 2013		
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283		WELL API NO. 30-025-29964		
811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION	5. Indicate Type of Lease		
<u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.	STATE FEE X		
<u>District IV</u> – (505) 476-3460	Santa Fe, NM 87505	6. State Oil & Gas Lease No.		
1220 S. St. Francis Dr., Santa Fe, NM 87505	313857			
	AND REPORTS ON WELLS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name		
DIFFERENT RESERVOIR. USE "APPLICATION		WEST DOLLARHIDE QUEEN SANDS UNIT		
PROPOSALS.) 1. Type of Well: Oil Well X Gas	8. Well Number 72			
Name of Operator	9. OGRID Number			
RAM ENERGY	Y LLC	309777		
3. Address of Operator	10. Pool name or Wildcat 18810			
	2100 S UTICA AVE., STE #175, TULSA, OK 74114			
4. Well Location Unit Letter P: 150) feet from the <u>E</u> line and	150feet from theSline		
	Township 24S Range 38E	NMPM County LEA		
- 50	Elevation (Show whether DR, RKB, RT, GR,	, EET		
	3166 KB			
12. Check Appr	opriate Box to Indicate Nature of Not	ice, Report or Other Data		
NOTICE OF INTER	NTION TO:	SUBSEQUENT REPORT OF:		
	UG AND ABANDON 🛣 REMEDIAL V			
		DRILLING OPNS. P AND A		
PULL OR ALTER CASING ML	JLTIPLE COMPL CASING/CEN	MENT JOB		
DOWNHOLE COMMINGLE				
CLOSED-LOOP SYSTEM	□ OTHER:			
OTHER: 13 Describe proposed or completed		s, and give pertinent dates, including estimated date		
	SEE RULE 19.15.7.14 NMAC. For Multiple			
proposed completion or recompl		•		
MANUA MANUE AND		DT CIDD 0 4510		
	OOH W/ EXISTING STRING. RU EWL & S ERFS @ 3618 - 3784. PU WORKSTRING &	9		
	ET 2ND CIBP @ 2760 & SPOT 35 FT CMT			
	FT CMT PLUG ON CIBP. PERF AT 520 & C			
	L BEGIN IMMEDIATELY FOLLOWING A			
Spud Date:	Rig Release Date:			
I hereby certify that the information above	e is true and complete to the best of my know	rledge and belief.		
7 1 1 1 1				
SIGNATURE MACH	TITLE_OPERATIONS M	ANAGER DATE 9/12/21		
, ,				
	<u>TERSON</u> E-mail address:MPATTERSON	N@RAMENERGY.NETPHONE:918-947-6301		
For State Use Only				
APPROVED BY:	TITLE	DATE		
Conditions of Approval (if any):				

WELLBORE DIAGRAM WEST DOLLARHIDE QUEEN SAND UNIT #72 CURRENT

Conform	Carina a				
Surface Size:	Casing <u>8 5/8"</u>				
Wt.:	<u>8 3/8</u> 24#				
Depth:	417'				
Sxs Cmt:	<u>250</u>				
Circulate:	yes				
TOC:	<u>surface</u>				
Hole Size:	12-1/4"				
Formatio	-				
T. Salt	<u>1230'</u>				
B. Salt	<u>2522'</u>				
Productio	n Casing				
Size:	5-1/2"				
Wt.:	<u>15.5#</u>				
Depth:	3867'				
Sxs Cmt:	1100				
Circulate:	<u>yes</u>				
TOC:	<u>surface</u>				
Hole Size:	<u>7-7/8"</u>				
			PERFS	3618'-	3784'

WELLBORE DIAGRAM WEST DOLLARHIDE QUEEN SAND UNIT #72 PROPOSED



District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 48031

CONDITIONS

Operator:	OGRID:
RAM ENERGY LLC	309777
5100 East Skelly Drive	Action Number:
Tulsa, OK 74135	48031
	Action Type:
	[C-103] NOI Plug & Abandon (C-103F)

CONDITIONS

Created By	Condition	Condition Date
kfortner	See attached conditions of approval	9/14/2021