Cestile the District 24 PM	State of New Mexico	OCD ACTION ID 41523 Form C-103 <sup>1</sup> of
Office <u>District I</u> – (575) 393-6161 Energy	, Minerals and Natural Resources	8/11/21 Revised July 18, 2013
1625 N. French Dr., Hobbs, NM 88240		WELL API NO.
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210 OIL C	CONSERVATION DIVISION	30-025-20830
<u>District III</u> – (505) 334-6178	220 South St. Francis Dr.	5. Indicate Type of Lease  STATE  X  FEE
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM	2 1 3, 1 1 3 , 2 3 2	
87505		B-1399
SUNDRY NOTICES AND RI		7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILI DIFFERENT RESERVOIR. USE "APPLICATION FOR PR		Vacuum Glorieta East Unit
PROPOSALS.)	_	Tract 5
1. Type of Well: Oil Well X Gas Well	Other	8. Well Number 002
2. Name of Operator ConocoPhillips Co	mpany	9. OGRID Number
·	Прапу	217817 10. Pool name or Wildcat
3. Address of Operator	a. Midland TV 70704	
	e; Midland, TX 79701	Vacuum; Glorieta
4. Well Location	o d Ossath B	000 0 0 1 Fast 11
		660 feet from the East line
	ownship 17S Range 35E	NMPM Lea County
11. Elevation	on (Show whether DR, RKB, RT, GR, etc.	c.)
42 ~ 1	5 7 11 37 037 1	<b>D</b> 01 <b>D</b>
12. Check Appropriate	Box to Indicate Nature of Notice	e, Report or Other Data
NOTICE OF INTENTION	TO:   CI	PSECLIENT DEDODT OF:
		BSEQUENT REPORT OF:
	ABANDON X REMEDIAL WO	
	<del></del>	
	COMPL CASING/CEME	NI JOB
CLOSED-LOOP SYSTEM  OTHER:	□ OTHER:	П
		nd give pertinent dates, including estimated date
of starting any proposed work). SEE RU		
proposed completion or recompletion.	_	
ConocoPhillips Company respectful	ly requests to permanently plug t	his well according to the following procedu
and attached schematics.		
1. MIRU. ND WH, NU BOP.		
2. Pull tbg and ESP.		
3. Set CIBP @ 6,012'.		
4. Circ hole w/ MLF. Pressure test of	sg. Open 8-5/8" x 4-1/2" valve du	uring pressure test.
5. Spot 25 sxs cmt @ 6,012' - 5,812	<b>O</b> .	
6. Perf and squeeze 40 sxs cmt @ 4		
7. Perf and squeeze 40 sxs cmt @ 3		
8. Perf and squeeze 90 sxs cmt @ 3		
9. Perf and squeeze 75 sxs cmt @	1.712' – 1.487', WOC – Tag	
10. Perf and squeeze 25 sxs cmt @	68× 3'. Verify cmt in all annuli.	P&S 100 sx 150'-3'
11. Cut of WH and anchors. Install I	OH marker ———	
Spud Date:	Rig Release Date: SI	EE ATTACHED CONDITIONS
	O	F APPROVAL
4" diameter 4' tall Above Ground N		
hereby certify that the information above is true	and complete to the best of my knowled	lge and belief.
	Conion Demileter	Coordinator - 8/11/2021
SIGNATURE	TITLE Senior Regulatory	Coordinator <sub>DATE</sub> 8/11/2021
D D M	_ Susan.B.Maunder@co	onocophillips.com PHONE: 432-269-4378
Type or print name Susan B. Maunder	E-mail address:	PHONE: 402-209-4070
For State Use Only		
APPROVED BY: Kerry Forther	TITLE Compliance Officer A	A DATE 9/15/21
Conditions of Approval (if any):	IIILEOIIIPIIAIIGE OIIIGEI /	DATE
Ondifions of Annroval Litania.		

## CURRENT WELLBORE SKETCH ConocoPhillips Company -- Permian Basin Business Unit

Date: 8/9/2021

Surface - 8-5/8", 24# to 1,662' Circ'd to surface

Production - 4-1/2", 9.5# to 6,300' 700 sxs cmt Circ'd to 4,750' ES Ρ Perfs - 6,112' - 6,170'

Buckeye East

D.: Vacuum Glorieta East Unit 05-02

Vacuum Glorieta East Unit 05-02 Subarea : <u>B</u> Lease & Well No. : Legal Description : 32° 48' 14.508" N 103° 28' 21.792" W County: State: New Mexico Vacuum Glorieta Unit 7/26/1964 Field: Date Spudded : API Number : 30-025-20830 Operator Number:

Lease ID: Field Number:

Date: 8/9/2021

## PROPOSED WELLBORE SKETCH ConocoPhillips Company -- Permian Basin Business Unit

KB		968				
GL		958				
DF	: <u>3,</u>	958	3	Subarea :		eye East
			100 sx 150'	Lease & Well No		Vacuum Glorieta East Unit 05-02
			100 sx 150'	Legal Description	n:	32° 48' 14.508" N 103° 28' 21.792" W
			P&S 295x cmt @ 616'-3'	County:	Lea	State: New Mexico
			Surface - 8-5/8", 24# to 1,662'	Field :	Vacuu	um Glorieta Unit
			Circ'd to surface	Date Spudded :		7/26/1964
				API Number :		25-20830
						Operator Number:
			P&S 75sx cmt @ 1712'-1487' - Tag			Lease ID:
						Field Number:
		_				
		٧.	P&S 90sx cmt @ 3162'-2765' - Tag			
			Production - 4-1/2", 9.5# to 6,300'			
			700 sxs cmt			
		- 10	Circ'd to 4,750'			
$\perp$		_				
			P&S 40sx cmt @ 3730'-3630' - Tag			
		İ				
			P&S 40sx cmt @ 4416'-4316' - Tag			
		_				
			0			
			Spot 25sx cmt @ 6012'-5812'			
	ШЦ		Set CIBP @ 6012'			
			Perfs - 6,112' - 6,170'			
		=				
		Ξ				
	1					

# CONDITIONS OF APPROVAL FOR PLUGGING AND ABANDONMENT OCD - Southern District

The following is a guide or checklist in preparation of a plugging program, this is not all inclusive and care must be exercised in establishing special plugging programs in unique and unusual cases, Notify NMOCD District Office I (Hobbs) at (575)-263-6633 at least 24 hours before beginning work. After MIRU rig will remain on well until it is plugged to surface. OCD is to be notified before rig down.

#### Company representative will be on location during plugging procedures.

- **1.** A notice of intent to plug and abandon a wellbore is required to be approved before plugging operations are conducted. A cement evaluation tool is required in order to ensure isolation of producing formations, protection of water and correlative rights. A cement bond log or other accepted cement evaluation tool is to be provided to the division for evaluation if one has not been previously run or if the well did not have cement circulated to surface during the original casing cementing job or subsequent cementing jobs. Insure all bradenheads have been exposed, identified and valves are operational prior to rig up.
- **2.** Closed loop system is to be used for entire plugging operation. Upon completion, contents of steel pits are to be hauled to a permitted disposal location.
- **3.** Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private- shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator as well as the contractor, to verify that this permit is in place prior to performing work. Drivers shall be able to produce a copy upon request of an NMOCD Field inspector.
- 4. Filing a subsequent C-103 will serve as notification that the well has been plugged.
- **5.** A final C-103 shall be filed (and a site inspection by NMOCD Inspector to determine if the location is satisfactorily cleaned, all equipment, electric poles and trash has been removed to Meet NMOCD standards) before bonding can +be released.
- **6.** If work has not begun within 1 Year of the approval of this procedure, an extension request must be file stating the reason the well has not been plugged.
- 7. Squeeze pressures are not to exceed 500 psi, unless approval is given by NMOCD.
- **8.** Produced water will not be used during any part of the plugging operation.
- 9. Mud laden fluids must be placed between all cement plugs mixed at 25 sacks per 100 bbls of water.
- **10.** All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater. 50' of calculated cement excess required for inside casing plugs and 100% calculated cement excess required on outside casing plugs.
- 11. Class 'C' cement will be used above 7500 feet.
- 12. Class 'H' cement will be used below 7500 feet.
- **13.** A cement plug is required to be set 50' above and 50' below, casing stubs, DV tools, attempted casing cut offs, cement tops outside casing, salt sections and anywhere the casing is perforated, these plugs require a 4 hour WOC and then will be tagged
- **14.** All Casing Shoes Will Be Perforated 50' below shoe depth and Attempted to be Squeezed, cement needs to be 50' above and 50' Below Casing Shoe inside the Production Casing.
- **16.** When setting the top out cement plug in production, intermediate and surface casing, wellbores should remain full at least 30 minutes after plugs are set
- 17. A CIBP is to be set within 100' of production perforations, capped with 100' of cement, WOC 4 hours and tag.
- **18.** A CIBP with 35' of cement may be used in lieu of the 100' plug if set with a bailer. This plug will be placed within 100' of the top perforation, (WOC 4 hrs and tag).

- 19. No more than 3000' is allowed between cement plugs in cased hole and 2000' in open hole.
- 20. Some of the Formations to be isolated with cement plugs are: These plugs to be set to isolate formation tops
- A) Fusselman
- B) Devonian
- C) Morrow
- D) Wolfcamp
- E) Bone Springs
- F) Delaware
- G) Any salt sections
- H) Abo
- I) Glorieta
- J) Yates.
- K) Potash---(In the R-111-P Area (Potash Mine Area),

A solid cement plug must be set across the salt section. Fluid used to mix the cement shall be saturated with the salts that are common to the section penetrated and in suitable proportions, not more than 3% calcium chloride (by weight of cement) will be considered the desired mixture whenever possible, WOC 4 hours and tag, this plug will be 50' below the bottom and 50' above the top of the Formation.

**21.** If cement does not exist behind casing strings at recommended formation depths, the casing can be cut and pulled with plugs set at recommended depths. If casing is not pulled, perforations will be shot and cement squeezed behind casing, WOC and tagged. These plugs will be set 50' below formation bottom to 50' above formation top inside the casing.

### DRY HOLE MARKER REQ.UIRMENTS

The operator shall mark the exact location of the plugged and abandoned well with a steel marker not less than four inches in diameter, 3' below ground level with a plate of at least ¼" welded to the top of the casing and the dry hole marker welded on the plate with the following information welded on the dry hole marker:

- 1. Operator name
- 2. Lease and Well Number
- 3. API Number
- 4. Unit letter
- 5. Quarter Section (feet from the North, South, East or West)
- 6. Section, Township and Range
- 7. Plugging Date
- 8. County

#### SPECIAL CASES ----AGRICULTURE OR PRARIE CHICKEN BREEDING AREAS

In these areas, a below ground marker is required with all pertinent information mentioned above on a plate, set 3' below ground level, a picture of the plate will be supplied to NMOCD for record, the exact location of the marker (longitude and latitude by GPS) will be provided to NMOCD (We typically require a current survey to verify the GPS)

#### SITE REMEDIATION DUE WITHIN ONE YEAR OF WELL PLUGGING COMPLETION

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone: (575) 748-1283 Fax: (575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. **Santa Fe, NM 87505** 

CONDITIONS

Action 41523

#### **CONDITIONS**

Operator:	OGRID:
CONOCOPHILLIPS COMPANY	217817
600 W. Illinois Avenue	Action Number:
Midland, TX 79701	41523
	Action Type:
	[C-103] NOI Plug & Abandon (C-103F)

#### CONDITIONS

Created By	Condition	Condition Date
kfortner	See attached conditions of approval	9/15/2021