
0		
Submit 1 Copy To Appropriate District Office	State of New Mexico	Form C-103
District I – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resources	Revised July 18, 2013 WELL API NO.
District II – (575) 748-1283	OIL CONSERVATION DIVISION	30-025-10480
811 S. First St., Artesia, NM 88210 District III – (505) 334-6178	1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 District IV – (505) 476-3460	Santa Fe, NM 87505	STATE FEE 6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM		o. State on & Gas Lease No.
87505 SUNDRY NOT	ICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPO	SALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	Langlie Mattix Penrose Sand Unit
PROPOSALS.)	CATION FOR PERMIT" (FORM C-101) FOR SUCH	8. Well Number #134
1. Type of Well: Oil Well	Gas Well 🗌 Other	
2. Name of Operator Legacy Reserves Operating LP		9. OGRID Number 240974
3. Address of Operator		10. Pool name or Wildcat
P.O. Box 10848, Midland, TX 79	702	Langlie Mattix; 7 Rivers;Q;Grbg
4. Well Location		
Unit Letter <u>E</u> :		
Section 27	Township 22S Range 37E 11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
	3341' GR	
12. Check	Appropriate Box to Indicate Nature of Notice, I	Report or Other Data
NOTICE OF IN	ITENTION TO: SUB	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	
TEMPORARILY ABANDON	CHANGE PLANS COMMENCE DRII	
DOWNHOLE COMMINGLE		10B 🗌
CLOSED-LOOP SYSTEM	_	_
OTHER:	Deted operations. (Clearly state all pertinent details, and	Laive pertinent dates including estimated date
of starting any proposed w	ork). SEE RULE 19.15.7.14 NMAC. For Multiple Con	npletions: Attach wellbore diagram of
proposed completion or rec	ompletion.	
	c hole w/ MLF. Pressure test csg.	
	502-3100'. WOC & Tag (7" Shoe & TOL)	
	40'. WOC & Tag (D/Salt) 40'. WOC & Tag (T/Salt & 7" DVT)	
5. Perf & Sqz 40 sx cmt @ 2	11' to surface.	
6. Cut off well head, verify of	emt @ surface, weld on Dry Hole Marker.	
4" diameter 4' tall Above G		
4 diameter 4 tail Above G	round marker CONDIT	IONS OF APPROVAL
		
Spud Date:	Rig Release Date:	
E lereby certify that the information	above is true and complete to the best of my knowledge	and helief
4	above is true and complete to the best of my knowledge	
SIGNATURE MUCH		DATE 10/20/2021
SIGNATURE	TITLE Compliance Coordin	natorDATE10/29/2021
Type or print name <u>Melan</u>	ie Reyes E-mail address: _mreyes@legacyre	serves.com PHONE: <u>(432) 221-6358</u>
S For State Use Only		
APPROVED BY: XIII	Forther TITLE Compliance Officer A	DATE11/19/21
Conditions of Approval (if any)		
Reu		

Released to Imaging: 11/19/2021 3:31:25 PM

•

Langlie Mattix Penrose Sand Unit #134 Plugging Plan

- 1. Set 5" CIBP @ 3502'. Circ hole w/ MLF. Pressure test csg.
- 2. Perf & Sqz 50 sx cmt @ 3502-3100'. WOC & Tag (7" Shoe & TOL)
- 3. Spot 25 sx cmt @ 2530-2430'. WOC & Tag (B/Salt)
- 4. Spot 75 sx cmt @ 1540-1140'. WOC & Tag (T/Salt & 7" DVT)
- 5. Perf & Sqz 40 sx cmt @ 211' to surface.
- 6. Cut off well head, verify cmt @ surface, weld on Dry Hole Marker.



0													
Legacy		****	PROPOSE)		Description	0.D.	Grade	Weight	Depth	Hole	Cmt Sx	TOC
Author:	Abby @ BCM						Î	1			8		<u></u>
Well Name	Langlie Mattix Penrose Sand Unit	Well No.	#	#134		Surface Csg	10 3/4		40#	161	13 3/7	100	0
Field/Pool	LM; 7 Rvs, Qn, Grbg	API#:	30-03	25-10480		Drad Can			004	0.005	0.40	400	
County	Lea	Location:	BAAM	T22S, R37E		Prod Csg	7		22#	3,385	8 1/2	400	0
State Spud Date	New Mexico 2/16/1937	- GL:		L & 660 FEL 3341		Liner	5		15#	3385- 3675	6 1/4	250	3,385
	Liferiooi			JU-1		.	¥	1		3075	L	Formation	Top
		~~~~										T/Salt	1490
												B/Salt	2480
												Anhy	1166 +/-
			10 3/4 40#	CSG @	161							Yates	2653 +/-
			Hole Size:	13 3/7	101								
			noie Oize.	10 0/1								7 Rivers	2851 +/-
2		A 5 Port	& Sqz 40 sx	cmt @ 211	to ourfoor							Queen	3414+/-
7" DVT @ 1220'	×	3. Spot	t 25 sx cmt @	) 2530-2430	'. WOC & '								
		2. Pe			02-3100'.	WOC & Tag (7"	' Shoe	& TOL	)				
	41		7 22#	CSG @ 3	,385								
			Hole Size:										
		1. Se	t 5" CIBP @ :	3502'. Circ	hole w/ Ml	.F. Pressure te	st csg	<b>j</b> .					
		2008	3552-3645 5" Line: 15#	set @ 3388	5-3675 0L 5-3 575 0L 57	10/1937: Open h (17/1970: Attemp uip)and cleanou ave junk in hol It beside junk. (5,35 sxs and 35 d drilled new h	t to f t well e. Los Could sxs c	ish junk . Unsucc τ 6" bit not fish ement an	(91'5" essful i and 57' Filled d set 2 v	OD line 1 runnin of 2 7/ 1 OH wit whipstoc	r and 1g impr '8" DP 1h 600 1ks at	misc cable ession blo while dril sxs,300 sx 3425' and	tool ock. ling s,75 3405'
	о @ 3675 в @ 3610				ar	d drilled new h d cemented w/ 2 erfs w/ 60,000 g	50 sxs	, perfor	ated 3522	2'-3645'	, and	at 3305'-3 fraced new	675

.

•

# CONDITIONS OF APPROVAL FOR PLUGGING AND ABANDONMENT OCD - Southern District

The following is a guide or checklist in preparation of a plugging program, this is not all inclusive and care must be exercised in establishing special plugging programs in unique and unusual cases, Notify NMOCD District Office I (Hobbs) at (575)-263-6633 at least 24 hours before beginning work. After MIRU rig will remain on well until it is plugged to surface. OCD is to be notified before rig down.

## Company representative will be on location during plugging procedures.

**1.** A notice of intent to plug and abandon a wellbore is required to be approved before plugging operations are conducted. A cement evaluation tool is required in order to ensure isolation of producing formations, protection of water and correlative rights. A cement bond log or other accepted cement evaluation tool is to be provided to the division for evaluation if one has not been previously run or if the well did not have cement circulated to surface during the original casing cementing job or subsequent cementing jobs. Insure all bradenheads have been exposed, identified and valves are operational prior to rig up.

**2.** Closed loop system is to be used for entire plugging operation. Upon completion, contents of steel pits are to be hauled to a permitted disposal location.

**3.** Trucking companies being used to haul oilfield waste fluids to a disposal - commercial or private- shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator as well as the contractor, to verify that this permit is in place prior to performing work. Drivers shall be able to produce a copy upon request of an NMOCD Field inspector.

4. Filing a subsequent C-103 will serve as notification that the well has been plugged.

**5.** A final C-103 shall be filed (and a site inspection by NMOCD Inspector to determine if the location is satisfactorily cleaned, all equipment, electric poles and trash has been removed to Meet NMOCD standards) before bonding can +be released.

**6.** If work has not begun within 1 Year of the approval of this procedure, an extension request must be file stating the reason the well has not been plugged.

7. Squeeze pressures are not to exceed 500 psi, unless approval is given by NMOCD.

8. Produced water will not be used during any part of the plugging operation.

9. Mud laden fluids must be placed between all cement plugs mixed at 25 sacks per 100 bbls of water.

**10.** All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater. 50' of calculated cement excess required for inside casing plugs and 100% calculated cement excess required on outside casing plugs.

11. Class 'C' cement will be used above 7500 feet.

12. Class 'H' cement will be used below 7500 feet.

**13.** A cement plug is required to be set 50' above and 50' below, casing stubs, DV tools, attempted casing cut offs, cement tops outside casing, salt sections and anywhere the casing is perforated, these plugs require a 4 hour WOC and then will be tagged

**14.** All Casing Shoes Will Be Perforated 50' below shoe depth and Attempted to be Squeezed, cement needs to be 50' above and 50' Below Casing Shoe inside the Production Casing.

**16.** When setting the top out cement plug in production, intermediate and surface casing, wellbores should remain full at least 30 minutes after plugs are set

17. A CIBP is to be set within 100' of production perforations, capped with 100' of cement, WOC 4 hours and tag.

**18.** A CIBP with 35' of cement may be used in lieu of the 100' plug if set with a bailer. This plug will be placed within 100' of the top perforation, (WOC 4 hrs and tag).

19. No more than 3000' is allowed between cement plugs in cased hole and 2000' in open hole.

20. Some of the Formations to be isolated with cement plugs are: These plugs to be set to isolate formation tops

- A) Fusselman
- B) Devonian
- C) Morrow
- D) Wolfcamp
- E) Bone Springs
- F) Delaware
- G) Any salt sections
- H) Abo
- I) Glorieta
- J) Yates.

#### K) Potash---(In the R-111-P Area (Potash Mine Area),

A solid cement plug must be set across the salt section. Fluid used to mix the cement shall be saturated with the salts that are common to the section penetrated and in suitable proportions, not more than 3% calcium chloride (by weight of cement) will be considered the desired mixture whenever possible, WOC 4 hours and tag, this plug will be 50' below the bottom and 50' above the top of the Formation.

**21.** If cement does not exist behind casing strings at recommended formation depths, the casing can be cut and pulled with plugs set at recommended depths. If casing is not pulled, perforations will be shot and cement squeezed behind casing, WOC and tagged. These plugs will be set 50' below formation bottom to 50' above formation top inside the casing.

# DRY HOLE MARKER REQ.UIRMENTS

The operator shall mark the exact location of the plugged and abandoned well with a steel marker not less than four inches in diameter, 3' below ground level with a plate of at least ¼" welded to the top of the casing and the dry hole marker welded on the plate with the following information welded on the dry hole marker:

- 1. Operator name
- 2. Lease and Well Number
- 3. API Number
- 4. Unit letter
- 5. Quarter Section (feet from the North, South, East or West)
- 6. Section, Township and Range
- 7. Plugging Date
- 8. County


### SPECIAL CASES -----AGRICULTURE OR PRARIE CHICKEN BREEDING AREAS

In these areas, a below ground marker is required with all pertinent information mentioned above on a plate, set 3' below ground level, a picture of the plate will be supplied to NMOCD for record, the exact location of the marker (longitude and latitude by GPS) will be provided to NMOCD (We typically require a current survey to verify the GPS)

### SITE REMEDIATION DUE WITHIN ONE YEAR OF WELL PLUGGING COMPLETION

# Langlie Mattix Penrose Sand Unit #134 Plugging Plan

- 1. Set 5" CIBP @ 3502'. Circ hole w/ MLF. Pressure test csg.
- 2. Perf & Sqz 50 sx cmt @ 3502-3100'. WOC & Tag (7" Shoe & TOL)
- 3. Spot 25 sx cmt @ 2530-2430'. WOC & Tag (B/Salt)
- 4. Spot 75 sx cmt @ 1540-1140'. WOC & Tag (T/Salt & 7" DVT)
- 5. Perf & Sqz 40 sx cmt @ 211' to surface.
- 6. Cut off well head, verify cmt @ surface, weld on Dry Hole Marker.



Legacy			PROPOSED	Description	0.D.	Grade	Weight	Depth	Hole	Cmt Sx	TOC
Author:	Abby @ BCM				Î						
Well Name	Langlie Mattix Penrose Sand Unit	Well No.	#134	Surface Csg	10 3/4		40#	161	13 3/7	100	0
Field/Pool	LM; 7 Rvs, Qn, Grbg	API#	30-025-10480	Prod Csg	7		22#	3,385	8 1/2	400	0
County State	Lea New Mexico	Location:	Sec 27, T22S, R37E 1980 FNL & 660 FEL		ļ						
Spud Date	2/16/1937	GL:	3341	Liner	5		15#	3385- 3675	6 1/4	250	3,385
										Formation	Тор
200										T/Salt	1490
										B/Salt	2480
										Anhy	1166 +/-
			10 3/4 40# CSG @ 161							Yates	2653 +/-
			Hole Size: 13 3/7							7 Rivers	2851 +/-
										Queen	3414+/-
2		N 5. Perf	& Sqz 40 sx cmt @ 211' to su	rface.					1		
7" DVT @			75 sx cmt @ 1540-1140'. WO 25 sx cmt @ 2530-2430'. WO		י סעד	)					
		2. Pe	rf & Sqz 50 sx cmt @ 3502-31	00'. WOC & Tag (7'	Shoe	& TOL	)				
2		Ň	7 22# CSG @ 3,385	<b>U</b> (*							
			Hole Size: 8 1/2								
		🕺 1. Se	t 5" CIBP @ 3502'. Circ hole v	v/ MLF. Pressure te	stcsc	1.					
		Perfs @	3552-3645 5" Line: 15# set @ 3385-3675	4/10/1937: Open th 8/17/1970: Attemp equip)and cleanou Leave junk in hol out beside junk. sxs.35 sxs and 35	ole sh t to f t well e. Los Could Sxs c	ot with ish junk . Unsucc t 6" bit not fish ement an	(91'5" essful in and 57' Fillen d set 2 w	OD line runnin of 2 7/ i OH wit whipstoc	r and g impr 8" DP h 600 ks at	misc cable ession blo while dril sxs,300 sx 3425' and	tool ck. ling s,75 3405'
TD TDPI				and drilled new h and cemented w/ 2 perfs w/ 60,000 g	ole to 50 sxs	3675' T , perfor	D. Insta ated 3522	lled 5"	liner	at 3305'-3	675

.

•

District I 1625 N. French Dr., Hobbs, NM 88240 Phone: (575) 393-6161 Fax: (575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV 1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

# **State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. Santa Fe, NM 87505

Page 10 of 10

CONDITIONS

Action 58724

CONDITIONS OGRID: Operator: LEGACY RESERVES OPERATING, LP 240974 15 Smith Road Action Number: Midland, TX 79705 58724 Action Type: . [C-103] NOI Plug & Abandon (C-103F)

CONDITIONS

Created By	Condition	Condition Date
kfortner	see attached conditions of approval	11/19/2021