Office	State of New Mexico	Form CP48931 of
<u>District I</u> – (575) 393-6161 End 1625 N. French Dr., Hobbs, NM 88240	ergy, Minerals and Natural Resour	rces Revised July 18, 2013 WELL API NO.
District II (575) 749 1292	L CONSERVATION DIVISIO	DN 30-015-40977
<u>District III</u> - (505) 334-6178	1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 District IV – (505) 476-3460	Santa Fe, NM 87505	STATE FEE 6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505		0. State Off de Ods Loase No.
SUNDRY NOTICES AN (DO NOT USE THIS FORM FOR PROPOSALS TO I	D REPORTS ON WELLS	7. Lease Name or Unit Agreement Name Higgins Trust 13 A
DIFFERENT RESERVOIR. USE "APPLICATION FO		8. Well Number #2
PROPOSALS.) 1. Type of Well: Oil Well Gas Wel	1 🗍 Other	$3. \mathbf{W} \in \mathbf{H} \times \mathbf{H} \times \mathbf{H} = 1 +$
2. Name of Operator		9. OGRID Number
Redwood Operating, LLC 3. Address of Operator		330211 10. Pool name or Wildcat
PO Box 1370, Artesia, NM 882111370		Red Lake, Glorieta-Yeso (51120)
4. Well Location		
	_feet from the line and	<u>330</u> feet from the <u>E</u> line
	nship 18S Range 26E	NMPM County Eddy
11. Ele	evation (Show whether DR, RKB, RT, 3289' GL	GR, etc.)
12. Check Appropr	iate Box to Indicate Nature of 1	Notice, Report or Other Data
NOTICE OF INTENTI		Ý *
—		NCE DRILLING OPNS. P AND A
	PLE COMPL 🔲 CASING/	
		Notify OCD 24 hrs. prior to any work
CLOSED-LOOP SYSTEM		Notify OCD 24 first prior to any work
OTHER:		done
13. Describe proposed or completed ope	rations. (Clearly state all pertinent de	etails, and give pertinent dates, including estimated date
 Describe proposed or completed ope of starting any proposed work). SEI 	rations. (Clearly state all pertinent de 3 RULE 19.15.7.14 NMAC. For Mul	tails, and give pertinent dates, menuting estimated date tiple Completions: Attach wellbore diagram of
13. Describe proposed or completed ope	rations. (Clearly state all pertinent de 3 RULE 19.15.7.14 NMAC. For Mul	etails, and give pertinent dates, menuing estimated date
 Describe proposed or completed ope of starting any proposed work). SEI proposed completion or recompletion 	rations. (Clearly state all pertinent de 3 RULE 19.15.7.14 NMAC. For Mul n.	etails, and give pertinent dates, including estimated date htiple Completions: Attach wellbore diagram of
 Describe proposed or completed ope of starting any proposed work). SEI proposed completion or recompletion Set 5 1/2" CIBP @ 2975'. Circ 1 	rations. (Clearly state all pertinent de 3 RULE 19.15.7.14 NMAC. For Mul n. hole w/ MLF. Pressure test csg. Spo	etails, and give permient dates, mendoing estimated date ltiple Completions: Attach wellbore diagram of
 Describe proposed or completed ope of starting any proposed work). SEI proposed completion or recompletion Set 5 ¹/₂" CIBP @ 2975'. Circ I Spot 25 sx cmt @ 1086-886'. V Perf & Sqz 100 sx cmt @ 455' 	rations. (Clearly state all pertinent de E RULE 19.15.7.14 NMAC. For Mul n. hole w/ MLF. Pressure test csg. Spo VOC & Tag (San Andres) to surface. (8 5/8 Shoe, & Queen)	etails, and give pertment dates, menduing estimated date htiple Completions: Attach wellbore diagram of ot 25 sx cmt @ 2975-2775'. WOC & Tag
 Describe proposed or completed ope of starting any proposed work). SEI proposed completion or recompletion Set 5 ¹/₂" CIBP @ 2975'. Circ I Spot 25 sx cmt @ 1086-886'. V Perf & Sqz 100 sx cmt @ 455' 	rations. (Clearly state all pertinent de ERULE 19.15.7.14 NMAC. For Mul n. hole w/ MLF. Pressure test csg. Spo VOC & Tag (San Andres)	etails, and give pertinent dates, including estimated date htiple Completions: Attach wellbore diagram of ot 25 sx cmt @ 2975-2775'. WOC & Tag
 Describe proposed or completed ope of starting any proposed work). SEI proposed completion or recompletion Set 5 ¹/₂" CIBP @ 2975'. Circ I Spot 25 sx cmt @ 1086-886'. V Perf & Sqz 100 sx cmt @ 455' 	rations. (Clearly state all pertinent de E RULE 19.15.7.14 NMAC. For Mul n. hole w/ MLF. Pressure test csg. Spo VOC & Tag (San Andres) to surface. (8 5/8 Shoe, & Queen)	etails, and give pertment dates, including estimated date htiple Completions: Attach wellbore diagram of ot 25 sx cmt @ 2975-2775'. WOC & Tag
 Describe proposed or completed ope of starting any proposed work). SEI proposed completion or recompletion Set 5 ¹/₂" CIBP @ 2975'. Circ I Spot 25 sx cmt @ 1086-886'. V Perf & Sqz 100 sx cmt @ 455' 	rations. (Clearly state all pertinent de E RULE 19.15.7.14 NMAC. For Mul n. hole w/ MLF. Pressure test csg. Spo VOC & Tag (San Andres) to surface. (8 5/8 Shoe, & Queen)	etails, and give permittin dates, including estimated date htiple Completions: Attach wellbore diagram of of 25 sx cmt @ 2975-2775'. WOC & Tag
 Describe proposed or completed ope of starting any proposed work). SEI proposed completion or recompletion Set 5 ¹/₂" CIBP @ 2975'. Circ I Spot 25 sx cmt @ 1086-886'. V Perf & Sqz 100 sx cmt @ 455' 	rations. (Clearly state all pertinent de E RULE 19.15.7.14 NMAC. For Mul n. hole w/ MLF. Pressure test csg. Spo VOC & Tag (San Andres) to surface. (8 5/8 Shoe, & Queen)	etails, and give permittin dates, including estimated date htiple Completions: Attach wellbore diagram of of 25 sx cmt @ 2975-2775'. (WOC & Tag)
 Describe proposed or completed ope of starting any proposed work). SEI proposed completion or recompletion Set 5 ¹/₂" CIBP @ 2975'. Circ I Spot 25 sx cmt @ 1086-886'. V Perf & Sqz 100 sx cmt @ 455' 	rations. (Clearly state all pertinent de E RULE 19.15.7.14 NMAC. For Mul n. hole w/ MLF. Pressure test csg. Spo VOC & Tag (San Andres) to surface. (8 5/8 Shoe, & Queen)	etails, and give pertment dates, including estimated date htiple Completions: Attach wellbore diagram of ot 25 sx cmt @ 2975-2775'. WOC & Tag
 Describe proposed or completed ope of starting any proposed work). SEI proposed completion or recompletion Set 5 ¹/₂" CIBP @ 2975'. Circ I Spot 25 sx cmt @ 1086-886'. V Perf & Sqz 100 sx cmt @ 455' Cut off well head, verify cmt @ 	rations. (Clearly state all pertinent de RULE 19.15.7.14 NMAC. For Mul n. hole w/ MLF. Pressure test csg. Spo VOC & Tag (San Andres) to surface. (8 5/8 Shoe, & Queen) 2 surface, weld on Dry Hole Marke	etails, and give pertment dates, menduing estimated date htiple Completions: Attach wellbore diagram of ot 25 sx cmt @ 2975-2775'. WOC & Tag
 Describe proposed or completed ope of starting any proposed work). SEI proposed completion or recompletion Set 5 ¹/₂" CIBP @ 2975'. Circ I Spot 25 sx cmt @ 1086-886'. V Perf & Sqz 100 sx cmt @ 455' 	rations. (Clearly state all pertinent de E RULE 19.15.7.14 NMAC. For Mul n. hole w/ MLF. Pressure test csg. Spo VOC & Tag (San Andres) to surface. (8 5/8 Shoe, & Queen)	etails, and give pertment dates, menduing estimated date htiple Completions: Attach wellbore diagram of ot 25 sx cmt @ 2975-2775'. WOC & Tag
 Describe proposed or completed ope of starting any proposed work). SEI proposed completion or recompletion Set 5 ¹/₂" CIBP @ 2975'. Circ I Spot 25 sx cmt @ 1086-886'. V Perf & Sqz 100 sx cmt @ 455' Cut off well head, verify cmt @ 	Rig Release Date:	etails, and give pertment dates, including estimated date htiple Completions: Attach wellbore diagram of ot 25 sx cmt @ 2975-2775'. WOC & Tag
 13. Describe proposed or completed ope of starting any proposed work). SEI proposed completion or recompletion 1. Set 5 ½" CIBP @ 2975'. Circ I 2. Spot 25 sx cmt @ 1086-886'. V 3. Perf & Sqz 100 sx cmt @ 455' 4. Cut off well head, verify cmt @ 	rations. (Clearly state all pertinent de BRULE 19.15.7.14 NMAC. For Mul n. hole w/ MLF. Pressure test csg. Spo VOC & Tag (San Andres) to surface. (8 5/8 Shoe, & Queen) @ surface, weld on Dry Hole Marke Rig Release Date:	etails, and give permient dates, including estimated date htiple Completions: Attach wellbore diagram of of 25 sx cmt @ 2975-2775'. WOC & Tag er.
 13. Describe proposed or completed ope of starting any proposed work). SEI proposed completion or recompletion 1. Set 5 ¹/₂" CIBP @ 2975'. Circ I 2. Spot 25 sx cmt @ 1086-886'. V 3. Perf & Sqz 100 sx cmt @ 455' 4. Cut off well head, verify cmt @ Spud Date: ****SEE ATTACHED CO I hereby certify that the information above is	Rig Release Date:	etails, and give permient dates, including estimated date htiple Completions: Attach wellbore diagram of of 25 sx cmt @ 2975-2775'. WOC & Tag er. Ist be plugged by 12/23/2022 nowledge and belief.
 13. Describe proposed or completed ope of starting any proposed work). SEI proposed completion or recompletion 1. Set 5 ¹/₂" CIBP @ 2975'. Circ I 2. Spot 25 sx cmt @ 1086-886'. V 3. Perf & Sqz 100 sx cmt @ 455' 4. Cut off well head, verify cmt @ 	rations. (Clearly state all pertinent de BRULE 19.15.7.14 NMAC. For Mul n. hole w/ MLF. Pressure test csg. Spo VOC & Tag (San Andres) to surface. (8 5/8 Shoe, & Queen) @ surface, weld on Dry Hole Marke Rig Release Date:	etails, and give periment dates, including estimated date htiple Completions: Attach wellbore diagram of of 25 sx cmt @ 2975-2775'. WOC & Tag er. Ist be plugged by 12/23/2022 nowledge and belief.
 13. Describe proposed or completed ope of starting any proposed work). SEI proposed completion or recompletion 1. Set 5 ½" CIBP @ 2975'. Circ I 2. Spot 25 sx cmt @ 1086-886'. V 3. Perf & Sqz 100 sx cmt @ 455' 4. Cut off well head, verify cmt @ Spud Date: ****SEE ATTACHED CO I hereby certify that the information above is SIGNATURE Delilah Flores	rations. (Clearly state all pertinent de RULE 19.15.7.14 NMAC. For Muln. hole w/ MLF. Pressure test csg. Spot VOC & Tag (San Andres) to surface. (8 5/8 Shoe, & Queen) ② surface, weld on Dry Hole Market DA's**** Mu TITLE_Regulatory Te	etails, and give periment dates, including estimated date htiple Completions: Attach wellbore diagram of of 25 sx cmt @ 2975-2775'. WOC & Tag er. Ist be plugged by 12/23/2022 nowledge and belief. DATE_12/20/2021
 13. Describe proposed or completed ope of starting any proposed work). SEI proposed completion or recompletion 1. Set 5 ¹/₂" CIBP @ 2975'. Circ I 2. Spot 25 sx cmt @ 1086-886'. V 3. Perf & Sqz 100 sx cmt @ 455' 4. Cut off well head, verify cmt @ 	Rig Release Date:	etails, and give permient dates, including estimated date htiple Completions: Attach wellbore diagram of of 25 sx cmt @ 2975-2775'. WOC & Tag er. Ist be plugged by 12/23/2022 nowledge and belief. DATE_12/20/2021
 13. Describe proposed or completed ope of starting any proposed work). SEI proposed completion or recompletion 1. Set 5 ½" CIBP @ 2975'. Circ I 2. Spot 25 sx cmt @ 1086-886'. V 3. Perf & Sqz 100 sx cmt @ 455' 4. Cut off well head, verify cmt @ Spud Date: <u>****SEE ATTACHED CC</u> I hereby certify that the information above is SIGNATURE Delilah Flores Type or print name Delilah Flores	rations. (Clearly state all pertinent de RULE 19.15.7.14 NMAC. For Muln. n. hole w/ MLF. Pressure test csg. Spot VOC & Tag (San Andres) to surface. (8 5/8 Shoe, & Queen) @ surface, weld on Dry Hole Market @ surface, weld on Dry Hole Market DA's**** Mu true and complete to the best of my k	etails, and give pertinent dates, including estimated date htiple Completions: Attach wellbore diagram of of 25 sx cmt @ 2975-2775'. WOC & Tag er. Ist be plugged by 12/23/2022 nowledge and belief. DATE_12/20/2021

.

CONDITIONS FOR PLUGGING AND ABANDONMENT

OCD - Southern District

The following is a guide or checklist in preparation of a plugging program, this is not all inclusive and care must be exercised in establishing special plugging programs in unique and unusual cases, Notify NMOCD District Office II at (575)-748-1283 at least 24 hours before beginning work. After MIRU rig will remain on well until it is plugged to surface. OCD is to be notified before rig down. Company representative will be on location during plugging procedures.

- 1. A notice of intent to plug and abandon a wellbore is required to be approved before plugging operations are conducted. A cement evaluation tool is required in order to ensure isolation of producing formations, protection of water and correlative rights. A cement bond log or other accepted cement evaluation tool is to be provided to the division for evaluation if one has not been previously run or if the well did not have cement circulated to surface during the original casing cementing job or subsequent cementing jobs. Insure all bradenheads have been exposed, identified and valves are operational prior to rig up.
- 2. Closed loop system is to be used for entire plugging operation. Upon completion, contents of steel pits are to be hauled to a permitted disposal location.
- 3. Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator as well as the contractor, to verify that this permit is in place prior to performing work. Drivers shall be able to produce a copy upon request of an NMOCD Field inspector.
- 4. Filing a subsequent C-103 will serve as notification that the well has been plugged.
- 5. A final C-103 shall be filed (and a site inspection by NMOCD Inspector to determine if the location is satisfactorily cleaned, all equipment, electric poles and trash has been removed to Meet NMOCD standards) before bonding can be released.
- 6. If work has not begun within 1 Year of the approval of this procedure, an extension request must be file stating the reason the well has not been plugged.
- 7. Squeeze pressures are not to exceed 500 psi, unless approval is given by NMOCD.
- 8. Produced water will not be used during any part of the plugging operation.
- 9. Mud laden fluids must be placed between all cement plugs mixed at 25 sacks per 100 bbls of water.
- 10. All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater. 50' of calculated cement excess required for inside casing plugs and 100% calculated cement excess required on outside casing plugs.
- 11. Class 'C' cement will be used above 7500 feet.
- 12. Class 'H' cement will be used below 7500 feet.
- 13. A cement plug is required to be set 50' above and 50' below, casing stubs, DV tools, attempted casing cut offs, cement tops outside casing, salt sections and anywhere the casing is perforated, these plugs require a 4 hour WOC and then will be tagged
- 14. All Casing Shoes Will Be Perforated 50' below shoe depth and Attempted to be Squeezed, cement needs to be 50' above and 50' Below Casing Shoe inside the Production Casing.

- 16. When setting the top out cement plug in production, intermediate and surface casing, wellbores should remain full at least 30 minutes after plugs are set
- 17. A CIBP is to be set within 100' of production perforations, capped with 100' of cement, WOC 4 hours and tag.
- 18. A CIBP with 35' of cement may be used in lieu of the 100' plug if set with a bailer. This plug will be placed within 100' of the top perforation, (WOC 4 hrs and tag).
- 19. No more than 3000' is allowed between cement plugs in cased hole and 2000' in open hole.
- 20. Some of the Formations to be isolated with cement plugs are: These plugs to be set to isolate formation tops
 - A) Fusselman
 - B) Devonian
 - C) Morrow
 - D) Wolfcamp
 - E)Bone Springs
 - F) Delaware
 - G) Any salt sections
 - H) Abo
 - I) Glorieta
 - J) Yates.
 - K)Potash---(In the R-111-P Area (Page 3 & 4), a solid cement plug must be set across the salt section. Fluid used to mix the cement shall be saturated with the salts that are common to the section penetrated and in suitable proportions, not more than 3% calcium chloride (by weight of cement) will be considered the desired mixture whenever possible, WOC 4 hours and tag, this plug will be 50' below the bottom and 50' above the top of the Formation.
- 21. If cement does not exist behind casing strings at recommended formation depths, the casing can be cut and pulled with plugs set at recommended depths. If casing is not pulled, perforations will be shot and cement squeezed behind casing, WOC and tagged. These plugs will be set 50' below formation bottom to 50' above formation top inside the casing

DRY HOLE MARKER REQUIRMENTS

The operator shall mark the exact location of the plugged and abandoned well with a steel marker not less than four inches in diameter, 3' below ground level with a plate of at least ¼" welded to the top of the casing and the dry hole marker welded on the plate with the following information welded on the dry hole marker:

1. Operator name2. Lease and Well Number3. API Number4. Unit Letter5. QuarterSection (feet from the North, South, East or West)6. Section, Township and Range7. Plugging Date8. County(SPECIAL CASES)------AGRICULTURE OR PRARIE CHICKEN BREEDING AREAS

In these areas, a below ground marker is required with all pertinent information mentioned above on a plate, set 3' below ground level, a picture of the plate will be supplied to NMOCD for record, the exact location of the marker (longitude and latitude by GPS) will be provided to NMOCD (We typically require a current survey to verify the GPS)

SITE REMEDIATION DUE WITHIN ONE YEAR OF WELL PLUGGING COMPLETION

R-111-P Area

T 18S – R 30E

Sec 10 Unit P. Sec 11 Unit M,N. Sec 13 Unit L,M,N. Sec 14 Unit C -P. Sec 15 Unit A G,H,I,J,K,N,O,P. Sec 22 Unit All except for M. Sec 23, Sec 24 Unit C,D,E,L, Sec 26 Unit A-G, Sec 27 Unit A,B,C

T 19S – R 29E

Sec 11 Unit P. Sec 12 Unit H-P. Sec 13. Sec 14 Unit A,B,F-P. Sec 15 Unit P. Sec 22 Unit A,B,C,F,G,H,I,J K,N,O,P. Sec 23. Sec 24. Sec 25 Unit D. Sec 26 Unit A- F. Sec 27 Unit A,B,C,F,G,H.

T 19S – R 30E

Sec 2 Unit K,L,M,N. Sec 3 Unit I,L,M,N,O,P. Sec 4 Unit C,D,E,F,G,I-P. Sec 5 Unit A,B,C,E-P. Sec 6 Unit I,O,P. Sec 7 – Sec 10. Sec 11 Unit D, G—P. Sec 12 Unit A,B,E-P. Sec 13 Unit A-O. Sec 14-Sec 18. Sec 19 Unit A-L, P. Sec 20 – Sec 23. Sec 24 Unit C,D,E,F,L,M,N. Sec 25 Unit D. Sec 26 Unit A-G, I-P. Sec 27, Sec 28, Sec 29 Unit A,B,C,D,F,G,H,I,J,O,P. Sec 32 Unit A,B,G,H,I,J,N,O,P. Sec 33. Sec 34. Sec 35. Sec 36 Unit D,E,F,I-P.

T 19S – R 31E

Sec 7 Unit C,D,E,F,L. Sec 18 Unit C,D,E,F,G,K,L. Sec 31 Unit M. Sec 34 Unit P. Sec 35 Unit M,N,O. Sec 36 Unit O,P.

T 20S – R 29E

Sec 1 Unit H,I,P. Sec 13 Unit E,L,M,N. Sec 14 Unit B-P. Sec 15 Unit A,H,I,J,N,O,P. Sec 22 Unit A,B,C,F,G,H,I,J,O,P. Sec 23. Sec 24 Unit C,D,E,F,G,J-P. Sec 25 Unit A-O. Sec 26. Sec 27 Unit A,B,G,H,I,J,O,P. Sec 34 Unit A,B,G,H. Sec 35 Unit A-H. Sec 36 Unit B-G.

T 20S – R 30E

Sec 1 – Sec 4. Sec 5 Unit A,B,C,E-P. Sec 6 Unit E,G-P. Sec 7 Unit A-H,I,J,O,P. Sec 8 – 17. Sec 18 Unit A,B,G,H,I,J,O,P. Sec 19 Unit A,B,G,H,I,J,O,P. Sec 20 – 29. Sec 30 Unit A-L,N,O,P. Sec 31 Unit A,B,G,H,I,P. Sec 32 – Sec 36.

T 20S – R 31E

Sec 1 Unit A,B,C,E-P. Sec 2. Sec 3 Unit A,B,G,H,I,J,O,P. Sec 6 Unit D,E,F,J-P. Sec 7. Sec 8 Unit E-P. Sec 9 Unit E,F,J-P. Sec 10 Unit A,B,G-P. Sec 11 – Sec 36.

T 21S – R 29E

Sec 1 – Sec 3. Sec 4 Unit L1 – L16,I,J,K,O,P. Sec 5 Unit L1. Sec 10 Unit A,B,H,P. Sec 11 – Sec 14. Sec 15 Unit A,H,I. Sec 23 Unit A,B. Sec 24 Unit A,B,C,D,F,G,H,I,J,O,P. Sec 25 Unit A,O,P. Sec 35 Unit G,H,I,J,K,N,O,P. Sec 36 A,B,C,F – P.

T 21S – R 30E

Sec 1 – Sec 36

T 21S – R 31E

Sec 1 – Sec 36

T 22S – R 28E

Sec 36 Unit A,H,I,P.

T 22S – R 29E

Sec 1. Sec2. Sec 3 Unit I,J,N,O,P. Sec 9 Unit G – P. Sec 10 – Sec 16. Sec 19 Unit H,I,J. Sec 20 – Sec 28. Sec 29 Unit A,B,C,D,G,H,I,J,O,P. Sec 30 Unit A. Section 31 Unit C – P. Sec 32 – Sec 36

T 22S – R 30E

Sec 1 – Sec 36

T 22S – R 31E

Sec 1 – Sec 11. Sec 12 Unit B,C,D,E,F,L. Sec 13 Unit E,F,K,L,M,N. Sec 14 – Sec 23. Sec 24 Unit C,D,E,F,K,L,M,N. Sec 25 Unit A,B,C,D. Sec 26 Unit A,B,C,D,G,H. Sec 27 – Sec 34.

T 23S – R 28E

Sec 1 Unit A

T 23S – R 29E

Sec 1 – Sec 5. Sec 6 Unit A – I, N,O,P. Sec 7 Unit A,B,C,G,H,I,P. Sec 8 Unit A – L, N,O,P. Sec 9 – Sec 16. Sec 17 Unit A,B,G,H,I,P. Sec 21 – Sec 23. Sec 24 Unit A – N. Sec 25 Unit D,E,L. Sec 26. Sec 27. Sec 28 Unit A – J, N,O,P. Sec 33 Unit A,B,C. Sec 34 Unit A,B,C,D,F,G,H. Sec 35. Sec 36 Unit B,C,D,E,F,G,K,L.

T 23S – R 30E

Sec 1 – Sec 18. Sec 19 Unit A – I,N,O,P. Sec 20, Sec 21. Sec 22 Unit A – N, P. Sec 23, Sec 24, Sec 25. Sec 26 Unit A,B,F-P. Sec 27 Unit C,D,E,I,N,O,P. Sec 28 Unit A – H, K,L,M,N. Sec 29 Unit A – J, O,P. Sec 30 Unit A,B. Sec 32 A,B. Sec 33 Unit C,D,H,I,O,P. Sec 34, Sec 35, Sec 36.

T 23S – R 31E

Sec 2 Unit D,E,J,O. Sec 3 – Sec 7. Sec 8 Unit A – G, K – N. Sec 9 Unit A,B,C,D. Sec 10 Unit D,P. Sec 11 Unit G,H,I,J,M,N,O,P. Sec 12 Unit E,L,K,M,N. Sec 13 Unit C,D,E,F,G,J,K,L,M,N,O. Sec 14. Sec 15 Unit A,B,E – P. Sec 16 Unit I, K – P. Sec 17 Unit B,C,D,E, I – P. Sec 18 – Sec 23. Sec 24 Unit B – G, K,L,M,N. Sec 25 Unit B – G, J,K,L. Sec 26 – Sec 34. Sec 35 Unit C,D,E.

T 24S – R 29E

Sec 2 Unit A, B, C, D. Sec 3 Unit A

T 24S – R 30E


Sec 1 Unit A – H, J – N. Sec 2, Sec 3. Sec 4 Unit A,B,F – K, M,N,O,P. Sec 9 Unit A – L. Sec 10 Unit A – L, O,P. Sec 11. Sec 12 Unit D,E,L. Sec 14 Unit B – G. Sec 15 Unit A,B,G,H.

T 24S – R 31E

Sec 3 Unit B – G, J – O. Sec 4. Sec 5 Unit A – L, P. Sec 6 Unit A – L. Sec 9 Unit A – J, O,P. Sec 10 Unit B – G, K – N. Sec 35 Unit E – P. Sec 36 Unit E,K,L,M,N.


T 25S – R 31E


Sec 1 Unit C,D,E,F. Sec 2 Unit A – H.



covinent by OCD: Apa/20/20 Distics 6:47 PN		Form 240 37 of
<u>District I</u> - (575) 393-6161	Energy, Minerals and Natural Resources	Revised July 18, 2013 WELL API NO.
1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1283		30-015-40977
811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION	5. Indicate Type of Lease
District III - (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.	STATE STATE SEE
<u>District IV</u> – (505) 476-3460	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505		
	AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
•	TO DRILL OR TO DEEPEN OR PLUG BACK TO A	Higgins Trust 13 A
DIFFERENT RESERVOIR. USE "APPLICATIO PROPOSALS.)	IN FOR PERMIT (FORM C-101) FOR SUCH	8. Well Number #2
	Well Other	
2. Name of Operator		9. OGRID Number
Redwood Operating, LLC 3. Address of Operator		330211 10. Pool name or Wildcat
PO Box 1370, Artesia, NM 882111370		Red Lake, Glorieta-Yeso (51120)
4. Well Location		
Unit Letter A : 330	feet from theNline and3	30 feet from the E line
	Township 18S Range 26E	NMPM County Eddy
	Elevation (Show whether DR, RKB, RT, GR,	
11	3289' GL	
12. Check Appr	opriate Box to Indicate Nature of Noti	ce. Report or Other Data
		· •
		UBSEQUENT REPORT OF:
PULL OR ALTER CASING I MU DOWNHOLE COMMINGLE		IENT JOB
CLOSED-LOOP SYSTEM		
OTHER:	OTHER:	
13. Describe proposed or completed	operations. (Clearly state all pertinent details	, and give pertinent dates, including estimated date
of starting any proposed work).	SEE RULE 19.15.7.14 NMAC. For Multiple	Completions: Attach wellbore diagram of
proposed completion or recompl	letion.	
1. Set 5 ½" CIBP @ 2975'. C	irc hole w/ MLF. Pressure test csg. Spot 25	sx cmt @ 2975-2775'.
2. Spot 25 sx cmt @ 1086-886	6'. WOC & Tag (San Andres)	
	455' to surface. (8 5/8 Shoe, & Queen)	
4. Cut off well head, verify c	mt @ surface, weld on Dry Hole Marker.	
Spud Date:	Rig Release Date:	
- r · · · · - · · · · · · · · · · · · · ·		
I hereby certify that the information abov	e is true and complete to the best of my knowl	edge and helief
SIGNATUKE	11TLE	DATE
Type or print name	E-mail address	PHONE:
For State Use Only	17 Indit (didi 055	FRONE.
APPROVED BY:	TITLE	DATE
Conditions of Approval (if any):		

.





×4.,

District I 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV 1220 S. St Francis Dr., Santa Fe, NM 87505 Phone: (505) 476-3470 Fax: (505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Operator: 0	OGRID:
Redwood Operating LLC	330211
PO Box 1370	Action Number:
Artesia, NM 882111370	68037
A	Action Type:
	[C-103] NOI Plug & Abandon (C-103F)
CONDITIONS	

Created By	Condition	Condition Date		
gcordero	None	12/23/2021		

CONDITIONS

Action 68037

Page 10 of 10

.