

U.S. Department of the Interior BUREAU OF LAND MANAGEMENT

Sundry Print Report

Well Name: LOCO HILLS SWD 33 Well Location: T17S / R30E / SEC 33 / County or Parish/State: EDDY /

SWNE /

INIVI

Well Number: 6 Type of Well: INJECTION - ENHANCED Allottee or Tribe Name:

RECOVERY

Lease Number: NMNM0558581 Unit or CA Name: Unit or CA Number:

US Well Number: 3001539478 Well Status: Water Disposal Well Operator: SPUR ENERGY

PARTNERS LLC

## **Notice of Intent**

**Sundry ID: 2656004** 

Type of Submission: Notice of Intent

Type of Action: Workover Operations

Date Sundry Submitted: 02/07/2022 Time Sundry Submitted: 04:17

Date proposed operation will begin: 02/10/2022

**Procedure Description:** Attached is a WBD for the Loco Hills 33 #6 SWD and a procedure. We are pulling it to replace a leaking packer / hole in tubing and will be running back in with the same design and setting the packer within 50' of its current depth.

# **Surface Disturbance**

Is any additional surface disturbance proposed?: No

## **NOI Attachments**

# **Procedure Description**

 $Loco\_Hills\_33\_6\_HIT\_or\_Packer\_Leak Procedure\_20220207161656.pdf$ 

Loco\_Hills\_33\_6\_WBD\_20220207161656.pdf

eived by OCD: 2/24/2022 12:12:41 PM Well Name: LOCO HILLS SWD 33

Well Location: T17S / R30E / SEC 33 /

SWNE /

County or Parish/State: Page 2 of

Well Number: 6

**RECOVERY** 

Lease Number: NMNM0558581

**Unit or CA Name:** 

**Unit or CA Number:** 

**US Well Number:** 3001539478

Well Status: Water Disposal Well

**Operator: SPUR ENERGY** 

PARTNERS LLC

Zip:

# **Conditions of Approval**

## **Specialist Review**

Workover\_or\_Vertical\_Deepen\_COA\_20220224113019.pdf

# **Operator Certification**

I certify that the foregoing is true and correct. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction. Electronic submission of Sundry Notices through this system satisfies regulations requiring a submission of Form 3160-5 or a Sundry Notice.

**Operator Electronic Signature: SARAH CHAPMAN** Signed on: FEB 07, 2022 04:17 PM

Name: SPUR ENERGY PARTNERS LLC

Title: Regulatory Directory

Street Address: 9655 KATY FREEWAY, SUITE 500

City: Houston State: TX

Phone: (832) 930-8613

Email address: SCHAPMAN@SPUREPLLC.COM

# **Field Representative**

**Representative Name:** 

**Street Address:** 

State: City:

Phone:

**Email address:** 

# **BLM Point of Contact**

Signature: Jonathon Shepard

**BLM POC Name:** Jonathon W Shepard **BLM POC Title:** Petroleum Engineer

**BLM POC Phone:** 5752345972 **BLM POC Email Address:** jshepard@blm.gov

**Disposition:** Approved **Disposition Date:** 02/24/2022

Page 2 of 2

### **BUREAU OF LAND MANAGEMENT**

Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

# Conditions of Approval for Workover/Deepening of a Well

- 1. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any operations. For wells in Eddy County, call 575-361-2822. For wells in Lea County, call 575-689-5981
- 2. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,100 feet, a 3M system for a well not deeper than 13,600 feet, or a 5M system for a well not deeper than 22,700 feet (all depths are for measured well depth).
- 3. Cement: Notify BLM if cement fails to circulate.
- 4. <u>Subsequent Reporting:</u> Within 30 days after work is completed, file a Subsequent Report (Form 3160-5) to BLM. The report should give in detail the manner in which the work was carried out. <u>Show date work was completed</u>. If producing a new zone, submit a Completion Report (Form 3160-4) with the Subsequent Report.
- 5. <u>Trash</u>: All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.
- 6. If well location is within the Timing Limitation Stipulation Area for Lesser Prairie-Chicken: From March 1<sup>st</sup> through June 15<sup>th</sup> annually, activities will be allowed except between the hours from 3:00 am and 9:00 am. Normal vehicle use on existing roads will not be restricted.

### Loco Hills SWD 33 #6

HIT or Packer Leak AFE -Laurel Marsh 832-646-8568



## **OBJECTIVES**

The Loco Hills SWD 33 # 6 is unable to hold pressure, indicating a hole in tubing or a leaking packer.

- RIH w/ plug on slickline and test tbg to 1,000 psi
- If tubing does not test, get off O/O tool and POOH
- If tubing does test, POOH with tubing and packer
- RBIH while hydrotesting tubing to 6,000 lbs below slips
- Set packer, get off O/O tool, circulate packer fluid and test backside to 500 psi for 15 minutes

## **Current Tubing Detail**

Tul	Tubing Strings										
Tubing Description Production Tubing				Set Depth (ftKB) 8,371.4			Run Date 2/18/2012				
Tubing Components											
Jts	Item Des	OD (in)	ID (in)	Wt (lb/ft)	Grade	Top Thread	Top Connection Type	Len (ft)	Cum Len (ft)	Top (ftKB)	Btm (ftKB)
	KELLY BUSHING							13.00	8,371.41	0.0	13.0
1	TUBING	3 1/2	2.65	9.30	J55			32.55	8,358.41	13.0	45.6
	PUP JOINT	3 1/2	2.65	9.30	J55			10.15	8,325.86	45.6	55.7
255	TUBING	3 1/2	2.65	9.30	J55			8,297.21	8,315.71	55.7	8,352.9
	CROSS OVER DOWN	3 1/2						0.53	18.50	8,352.9	8,353.4
	ON/OFF TOOL	5 7/8						1.48	17.97	8,353.4	8,354.9
	F NIPPLE							1.00	16.49	8,354.9	8,355.9
	PRODUCTION PACKER	5 7/8	2.44					8.23	15.49	8,355.9	8,364.2
	PUP JOINT	2 7/8	2.50	6.70	N-80			5.79	7.26	8,364.2	8,369.9
	R NIPPLE	3.668	2.25					1.00	1.47	8,369.9	8,370.9
	PUMP OUT PLUG	3 5/8	2.50					0.47	0.47	8,370.9	8,371.4

WIRELINE. TIH W/ 5.95 GAUGE RING 8370'. TOH. TIH W/ PUMP OUT PLUG, 2.31 R NIPPLE, 6' 2 7/8 NICKEL COATED SUB, 10K ARROWSET PACKER, 2.31 F NIPPLE, ON OFF TOOL AND SETTING TOOL. SET PACKER AT 8350'. TOP PERF IS 8392'.

### **PROCEDURE**

Spur Energy Partners LLC is committed to providing a safe working environment for all personnel. A safety meeting will be held prior to commencing each operation in order to define/clarify objectives, roles and responsibilities, identify all potential risk/hazards and establish a work procedure that is safe and environmentally sound. Meetings are to be documented on the reports returned to Spur Energy Partners LLC.

#### PERFORM SAFETY CHECKS AND SAFETY MEETING

1. Perform a safety meeting prior to rigging up **ANY** equipment on location. Discuss the job procedure and objective with all personnel on location. Document the safety meeting on the daily report sent to Spur. Make note of all potential risks/hazards, and clearly identify an emergency route and emergency vehicle. Also make note of any new or inexperienced personnel on location. Ensure proper Personal Protective Equipment (PPE) is used during the job. Minimums are hard hats, steel toes, safety glasses, H<sub>2</sub>S monitors, and FR certified clothing as required. Designate a smoking area off location and 100' from any potential hydrocarbons.

### **PROCEDURE**

Spur Energy Partners LLC is committed to providing a safe working environment for all personnel. A safety meeting will be held prior to commencing each operation in order to define/clarify objectives, roles and responsibilities, identify all potential risk/hazards and establish a work procedure that is safe and environmentally sound. Meetings are to be documented on the reports returned to Spur Energy Partners LLC.

### PERFORM SAFETY CHECKS AND SAFETY MEETING

2. Perform a safety meeting prior to rigging up ANY equipment on location. Discuss the job procedure and objective with all personnel on location. Document the safety meeting on the daily report sent to Spur. Make note of all potential risks/hazards, and clearly identify an emergency route and emergency vehicle. Also make note of any new or inexperienced personnel on location. Ensure proper Personal Protective Equipment (PPE) is used during the job. Minimums are hard hats, steel toes, safety glasses, H<sub>2</sub>S monitors, and FR certified clothing as required. Designate a smoking area off location and 100' from any potential hydrocarbons.

## REPORTING STANDARDS

- 1. Communicate with the Spur Workovers group at a minimum of every 2 hrs including any critical operations.
- 2. Record <u>ALL</u> costs and input into WellView. If you are unable to get the cost from the vendor, use an estimate and put in the comments that it is an estimated cost.


### MIRU WOR AND SL Unit


- 1. Shut-in the well on the flowlines. Ensure that the H-Pump is shut off. Check the pressure on the tubing, production casing, & surface casing and record in WellView.
- 3. MIRU workover rig and kill truck.
- 4. Bull-head the minimum amount of Fresh Water (8.33 ppg) down the tubing to maintain safe control of the well.
  - a) Treat all fluid pumped into the well with 5 gals biocide per 130 bbls fresh water.
  - b) Ensure that the well is dead. If tubing pressures up, test the tubing to 500 psi for 5 minutes.
  - c) Record the volume of fluid pumped in WellView.
- 5. RIH w/ F profile nipple and set in packer profile. 2.31 F Nipple.
- 6. Pressure up on the tubing to 1000 psi and note any leakoff
- 7. If tubing does not hold get off the O/O tool (It is a T-2 tool but well files are unclear)
- 8. If tubing holds, unset the packer and POOH

## RIH w/ 3-1/2" IPC TUBING (AND PACKER IF TUBING TESTED GOOD)

- 9. MI 3-1/2" IPC from the BKU yard to replace bad joints as needed
- 10. RU 3-1/2" tubing tongs and elevators.
- 11. MIRU tubing testers and pressure test the tubing RIH to 6,000 psi Below Slips.
  - a) Ensure tubing is loaded with FW while testing in to maintain control of the well.
- 12. RIH with the tubing as shown in the TUBING DESIGN ON PAGE 1.

- 13. Set the packer at +/- 8,355' (No change to packer depth)
- 14. Get off the O/O tool and circulate packer fluid
- 15. Latch back onto the O/O tool and test the backside to 500 psi for 15 Minutes
- 16. Inform the Foreman that the work has been completed and the well is ready to resume injection.
  - a) SWD Foreman: Hilario Jimenez 575.703.4925
  - b) Loco Hills Sr Foreman: JP Hermes 575.703.6218
  - c) Loco Hills SWD Tech: Brian Thompson 575.703.4565





District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. **Santa Fe, NM 87505** 

COMMENTS

Action 83987

#### **COMMENTS**

Operator:	OGRID:
Spur Energy Partners LLC	328947
9655 Katy Freeway	Action Number:
Houston, TX 77024	83987
	Action Type:
	[C-103] NOI Workover (C-103G)

#### COMMENTS

Created By	Comment	Comment Date
drose	UIC	3/3/2022

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. **Santa Fe, NM 87505** 

CONDITIONS

Action 83987

### **CONDITIONS**

Operator:	OGRID:
Spur Energy Partners LLC	328947
9655 Katy Freeway	Action Number:
Houston, TX 77024	83987
	Action Type:
	[C-103] NOI Workover (C-103G)

#### CONDITIONS

Created By		Condition Date
drose	None	3/3/2022