

Received by OCD: 6/17/2022 1:07:09 PM

	CW MEXICO	Form C-103		
District 1 - (575) 575-0101	nd Natural Resources Revise WELL API NO.	ed July 18, 2013		
1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1283	ATION DIVISION 30-25-27586			
811 S First St Artesia NM 88210 OIL CONDERV	St. Francis Dr. 5. Indicate Type of Lease	вП		
100000	NM 87505 6. State Oil & Gas Lease N			
1220 S. St. Francis Dr., Santa Fe, NM	307068			
87505 SUNDRY NOTICES AND REPORTS ON	WELLS 7. Lease Name or Unit Agre	ement Name		
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEP. DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM	Bobbi State Waterflo	ood Unit		
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other	8. Well Number 4			
2. Name of Operator	9. OGRID Number			
SUNDOWN ENERGY LP	232611 10. Pool name or Wildcat			
3. Address of Operator 16400 DALLAS PARKWAY, STE. 100 DALLAS, TX 73		res, West		
4. Well Location		- 1		
Unit Letter <u>L</u> : <u>1650</u> feet from the <u>So</u>				
Section 20 Township 18S	Range36ENMPMLEACountyether DR, RKB, RT, GR, etc.)			
3838' GR				
	the Difference of the Determination of the Determination			
12. Check Appropriate Box to Inc	licate Nature of Notice, Report or Other Data	_		
NOTICE OF INTENTION TO:)F: g casing □		
PERFORM REMEDIAL WORK D PLUG AND ABANDON	REMEDIAL WORK ALTERING COMMENCE DRILLING OPNS. P AND A			
TEMPORARILY ABANDON				
	-			
	OTHER: Did not convert to inj.			
OTHER:	state all pertinent details, and give pertinent dates, includin	ig estimated date		
of starting any proposed work). SEE RULE 19.15.7.	14 NMAC. For Multiple Completions: Attach wellbore dia	agram of		
proposed completion or recompletion.				
TOC = 5100' behind 4 ½" csg				
1) Unset PKR. POOH w/ tbg and PKR.				
 2) TIH w/ CIBP on tubing. Set CIBP at 5100'. Circulate well with 9.5 PPG mud. 				
3) Perf sqz holes at 5000'. Perf and Squeeze 75 sx	s cement plug from 4800' to 5100' (top of SA zone @	4958').		
4) Perf and Squeeze 75 sxs cement 4231' to 4431' (top of Queen zone @ 4431').				
5) Perf and Squeeze 75 sxs cement 3098 to 3298' (top of Yates zone @ 3298' & top of Lwr Salt zone @ 3136').				
6) Perf and Squeeze 75 sxs cement 1751' to 1951'	$(85/8^{\circ} \text{ csg snoe } \oplus 1901)$.			
7) Perf @ 300' and Spot 40 sxs cement from 0 to 3				
Spud Date: 4" Diameter 4' tall above ground marker Rig F	Release Date: See attached conditions of approval			
I hereby certify that the information above is true and comple	te to the best of my knowledge and belief.			
1- 71				
	LE Joint Ops Engineer DATE 6/15/2022	vt 2114		
Type or print name <u>Steve Flynn</u> E-mail address: <u>sflynn@sundownenergy.com</u> PHONE <u>214-368-6100 Ext 2114</u>				
For State Use Only	E Compliance Officer A DATE 6/23/2	2		
APPROVED BY: <u>Kiny Jother</u> TITI	E Compliance Officer A DATE 6/23/2	۷		
Conditions of Approval (if any): Released to Imaging: 6/24/2022 7:24:58 AM				

Received by OCD: 6/17/2022 1:07:09 PM

WELL DATA SHEET





CONDITIONS OF APPROVAL FOR PLUGGING AND ABANDONMENT OCD - Southern District

The following is a guide or checklist in preparation of a plugging program, this is not all inclusive and care must be exercised in establishing special plugging programs in unique and unusual cases, Notify NMOCD District Office I (Hobbs) at (575)-263-6633 at least 24 hours before beginning work. After MIRU rig will remain on well until it is plugged to surface. OCD is to be notified before rig down.

Company representative will be on location during plugging procedures.

1. A notice of intent to plug and abandon a wellbore is required to be approved before plugging operations are conducted. A cement evaluation tool is required in order to ensure isolation of producing formations, protection of water and correlative rights. A cement bond log or other accepted cement evaluation tool is to be provided to the division for evaluation if one has not been previously run or if the well did not have cement circulated to surface during the original casing cementing job or subsequent cementing jobs. Insure all bradenheads have been exposed, identified and valves are operational prior to rig up.

2. Closed loop system is to be used for entire plugging operation. Upon completion, contents of steel pits are to be hauled to a permitted disposal location.

3. Trucking companies being used to haul oilfield waste fluids to a disposal - commercial or private- shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator as well as the contractor, to verify that this permit is in place prior to performing work. Drivers shall be able to produce a copy upon request of an NMOCD Field inspector.

4. Filing a subsequent C-103 will serve as notification that the well has been plugged.

5. A final C-103 shall be filed (and a site inspection by NMOCD Inspector to determine if the location is satisfactorily cleaned, all equipment, electric poles and trash has been removed to Meet NMOCD standards) before bonding can +be released.

6. If work has not begun within 1 Year of the approval of this procedure, an extension request must be file stating the reason the well has not been plugged.

7. Squeeze pressures are not to exceed 500 psi, unless approval is given by NMOCD.

8. Produced water will not be used during any part of the plugging operation.

9. Mud laden fluids must be placed between all cement plugs mixed at 25 sacks per 100 bbls of water.

10. All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater. 50' of calculated cement excess required for inside casing plugs and 100% calculated cement excess required on outside casing plugs.

11. Class 'C' cement will be used above 7500 feet.

12. Class 'H' cement will be used below 7500 feet.

13. A cement plug is required to be set 50' above and 50' below, casing stubs, DV tools, attempted casing cut offs, cement tops outside casing, salt sections and anywhere the casing is perforated, these plugs require a 4 hour WOC and then will be tagged

14. All Casing Shoes Will Be Perforated 50' below shoe depth and Attempted to be Squeezed, cement needs to be 50' above and 50' Below Casing Shoe inside the Production Casing.

16. When setting the top out cement plug in production, intermediate and surface casing, wellbores should remain full at least 30 minutes after plugs are set

17. A CIBP is to be set within 100' of production perforations, capped with 100' of cement, WOC 4 hours and tag.

18. A CIBP with 35' of cement may be used in lieu of the 100' plug if set with a bailer. This plug will be placed within 100' of the top perforation, (WOC 4 hrs and tag).

19. No more than 3000' is allowed between cement plugs in cased hole and 2000' in open hole.

20. Some of the Formations to be isolated with cement plugs are: These plugs to be set to isolate formation tops

- A) Fusselman
- B) Devonian
- C) Morrow
- D) Wolfcamp
- E) Bone Springs
- F) Delaware
- G) Any salt sections
- H) Abo
- I) Glorieta
- J) Yates.

K) Potash---(In the R-111-P Area (Potash Mine Area),

A solid cement plug must be set across the salt section. Fluid used to mix the cement shall be saturated with the salts that are common to the section penetrated and in suitable proportions, not more than 3% calcium chloride (by weight of cement) will be considered the desired mixture whenever possible, WOC 4 hours and tag, this plug will be 50' below the bottom and 50' above the top of the Formation.

21. If cement does not exist behind casing strings at recommended formation depths, the casing can be cut and pulled with plugs set at recommended depths. If casing is not pulled, perforations will be shot and cement squeezed behind casing, WOC and tagged. These plugs will be set 50' below formation bottom to 50' above formation top inside the casing.

DRY HOLE MARKER REQ.UIRMENTS

The operator shall mark the exact location of the plugged and abandoned well with a steel marker not less than four inches in diameter, 3' below ground level with a plate of at least ¼" welded to the top of the casing and the dry hole marker welded on the plate with the following information welded on the dry hole marker:

- 1. Operator name
- 2. Lease and Well Number
- 3. API Number
- 4. Unit letter
- 5. Quarter Section (feet from the North, South, East or West)
- 6. Section, Township and Range
- 7. Plugging Date
- 8. County

SPECIAL CASES -----AGRICULTURE OR PRARIE CHICKEN BREEDING AREAS

In these areas, a below ground marker is required with all pertinent information mentioned above on a plate, set 3' below ground level, a picture of the plate will be supplied to NMOCD for record, the exact location of the marker (longitude and latitude by GPS) will be provided to NMOCD (We typically require a current survey to verify the GPS)

SITE REMEDIATION DUE WITHIN ONE YEAR OF WELL PLUGGING COMPLETION

District I 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV 1220 S. St Francis Dr., Santa Fe, NM 87505 Phone: (505) 476-3470 Fax: (505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

COMMENTS

Operator: (OGRID:
SUNDOWN ENERGY LP	232611
16400 Dallas Pkwy	Action Number:
Dallas, TX 75248	118416
	Action Type:
	[C-103] NOI Plug & Abandon (C-103F)

COMMENTS

Created By	Comment	Comment Date
plmartinez	DATA ENTRY PM	6/24/2022

Page 6 of 7

.

Action 118416

District I 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV 1220 S. St Francis Dr., Santa Fe, NM 87505 Phone: (505) 476-3470 Fax: (505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Operator:	OGRID:
SUNDOWN ENERGY LP	232611
16400 Dallas Pkwy	Action Number:
Dallas, TX 75248	118416
	Action Type:
	[C-103] NOI Plug & Abandon (C-103F)

CONDITIONS

Created By		Condition Date
kfortner	See attached COA	6/23/2022

Page 7 of 7

Action 118416