Submit 1 Copy To Appropriate District Office	State of New Me	exico	Form C-103			
District I - (575) 393-6161	Energy, Minerals and Natu	ural Resources	Revised July 18, 2013			
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283	ON GONGERNAL TOO	I DALWATAN	WELL API NO. 30-25-27641			
811 S. First St., Artesia, NM 88210 District III – (505) 334-6178	OIL CONSERVATION		5. Indicate Type of Lease			
1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Fra		STATE S FEE			
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM	Santa Fe, NM 8	7505	6. State Oil & Gas Lease No.			
87505			309115			
	ICES AND REPORTS ON WELLS		7. Lease Name or Unit Agreement Name			
	SALS TO DRILL OR TO DEEPEN OR PL CATION FOR PERMIT" (FORM C-101) FO		D 11' G . W . G . IXI '			
PROPOSALS.)			Bobbi State Waterflood Unit			
1. Type of Well: Oil Well	Gas Well Other		8. Well Number 5			
2. Name of Operator SUNDOWN ENERGY LP			9. OGRID Number			
3. Address of Operator			232611 10. Pool name or Wildcat			
16400 DALLAS PARKWAY, ST	E. 100 DALLAS, TX 75248		Arkansas Junction; San Andres, West			
4. Well Location						
Unit Letter <u>E</u> :	2310 feet from the <u>NORTH</u>	line and	990 feet from the <u>WEST</u> line			
Section 20	Township 18S Rang	ge 36E	NMPM LEA County			
	11. Elevation (Show whether DR	, RKB, RT, GR, etc.,				
	3847' GR					
12 Charle	Ammanuista Dan ta Indianta N	Internal of NI-41	Daniel an Other Date			
12. Check A	Appropriate Box to Indicate N	lature of Notice,	Report or Other Data			
NOTICE OF IN	ITENTION TO:	SUB	SEQUENT REPORT OF:			
PERFORM REMEDIAL WORK	PLUG AND ABANDON 🛛	REMEDIAL WOR				
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRI	-			
PULL OR ALTER CASING DOWNHOLE COMMINGLE	MULTIPLE COMPL	CASING/CEMENT	I JOB			
CLOSED-LOOP SYSTEM						
OTHER:		OTHER: Did not c				
			give pertinent dates, including estimated date			
of starting any proposed we proposed completion or rec		C. For Multiple Con	npletions: Attach wellbore diagram of			
proposed completion of rec	ompletion.					
TOC = 5100' calc behind 4	½" csg					
1) Upont DVD DOOLL/th						
 Unset PKR. POOH w/ tbg TIH w/ CIBP on tubing. S 	g and PKK. Set CIBP at 5240'. Circulate well	with 0 5 DDC	Spot 25 sx Class C 5240			
			o 5100' (top of SA zone @ 4952').			
	cement 4226' to 4426' (top of Q					
-			& top of Lwr Salt zone @ 3132').			
	cement 1745' to 1945' (8 5/8" c					
	0 sxs cement from 0 to 300' (insi	-				
			0,			
4" diameter 4' tall ab	ove ground marker	See attached	conditions of approval			
Spud Date:	Rig Release Da	ite:				
I hereby certify that the information	above is true and complete to the be	est of my knowledge	and belief.			
SIGNATURE Street	TITLE Joint	Ops Engineer	DATE 6/15/2022			
Type or print name Steve Flynn	E-mail address: sflynn@s	undownenergy.com	PHONE 214-368-6100 Ext 2114			
For State Use Only						
APPROVED BY: _ Kerry Fo	ither TITLE (ompliance Of	frien A DATE 6/23/22			
Conditions of Appro. Released to Imaging: 6/24/2022 7:2	C:40.41V	1 1	V			
Keteasea to 1maging: 0/24/2022 7:2	0:40 AM					

WELL DATA SHEET

		AAFFI	DATA STILL			
LEASE:	BOBBI	WELL:	5	FIELD: W.	ARKANSAS JUNC	TION - S
LOC: STATUS: TD: PBTD: COTD:	2310' FNL & 990' FWL ACTIVE 5724' 5713'		STATE EA MEXICO	Unit: E Sec: API NO: LEASE #	20 Township: 18S 30-025-27641 LG-1869	Range: 3
Spud Date: Comp.Date: GL: DF: KB:	5'	40 sxs 	8-5/8" OD, csg set @ Circ? YES Hole Size: 4-1/2" OD,	1895' w/ TOC @	SURF By	ST&C ST&C CALC
	Cmt Plug 3 3092' to 3292'		Lwr Salt Zone 3132' Yates Zone 3292'			
	Cmt Plug 2 4226' to 44261'	75 sxs	Queen Zone 4426'			
	Cmt Plug 1 4700' to 5100' Cibp' \$ \$100 Cibp	75 sxs	Top of San Andres zone 4958' TOC at 5100' calc 5293 - 5307' 2 SPF, 13			
	5713' PBTD CSG SHOE		5724' TD			

WELL DATA SHEET

			VVLL	LUAI	A OHILL I				
LEASE:	BOBBI	WELL	:	5		FIELD: V	V. ARKANSAS JI	JNCT	ION - S
LOC:	2310' FNL & 990' FWL	Fed, S	tate, Fee		STATE	Unit: E S	Sec: 20 Township:	185	Range: 3
STATUS:	ACTIVE	CO:	L	EA		API NO:	30-025-2764	1	
TD:	5724'	ST:	NEW N	VEXICO		LEASE #	LG-1869		
PBTD:	5713'								
COTD:									
Spud Date:	11/16/81	1	TI	_	Csg Detail:				
Comp.Date:	1/20/82		11		Hole Size: 8-5/8"	12-1/4" OD, 24	#/ft, grade		ST&C
GL:	3836'		100	43	csg set @	1895'	w/ 925	SX.	0.00
DF:		l			Circ? YE	S TOC @	SURF By		
KB	3847'				Hole Size:	7-7/8"			
						OD , 10.5			ST&C
					csg set @	5713'	w/ 175	sx.	CALC
					Circ?	TOC @	5100' By		CALC
		1							
	<i>></i>								
	PRODUCER		1						
		1							
		1	1						
		100	1						
		1							
		1	1						
		1	-						
		ı							
		1							
		1							
		1	1						
		1	1						
	1	8	100						
			#						
			7	5293 -	5307' 2 SP	F, 12 HOLES	SA		
	5713' PBTD								
	CSG SHOE	1	1	5724'	TD				
		4	2						

Corrent

CONDITIONS OF APPROVAL FOR PLUGGING AND ABANDONMENT OCD - Southern District

The following is a guide or checklist in preparation of a plugging program, this is not all inclusive and care must be exercised in establishing special plugging programs in unique and unusual cases, Notify NMOCD District Office I (Hobbs) at (575)-263-6633 at least 24 hours before beginning work. After MIRU rig will remain on well until it is plugged to surface. OCD is to be notified before rig down.

Company representative will be on location during plugging procedures.

- **1.** A notice of intent to plug and abandon a wellbore is required to be approved before plugging operations are conducted. A cement evaluation tool is required in order to ensure isolation of producing formations, protection of water and correlative rights. A cement bond log or other accepted cement evaluation tool is to be provided to the division for evaluation if one has not been previously run or if the well did not have cement circulated to surface during the original casing cementing job or subsequent cementing jobs. Insure all bradenheads have been exposed, identified and valves are operational prior to rig up.
- **2.** Closed loop system is to be used for entire plugging operation. Upon completion, contents of steel pits are to be hauled to a permitted disposal location.
- **3.** Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private- shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator as well as the contractor, to verify that this permit is in place prior to performing work. Drivers shall be able to produce a copy upon request of an NMOCD Field inspector.
- 4. Filing a subsequent C-103 will serve as notification that the well has been plugged.
- **5.** A final C-103 shall be filed (and a site inspection by NMOCD Inspector to determine if the location is satisfactorily cleaned, all equipment, electric poles and trash has been removed to Meet NMOCD standards) before bonding can +be released.
- **6.** If work has not begun within 1 Year of the approval of this procedure, an extension request must be file stating the reason the well has not been plugged.
- 7. Squeeze pressures are not to exceed 500 psi, unless approval is given by NMOCD.
- **8.** Produced water will not be used during any part of the plugging operation.
- 9. Mud laden fluids must be placed between all cement plugs mixed at 25 sacks per 100 bbls of water.
- **10.** All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater. 50' of calculated cement excess required for inside casing plugs and 100% calculated cement excess required on outside casing plugs.
- 11. Class 'C' cement will be used above 7500 feet.
- 12. Class 'H' cement will be used below 7500 feet.
- **13.** A cement plug is required to be set 50' above and 50' below, casing stubs, DV tools, attempted casing cut offs, cement tops outside casing, salt sections and anywhere the casing is perforated, these plugs require a 4 hour WOC and then will be tagged
- **14.** All Casing Shoes Will Be Perforated 50' below shoe depth and Attempted to be Squeezed, cement needs to be 50' above and 50' Below Casing Shoe inside the Production Casing.
- **16.** When setting the top out cement plug in production, intermediate and surface casing, wellbores should remain full at least 30 minutes after plugs are set
- 17. A CIBP is to be set within 100' of production perforations, capped with 100' of cement, WOC 4 hours and tag.
- **18.** A CIBP with 35' of cement may be used in lieu of the 100' plug if set with a bailer. This plug will be placed within 100' of the top perforation, (WOC 4 hrs and tag).

- 19. No more than 3000' is allowed between cement plugs in cased hole and 2000' in open hole.
- 20. Some of the Formations to be isolated with cement plugs are: These plugs to be set to isolate formation tops
- A) Fusselman
- B) Devonian
- C) Morrow
- D) Wolfcamp
- E) Bone Springs
- F) Delaware
- G) Any salt sections
- H) Abo
- I) Glorieta
- J) Yates.
- K) Potash---(In the R-111-P Area (Potash Mine Area),

A solid cement plug must be set across the salt section. Fluid used to mix the cement shall be saturated with the salts that are common to the section penetrated and in suitable proportions, not more than 3% calcium chloride (by weight of cement) will be considered the desired mixture whenever possible, WOC 4 hours and tag, this plug will be 50' below the bottom and 50' above the top of the Formation.

21. If cement does not exist behind casing strings at recommended formation depths, the casing can be cut and pulled with plugs set at recommended depths. If casing is not pulled, perforations will be shot and cement squeezed behind casing, WOC and tagged. These plugs will be set 50' below formation bottom to 50' above formation top inside the casing.

DRY HOLE MARKER REQ.UIRMENTS

The operator shall mark the exact location of the plugged and abandoned well with a steel marker not less than four inches in diameter, 3' below ground level with a plate of at least ¼" welded to the top of the casing and the dry hole marker welded on the plate with the following information welded on the dry hole marker:

- 1. Operator name
- 2. Lease and Well Number
- 3. API Number
- 4. Unit letter
- 5. Quarter Section (feet from the North, South, East or West)
- 6. Section, Township and Range
- 7. Plugging Date
- 8. County

SPECIAL CASES ----AGRICULTURE OR PRARIE CHICKEN BREEDING AREAS

In these areas, a below ground marker is required with all pertinent information mentioned above on a plate, set 3' below ground level, a picture of the plate will be supplied to NMOCD for record, the exact location of the marker (longitude and latitude by GPS) will be provided to NMOCD (We typically require a current survey to verify the GPS)

SITE REMEDIATION DUE WITHIN ONE YEAR OF WELL PLUGGING COMPLETION

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

COMMENTS

Action 118417

COMMENTS

Operator:	OGRID:
SUNDOWN ENERGY LP	232611
16400 Dallas Pkwy	Action Number:
Dallas, TX 75248	118417
	Action Type:
	[C-103] NOI Plug & Abandon (C-103F)

COMMENTS

Created By		Comment Date
plmartinez	DATA ENTRY PM	6/24/2022

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III 1000 Rio Brazos Rd., Aztec, NM 87410

Phone:(505) 334-6178 Fax:(505) 334-6170 1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 118417

CONDITIONS

Operator:	OGRID:
SUNDOWN ENERGY LP	232611
16400 Dallas Pkwy	Action Number:
Dallas, TX 75248	118417
	Action Type:
	[C-103] NOI Plug & Abandon (C-103F)

CONDITIONS

Created By		Condition Date
kfortner	See attached COA	6/23/2022