Received by OCD: 1/3/2023 2:40:36 PM	N. Madas	Form C-103 of
	New Mexico	Revised July 18, 2013
District I – (575) 393-6161 Energy, Minerals	and Natural Resources	WELL API NO.
1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1283		30-005-20337
811 S. First St. Artesia, NM 88210	VATION DIVISION	Indicate Type of Lease
District III - (505) 334-6178 1220 South	n St. Francis Dr.	STATE FEE X
1000 Rio Brazos Rd., Aztec, NM 87410 District IV - (505) 476-3460	e, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM		1.
87505	NWELLC	7. Lease Name or Unit Agreement Name
SUNDRY NOTICES AND REPORTS O (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEE	PEN OR PLUG BACK TO A	7. Lease Name of Olitersgreeness runn
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FOR	M C-101) FOR SUCH	Double L Queen Unit
PROPOSALS.)		8. Well Number. 002P
1. Type of Well: Oil Well X Gas Well Other		000.002.27050.000.000.0000
2. Name of Operator		9. OGRID Number 269864
State of New Mexico formerly Canyon E&P Company		10. Pool name or Wildcat
3. Address of Operator		Double L
1625 N. French Drive, Hobbs, N 88240		20002
4. Well Location		2310 feet from the E line
Unit Letter <u>G</u> : 1660 feet from the	Transport Television (1997)	
Section 6 Township	15S Range 30E	NMPM Chaves County
11. Elevation (Show w	hether DR, RKB, RT, GR, et	(c.)
建筑建设铁铁层建筑		
12. Check Appropriate Box to I	ndicate Nature of Notice	e, Report or Other Data
NOTICE OF INTENTION TO:	The state of the s	BSEQUENT REPORT OF: ORK ALTERING CASING
PERFORM REMEDIAL WORK PLUG AND ABANDO		- De 198 Aug
TEMPORARILY ABANDON		
PULL OR ALTER CASING MULTIPLE COMPL	☐ CASING/CEME	INI JOB L
DOWNHOLE COMMINGLE		
CLOSED-LOOP SYSTEM	☐ OTHER:	
OTHER: 13. Describe proposed or completed operations. (Clear	ly state all pertinent details :	and give pertinent dates, including estimated date
of starting any proposed work). SEE RULE 19.15.	7 14 NMAC For Multiple (Completions: Attach wellbore diagram of
proposed completion or recompletion.	7.14 Interior For Findiple	
proposed completion of recompletion.		
Intent to P&A this well. Notify NMOCD to witnes	s plugging operations.	
MIRU, NU BOP, POH with tbg (4.5" casing @ 202	21' w/200 sxs cement circula	nted)
Set CR or CIBP @ 1878'. Cement with 25 sxs.		
RIH, circ well with weighted water.		
PUH to 1241'. Cement with 25 sxs.		
TOH, Perforate @ 950', Coment 100' inside and or		
TOH, Periorate @ 451. Centent 100 histoc and o	utside 4.5" casing, tag. (8-5/8	R" casing @ 381' w/200 sxs circulated).
Perforate 4.5" @ 50': circulate cement to surface	utside 4.5" casing, tag (8-5/8	3" casing @ 381' w/200 sxs circulated).
Perforate 4.5" @ 50'; circulate cement to surface.	utside 4.5" casing, tag (8-5/8	
Perforate 4.5" @ 50'; circulate cement to surface. Cut off WH. Install 4" diameter 4' tall Above Grad	utside 4.5" casing, tag (8-5/8	
Cut off WH. Install 4" diameter 4' tall Above Grad	utside 4.5" casing, tag (8-5/8	necessary. Record Long/Lat
Perforate 4.5" @ 50'; circulate cement to surface. Cut off WH. Install 4" diameter 4' tall Above Grad Note: Brine Gel will be placed between all cement Note: 100' or 25 sxs cement minimum.	utside 4.5" casing, tag (8-5/8	necessary. Record Long/Lat SEE ATTACHED CONDITION
Cut off WH. Install 4" diameter 4' tall Above Grad Note: Brine Gel will be placed between all cement	utside 4.5" casing, tag (8-5/8	necessary. Record Long/Lat
Note: Brine Gel will be placed between all cement Note: 100' or 25 sxs cement minimum. Note: CBL will be run after setting CIBP.	utside 4.5" casing, tag (8-5/8 le P&A marker. Top off as a plugs.	SEE ATTACHED CONDITION OF APPROVAL
Note: Brine Gel will be placed between all cement Note: 100' or 25 sxs cement minimum.	utside 4.5" casing, tag (8-5/8 le P&A marker. Top off as a plugs.	SEE ATTACHED CONDITION OF APPROVAL
Note: Brine Gel will be placed between all cement Note: 100' or 25 sxs cement minimum. Note: CBL will be run after setting CIBP.	utside 4.5" casing, tag (8-5/8 le P&A marker. Top off as a plugs.	SEE ATTACHED CONDITION OF APPROVAL
Note: Brine Gel will be placed between all cement Note: 100' or 25 sxs cement minimum. Note: CBL will be run after setting CIBP. I hereby certify that the information above is true and comp.	utside 4.5" casing, tag (8-5/8 le P&A marker. Top off as a plugs.	SEE ATTACHED CONDITION OF APPROVAL edge and belief.
Note: Brine Gel will be placed between all cement Note: 100' or 25 sxs cement minimum. Note: CBL will be run after setting CIBP. I hereby certify that the information above is true and complete SIGNATURE.	te P&A marker. Top off as a plugs. The to the best of my knowled the total and the first of the	SEE ATTACHED CONDITION OF APPROVAL edge and belief.
Note: Brine Gel will be placed between all cement Note: 100' or 25 sxs cement minimum. Note: CBL will be run after setting CIBP. I hereby certify that the information above is true and complete SIGNATURE.	te P&A marker. Top off as a plugs. The to the best of my knowled the total and the first of the	SEE ATTACHED CONDITION OF APPROVAL edge and belief.
Note: Brine Gel will be placed between all cement Note: 100' or 25 sxs cement minimum. Note: CBL will be run after setting CIBP. I hereby certify that the information above is true and comp. SIGNATURE All Landers E-	utside 4.5" casing, tag (8-5/8 le P&A marker. Top off as a plugs.	SEE ATTACHED CONDITION OF APPROVAL edge and belief.
Note: Brine Gel will be placed between all cement Note: 100' or 25 sxs cement minimum. Note: CBL will be run after setting CIBP. I hereby certify that the information above is true and complete SIGNATURE. Type or print name. Mell Lindenmy E- For State Use Only	te P&A marker. Top off as a plugs. The best of my knowled the best	SEE ATTACHED CONDITION OF APPROVAL edge and belief. DATE 12/28/20 PHONE: 505 4866 958
Note: Brine Gel will be placed between all cement Note: 100' or 25 sxs cement minimum. Note: CBL will be run after setting CIBP. I hereby certify that the information above is true and complete SIGNATURE. Type or print name. Mell Lindenmy E- For State Use Only	te P&A marker. Top off as a plugs. The to the best of my knowled the total and the first of the	SEE ATTACHED CONDITION OF APPROVAL edge and belief. DATE 12/28/20 PHONE: 505 4866 958
Note: Brine Gel will be placed between all cement Note: 100' or 25 sxs cement minimum. Note: CBL will be run after setting CIBP. I hereby certify that the information above is true and complete SIGNATURE Type or print name Manhayer E- For State Use Only	te P&A marker. Top off as a plugs. The best of my knowled the best	SEE ATTACHED CONDITION OF APPROVAL edge and belief. DATE 12/28/20 PHONE: 505 4866 958

CONDITIONS OF APPROVAL FOR PLUGGING AND ABANDONMENT OCD - Southern District

The following is a guide or checklist in preparation of a plugging program, this is not all inclusive and care must be exercised in establishing special plugging programs in unique and unusual cases, Notify NMOCD District Office I (Hobbs) at (575)-263-6633 at least 24 hours before beginning work. After MIRU rig will remain on well until it is plugged to surface. OCD is to be notified before rig down.

Company representative will be on location during plugging procedures.

- **1.** A notice of intent to plug and abandon a wellbore is required to be approved before plugging operations are conducted. A cement evaluation tool is required in order to ensure isolation of producing formations, protection of water and correlative rights. A cement bond log or other accepted cement evaluation tool is to be provided to the division for evaluation if one has not been previously run or if the well did not have cement circulated to surface during the original casing cementing job or subsequent cementing jobs. Insure all bradenheads have been exposed, identified and valves are operational prior to rig up.
- **2.** Closed loop system is to be used for entire plugging operation. Upon completion, contents of steel pits are to be hauled to a permitted disposal location.
- **3.** Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private- shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator as well as the contractor, to verify that this permit is in place prior to performing work. Drivers shall be able to produce a copy upon request of an NMOCD Field inspector.
- 4. Filing a subsequent C-103 will serve as notification that the well has been plugged.
- **5.** A final C-103 shall be filed (and a site inspection by NMOCD Inspector to determine if the location is satisfactorily cleaned, all equipment, electric poles and trash has been removed to Meet NMOCD standards) before bonding can +be released.
- **6.** If work has not begun within 1 Year of the approval of this procedure, an extension request must be file stating the reason the well has not been plugged.
- 7. Squeeze pressures are not to exceed 500 psi, unless approval is given by NMOCD.
- **8.** Produced water will not be used during any part of the plugging operation.
- 9. Mud laden fluids must be placed between all cement plugs mixed at 25 sacks per 100 bbls of water.
- **10.** All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater. 50' of calculated cement excess required for inside casing plugs and 100% calculated cement excess required on outside casing plugs.
- 11. Class 'C' cement will be used above 7500 feet.
- 12. Class 'H' cement will be used below 7500 feet.
- **13.** A cement plug is required to be set 50' above and 50' below, casing stubs, DV tools, attempted casing cut offs, cement tops outside casing, salt sections and anywhere the casing is perforated, these plugs require a 4 hour WOC and then will be tagged
- **14.** All Casing Shoes Will Be Perforated 50' below shoe depth and Attempted to be Squeezed, cement needs to be 50' above and 50' Below Casing Shoe inside the Production Casing.
- **16.** When setting the top out cement plug in production, intermediate and surface casing, wellbores should remain full at least 30 minutes after plugs are set
- 17. A CIBP is to be set within 100' of production perforations, capped with 100' of cement, WOC 4 hours and tag.
- **18.** A CIBP with 35' of cement may be used in lieu of the 100' plug if set with a bailer. This plug will be placed within 100' of the top perforation, (WOC 4 hrs and tag).

- 19. No more than 3000' is allowed between cement plugs in cased hole and 2000' in open hole.
- 20. Some of the Formations to be isolated with cement plugs are: These plugs to be set to isolate formation tops
- A) Fusselman
- B) Devonian
- C) Morrow
- D) Wolfcamp
- E) Bone Springs
- F) Delaware
- G) Any salt sections
- H) Abo
- I) Glorieta
- J) Yates.
- K) Potash---(In the R-111-P Area (Potash Mine Area),

A solid cement plug must be set across the salt section. Fluid used to mix the cement shall be saturated with the salts that are common to the section penetrated and in suitable proportions, not more than 3% calcium chloride (by weight of cement) will be considered the desired mixture whenever possible, WOC 4 hours and tag, this plug will be 50' below the bottom and 50' above the top of the Formation.

21. If cement does not exist behind casing strings at recommended formation depths, the casing can be cut and pulled with plugs set at recommended depths. If casing is not pulled, perforations will be shot and cement squeezed behind casing, WOC and tagged. These plugs will be set 50' below formation bottom to 50' above formation top inside the casing.

DRY HOLE MARKER REQ.UIRMENTS

The operator shall mark the exact location of the plugged and abandoned well with a steel marker not less than four inches in diameter, 3' below ground level with a plate of at least ¼" welded to the top of the casing and the dry hole marker welded on the plate with the following information welded on the dry hole marker:

- 1. Operator name
- 2. Lease and Well Number
- 3. API Number
- 4. Unit letter
- 5. Quarter Section (feet from the North, South, East or West)
- 6. Section, Township and Range
- 7. Plugging Date
- 8. County

SPECIAL CASES ----AGRICULTURE OR PRARIE CHICKEN BREEDING AREAS

In these areas, a below ground marker is required with all pertinent information mentioned above on a plate, set 3' below ground level, a picture of the plate will be supplied to NMOCD for record, the exact location of the marker (longitude and latitude by GPS) will be provided to NMOCD (We typically require a current survey to verify the GPS)

SITE REMEDIATION DUE WITHIN ONE YEAR OF WELL PLUGGING COMPLETION


Received by OCD: 1/3/2023 2:40:36 PM Submit 1 Copy To Appropriate District	State of New Mexi-			Form C-1034 of 8
Office District I - (575) 393-6161 Energy	y, Minerals and Natural	l Resources	WELL API NO.	Revised July 18, 2013
1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1283			30-005-20337	
811 S. First St., Artesia, NM 88210	CONSERVATION D		5. Indicate Type	
<u>District III</u> - (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Franci		STATE	☐ FEE ☐ X
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM	Santa Fe, NM 875	05	6. State Oil & G	as Lease No.
SUNDRY NOTICES AND R (DO NOT USE THIS FORM FOR PROPOSALS TO DRII	EPORTS ON WELLS	BACK TO A	7. Lease Name of	or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR I	PERMIT" (FORM C-101) FOR	SUCH	Double L Que	een Unit
PROPOSALS.)	ACTION AND ADMINISTRATION OF THE PERSON OF T		8. Well Number	
Type of Well: Oil Well X Gas Well Name of Operator	Other		9. OGRID Num	ber
State of New Mexico formerly Canyon E&P	Company		269864	
3. Address of Operator			10. Pool name o	or Wildcat
1625 N. French Drive, Hobbs, N 88240			Double L	
4. Well Location		1140*2720/22244	2210 Foot fo	rom the E line
	eet from the N	line and	2310 feet fr NMPM	Chaves County
	ownship 15S Ration (Show whether DR, F	ange 30E		Chaves County
11, Eleval	non (snow whether DR, P	(KD, KI, OK, C		
12. Check Appropriat	e Box to Indicate Nat	ture of Notice	e, Report or Othe	r Data
	T.		BSEQUENT RI	
NOTICE OF INTENTION		REMEDIAL WO		ALTERING CASING
PERFORM REMEDIAL WORK ☐ PLUG AN TEMPORARILY ABANDON ☐ CHANGE			RILLING OPNS.	P AND A
	100000000000000000000000000000000000000	CASING/CEME	Part of the Control o	
DOWNHOLE COMMINGLE				
CLOSED-LOOP SYSTEM		OTHER:		П
OTHER: 13. Describe proposed or completed operate	ions (Clearly state all pe	ertinent details, a	and give pertinent da	ates, including estimated date
of starting any proposed work). SEE R	ULE 19.15.7.14 NMAC.	For Multiple C	Completions: Attach	wellbore diagram of
proposed completion or recompletion.				
Intent to P&A this well. Notify NMOO	CD to witness plugging op	perations.		
			tod)	
MIRU, NU BOP, POH with tbg (4.5" of Set CR or CIBP @ 1878'. Cement with	casing @ 2021 W/200 SXS	s cement circuia	tea)	
RIH, circ well with weighted water.	1 23 383.			
PUH to 1241'. Cement with 25 sxs.				
TOH, Perforate @ 950', Cement 100' i TOH, Perforate @ 431', Cement 100'	inside and outside 4.5" ca	sing, tag.	" casina @ 381' w/	200 sys circulated)
Perforate 4.5" @ 50'; circulate cement	to surface	asing, tag (6-5/6	casing to 501 wi	zov sta chedimedy.
Cut off WH. Install 4" diameter 4' tall	Above Grade P&A mark	er. Top off as r	necessary. Record L	ong/Lat
Note: Brine Gel will be placed between Note: 100' or 25 sxs cement minimum				
Note: CBL will be run after setting CII				
		N 1020 E 1 E		
I hereby certify that the information above is tru	ie and complete to the bes	st of my knowle	dge and belief.	
1 1 0				1 1
SIGNATURE AM Jank	TITLE GAGI	reer Ject	4 1	DATE 12/28/22
Type or print name Nell Consenses		nelland	sulleon .	PHONE 505486958
Type or print name //// Consense for State Use Only	E-mail address:	Her Eugh	SWALL COLL	THOINE:
APPROVED BY:	TITLE		I	DATE
Conditions of Approval (if any):				Miles and the Colonia of the Cal

Double L Queen Unit 002P

Current WBD

Double L Queen

Unit G, 1660' FNL & 2310' FEL, Section 6, T15S, R30E Chaves County, NM, API #30-005-20337




Double L Queen Unit 002P

Proposed P&A

Double L Queen

Unit G, 1660' FNL & 2310' FEL, Section 6, T15S, R30E Chaves County, NM, API #30-005-20337



District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

COMMENTS

Action 171915

COMMENTS

Operator:	OGRID:
A-PLUS WELL SERVICE, INC.	370317
P.O. Box 1979	Action Number:
Farmington, NM 87499	171915
	Action Type:
	[C-103] NOI Plug & Abandon (C-103F)

COMMENTS

Created By	Comment	Comment Date
plmartinez	DATA ENTRY PM	1/11/2023

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 171915

CONDITIONS

Operator:	OGRID:
A-PLUS WELL SERVICE, INC.	370317
P.O. Box 1979	Action Number:
Farmington, NM 87499	171915
	Action Type:
	[C-103] NOI Plug & Abandon (C-103F)

CONDITIONS

Created By		Condition Date
kfortner	See attached COA	1/10/2023