

Office	3 Appropriate 13 istrict		tate of New Me				orm C-103
<u>District I</u> – (575) 3	393-6161 r., Hobbs, NM 88240	Energy, M	inerals and Natu	ral Resources	WELL API N		July 18, 2013
<u>District II</u> – (575)		OH CO	JCEDNATION	DIVICION	30-025-28276		
811 S. First St., An District III – (505)	*		NSERVATION) South St. Frai		5. Indicate Ty		
	Rd., Aztec, NM 87410				STATE		
District IV – (505)) 476-3460 s Dr., Santa Fe, NM	S	anta Fe, NM 87	7303	6. State Oil &	de Gas Lease No.	
87505	3 D1., Santa 1 C, 14141						
(DO NOT USE TI	SUNDRY NOT: HIS FORM FOR PROPO		ORTS ON WELLS TO DEEPEN OR PL		7. Lease Nam	ne or Unit Agreem	ent Name
DIFFERENT RES PROPOSALS.)	SERVOIR. USE "APPLI	CATION FOR PERM	IT" (FORM C-101) FO	OR SUCH	STATE A A/O		
	ell: Oil Well 🛚	Gas Well 🔲 C	ther		8. Well Num	ber #067	
2. Name of Op	perator				9. OGRID Nu	umber	
FAE II Operati					329326	*****	
3. Address of	Operator reeway, Suite 725, H	ouston TV 77070)		10. Pool nam	e or Wildcat CE; 7 RVRs-QUEEN	HTHO2 L
-		ousion, 1A //0/S	<i>)</i>		[24130] EONIC	E, / KVKS-QUEER	N, 3001H
4. Well Locati Unit I		2615 fact from	the COUTH	line and 1	2.45 foot from	a tha WEST	lina
		2615 feet from			feet from		_line
Section	on 09		wnship 22S Show whether DR	0		MPM LEA	County
		3580'	snow whether DR	KKD, KI, UK, etc			
	12. Check A	Appropriate Bo	x to Indicate N	ature of Notice	. Report or Otl	her Data	
		11 1		1			
	NOTICE OF IN				_	REPORT OF:	
	MEDIAL WORK	PLUG AND AB CHANGE PLAI		REMEDIAL WO	_	☐ ALTERING C ☐ P AND A	ASING _
TEMPORARIL PULL OR ALTI		MULTIPLE CO		CASING/CEME	RILLING OPNS.[NT. IOB] PANDA	Ш
DOWNHOLE (WOLTH EE OO		O TOIL TO TOLIVIE	11 002	_	
CLOSED-LOO	=						
OTHER:	CONVERT TO IN	JECTION	\boxtimes	OTHER:			
				4' 4 1 4 '1			
12 Describ	ne proposed or comp	lated operations	(Clearly state all s		nd aiva nartinant	dotac including a	stimuted data
of start	be proposed or comp	ork). SEE RULE					
of start		ork). SEE RULE					
of start propose	ing any proposed wo	ork). SEE RULE					
of start	ing any proposed wo	ork). SEE RULE					
of start proposed PROPOSED PR MIRU. POOH v	any proposed we ed completion or reconcern and completion or reconcern and completion or reconcern and complete w/ rods, pump & tbg	ork). SEE RULE completion. TIH w/ 4-3/4" b	19.15.7.14 NMAG	E. For Multiple Co	ompletions: Attac	ch wellbore diagra	am of H w/ CIBP.
of start proposed PROPOSED PR MIRU. POOH v Set @ ~3710'. S	any proposed wo ed completion or rec ROCEDURE w/rods, pump & tbg Set CICR @ ~3100'.	ork). SEE RULE completion. TIH w/ 4-3/4" b Sqz YATES & 7	it. Tag bottom. Cle RVRs perfs 3122	E. For Multiple Co can out to TD. Circ -3699'. WO cmt. 1	ompletions: Attac culate hole clean. Drill out CICR &	ch wellbore diagra POOH w/ bit. RII cmt to top of CIB	am of H w/ CIBP. P. Circulate
of start proposed PROPOSED PR MIRU. POOH v Set @ ~3710'. S clean. Pressure t	any proposed we ed completion or reconstruction or reconstruction or reconstruction of the completion of reconstruction of the completion	ork). SEE RULE completion. TIH w/ 4-3/4" b Sqz YATES & 7 fails, re-sqz perfs	it. Tag bottom. Cle RVRs perfs 3122 . If test good, drill	ean out to TD. Circa out CIBP. Clean out	culate hole clean. Drill out CICR & out to TD. Perf 37	POOH w/ bit. RII cmt to top of CIB 720-3752' (2 SPF)	am of H w/ CIBP. P. Circulate . Acidize
of start proposed PROPOSED PR MIRU. POOH v Set @ ~3710'. S clean. Pressure t 3720-3826' w/ 1	any proposed we ed completion or reconstruction or reconstruction or reconstruction or reconstruction and the completion of reconstruction and the complete	ork). SEE RULE completion. TIH w/ 4-3/4" b Sqz YATES & 7 fails, re-sqz perfs E HCL acid, 300#	it. Tag bottom. Clo RVRs perfs 3122 . If test good, drill rock salt & flush	ean out to TD. Circa out CIBP. Clean out	culate hole clean. Drill out CICR & out to TD. Perf 37 CL water. TIH w	POOH w/ bit. RII cmt to top of CIB 720-3752' (2 SPF) / injection string:	H w/ CIBP. P. Circulate . Acidize ~114 jts 2-
of start proposed PROPOSED PR MIRU. POOH v Set @ ~3710'. S clean. Pressure t 3720-3826' w/ 1 3/8" L-80 IPC th	cing any proposed we ed completion or reconstruction or reconstruction of the completion of reconstruction of the completion of the complete comple	ork). SEE RULE completion. TIH w/ 4-3/4" b Sqz YATES & 7 fails, re-sqz perfs E HCL acid, 300#	it. Tag bottom. Clo RVRs perfs 3122 . If test good, drill rock salt & flush	ean out to TD. Circa out CIBP. Clean out	culate hole clean. Drill out CICR & out to TD. Perf 37 CL water. TIH w	POOH w/ bit. RII cmt to top of CIB 720-3752' (2 SPF) / injection string:	H w/ CIBP. P. Circulate . Acidize ~114 jts 2-
of start proposed PROPOSED PR MIRU. POOH v Set @ ~3710'. S clean. Pressure t 3720-3826' w/ 1 3/8" L-80 IPC th	any proposed we ed completion or reconstruction or reconstruction or reconstruction or reconstruction and the completion of reconstruction and the complete	ork). SEE RULE completion. TIH w/ 4-3/4" b Sqz YATES & 7 fails, re-sqz perfs E HCL acid, 300#	it. Tag bottom. Clo RVRs perfs 3122 . If test good, drill rock salt & flush	ean out to TD. Circa out CIBP. Clean out	culate hole clean. Drill out CICR & Dut to TD. Perf 37 CL water. TIH w	POOH w/ bit. RII cmt to top of CIB 720-3752' (2 SPF) / injection string:	H w/ CIBP. P. Circulate Acidize ~114 jts 2-
of start proposed PROPOSED PR MIRU. POOH v Set @ ~3710'. S clean. Pressure t 3720-3826' w/ 1 3/8" L-80 IPC th	cing any proposed we ed completion or reconstruction or reconstruction of the completion of reconstruction of the completion of the complete comple	ork). SEE RULE completion. TIH w/ 4-3/4" b Sqz YATES & 7 fails, re-sqz perfs E HCL acid, 300#	it. Tag bottom. Clo RVRs perfs 3122 . If test good, drill rock salt & flush	ean out to TD. Circa out CIBP. Clean out	culate hole clean. Drill out CICR & out to TD. Perf 37 CL water. TIH w	POOH w/ bit. RII cmt to top of CIB 720-3752' (2 SPF) / injection string: // ition of Approva	H w/ CIBP. P. Circulate . Acidize ~114 jts 2- l: notify hours
of start proposed PROPOSED PR MIRU. POOH v Set @ ~3710'. S clean. Pressure t 3720-3826' w/ 1 3/8" L-80 IPC th	cing any proposed we ed completion or reconstruction or reconstruction of the completion of reconstruction of the completion of the complete comple	ork). SEE RULE completion. TIH w/ 4-3/4" b Sqz YATES & 7 fails, re-sqz perfs E HCL acid, 300#	it. Tag bottom. Clo RVRs perfs 3122 . If test good, drill rock salt & flush	ean out to TD. Circa out CIBP. Clean out	culate hole clean. Drill out CICR & out to TD. Perf 37 CL water. TIH w	POOH w/ bit. RII cmt to top of CIB 720-3752' (2 SPF) / injection string:	H w/ CIBP. P. Circulate . Acidize ~114 jts 2- l: notify hours
of start proposed PROPOSED PR MIRU. POOH v Set @ ~3710'. S clean. Pressure t 3720-3826' w/ 1 3/8" L-80 IPC th	cing any proposed we ed completion or reconstruction or reconstruction of the completion of reconstruction of the completion of the complete comple	ork). SEE RULE completion. TIH w/ 4-3/4" b Sqz YATES & 7 fails, re-sqz perfs E HCL acid, 300#	it. Tag bottom. Clo RVRs perfs 3122 . If test good, drill rock salt & flush	ean out to TD. Circ -3699'. WO cmt. I out CIBP. Clean ow/ 100 bbls 2% K	culate hole clean. Drill out CICR & out to TD. Perf 37 CL water. TIH w	POOH w/ bit. RII cmt to top of CIB 720-3752' (2 SPF) / injection string: // ition of Approva	H w/ CIBP. P. Circulate . Acidize ~114 jts 2- l: notify hours
of start proposed PROPOSED PR MIRU. POOH v Set @ ~3710'. S clean. Pressure t 3720-3826' w/ J 3/8" L-80 IPC tt	ing any proposed we ed completion or reconce completion or reconce completion or reconce completion or reconce complete	ork). SEE RULE completion. TIH w/ 4-3/4" b Sqz YATES & 7 fails, re-sqz perfs E HCL acid, 300#	it. Tag bottom. Cle RVRs perfs 3122. If test good, drill rock salt & flush Start injection.	ean out to TD. Circ -3699'. WO cmt. I out CIBP. Clean ow/ 100 bbls 2% K	culate hole clean. Drill out CICR & out to TD. Perf 37 CL water. TIH w Condi OCE prior of	POOH w/ bit. RII cmt to top of CIB 720-3752' (2 SPF) / injection string: // ition of Approva	H w/ CIBP. P. Circulate . Acidize ~114 jts 2- l: notify hours
of start proposed PROPOSED PR MIRU. POOH v Set @ ~3710'. S clean. Pressure t 3720-3826' w/ I 3/8" L-80 IPC tl INJECTION OF	ing any proposed we ed completion or reconstruction or reconstruction and the completion of reconstruction of the complete comple	ork). SEE RULE completion. TIH w/ 4-3/4" b Sqz YATES & 7 fails, re-sqz perfs E HCL acid, 300# 23705'. RDMO	it. Tag bottom. Cle RVRs perfs 3122 . If test good, drill rock salt & flush . Start injection.	ean out to TD. Circ-3699'. WO cmt. I out CIBP. Clean ow/ 100 bbls 2% K	culate hole clean. Drill out CICR & out to TD. Perf 37 CL water. TIH w Condi OCD prior of	POOH w/ bit. RII cmt to top of CIB 720-3752' (2 SPF) / injection string: // ition of Approva	H w/ CIBP. P. Circulate . Acidize ~114 jts 2- l: notify hours
of start proposed PROPOSED PR MIRU. POOH v Set @ ~3710'. S clean. Pressure t 3720-3826' w/ I 3/8" L-80 IPC tl INJECTION OF	ing any proposed we ed completion or reconce completion or reconce completion or reconce completion or reconce complete	ork). SEE RULE completion. TIH w/ 4-3/4" b Sqz YATES & 7 fails, re-sqz perfs E HCL acid, 300# 23705'. RDMO	it. Tag bottom. Cle RVRs perfs 3122 . If test good, drill rock salt & flush . Start injection.	ean out to TD. Circ-3699'. WO cmt. I out CIBP. Clean ow/ 100 bbls 2% K	culate hole clean. Drill out CICR & out to TD. Perf 37 CL water. TIH w Condi OCD prior of	POOH w/ bit. RII cmt to top of CIB 720-3752' (2 SPF) / injection string: // ition of Approva	H w/ CIBP. P. Circulate . Acidize ~114 jts 2- l: notify hours
of start proposed PROPOSED PR MIRU. POOH v Set @ ~3710'. S clean. Pressure t 3720-3826' w/ I 3/8" L-80 IPC tl INJECTION OF	ing any proposed we ed completion or reconstruction or reconstruction and the completion of reconstruction of the complete comple	ork). SEE RULE completion. TIH w/ 4-3/4" b Sqz YATES & 7 fails, re-sqz perfs E HCL acid, 300# 23705'. RDMO	it. Tag bottom. Cle RVRs perfs 3122 . If test good, drill rock salt & flush . Start injection.	ean out to TD. Circ-3699'. WO cmt. I out CIBP. Clean ow/ 100 bbls 2% K	culate hole clean. Drill out CICR & out to TD. Perf 37 CL water. TIH w Condi OCD prior of	POOH w/ bit. RII cmt to top of CIB 720-3752' (2 SPF) / injection string: // ition of Approva	H w/ CIBP. P. Circulate . Acidize ~114 jts 2- l: notify hours
of start proposed PROPOSED PR MIRU. POOH vset @ ~3710'. Sclean. Pressure ts 3720-3826' w/ ls 3/8" L-80 IPC ts INJECTION OF Spud Date:	ing any proposed we ed completion or reconstruction or reconstruction and the completion of reconstruction of the complete comple	ork). SEE RULE completion. TIH w/ 4-3/4" b Sqz YATES & 7 fails, re-sqz perfs E HCL acid, 300# 23705'. RDMO	it. Tag bottom. Cle RVRs perfs 3122 . If test good, drill rock salt & flush . Start injection. Rig Release Da	ean out to TD. Circ-3699'. WO cmt. I out CIBP. Clean ow/ 100 bbls 2% K	culate hole clean. Drill out CICR & out to TD. Perf 37 CL water. TIH w Condi OCE prior of 01/20/2023	POOH w/ bit. RII cmt to top of CIB 720-3752' (2 SPF) / injection string: // ition of Approva Hobbs office 24 running MIT To	H w/ CIBP. P. Circulate Acidize ~114 jts 2- l: notify hours est & Chart
of start proposed PROPOSED PR MIRU. POOH v Set @ ~3710'. S clean. Pressure t 3720-3826' w/ I 3/8" L-80 IPC tl INJECTION OF	ing any proposed we ed completion or reconstruction or reconstruction and the completion of reconstruction of the complete comple	ork). SEE RULE completion. TIH w/ 4-3/4" b Sqz YATES & 7 fails, re-sqz perfs E HCL acid, 300# 23705'. RDMO	it. Tag bottom. Cle RVRs perfs 3122 . If test good, drill rock salt & flush . Start injection. Rig Release Da	ean out to TD. Circ-3699'. WO cmt. I out CIBP. Clean ow/ 100 bbls 2% K	culate hole clean. Drill out CICR & out to TD. Perf 37 CL water. TIH w Condi OCE prior of 01/20/2023	POOH w/ bit. RII cmt to top of CIB 720-3752' (2 SPF) / injection string: // ition of Approva	H w/ CIBP. P. Circulate Acidize ~114 jts 2- l: notify hours est & Chart
of start proposed PROPOSED PR MIRU. POOH v Set @ ~3710'. S clean. Pressure t 3720-3826' w/ 1 3/8" L-80 IPC tt INJECTION OF Spud Date: I hereby certify SIGNATURE Type or print na	ting any proposed we ed completion or reconsected complete co	ork). SEE RULE completion. TIH w/ 4-3/4" b Sqz YATES & 7 fails, re-sqz perfs E HCL acid, 300# 23705". RDMO	it. Tag bottom. Cle RVRs perfs 3122 . If test good, drill rock salt & flush . Start injection. Rig Release Da complete to the b	ean out to TD. Circ-3699'. WO cmt. I out CIBP. Clean ow/ 100 bbls 2% K	culate hole clean. Drill out CICR & Drill out TD. Perf 37 CL water. TIH w Condi OCE prior of 01/20/2023	POOH w/ bit. RII cmt to top of CIB 720-3752' (2 SPF) / injection string: // injection string: // hobbs office 24 running MIT To	H w/ CIBP. P. Circulate Acidize ~114 jts 2- l: notify hours est & Chart
of start proposed PROPOSED PR MIRU. POOH v Set @ ~3710'. S clean. Pressure t 3720-3826' w/ J 3/8" L-80 IPC tt INJECTION OF Spud Date: I hereby certify SIGNATURE	ing any proposed we ed completion or reconstruction or reconstruction and the completion or reconstruction of the completion of reconstruction of the completion of the comple	ork). SEE RULE completion. TIH w/ 4-3/4" b Sqz YATES & 7 fails, re-sqz perfs E HCL acid, 300# 23705". RDMO	it. Tag bottom. Cle RVRs perfs 3122 . If test good, drill rock salt & flush . Start injection. Rig Release Da complete to the b	ean out to TD. Circ-3699'. WO cmt. I out CIBP. Clean out 100 bbls 2% K	culate hole clean. Drill out CICR & Drill out TD. Perf 37 CL water. TIH w Condi OCE prior of 01/20/2023	POOH w/ bit. RII cmt to top of CIB 720-3752' (2 SPF) / injection string: // injection string: // hobbs office 24 running MIT To	H w/ CIBP. P. Circulate Acidize 114 jts 2- I: notify I hours est & Chart
of start proposed PROPOSED PR MIRU. POOH v Set @ ~3710'. S clean. Pressure t 3720-3826' w/ 1 3/8" L-80 IPC tt INJECTION OF Spud Date: I hereby certify SIGNATURE Type or print na	ing any proposed we ed completion or reconstruction or reconstruction and the completion or reconstruction of the completion of reconstruction of the completion of the comple	ork). SEE RULE completion. TIH w/ 4-3/4" b Sqz YATES & 7 fails, re-sqz perfs E HCL acid, 300# 23705". RDMO	it. Tag bottom. Cle RVRs perfs 3122 . If test good, drill rock salt & flush . Start injection. Rig Release Da complete to the b	ean out to TD. Circ-3699'. WO cmt. I out CIBP. Clean out 100 bbls 2% K	culate hole clean. Drill out CICR & Drill out TD. Perf 37 CL water. TIH w Condi OCE prior of 01/20/2023	POOH w/ bit. RII cmt to top of CIB 720-3752' (2 SPF) / injection string: // injection string: // hobbs office 24 running MIT To	H w/ CIBP. P. Circulate Acidize 114 jts 2- I: notify I hours est & Chart



Other:

RIH with 2-3/8" IPC tubing and set packer $^{\sim}$ 3705'



Unknown tubulars in the well.

Other:

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 169429

CONDITIONS

Operator:	OGRID:
FAE II Operating LLC	329326
11757 Katy Freeway, Suite 725	Action Number:
Houston, TX 77079	169429
	Action Type:
	[C-103] NOI Workover (C-103G)

CONDITIONS

Created By		Condition Date
kfortner	Run PWOT MIT/BHT	2/1/2023