Office <u>District I</u> – (575) 393		:07 AM	State of New M	<i>A</i> exico		Form C-103	
1625 N E 1 D		Energy,	Minerals and Na	tural Resources	WELL API NO.	Revised July 18, 2013	
1625 N. French Dr., <u>District II</u> – (575) 74	8-1283			NDUISION		5-10384	
	Astrict II(575) /46126511 S. First St., Artesia, NM 88210OIL CONSERVATION DIVISIONDistrict III(505) 334-61781220 South St. Francis Dr.					ise	
1000 Rio Brazos Rd.	Rd., Aztec, NM 87410 Sente Fe, NIM 87505				STATE FEE		
<u>District IV</u> – (505) 4 1220 S. St. Francis D			Salita Pe, Mivi	87505	6. State Oil & Gas Leas	se No.	
87505		TICES AND DE	PORTS ON WELI	[<u>c</u>	7. Lease Name or Unit	A graamant Nama	
	S FORM FOR PROP	POSALS TO DRILL	OR TO DEEPEN OR P	PLUG BACK TO A	Langlie Mattix Penrose		
DIFFERENT RESER PROPOSALS.)	RVOIR. USE "APP	LICATION FOR PE	RMIT" (FORM C-101)	FOR SUCH	8. Well Number		
1. Type of Well	: Oil Well 🛛	Gas Well	Other		102		
2. Name of Ope					9. OGRID Number		
3. Address of O		ACY RESERV	ES OPERATING L	<u>_P</u>	240974 10. Pool name or Wildo	pat	
J. Address of O		MITH ROAD, S	UITE 3000, MIDL	AND, TX 79705	Langlie Mattix; 7 Rvrs-		
4. Well Location					0,		
Unit Le	tter <u>K</u>	: <u>1980</u> fe	et from the <u>SOU</u>	UTH line and	<u>1980</u> feet from the	e <u>WEST</u> line	
Section	21		ownship 22S	Range 37E	NMPM	County LEA	
		11. Elevatio	n (Show whether D	DR, RKB, RT, GR, etc.)		
	10 01 1						
	12. Check	Appropriate	Box to Indicate	Nature of Notice,	Report or Other Data		
	IOTICE OF I	NTENTION	TO:	SUB	SEQUENT REPOR	T OF:	
PERFORM REM				REMEDIAL WOR			
TEMPORARILY				COMMENCE DR		DA 🗌	
PULL OR ALTER DOWNHOLE CO			COMPL	CASING/CEMEN	I JOB		
CLOSED-LOOP]					
OTHER:		_		OTHER:			
					d give pertinent dates, inc		
	g any proposed v l completion or r		LE 19.15.7.14 MMA	AC. For Multiple Co	mpletions: Attach wellbo	re diagram of	
1 1	1	Ĩ					
l. Previous TA. M							
/ RIH Xr too TIV	<i>C</i> . Record depth.	Circ hole with N	ILF.				
			1 (D 1))				
3. Spot 25 sx cmt	@2674'-2574'. (WOC & Tag (Tr	ansıl (B-salt))				
8. Spot 25 sx cmt 4. Spot 25 sx cmt 5. Spot 25 sx cmt	<pre>@2674'-2574'. (@ 2506'-2406'. ' @ 2093'-1993'. '</pre>	WOC & Tag (Es	t TOC 7")				
 Spot 25 sx cmt Spot 25 sx cmt Spot 25 sx cmt Spot 25 sx cmt Perf & Sqz 73 s 	@2674'-2574'. (@ 2506'-2406'. @ 2093'-1993'. sx cmt @ 1394'-	WOC & Tag (Es 1175'. WOC & T		Surf. Csg Shoe)			
 Spot 25 sx cmt Spot 25 sx cmt Spot 25 sx cmt Perf & Sqz 73 s Perf & Sqz 33 s 	 @2674'-2574'. (@ 2506'-2406'. ` @ 2093'-1993'. ` \$x cmt @ 1394'- ` \$x cmt @ 100'-0' 	WOC & Tag (Es 1175'. WOC & T . (Surface Plug)	t TOC 7") ag (Rustler T-salt/	Surf. Csg Shoe)			
 Spot 25 sx cmt Spot 25 sx cmt Spot 25 sx cmt Perf & Sqz 73 s Perf & Sqz 33 s 	 @2674'-2574'. (@ 2506'-2406'. ` @ 2093'-1993'. ` \$x cmt @ 1394'- ` \$x cmt @ 100'-0' 	WOC & Tag (Es 1175'. WOC & T . (Surface Plug)	t TOC 7")	Surf. Csg Shoe)			
 Spot 25 sx cmt Spot 25 sx cmt Spot 25 sx cmt Spot 25 sx cmt Perf & Sqz 73 s Perf & Sqz 33 s Cut off well heat 	 @2674'-2574'. (@ 2506'-2406'. ` @ 2093'-1993'. ` \$x cmt @ 1394'-` \$x cmt @ 100'-0' ad, verify cmt at 	WOC & Tag (Es 1175'. WOC & T . (Surface Plug) surface, weld on	t TOC 7") ag (Rustler T-salt/				
 B. Spot 25 sx cmt Spot 25 sx cmt Spot 25 sx cmt Spot 25 sx cmt Perf & Sqz 73 s Perf & Sqz 33 s Cut off well heat 	 @2674'-2574'. (@ 2506'-2406'. ` @ 2093'-1993'. ` \$x cmt @ 1394'-` \$x cmt @ 100'-0' ad, verify cmt at 	WOC & Tag (Es 1175'. WOC & T . (Surface Plug) surface, weld on	t TOC 7") ag (Rustler T-salt/	SEE ATTACHEI	D CONDITIONS		
 Spot 25 sx cmt Spot 25 sx cmt Spot 25 sx cmt Spot 25 sx cmt Perf & Sqz 73 s Perf & Sqz 33 s Cut off well heat 	 @2674'-2574'. (@ 2506'-2406'. ` @ 2093'-1993'. ` \$x cmt @ 1394'-` \$x cmt @ 100'-0' ad, verify cmt at 	WOC & Tag (Es 1175'. WOC & T . (Surface Plug) surface, weld on	t TOC 7") ag (Rustler T-salt/				
 3. Spot 25 sx cmt 4. Spot 25 sx cmt 5. Spot 25 sx cmt 5. Perf & Sqz 73 s 7. Perf & Sqz 33 s 8. Cut off well heat " diameter 4' tage 	 @2674'-2574'. (@ 2506'-2406'. ` @ 2093'-1993'. ` \$x cmt @ 1394'-` \$x cmt @ 100'-0' ad, verify cmt at 	WOC & Tag (Es 1175'. WOC & T . (Surface Plug) surface, weld on	t TOC 7") 'ag (Rustler T-salt/ dry hole marker.	SEE ATTACHEI OF APPROVAL			
3. Spot 25 sx cmt 4. Spot 25 sx cmt 5. Spot 25 sx cmt 5. Perf & Sqz 73 s 7. Perf & Sqz 33 s 8. Cut off well hea • diameter 4' ta	 @2674'-2574'. (@ 2506'-2406'. ` @ 2093'-1993'. ` \$x cmt @ 1394'-` \$x cmt @ 100'-0' ad, verify cmt at 	WOC & Tag (Es 1175'. WOC & T . (Surface Plug) surface, weld on	t TOC 7") ag (Rustler T-salt/	SEE ATTACHEI OF APPROVAL			
3. Spot 25 sx cmt 4. Spot 25 sx cmt 5. Spot 25 sx cmt 5. Perf & Sqz 73 s 7. Perf & Sqz 33 s 8. Cut off well hea • diameter 4' ta	 @2674'-2574'. (@ 2506'-2406'. ` @ 2093'-1993'. ` \$x cmt @ 1394'-` \$x cmt @ 100'-0' ad, verify cmt at 	WOC & Tag (Es 1175'. WOC & T . (Surface Plug) surface, weld on	t TOC 7") 'ag (Rustler T-salt/ dry hole marker.	SEE ATTACHEI OF APPROVAL			
3. Spot 25 sx cmt 4. Spot 25 sx cmt 5. Spot 25 sx cmt 5. Perf & Sqz 73 s 7. Perf & Sqz 33 s 8. Cut off well hea • diameter 4' ta	 @2674'-2574'. (@ 2506'-2406'. ` @ 2093'-1993'. ` sx cmt @ 1394'- ` sx cmt @ 100'-0' ad, verify cmt at 	WOC & Tag (Es 1175'. WOC & T . (Surface Plug) surface, weld on nd Marker	t TOC 7") ag (Rustler T-salt/ dry hole marker. Rig Release I	SEE ATTACHEI OF APPROVAL Date:			
3. Spot 25 sx cmt 4. Spot 25 sx cmt 5. Spot 25 sx cmt 5. Perf & Sqz 73 s 7. Perf & Sqz 33 s 8. Cut off well hea 4" diameter 4' ta Spud Date:	 @2674'-2574'. (@ 2506'-2406'. ` @ 2093'-1993'. ` sx cmt @ 1394'- ` sx cmt @ 100'-0' ad, verify cmt at 	WOC & Tag (Es 1175'. WOC & T . (Surface Plug) surface, weld on nd Marker	t TOC 7") ag (Rustler T-salt/ dry hole marker. Rig Release I	SEE ATTACHEI OF APPROVAL			
3. Spot 25 sx cmt 4. Spot 25 sx cmt 5. Spot 25 sx cmt 5. Perf & Sqz 73 s 7. Perf & Sqz 33 s 8. Cut off well head 4" diameter 4' tag Spud Date:	 @2674'-2574'. (@ 2506'-2406'. ` @ 2093'-1993'. ` @ 2093'-1993'. ` \$x cmt @ 1394'-` \$x cmt @ 100'-0' ad, verify cmt at all Above Grou at the information	WOC & Tag (Es 1175'. WOC & T . (Surface Plug) surface, weld on nd Marker	t TOC 7") Fag (Rustler T-salt/ dry hole marker. Rig Release I	SEE ATTACHEI OF APPROVAL Date:	ge and belief.		
3. Spot 25 sx cmt 4. Spot 25 sx cmt 5. Spot 25 sx cmt 6. Perf & Sqz 73 s 7. Perf & Sqz 33 s 8. Cut off well hea 4" diameter 4' ta	 @2674'-2574'. (@ 2506'-2406'. ` @ 2093'-1993'. ` @ 2093'-1993'. ` \$x cmt @ 1394'-` \$x cmt @ 100'-0' ad, verify cmt at all Above Grou at the information	WOC & Tag (Es 1175'. WOC & T . (Surface Plug) surface, weld on nd Marker	t TOC 7") ag (Rustler T-salt/ dry hole marker. Rig Release I	SEE ATTACHEI OF APPROVAL Date:	ge and belief.	1/23/2023	
3. Spot 25 sx cmt 4. Spot 25 sx cmt 5. Spot 25 sx cmt 5. Perf & Sqz 73 s 7. Perf & Sqz 33 s 8. Cut off well head 1. diameter 4' tag Spud Date:	@2674'-2574'. (@ 2506'-2406'. ` @ 2093'-1993'. ` ax cmt @ 1394'- ax cmt @ 100'-0' ad, verify cmt at all Above Grou at the informatic <i>Melanie</i> /	WOC & Tag (Es 1175'. WOC & T . (Surface Plug) surface, weld on nd Marker	t TOC 7") ag (Rustler T-salt/ dry hole marker. Rig Release I and complete to the 	SEE ATTACHEI OF APPROVAL Date:	ge and belief. DATE0		
3. Spot 25 sx cmt 4. Spot 25 sx cmt 5. Spot 25 sx cmt 5. Perf & Sqz 73 s 7. Perf & Sqz 33 s 8. Cut off well hear " diameter 4' tan Spud Date:	@2674'-2574'. (@ 2506'-2406'. ` @ 2093'-1993'. ` sx cmt @ 1394'-` sx cmt @ 100'-0' ad, verify cmt at all Above Grou at the informatic <i>Melanis</i> / me <u>MELANI</u>	WOC & Tag (Es 1175'. WOC & T . (Surface Plug) surface, weld on nd Marker	t TOC 7") ag (Rustler T-salt/ dry hole marker. Rig Release I and complete to the 	SEE ATTACHEI OF APPROVAL Date:	ge and belief.		
Spot 25 sx cmt Cut off & Sqz 73 s Cut off well hea Gpud Date:	@2674'-2574'. (@ 2506'-2406'. ` @ 2093'-1993'. ` sx cmt @ 1394'-` sx cmt @ 100'-0' ad, verify cmt at all Above Grou at the informatic <i>Melania</i> / he <u>MELANI</u> <u>aly</u>	WOC & Tag (Es 1175'. WOC & T . (Surface Plug) surface, weld on nd Marker	t TOC 7") ag (Rustler T-salt/ dry hole marker. Rig Release I ind complete to the TITLE E-mail address	SEE ATTACHEI OF APPROVAL Date:	ge and belief. DATE0 reserves.com PHONE:	432-221-6358	

•

Released to Imaging:	2/3/2023 2:19:12 PM
-----------------------------	---------------------

CONDITIONS OF APPROVAL FOR PLUGGING AND ABANDONMENT OCD - Southern District

The following is a guide or checklist in preparation of a plugging program, this is not all inclusive and care must be exercised in establishing special plugging programs in unique and unusual cases, Notify NMOCD District Office I (Hobbs) at (575)-263-6633 at least 24 hours before beginning work. After MIRU rig will remain on well until it is plugged to surface. OCD is to be notified before rig down.

Company representative will be on location during plugging procedures.

1. A notice of intent to plug and abandon a wellbore is required to be approved before plugging operations are conducted. A cement evaluation tool is required in order to ensure isolation of producing formations, protection of water and correlative rights. A cement bond log or other accepted cement evaluation tool is to be provided to the division for evaluation if one has not been previously run or if the well did not have cement circulated to surface during the original casing cementing job or subsequent cementing jobs. Insure all bradenheads have been exposed, identified and valves are operational prior to rig up.

2. Closed loop system is to be used for entire plugging operation. Upon completion, contents of steel pits are to be hauled to a permitted disposal location.

3. Trucking companies being used to haul oilfield waste fluids to a disposal - commercial or private- shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator as well as the contractor, to verify that this permit is in place prior to performing work. Drivers shall be able to produce a copy upon request of an NMOCD Field inspector.

4. Filing a subsequent C-103 will serve as notification that the well has been plugged.

5. A final C-103 shall be filed (and a site inspection by NMOCD Inspector to determine if the location is satisfactorily cleaned, all equipment, electric poles and trash has been removed to Meet NMOCD standards) before bonding can +be released.

6. If work has not begun within 1 Year of the approval of this procedure, an extension request must be file stating the reason the well has not been plugged.

7. Squeeze pressures are not to exceed 500 psi, unless approval is given by NMOCD.

8. Produced water will not be used during any part of the plugging operation.

9. Mud laden fluids must be placed between all cement plugs mixed at 25 sacks per 100 bbls of water.

10. All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater. 50' of calculated cement excess required for inside casing plugs and 100% calculated cement excess required on outside casing plugs.

11. Class 'C' cement will be used above 7500 feet.

12. Class 'H' cement will be used below 7500 feet.

13. A cement plug is required to be set 50' above and 50' below, casing stubs, DV tools, attempted casing cut offs, cement tops outside casing, salt sections and anywhere the casing is perforated, these plugs require a 4 hour WOC and then will be tagged

14. All Casing Shoes Will Be Perforated 50' below shoe depth and Attempted to be Squeezed, cement needs to be 50' above and 50' Below Casing Shoe inside the Production Casing.

16. When setting the top out cement plug in production, intermediate and surface casing, wellbores should remain full at least 30 minutes after plugs are set

17. A CIBP is to be set within 100' of production perforations, capped with 100' of cement, WOC 4 hours and tag.

18. A CIBP with 35' of cement may be used in lieu of the 100' plug if set with a bailer. This plug will be placed within 100' of the top perforation, (WOC 4 hrs and tag).

19. No more than 3000' is allowed between cement plugs in cased hole and 2000' in open hole.

20. Some of the Formations to be isolated with cement plugs are: These plugs to be set to isolate formation tops

- A) Fusselman
- B) Devonian
- C) Morrow
- D) Wolfcamp
- E) Bone Springs
- F) Delaware
- G) Any salt sections
- H) Abo
- I) Glorieta
- J) Yates.

K) Potash---(In the R-111-P Area (Potash Mine Area),

A solid cement plug must be set across the salt section. Fluid used to mix the cement shall be saturated with the salts that are common to the section penetrated and in suitable proportions, not more than 3% calcium chloride (by weight of cement) will be considered the desired mixture whenever possible, WOC 4 hours and tag, this plug will be 50' below the bottom and 50' above the top of the Formation.

21. If cement does not exist behind casing strings at recommended formation depths, the casing can be cut and pulled with plugs set at recommended depths. If casing is not pulled, perforations will be shot and cement squeezed behind casing, WOC and tagged. These plugs will be set 50' below formation bottom to 50' above formation top inside the casing.

DRY HOLE MARKER REQ.UIRMENTS

The operator shall mark the exact location of the plugged and abandoned well with a steel marker not less than four inches in diameter, 3' below ground level with a plate of at least ¼" welded to the top of the casing and the dry hole marker welded on the plate with the following information welded on the dry hole marker:

- 1. Operator name
- 2. Lease and Well Number
- 3. API Number
- 4. Unit letter
- 5. Quarter Section (feet from the North, South, East or West)
- 6. Section, Township and Range
- 7. Plugging Date
- 8. County

SPECIAL CASES -----AGRICULTURE OR PRARIE CHICKEN BREEDING AREAS

In these areas, a below ground marker is required with all pertinent information mentioned above on a plate, set 3' below ground level, a picture of the plate will be supplied to NMOCD for record, the exact location of the marker (longitude and latitude by GPS) will be provided to NMOCD (We typically require a current survey to verify the GPS)

SITE REMEDIATION DUE WITHIN ONE YEAR OF WELL PLUGGING COMPLETION

•

		Langlie-Mattix Pe	enrose Sa	nd Unit #102	API#:	30-02	5-10384		
	<u>I JAL</u>	Field/Pool:	Lanç	lie-Mattix	Section:		21		
R E S	ERVES	County:		Lea	Township:	22S	Range:	37E	
		State:	Nev	v Mexico	Location:		30' FSL x 198		Author:
		Spud Date:	1/2	27/1937	GL:	3359'	PBTD:	3265'	J. Valdez
						Durth			
		Description	O.D.	Weight	Тор	Depth	Hole	Cmt Sx	ТОС
		Surface	9	40	0	1354	12	555 Sx	0' calc
		Production	7	24	0	3350	8.875	200 sx	2043' cal
		Open Hole	6"		3350	3620	6"	ОН	N/A
								Formation	Tops:
								Rustler (T-Salt)	1225'*
								Transil (B-Salt)	2456'*
								Yates 7Rivers	2624'* 2830'*
								Queen	
								* Used offset well	
		9" surface casing @ 1354'							
		9" surface casing @ 1354' Est TOC 2043' calc							

•

	Langlie-Mattix Pe	enrose Sa	nd Unit #102	API#:	30-02	5-10384		
	Field/Pool:	Lanç	glie-Mattix	Section:		21		
	County:		Lea	Township:	22S	Range:		
	State:	-	v Mexico	Location:		80' FSL x 19		Author:
ll	Spud Date:	1/2	27/1937	GL:	3359'	PBTD:	3265'	J. Valdez
	Description	O.D.	Weight		Depth	Hole	Cmt Sx	ТОС
				Тор				
	Surface	9	40	0	1354	12	555 Sx	0' calc
	Production	7	24	0	3350	8.875	200 sx	2043' calc
	Open Hole	6"		3350	3620	6"	ОН	N/A
	7. Cut off well head, 6. Perf & Sqz 33 sx c 9" surface casing @ 1354' 5. Perf & Sqz 73 sx c	mt @ 100'-	0'. (Surface Plu	g)		rf. Csg Shoe	Formation Rustler (T-Salt) Transil (B-Salt) Yates 7Rivers Queen * Used offset wel	1225'* 2456'* 2624'* 2830'* 3394'*
	Est TOC 2043' calc 4. Spot 25 sx cmt @ 3. Spot 25 sx cmt @				t))			
	2. Spot 25 sx cmt @2	2674'-2574'	. (Yates)					
	1. RIH & tag TOC. Re CIBP @ 3300' with 35' c	cord depth ement cap.	n. Circ hole with No tag depth reco	MLF. orded.				
	7" Production Casing @ 3	350'						
	6" Open Hole Completion	2250' 2620'						

District I 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone: (505) 476-3470 Fax: (505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

COMMENTS

Operator:	OGRID:
LEGACY RESERVES OPERATING, LP	240974
15 Smith Road	Action Number:
Midland, TX 79705	178523
	Action Type:
	[C-103] NOI Plug & Abandon (C-103F)

COMMENTS

Created By	Comment	Comment Date
plmartinez	DATA ENTRY PM	2/3/2023

Page 6 of 7

Action 178523

District I 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV 1220 S. St Francis Dr., Santa Fe, NM 87505 Phone: (505) 476-3470 Fax: (505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Operator:	OGRID:
LEGACY RESERVES OPERATING, LP	240974
15 Smith Road	Action Number:
Midland, TX 79705	178523
	Action Type:
	[C-103] NOI Plug & Abandon (C-103F)

CONDITIONS

Created By		Condition Date
kfortner	See attached COA	2/3/2023

Page 7 of 7

Action 178523