PCENIERITY COPY Po Appropriate District 30 AM	State of New Mexico	Form C-103	
Office <u>District I</u> – (575) 393-6161 Ener	75) 393-6161 Energy, Minerals and Natural Resources		
1625 N. French Dr., Hobbs, NM 88240		WELL API NO.	
District II – (575) 748-1283	CONSERVATION DIVISION	30-025-10495	
811 S. First St., Artesia, NM 88210 District III – (505) 334-6178	1220 South St. Francis Dr.	5. Indicate Type of Lease	
1000 Rio Brazos Rd., Aztec, NM 87410		STATE FEE	
<u>District IV</u> – (505) 476-3460	Santa Fe, NM 87505	6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM 87505			
SUNDRY NOTICES AND	REPORTS ON WELLS	7. Lease Name or Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DR		Langlie Mattix Penrose Sand Unit	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PROPOSALS.)	PERMIT" (FORM C-101) FOR SUCH	8. Well Number	
1. Type of Well: Oil Well Gas Well	Other	241	
2. Name of Operator	- Care	9. OGRID Number	
	RVES OPERATING LP	240974	
3. Address of Operator		10. Pool name or Wildcat	
15 SMITH ROAD	O, SUITE 3000, MIDLAND, TX 79705	Langlie Mattix; 7 Rvrs-Q-Grayburg	
4. Well Location		1	
Unit Letter I : 2310	feet from the <u>SOUTH</u> line and	330 feet from the <u>EAST</u> line	
Section 28	Township 22S Range 37E	NMPM County LEA	
	ation (Show whether DR, RKB, RT, GR, etc.	, , , , , , , , , , , , , , , , , , ,	
TI. Elevi	3339' GL		
12 Check Appropria	te Box to Indicate Nature of Notice	Report or Other Data	
12. Спеск прргорги		, report of other Data	
NOTICE OF INTENTIO	N TO: SUI	BSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG A	ND ABANDON ⊠ REMEDIAL WO	RK ALTERING CASING	
TEMPORARILY ABANDON CHANGE	E PLANS	RILLING OPNS. P AND A	
PULL OR ALTER CASING MULTIPI	LE COMPL ☐ CASING/CEMEI	NT JOB	
DOWNHOLE COMMINGLE			
CLOSED-LOOP SYSTEM ☐	_		
OTHER:	OTHER:		
		nd give pertinent dates, including estimated date	
	RULE 19.15.7.14 NMAC. For Multiple Co	ompletions: Attach wellbore diagram of	
proposed completion or recompletion.			
1. Previous TA. Include most recent MIT with	this NOL P/T if expired		
2. RIH & tag TOC. Record depth. Circ hole with			
3. Spot 55 sx cmt @2698'-2435'. WOC & Tag.			
4. Spot 25 sx cmt @1340'-1240'. WOC & Tag.			
5. Perf & Sqz 45 sx cmt @ 1188'-1052'. WOC			
6. Perf & Sqz 33 Sx cmt @ 814'-714'. WOC &			
7. Perf & Sqz 100 sx cmt @ 174'-0'. (Surface C		sected no cmt behind 7" or 8.625" pipe)	
8. Cut off well head, verify cmt at surface, welc	l on dry hole marker.		
4" diameter 4' tall Above Ground Marker	SEE ATT	ACHED CONDITIONS	
	OF APPR		
Spud Date:	Rig Release Date:		
I hereby certify that the information above is tru	ue and complete to the best of my knowled	ge and belief.	
,	1		
701 1 . 0			
SIGNATURE Melanie Reyes	TITLE Regulatory Tec	<u>h</u> <u>DATE 01/30/2023</u>	
\mathcal{O}		_	
Type or print name MELANIE REYES	E-mail address: <u>mreyes@legac</u>	<u>yreserves.com</u> PHONE: <u>432-221-6358</u>	
For State Use Only	_		
APPROVED BY: Year Forth	TITLE Compliance Officer	A DATE 2/3/23	
Conditions of Approval (if any):		DATEZISIZS	
Conditions of Approval (II all	575-263-6633		

CONDITIONS OF APPROVAL FOR PLUGGING AND ABANDONMENT OCD - Southern District

The following is a guide or checklist in preparation of a plugging program, this is not all inclusive and care must be exercised in establishing special plugging programs in unique and unusual cases, Notify NMOCD District Office I (Hobbs) at (575)-263-6633 at least 24 hours before beginning work. After MIRU rig will remain on well until it is plugged to surface. OCD is to be notified before rig down.

Company representative will be on location during plugging procedures.

- 1. A notice of intent to plug and abandon a wellbore is required to be approved before plugging operations are conducted. A cement evaluation tool is required in order to ensure isolation of producing formations, protection of water and correlative rights. A cement bond log or other accepted cement evaluation tool is to be provided to the division for evaluation if one has not been previously run or if the well did not have cement circulated to surface during the original casing cementing job or subsequent cementing jobs. Insure all bradenheads have been exposed, identified and valves are operational prior to rig up.
- **2.** Closed loop system is to be used for entire plugging operation. Upon completion, contents of steel pits are to be hauled to a permitted disposal location.
- **3.** Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private- shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator as well as the contractor, to verify that this permit is in place prior to performing work. Drivers shall be able to produce a copy upon request of an NMOCD Field inspector.
- 4. Filing a subsequent C-103 will serve as notification that the well has been plugged.
- **5.** A final C-103 shall be filed (and a site inspection by NMOCD Inspector to determine if the location is satisfactorily cleaned, all equipment, electric poles and trash has been removed to Meet NMOCD standards) before bonding can +be released.
- **6.** If work has not begun within 1 Year of the approval of this procedure, an extension request must be file stating the reason the well has not been plugged.
- 7. Squeeze pressures are not to exceed 500 psi, unless approval is given by NMOCD.
- **8.** Produced water will not be used during any part of the plugging operation.
- 9. Mud laden fluids must be placed between all cement plugs mixed at 25 sacks per 100 bbls of water.
- **10.** All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater. 50' of calculated cement excess required for inside casing plugs and 100% calculated cement excess required on outside casing plugs.
- 11. Class 'C' cement will be used above 7500 feet.
- 12. Class 'H' cement will be used below 7500 feet.
- **13.** A cement plug is required to be set 50' above and 50' below, casing stubs, DV tools, attempted casing cut offs, cement tops outside casing, salt sections and anywhere the casing is perforated, these plugs require a 4 hour WOC and then will be tagged
- **14.** All Casing Shoes Will Be Perforated 50' below shoe depth and Attempted to be Squeezed, cement needs to be 50' above and 50' Below Casing Shoe inside the Production Casing.
- **16.** When setting the top out cement plug in production, intermediate and surface casing, wellbores should remain full at least 30 minutes after plugs are set
- 17. A CIBP is to be set within 100' of production perforations, capped with 100' of cement, WOC 4 hours and tag.
- **18.** A CIBP with 35' of cement may be used in lieu of the 100' plug if set with a bailer. This plug will be placed within 100' of the top perforation, (WOC 4 hrs and tag).

- 19. No more than 3000' is allowed between cement plugs in cased hole and 2000' in open hole.
- 20. Some of the Formations to be isolated with cement plugs are: These plugs to be set to isolate formation tops
- A) Fusselman
- B) Devonian
- C) Morrow
- D) Wolfcamp
- E) Bone Springs
- F) Delaware
- G) Any salt sections
- H) Abo
- I) Glorieta
- J) Yates.
- K) Potash---(In the R-111-P Area (Potash Mine Area),

A solid cement plug must be set across the salt section. Fluid used to mix the cement shall be saturated with the salts that are common to the section penetrated and in suitable proportions, not more than 3% calcium chloride (by weight of cement) will be considered the desired mixture whenever possible, WOC 4 hours and tag, this plug will be 50' below the bottom and 50' above the top of the Formation.

21. If cement does not exist behind casing strings at recommended formation depths, the casing can be cut and pulled with plugs set at recommended depths. If casing is not pulled, perforations will be shot and cement squeezed behind casing, WOC and tagged. These plugs will be set 50' below formation bottom to 50' above formation top inside the casing.

DRY HOLE MARKER REQ.UIRMENTS


The operator shall mark the exact location of the plugged and abandoned well with a steel marker not less than four inches in diameter, 3' below ground level with a plate of at least ¼" welded to the top of the casing and the dry hole marker welded on the plate with the following information welded on the dry hole marker:

- 1. Operator name
- 2. Lease and Well Number
- 3. API Number
- 4. Unit letter
- 5. Quarter Section (feet from the North, South, East or West)
- 6. Section, Township and Range
- 7. Plugging Date
- 8. County


SPECIAL CASES ----AGRICULTURE OR PRARIE CHICKEN BREEDING AREAS

In these areas, a below ground marker is required with all pertinent information mentioned above on a plate, set 3' below ground level, a picture of the plate will be supplied to NMOCD for record, the exact location of the marker (longitude and latitude by GPS) will be provided to NMOCD (We typically require a current survey to verify the GPS)

SITE REMEDIATION DUE WITHIN ONE YEAR OF WELL PLUGGING COMPLETION




Submit I Copy To Appropriate District Office	State of New Mexico	Form C-103
District I - (575) 393-6161	Energy, Minerals and Natural Resource	Revised July 18, 2013 WELL API NO.
1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1283	HOBBS	30-025-10495
811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION	5. Indicate Type of Lease
<u>District III</u> - (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Frances 12019	STATE FEE
District IV - (505) 476-3460	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	Santa Fe, NM 87505 RECEIVED	
	S AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSAL	LS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	
DIFFERENT RESERVOIR. USE "APPLICA" PROPOSALS.)	FION FOR PERMIT" (FORM C-101) FOR SUCH	Langlie Mattix Penrose Sand Unit
	as Well Other	8. Well Number 241
2. Name of Operator		9. OGRID Number
	RVES OPERATING LP	240974
3. Address of Operator	MIDLAND, TX 79702	10. Pool name or Wildcat Langlie Mattix; 7Rvrs-Queen-Grayburg
	WIDDAND, IX 19102	Langue Mattix, 7KV13-Queen-Grayoung
4. Well Location	2210 Foot from the SOLITIE line and 2	330 feet from the EAST line
	2310 feet from the SOUTH line and 3	
Section 28	Township 22S Range 37E 1. Elevation (Show whether DR, RKB, RT, GR, etc.	NMPM County LEA
	1. Elevation (Show whether DR, RKB, RI, GR, etc.	
Mark Many Committee Commit		Be desired the first of the second of the se
12 Check Apr	propriate Box to Indicate Nature of Notice,	Report or Other Data
12. Chook 1 pp		Acoport of Other Data
NOTICE OF INTE		SEQUENT REPORT OF:
	PLUG AND ABANDON 🔲 REMEDIAL WOR	**************************************
	CHANGE PLANS	
	IULTIPLE COMPL	T JOB
DOWNHOLE COMMINGLE		
CLOSED-LOOP SYSTEM		
	CT OTHER: MIT 6	- T∧ ⊠
OTHER:	OTHER: MIT to	
OTHER: 13. Describe proposed or complete	d operations. (Clearly state all pertinent details, an	d give pertinent dates, including estimated date
OTHER: 13. Describe proposed or complete	d operations. (Clearly state all pertinent details, an . SEE RULE 19.15.7.14 NMAC. For Multiple Co.	d give pertinent dates, including estimated date
OTHER: 13. Describe proposed or complete of starting any proposed work)	d operations. (Clearly state all pertinent details, an . SEE RULE 19.15.7.14 NMAC. For Multiple Co.	d give pertinent dates, including estimated date
OTHER: 13. Describe proposed or complete of starting any proposed work)	d operations. (Clearly state all pertinent details, an . SEE RULE 19.15.7.14 NMAC. For Multiple Co.	d give pertinent dates, including estimated date
OTHER: 13. Describe proposed or complete of starting any proposed work) proposed completion or recomp	d operations. (Clearly state all pertinent details, an . SEE RULE 19.15.7.14 NMAC. For Multiple Conpletion.	d give pertinent dates, including estimated date inpletions: Attach wellbore diagram of
OTHER: 13. Describe proposed or complete of starting any proposed work) proposed completion or recomp	d operations. (Clearly state all pertinent details, an . SEE RULE 19.15.7.14 NMAC. For Multiple Co.	d give pertinent dates, including estimated date inpletions: Attach wellbore diagram of
OTHER: 13. Describe proposed or complete of starting any proposed work) proposed completion or recomp	d operations. (Clearly state all pertinent details, an . SEE RULE 19.15.7.14 NMAC. For Multiple Conpletion.	d give pertinent dates, including estimated date inpletions: Attach wellbore diagram of
OTHER: 13. Describe proposed or complete of starting any proposed work) proposed completion or recomp	d operations. (Clearly state all pertinent details, an . SEE RULE 19.15.7.14 NMAC. For Multiple Condition. In the state of the state o	d give pertinent dates, including estimated date impletions: Attach wellbore diagram of art attached.
OTHER: 13. Describe proposed or complete of starting any proposed work) proposed completion or recomp	d operations. (Clearly state all pertinent details, an SEE RULE 19.15.7.14 NMAC. For Multiple Corpletion. In part of the state of the	d give pertinent dates, including estimated date impletions: Attach wellbore diagram of art attached.
OTHER: 13. Describe proposed or complete of starting any proposed work) proposed completion or recomp	d operations. (Clearly state all pertinent details, an . SEE RULE 19.15.7.14 NMAC. For Multiple Corpletion. In the state of the state	d give pertinent dates, including estimated date impletions: Attach wellbore diagram of art attached. FUS-EXTENSION 6:
OTHER: 13. Describe proposed or complete of starting any proposed work) proposed completion or recomp	d operations. (Clearly state all pertinent details, an . SEE RULE 19.15.7.14 NMAC. For Multiple Corpletion. Ing to 570#. OCD notified but unable to witness, check the second of TA EXPIRES Well needs to be PLUGO	d give pertinent dates, including estimated date impletions: Attach wellbore diagram of art attached. FUS-EXTENSION 6:
OTHER: 13. Describe proposed or complete of starting any proposed work) proposed completion or recomp	d operations. (Clearly state all pertinent details, an SEE RULE 19.15.7.14 NMAC. For Multiple Corpletion. Ing to 570#. OCD notified but unable to witness, chempton of the experiment of the experiment of the experiment of the experiment of the place of the production.	d give pertinent dates, including estimated date impletions: Attach wellbore diagram of art attached. FUS-EXTENSION S: 10/21/24 GED OR RETURNED
OTHER: 13. Describe proposed or complete of starting any proposed work) proposed completion or recomp	d operations. (Clearly state all pertinent details, an . SEE RULE 19.15.7.14 NMAC. For Multiple Corpletion. Ing to 570#. OCD notified but unable to witness, check the second of TA EXPIRES Well needs to be PLUGO	d give pertinent dates, including estimated date impletions: Attach wellbore diagram of art attached. FUS-EXTENSION S: 10/21/24 GED OR RETURNED
OTHER: 13. Describe proposed or complete of starting any proposed work) proposed completion or recomp	d operations. (Clearly state all pertinent details, an SEE RULE 19.15.7.14 NMAC. For Multiple Corpletion. Ing to 570#. OCD notified but unable to witness, chempton of the experiment of the experiment of the experiment of the experiment of the place of the production.	d give pertinent dates, including estimated date impletions: Attach wellbore diagram of art attached. FUS-EXTENSION S: 10/21/24 GED OR RETURNED
OTHER: 13. Describe proposed or complete of starting any proposed work) proposed completion or recomplete of starting any proposed work) proposed completion or recomplete of the proposed complete or recomplete o	d operations. (Clearly state all pertinent details, an SEE RULE 19.15.7.14 NMAC. For Multiple Corpletion. Ing to 570#. OCD notified but unable to witness, chempton of the experiment of the experiment of the experiment of the experiment of the place of the production.	d give pertinent dates, including estimated date impletions: Attach wellbore diagram of art attached. FUS-EXTENSION S: 10/21/24 GED OR RETURNED
OTHER: 13. Describe proposed or complete of starting any proposed work) proposed completion or recomplete of starting any proposed work) proposed completion or recomplete of the proposed complete or recomplete o	d operations. (Clearly state all pertinent details, an SEE RULE 19.15.7.14 NMAC. For Multiple Corpletion. In part of 570#. OCD notified but unable to witness, check to provide the providence of the providence	d give pertinent dates, including estimated date impletions: Attach wellbore diagram of art attached. FUS-EXTENSION S: 10/21/24 GED OR RETURNED
OTHER: 13. Describe proposed or complete of starting any proposed work) proposed completion or recomp	d operations. (Clearly state all pertinent details, an SEE RULE 19.15.7.14 NMAC. For Multiple Corpletion. In part of 570#. OCD notified but unable to witness, check to provide the providence of the providence	d give pertinent dates, including estimated date impletions: Attach wellbore diagram of art attached. FUS-EXTENSION S: 10/21/24 GED OR RETURNED
OTHER: 13. Describe proposed or complete of starting any proposed work) proposed completion or recomplete of starting any proposed work) proposed completion or recomplete of the starting and starting any proposed completion or recomplete of the starting any proposed complete or recomplete of starting any proposed complete or recomplete of starting any proposed or complete or starting any proposed work) proposed work) proposed complete or recomplete or starting any proposed work) proposed complete or recomplete or starting any proposed work) proposed complete or recomplete or starting any proposed work) proposed complete or recomplete or r	d operations. (Clearly state all pertinent details, an SEE RULE 19.15.7.14 NMAC. For Multiple Corpletion. In part of 570#. OCD notified but unable to witness, check to provide the providence of the providence	d give pertinent dates, including estimated date impletions: Attach wellbore diagram of art attached. FUS-EXTENSION S:/0/2]/24 GED OR RETURNED ABOVE:X
OTHER: 13. Describe proposed or complete of starting any proposed work) proposed completion or recomplete of starting any proposed work) proposed completion or recomplete of the starting and starting any proposed completion or recomplete of the starting any proposed complete or recomplete of starting any proposed complete or recomplete of starting any proposed or complete or starting any proposed work) proposed work) proposed complete or recomplete or starting any proposed work) proposed complete or recomplete or starting any proposed work) proposed complete or recomplete or starting any proposed work) proposed complete or recomplete or r	d operations. (Clearly state all pertinent details, an SEE RULE 19.15.7.14 NMAC. For Multiple Corpletion. Ing to 570#. OCD notified but unable to witness, check to be PLUGO to PRODUCTION BY THE DATE STATED ARIGINAL Rig Release Date:	d give pertinent dates, including estimated date impletions: Attach wellbore diagram of art attached. FUS-EXTENSION S:/0/2]/24 GED OR RETURNED ABOVE:X
OTHER: 13. Describe proposed or complete of starting any proposed work) proposed completion or recomplete of starting any proposed work) proposed completion or recomplete of the starting any proposed completion or recomplete of the starting any proposed work) proposed complete or recomplete of starting any proposed work) proposed complete or recomplete of starting any proposed or complete of starting any proposed or complete of starting any proposed work) proposed work) proposed complete or recomplete or recomplete of starting any proposed work) proposed completion or recomplete or	d operations. (Clearly state all pertinent details, an SEE RULE 19.15.7.14 NMAC. For Multiple Corpletion. In the state of	d give pertinent dates, including estimated date impletions: Attach wellbore diagram of art attached. FUS-EXTENSION S:
OTHER: 13. Describe proposed or complete of starting any proposed work) proposed completion or recomplete of starting any proposed work) proposed completion or recomplete of the starting and starting any proposed completion or recomplete of the starting any proposed complete or recomplete of starting any proposed complete or recomplete of starting any proposed or complete or starting any proposed work) proposed work) proposed complete or recomplete or starting any proposed work) proposed complete or recomplete or starting any proposed work) proposed complete or recomplete or starting any proposed work) proposed complete or recomplete or r	d operations. (Clearly state all pertinent details, an SEE RULE 19.15.7.14 NMAC. For Multiple Corpletion. Ing to 570#. OCD notified but unable to witness, check to be PLUGO to PRODUCTION BY THE DATE STATED ARIGINAL Rig Release Date:	d give pertinent dates, including estimated date impletions: Attach wellbore diagram of art attached. FUS-EXTENSION S:
OTHER: 13. Describe proposed or complete of starting any proposed work) proposed completion or recomplete of starting any proposed work) proposed completion or recomplete of starting any proposed work) proposed completion or recomplete of starting any proposed work) proposed complete of starting any proposed work) proposed complete of starting any proposed or complete of starting any proposed or complete of starting any proposed work) proposed complete of starting any proposed work) proposed complete of starting any proposed work) proposed completion or recomplete of starting any proposed work) proposed complete of starting any proposed work) proposed complete of starting any proposed work) proposed completion or recomplete of starting any proposed work) proposed completion or recomplete of starting any proposed work) proposed completion or recomplete of starting any proposed work) proposed completion or recomplete of starting any proposed work) proposed completion or recomplete of starting any proposed work) proposed complete of starting any proposed work and starting and s	d operations. (Clearly state all pertinent details, an SEE RULE 19.15.7.14 NMAC. For Multiple Corpletion. In part of 570#. OCD notified but unable to witness, check to 570#. Approval of TA EXPIRES Well needs to be PLUGO to PRODUCTION BY THE DATE STATED ARIGINATE Rig Release Date: TITLE Compliance Coordinate Coordina	art attached. FUS- EXTENSION S:/0/2 /2 /9 GED OR RETURNED ABOVE:
OTHER: 13. Describe proposed or complete of starting any proposed work) proposed completion or recomplete of starting any proposed work) proposed completion or recomplete of starting any proposed work) proposed completion or recomplete of starting any proposed work) proposed completion or recomplete of starting any proposed work) proposed complete of starting any proposed or complete of starting any proposed work) proposed work) proposed complete of starting any proposed work) proposed complete of starting any proposed work) proposed completion or recomplete of starting any proposed work) proposed complete of starting any proposed work) proposed complete of starting any proposed work) proposed complete of starting any proposed work) proposed completion or recomplete of starting any proposed work) proposed completion or recomplete of starting any proposed work) proposed completion or recomplete of starting any proposed work) proposed complete of starting any proposed complete of starting any proposed work) proposed complete of starting and starting any proposed work) proposed work and starting any proposed work and starting any proposed work and starting and starting and starting and starting any proposed work and starting and start	d operations. (Clearly state all pertinent details, an SEE RULE 19.15.7.14 NMAC. For Multiple Corpletion. In the state of	d give pertinent dates, including estimated date impletions: Attach wellbore diagram of art attached. FUS- EXTENSION S:/0/21/24 GED OR RETURNED ABOVE:
OTHER: 13. Describe proposed or complete of starting any proposed work) proposed completion or recomplete of starting any proposed work) proposed completion or recomplete of starting any proposed completion or recomplete of starting any proposed completion or recomplete of starting any proposed work) proposed complete of starting any proposed work) proposed complete of starting any proposed or complete of starting any proposed or complete of starting any proposed work) proposed complete of starting any proposed or complete of starting any proposed work) proposed complete of starting any proposed work) proposed completion or recomplete of starting any proposed work) proposed completion or recomplete or starting any proposed work) proposed completion or recomplete or starting any proposed work) proposed completion or recomplete or starting any proposed work) proposed completion or recomplete or starting any proposed work) proposed completion or recomplete or starting any proposed work) proposed completion or recomplete or starting any proposed complete or starting and starting any proposed complete or starting and starting any proposed complete or starting and starting any proposed complete or starting and starting any	d operations. (Clearly state all pertinent details, an SEE RULE 19.15.7.14 NMAC. For Multiple Corpletion. In part of 570#. OCD notified but unable to witness, change to 570#. OCD notified but unable to witness, change to 570#. Approval of TA EXPIRES Well needs to be PLUGO to PRODUCTION BY THE DATE STATED. Rig Release Date: Rig Release Date:	d give pertinent dates, including estimated date impletions: Attach wellbore diagram of art attached. FUS- EXTENSION S:/0/21/24 GED OR RETURNED ABOVE:
OTHER: 13. Describe proposed or complete of starting any proposed work) proposed completion or recomplete of starting any proposed work) proposed completion or recomplete of the starting any proposed completion or recomplete of the starting any proposed work) proposed completion or recomplete of the starting any proposed work) proposed complete of the starting any proposed or complete of starting any proposed or complete of starting any proposed work) proposed complete of the starting any proposed work) proposed complete of the starting any proposed or complete of starting any proposed work) proposed complete of the starting any proposed or complete of starting any proposed work) proposed complete or recomplete of starting any proposed work) proposed completion or recomplete or starting any proposed work) proposed completion or recomplete or starting any proposed work) proposed completion or recomplete or starting any proposed work) proposed completion or recomplete or starting any proposed work) proposed completion or recomplete or starting any proposed work) proposed completion or recomplete or starting any proposed work) proposed completion or recomplete or starting any proposed work) proposed completion or recomplete or starting any proposed work) proposed completion or recomplete or starting any proposed work and starting a	d operations. (Clearly state all pertinent details, an SEE RULE 19.15.7.14 NMAC. For Multiple Corpletion. In part of 570#. OCD notified but unable to witness, change to 570#. OCD notified but unable to 570#. OCD notified but unable to 570#. OCD notified but unable to witness, change to 570#. OCD notified but unable to 570#.	art attached. FUS- EXTENSION S:/0/2 /2 /9 GED OR RETURNED ABOVE:





Langlie-Mattix P	enrose Sand Unit #241	API#:	30-025-10495			
Field/Pool:	Langlie-Mattix; 7Rvrs- Queen-Grayburg	Section:		28		
County:	Lea	Township:	22S	Range:	37E	
State:	New Mexico	Location:	2310' FSL x 330' FEL		Author:	
Spud Date:	11/6/1936	GL:	3339'	PBTD:	3640'	J. Valdez



Description	O.D.	Weight	Тор	Depth	Hole	Cmt Sx	TOC
Surface	15.5	70	0	124	19	150 sx	circ'd
Int- Hole Stability	13.375	45	0	309	15	Landed Only- Hole stability. Pulled before 7"	N/a
Int- Hole Stability	10.75	35	0	719	15	Landed Only- Hole stability. Pulled before 7"	N/a
Intermediate	8.625	28	0	1152	15	300 sx	Est 764' calc
Production	7	24	0	3405	8	175 sx	Est 1138' calc
Open Hole	6		3405	3684	6	Open Hole	

6. Cut off well head, verify cmt at surface, weld on dry hole marker.

15.5" Surface Casing @ 124'

5. Perf & Sqz 100 sx cmt @ 174'-0'. (Surface Csg Shoe/Surface Plug- extra sx due to suspected no cmt behind 7" or 8.625" pipe)

Formation Tops:			
Rustler (T-Salt)	1290		
Transil (B-Salt)	2485		
Yates	2648'*		
7Rivers	2844'*		
Queen	3416'*		
Delaware	·		

* Used offset well LMPSU #601

Est TOC 8.625" @ 764'

4. Perf & Sqz 33 Sx cmt @ 814'-714'. WOC & Tag (Est TOC 8.625" Csg)

Est TOC 7" @ 1138'

8.625" Intermediate Csg @ 1152'
3. Perf & Sqz 45 sx cmt @ 1188'-1052'. WOC & Tag (Est TOC 7" Csg/ Int. Casing Shoe)

2. Spot 25 sx cmt @1340'-1240'. WOC & Tag. (Rustler T-salt)

1. Spot 55 sx cmt @2698'-2435'. WOC & Tag. (Yates/ Transil (B-salt))

Tag TOC and record depth.

CIBP set @ 3350' with 35' cement cap on 9/25/2019. MIT to 570# on 10/21/19.

7" Production Casing 0'- 3405'

6" Open Hole 3405'-3684'

PBTD 3640' TD 3684'

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

COMMENTS

Action 180546

COMMENTS

Operator:	OGRID:
LEGACY RESERVES OPERATING, LP	240974
15 Smith Road	Action Number:
Midland, TX 79705	180546
	Action Type:
	[C-103] NOI Plug & Abandon (C-103F)

COMMENTS

Created By	Comment	Comment Date
plmartinez	DATA ENTRY PM	2/3/2023

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 180546

CONDITIONS

Operator:	OGRID:
LEGACY RESERVES OPERATING, LP	240974
15 Smith Road	Action Number:
Midland, TX 79705	180546
	Action Type:
	[C-103] NOI Plug & Abandon (C-103F)

CONDITIONS

Created By		Condition Date
kfortner	See attached COA	2/3/2023