Received by OCD: 1/27/2023 7:54:19 AM Submit 1 Copy To Appropriate District State of New Mexico	Form C <sup>Page 1</sup> of 8 Revised July 18, 2013
Office <u>District I</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240 Energy, Minerals and Natural Res	WELL API NO.
District II - (575) 748-1283 B11 S. First St., Artesia, NM 88210 OIL CONSERVATION DIVIS	SION 30-025-24641 5. Indicate Type of Lease
District III - (505) 334-6178 1220 South St. Francis Di	STATE FEE X
1000 Rio Brazos Rd., Aztec, NM 87410         Santa Fe, NM 87505           District IV - (\$05) 476-3460         1220 S. St. Francis Dr., Santa Fe, NM	6. State Oil & Gas Lease No. FEE
87505 SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)	Indy
1. Type of Well: Oil Well X Gas Well Other Injection	8. Well Number. #1
2. Name of Operator	9. OGRID Number 37636
State of New Mexico formerly Primal Energy Corporation 3. Address of Operator	10. Pool name or Wildcat
1625 N. French Drive, Hobbs, N 88240	Langlie Mattix / 7 rivers
4. Well Location	and 1980 feet from the W line
	and 1980 feet from the Wline e 37E NMPM Lea County
Section 7 Township 25S Rang 11. Elevation (Show whether DR, RKB,	and the second s
3159' GR	
12. Check Appropriate Box to Indicate Nature	of Notice, Report or Other Data SUBSEQUENT REPORT OF:
	MENCE DRILLING OPNS. P AND A
DOWNHOLE COMMINGLE	
	-B-
13 Describe proposed or completed operations. (Clearly state all pertine)	nt details, and give pertinent dates, including estimated date
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For proposed completion or recompletion.	Multiple Completions: Attach wellbore diagram of
Intent to P&A this well. Notify NMOCD to witness plugging operati NOTE: There is a fish at 2575'. Procedure is based on that informati	ons. on
MIRU, NU BOP, unknown if tubing in well (4.5" casing @ 3617' w/ Set CR or CIBP @ 2565', Cement with 25 sxs Type III cement. TOI	I.
Perforate @ 1188'. Mix and pump 63 sxs Type III cement; 38 outsid Perforate @ 390'. Mix and pump 63 sxs Type III cement; 38 outside	and 25 inside; WOC and tag.
WOC and tag(8-5/8". Casing @ 340' w/175 sxs)	
Perforate @ 150. circulate cement to surface. Cut off WH. Install P&A marker. Top off as necessary. Record Lor	e/I at
4" diameter 4' tall Above Ground Marker	SEE ATTACHED CONDITIONS
Note: Brine Gel will be placed between all cement plugs. Note: 100' or 25 sxs cement minimum.	OF APPROVAL
Note: CBL will be run CR $(a)$ 2565. Procedure may change based on	results of CBL.
I hereby certify that the information above is true and complete to the best of r	y knowledge and beller.
SIGNATURE Mul Lang TITLE Engineer	DATE 12/19/22
For State Use Only	apluswell.com PHONE: 505-486-6958
APPROVED BY: Kerry Forther TITLE Compliance C	Officer A DATE 2/3/23
Conditions of Approval (if any 575-263-66	33

# CONDITIONS OF APPROVAL FOR PLUGGING AND ABANDONMENT OCD - Southern District

The following is a guide or checklist in preparation of a plugging program, this is not all inclusive and care must be exercised in establishing special plugging programs in unique and unusual cases, Notify NMOCD District Office I (Hobbs) at (575)-263-6633 at least 24 hours before beginning work. After MIRU rig will remain on well until it is plugged to surface. OCD is to be notified before rig down.

## Company representative will be on location during plugging procedures.

**1.** A notice of intent to plug and abandon a wellbore is required to be approved before plugging operations are conducted. A cement evaluation tool is required in order to ensure isolation of producing formations, protection of water and correlative rights. A cement bond log or other accepted cement evaluation tool is to be provided to the division for evaluation if one has not been previously run or if the well did not have cement circulated to surface during the original casing cementing job or subsequent cementing jobs. Insure all bradenheads have been exposed, identified and valves are operational prior to rig up.

**2.** Closed loop system is to be used for entire plugging operation. Upon completion, contents of steel pits are to be hauled to a permitted disposal location.

**3.** Trucking companies being used to haul oilfield waste fluids to a disposal - commercial or private- shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator as well as the contractor, to verify that this permit is in place prior to performing work. Drivers shall be able to produce a copy upon request of an NMOCD Field inspector.

4. Filing a subsequent C-103 will serve as notification that the well has been plugged.

**5.** A final C-103 shall be filed (and a site inspection by NMOCD Inspector to determine if the location is satisfactorily cleaned, all equipment, electric poles and trash has been removed to Meet NMOCD standards) before bonding can +be released.

**6.** If work has not begun within 1 Year of the approval of this procedure, an extension request must be file stating the reason the well has not been plugged.

7. Squeeze pressures are not to exceed 500 psi, unless approval is given by NMOCD.

8. Produced water will not be used during any part of the plugging operation.

9. Mud laden fluids must be placed between all cement plugs mixed at 25 sacks per 100 bbls of water.

**10.** All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater. 50' of calculated cement excess required for inside casing plugs and 100% calculated cement excess required on outside casing plugs.

11. Class 'C' cement will be used above 7500 feet.

12. Class 'H' cement will be used below 7500 feet.

**13.** A cement plug is required to be set 50' above and 50' below, casing stubs, DV tools, attempted casing cut offs, cement tops outside casing, salt sections and anywhere the casing is perforated, these plugs require a 4 hour WOC and then will be tagged

**14.** All Casing Shoes Will Be Perforated 50' below shoe depth and Attempted to be Squeezed, cement needs to be 50' above and 50' Below Casing Shoe inside the Production Casing.

**16.** When setting the top out cement plug in production, intermediate and surface casing, wellbores should remain full at least 30 minutes after plugs are set

17. A CIBP is to be set within 100' of production perforations, capped with 100' of cement, WOC 4 hours and tag.

**18.** A CIBP with 35' of cement may be used in lieu of the 100' plug if set with a bailer. This plug will be placed within 100' of the top perforation, (WOC 4 hrs and tag).

19. No more than 3000' is allowed between cement plugs in cased hole and 2000' in open hole.

20. Some of the Formations to be isolated with cement plugs are: These plugs to be set to isolate formation tops

- A) Fusselman
- B) Devonian
- C) Morrow
- D) Wolfcamp
- E) Bone Springs
- F) Delaware
- G) Any salt sections
- H) Abo
- I) Glorieta
- J) Yates.

### K) Potash---(In the R-111-P Area (Potash Mine Area),

A solid cement plug must be set across the salt section. Fluid used to mix the cement shall be saturated with the salts that are common to the section penetrated and in suitable proportions, not more than 3% calcium chloride (by weight of cement) will be considered the desired mixture whenever possible, WOC 4 hours and tag, this plug will be 50' below the bottom and 50' above the top of the Formation.

**21.** If cement does not exist behind casing strings at recommended formation depths, the casing can be cut and pulled with plugs set at recommended depths. If casing is not pulled, perforations will be shot and cement squeezed behind casing, WOC and tagged. These plugs will be set 50' below formation bottom to 50' above formation top inside the casing.

# DRY HOLE MARKER REQ.UIRMENTS

The operator shall mark the exact location of the plugged and abandoned well with a steel marker not less than four inches in diameter, 3' below ground level with a plate of at least ¼" welded to the top of the casing and the dry hole marker welded on the plate with the following information welded on the dry hole marker:


- 1. Operator name
- 2. Lease and Well Number
- 3. API Number
- 4. Unit letter
- 5. Quarter Section (feet from the North, South, East or West)
- 6. Section, Township and Range
- 7. Plugging Date
- 8. County


## SPECIAL CASES -----AGRICULTURE OR PRARIE CHICKEN BREEDING AREAS

In these areas, a below ground marker is required with all pertinent information mentioned above on a plate, set 3' below ground level, a picture of the plate will be supplied to NMOCD for record, the exact location of the marker (longitude and latitude by GPS) will be provided to NMOCD (We typically require a current survey to verify the GPS)

# SITE REMEDIATION DUE WITHIN ONE YEAR OF WELL PLUGGING COMPLETION

Received by OCD: 1/27/2023 7:54:19 A Submit 1 Copy To Appropriate District Office	State of New Mex			orm C-1034 of 8
District I - (575) 393-6161	Energy, Minerals and Natura	al Resources	WELL API NO.	July 10, 2015
1625 N. French Dr., Hobbs, NM 88240 District II - (575) 748-1283	OIL CONSERVATION	10	30-025-24641	
811 S. First St., Artesia, NM 88210	1220 South St. France		<ol><li>Indicate Type of Lease</li></ol>	
District III - (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 875	1223 (222 (222 (222 (222 (222 (222 (222	6. State Oil & Gas Lease No.	
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 87505	Santa Fe, INM 67.		FEE	
SUNDRY NOTICES	AND REPORTS ON WELLS		<ol><li>Lease Name or Unit Agreet</li></ol>	ment Name
(DO NOT USE THIS FORM FOR PROPOSALS T DIFFERENT RESERVOIR. USE "APPLICATIO	'O DRILL OR TO DEEPEN OR PLU N FOR PERMIT" (FORM C-101) FOI	SUCH	Indy	
PROPOSALS.)	(c) <u>trues</u> (see ) (		8. Well Number. #1	
	Well Other Injection		9. OGRID Number	
<ol> <li>Name of Operator State of New Mexico formerly Primal</li> </ol>	Energy Corporation		37636	
3. Address of Operator			10. Pool name or Wildcat	
1625 N. French Drive, Hobbs, N 88240			Langlie Mattix / 7 rivers	
4. Well Location		1	121 121 121 121	
Unit Letter C:_990		line and1980		line
Section 7	Township 25S	Range 37E	NMPM Lea	County
the second s	Elevation (Show whether DR. 3159' GR	RKB, RI, GR, etc.)		and the second
A STATE A SECTOR PORT CONTRACTOR	5157 GK	and the second second		
12 Check Appr	opriate Box to Indicate Na	ature of Notice. F	Report or Other Data	
25.76	0.50			22
NOTICE OF INTEN			EQUENT REPORT OF	
	UG AND ABANDON	REMEDIAL WORK COMMENCE DRIL		
		CASING/CEMENT		
PULL OR ALTER CASING ML DOWNHOLE COMMINGLE		ONOINCIDEMENT		
CLOSED-LOOP SYSTEM				14
OTHER:		OTHER:		
13. Describe proposed or completed	operations. (Clearly state all p	ertinent details, and	give pertinent dates, including	; estimated date
of starting any proposed work).	SEE RULE 19.15.7.14 NMAC	. For Multiple Con	ipietions: Atlacti wendore diag	gram or
proposed completion or recompl	cuon.			
Intent to P&A this well. Notify	NMOCD to witness plugging of	perations.		
NOTE: There is a fish at 2575'.	Procedure is based on that inf	ormation		
	11 (1 5" anting (0.26)	7' w/225 ave como	at)	
MIRU, NU BOP, unknown if tu Set CR or CIBP @ 2565', Cem	ong in well (4.5 casing @ 50)	TOH.	nr.)	
Perforate @ 1188'. Mix and put	np 63 sxs Type III cement; 38	outside and 25 insid	e; WOC and tag.	
Perforate @ 390'. Mix and pum	p 63 sxs Type III cement; 38 o	utside and 25 inside	;	
WOC and tag(8-5/8". Casing @				
Perforate @ 150. circulate ceme Cut off WH. Install P&A market	nt to surface.	rd Long/Lat		
Cut on write instant PocA marke	a. Top on as necessary. Reco	ia congreat		
Note: Brine Gel will be placed b	etween all cement plugs.			
Note: 100' or 25 sxs cement min	úmum.			
Note: CBL will be run CR @ 25	65. Procedure may change bas	sed on results of CB	L.	
I hereby certify that the information above	e is true and complete to the be	est of my knowledge	and belief.	
personal test statistics with 15 10	86			2
11,1	1	To A	DATE 12/13	1/22
SIGNATURE Mul Lan	TITLE COG	need to be	DATE	1170
Type or print name Nell Lindenmeyer_	E-mail address:	nell@apluswell.com	u PHONE: 505-486-6958	
For State Use Only				
	00000 50		DATE	
APPROVED BY: Conditions of Approval (if any):	TITLE		DATE	
conditions of Approval (if any):				





District I 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV 1220 S. St Francis Dr., Santa Fe, NM 87505 Phone: (505) 476-3470 Fax: (505) 476-3462

**State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. Santa Fe, NM 87505

COMMENTS

Operator:	OGRID:
A-PLUS WELL SERVICE, INC.	370317
P.O. Box 1979	Action Number:
Farmington, NM 87499	180238
	Action Type:
	[C-103] NOI Plug & Abandon (C-103F)

#### COMMENTS

Created By		Comment Date
plmartinez	DATA ENTRY PM	2/3/2023

Action 180238

Page 7 of 8 COMMENTS

District I 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV 1220 S. St Francis Dr., Santa Fe, NM 87505 Phone: (505) 476-3470 Fax: (505) 476-3462

**State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Operator:	OGRID:
A-PLUS WELL SERVICE, INC.	370317
P.O. Box 1979	Action Number:
Farmington, NM 87499	180238
	Action Type:
	[C-103] NOI Plug & Abandon (C-103F)

### CONDITIONS

Created By		Condition Date
kfortner	See attached COA	2/3/2023

Page 8 of 8

Action 180238