eceined by OCP; 2/6/2023 12:48:10 P.	M State of New M	Iexico		Form C-103
Office District I – (575) 393-6161	Energy, Minerals and Na			Revised July 18, 2013
1625 N. French Dr., Hobbs, NM 88240	637	Energy, witherars and reactial resources		
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION	N DIVISION	30-015-35237	
<u>District III</u> – (505) 334-6178	1220 South St. Fra	ancis Dr.	5. Indicate Type of Le STATE ⊠	FEE
1000 Rio Brazos Rd., Aztec, NM 87410 District IV – (505) 476-3460	Santa Fe, NM 8	37505	6. State Oil & Gas Lea	
1220 S. St. Francis Dr., Santa Fe, NM 87505				
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			7. Lease Name or Unit LEATHERSTOCKING	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)				
	as Well Other		8. Well Number #2	
2. Name of Operator V-F PETROLEUM INC.			9. OGRID Number 2	4010
3. Address of Operator			10. Pool name or Wild	leat
P.O. BOX 1889, MIDLAND, TX 797	02		Illinois Camp; Morrow, N	North (Gas) (78890)
4. Well Location				
Unit LetterM_::	810feet from theSOU	JTH line and	660feet from the	WEST_line
Section 18	Township 18-S Range			
	11. Elevation (Show whether D	R, RKB, RT, GR, etc	.)	
	3597' GL			
12 Check An	propriate Box to Indicate 1	Nature of Notice	Report or Other Date	a
-			•	
NOTICE OF INT			SEQUENT REPOR	
	PLUG AND ABANDON 🛛	REMEDIAL WOR		ERING CASING
 -	CHANGE PLANS MULTIPLE COMPL	CASING/CEMEN		ND A
DOWNHOLE COMMINGLE	WOETH EE OOM E	O/ (OII VO/ OEIVIEI)	Notify OCD 24 hrs. pi	ior to any work
CLOSED-LOOP SYSTEM			done	, , , , , , , , , , , , , , , , , , , ,
OTHER:		OTHER:		
13. Describe proposed or complet	ed operations. (Clearly state all). SEE RULE 19.15.7.14 NMA	l pertinent details, ar	nd give pertinent dates, incompletions: Attach wellbo	cluding estimated date
proposed completion or recon		ic. Tor windpic co	impletions. Attach wellow	ne diagram or
V-F Petroleum Inc. would like to P&A	this well as follows: MIRUSU			
Plug #1 (10200'-9870'): Morrow perfs		OBP @ 10,200' & to	p w/25 sx cmt (\sim 330). Wo	OC, tag cmt. Circ hole
w/P&A mud (25 sx gel/100 bbls water) Plug #2 (9000'-8341'): Top Atoka @ 9		lace a halanced 50 s	x nlug (~659') @ 9000' V	NOC tag emt
Plug #3 (8200'-7851'): Top Wolfcamp				
plug (~349') CL H cmt 50' below cuto				
Plug #4 (5000'-4390'): Place a balance			1 1 1100 1 (2	1(1) 027001 WOO
Plug #5 (2700'-2354'): 8-5/8" shoe @ tag cmt.	<u>2620'</u> : Perf @ 26/0' & attempt	to sqz cmt. Place a	balanced 100 sx plug (~34	16') @2/00'. WOC,
Plug #6 (2000'-1879'): Top of Graybus	g @1995'. Place a balanced 35	sx plug (~121') @ 2	2000'. WOC, tag cmt.	
Plug #7 (1000'-879'): Top of Seven Ri	vers @ 945'. Place a balanced	35 sx plug (~121') @	1000'. WOC, tag cmt.	
Plug #8 (510'-Surface): 13-3/8" shoe (6				
below surface csg flange. Top off all cs location. Any flow back will be into clo		with cmt. RD Move	off location, cut off ancho	ors and restore
Totalion They now out will be like th	soca roop system.			
Sand Data 12/19/06		1/21/07		
Spud Date: 12/19/00	Rig Release I	Date:		
****SEE ATTACHE) CΩΔ's***	MUST BE	PLUGGED BY 9/8/202	2
I hereby certify that the information ab				
mm	•	·		
SIGNATURE: Ryan & Cur	TITLE: Regulatory Sup	pervisor DATE:	2/6/2023	
Type or print name: Ryan Curry E-n	nail address: <u>Ryan@VFPetrole</u>	um.com PHONE:	432-683-3344	
For State Use Only				
APPROVED BY:	TITLE	Staff Man	iager DATE	2/8/2023
Conditions of Approval (if any):		(2)		

CONDITIONS FOR PLUGGING AND ABANDONMENT

OCD - Southern District

The following is a guide or checklist in preparation of a plugging program, this is not all inclusive and care must be exercised in establishing special plugging programs in unique and unusual cases, Notify NMOCD District Office II at (575)-748-1283 at least 24 hours before beginning work. After MIRU rig will remain on well until it is plugged to surface. OCD is to be notified before rig down. Company representative will be on location during plugging procedures.

- A notice of intent to plug and abandon a wellbore is required to be approved before plugging
 operations are conducted. A cement evaluation tool is required in order to ensure isolation of
 producing formations, protection of water and correlative rights. A cement bond log or other
 accepted cement evaluation tool is to be provided to the division for evaluation if one has not
 been previously run or if the well did not have cement circulated to surface during the original
 casing cementing job or subsequent cementing jobs. Insure all bradenheads have been
 exposed, identified and valves are operational prior to rig up.
- 2. Closed loop system is to be used for entire plugging operation. Upon completion, contents of steel pits are to be hauled to a permitted disposal location.
- 3. Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator as well as the contractor, to verify that this permit is in place prior to performing work. Drivers shall be able to produce a copy upon request of an NMOCD Field inspector.
- 4. Filing a subsequent C-103 will serve as notification that the well has been plugged.
- 5. A final C-103 shall be filed (and a site inspection by NMOCD Inspector to determine if the location is satisfactorily cleaned, all equipment, electric poles and trash has been removed to Meet NMOCD standards) before bonding can be released.
- 6. If work has not begun within 1 Year of the approval of this procedure, an extension request must be file stating the reason the well has not been plugged.
- 7. Squeeze pressures are not to exceed 500 psi, unless approval is given by NMOCD.
- 8. Produced water will not be used during any part of the plugging operation.
- 9. Mud laden fluids must be placed between all cement plugs mixed at 25 sacks per 100 bbls of water.
- 10. All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater. 50' of calculated cement excess required for inside casing plugs and 100% calculated cement excess required on outside casing plugs.
- 11. Class 'C' cement will be used above 7500 feet.
- 12. Class 'H' cement will be used below 7500 feet.
- 13. A cement plug is required to be set 50' above and 50' below, casing stubs, DV tools, attempted casing cut offs, cement tops outside casing, salt sections and anywhere the casing is perforated, these plugs require a 4 hour WOC and then will be tagged
- 14. All Casing Shoes Will Be Perforated 50' below shoe depth and Attempted to be Squeezed, cement needs to be 50' above and 50' Below Casing Shoe inside the Production Casing.

- 16. When setting the top out cement plug in production, intermediate and surface casing, wellbores should remain full at least 30 minutes after plugs are set
- 17. A CIBP is to be set within 100' of production perforations, capped with 100' of cement, WOC 4 hours and tag.
- 18. A CIBP with 35' of cement may be used in lieu of the 100' plug if set with a bailer. This plug will be placed within 100' of the top perforation, (WOC 4 hrs and tag).
- 19. No more than 3000' is allowed between cement plugs in cased hole and 2000' in open hole.
- 20. Some of the Formations to be isolated with cement plugs are: These plugs to be set to isolate formation tops
 - A) Fusselman
 - B) Devonian
 - C) Morrow
 - D) Wolfcamp
 - E) Bone Springs
 - F) Delaware
 - G) Any salt sections
 - H) Abo
 - 1) Glorieta
 - J) Yates.
 - K) Cherry Canyon Eddy County
 - L) Potash---(In the R-111-P Area (Page 3 & 4), a solid cement plug must be set across the salt section. Fluid used to mix the cement shall be saturated with the salts that are common to the section penetrated and in suitable proportions, not more than 3% calcium chloride (by weight of cement) will be considered the desired mixture whenever possible, WOC 4 hours and tag, this plug will be 50' below the bottom and 50' above the top of the Formation.
- 21. If cement does not exist behind casing strings at recommended formation depths, the casing can be cut and pulled with plugs set at recommended depths. If casing is not pulled, perforations will be shot and cement squeezed behind casing, WOC and tagged. These plugs will be set 50' below formation bottom to 50' above formation top inside the casing

DRY HOLE MARKER REQUIRMENTS

The operator shall mark the exact location of the plugged and abandoned well with a steel marker not less than four inches in diameter, 3' below ground level with a plate of at least ¼" welded to the top of the casing and the dry hole marker welded on the plate with the following information welded on the dry hole marker:

1. Operator name 2. Lease and Well Number 3.API Number 4. Unit Letter 5. Quarter Section (feet from the North, South, East or West) 6. Section, Township and Range 7. Plugging Date 8. County (SPECIAL CASES)------AGRICULTURE OR PRARIE CHICKEN BREEDING AREAS

In these areas, a below ground marker is required with all pertinent information mentioned above on a plate, set 3' below ground level, a picture of the plate will be supplied to NMOCD for record, the exact location of the marker (longitude and latitude by GPS) will be provided to NMOCD (We typically require a current survey to verify the GPS)

SITE REMEDIATION DUE WITHIN ONE YEAR OF WELL PLUGGING COMPLETION

R-111-P Area

T 18S - R 30E

Sec 10 Unit P. Sec 11 Unit M,N. Sec 13 Unit L,M,N. Sec 14 Unit C -P. Sec 15 Unit A G,H,I,J,K,N,O,P. Sec 22 Unit All except for M. Sec 23, Sec 24 Unit C,D,E,L, Sec 26 Unit A-G, Sec 27 Unit A,B,C

T 19S - R 29E

Sec 11 Unit P. Sec 12 Unit H-P. Sec 13. Sec 14 Unit A,B,F-P. Sec 15 Unit P. Sec 22 Unit A,B,C,F,G,H,I,J K,N,O,P. Sec 23. Sec 24. Sec 25 Unit D. Sec 26 Unit A-F. Sec 27 Unit A,B,C,F,G,H.

T 19S - R 30E

Sec 2 Unit K,L,M,N. Sec 3 Unit I,L,M,N,O,P. Sec 4 Unit C,D,E,F,G,I-P. Sec 5 Unit A,B,C,E-P. Sec 6 Unit I,O,P. Sec 7 – Sec 10. Sec 11 Unit D, G—P. Sec 12 Unit A,B,E-P. Sec 13 Unit A-O. Sec 14-Sec 18. Sec 19 Unit A-L, P. Sec 20 – Sec 23. Sec 24 Unit C,D,E,F,L,M,N. Sec 25 Unit D. Sec 26 Unit A-G, I-P. Sec 27, Sec 28, Sec 29 Unit A,B,C,D,F,G,H,I,J,O,P. Sec 32 Unit A,B,G,H,I,J,N,O,P. Sec 33. Sec 34. Sec 35. Sec 36 Unit D,E,F,I-P.

T 19S - R 31E

Sec 7 Unit C,D,E,F,L. Sec 18 Unit C,D,E,F,G,K,L. Sec 31 Unit M. Sec 34 Unit P. Sec 35 Unit M,N,O. Sec 36 Unit O,P.

T 20S - R 29E

Sec 1 Unit H,I,P. Sec 13 Unit E,L,M,N. Sec 14 Unit B-P. Sec 15 Unit A,H,I,J,N,O,P. Sec 22 Unit A,B,C,F,G,H,I,J,O,P. Sec 23. Sec 24 Unit C,D,E,F,G,J-P. Sec 25 Unit A-O. Sec 26. Sec 27 Unit A,B,G,H,I,J,O,P. Sec 34 Unit A,B,G,H. Sec 35 Unit A-H. Sec 36 Unit B-G.

T 20S - R 30E

Sec 1 – Sec 4. Sec 5 Unit A,B,C,E-P. Sec 6 Unit E,G-P. Sec 7 Unit A-H,I,J,O,P. Sec 8 – 17. Sec 18 Unit A,B,G,H,I,J,O,P. Sec 19 Unit A,B,G,H,I,J,O,P. Sec 30 Unit A-L,N,O,P. Sec 31 Unit A,B,G,H,I,P. Sec 32 – Sec 36.

T 20S - R 31E

Sec 1 Unit A,B,C,E-P. Sec 2. Sec 3 Unit A,B,G,H,I,J,O,P. Sec 6 Unit D,E,F,J-P. Sec 7. Sec 8 Unit E-P. Sec 9 Unit E,F,J-P. Sec 10 Unit A,B,G-P. Sec 11 – Sec 36.

T 21S - R 29E

Sec 1 – Sec 3. Sec 4 Unit L1 – L16,I,J,K,O,P. Sec 5 Unit L1. Sec 10 Unit A,B,H,P. Sec 11 – Sec 14. Sec 15 Unit A,H,I. Sec 23 Unit A,B. Sec 24 Unit A,B,C,D,F,G,H,I,J,O,P. Sec 25 Unit A,O,P. Sec 35 Unit G,H,I,J,K,N,O,P. Sec 36 A,B,C,F – P.

T 21S - R 30E

Sec 1 – Sec 36

T 21S - R 31E

Sec 1 – Sec 36

T 22S - R 28E

Sec 36 Unit A,H,I,P.

T 22S - R 29E

Sec 1. Sec2. Sec 3 Unit I,J,N,O,P. Sec 9 Unit G – P. Sec 10 – Sec 16. Sec 19 Unit H,I,J. Sec 20 – Sec 28. Sec 29 Unit A,B,C,D,G,H,I,J,O,P. Sec 30 Unit A. Section 31 Unit C – P. Sec 32 – Sec 36

T 22S - R 30E

Sec 1 – Sec 36

T 22S - R 31E

Sec 1 – Sec 11. Sec 12 Unit B,C,D,E,F,L. Sec 13 Unit E,F,K,L,M,N. Sec 14 – Sec 23. Sec 24 Unit C,D,E,F,K,L,M,N. Sec 25 Unit A,B,C,D. Sec 26 Unit A,BC,D,G,H. Sec 27 – Sec 34.

T 23S - R 28E

Sec 1 Unit A

T 23S - R 29E

Sec 1 – Sec 5. Sec 6 Unit A – I, N,O,P. Sec 7 Unit A,B,C,G,H,I,P. Sec 8 Unit A – L, N,O,P. Sec 9 – Sec 16. Sec 17 Unit A,B,G,H,I,P. Sec 21 – Sec 23. Sec 24 Unit A – N. Sec 25 Unit D,E,L. Sec 26. Sec 27. Sec 28 Unit A – J, N,O,P. Sec 33 Unit A,B,C. Sec 34 Unit A,B,C,D,F,G,H. Sec 35. Sec 36 Unit B,C,D,E,F,G,K,L.

T 23S - R 30E

Sec 1 – Sec 18. Sec 19 Unit A – I,N,O,P. Sec 20, Sec 21. Sec 22 Unit A – N, P. Sec 23, Sec 24, Sec 25. Sec 26 Unit A,B,F-P. Sec 27 Unit C,D,E,I,N,O,P. Sec 28 Unit A – H, K,L,M,N. Sec 29 Unit A – J, O,P. Sec 30 Unit A,B. Sec 32 A,B. Sec 33 Unit C,D,H,I,O,P. Sec 34, Sec 35, Sec 36.

T 23S - R 31E

Sec 2 Unit D,E,J,O. Sec 3 – Sec 7. Sec 8 Unit A – G, K – N. Sec 9 Unit A,B,C,D. Sec 10 Unit D,P. Sec 11 Unit G,H,I,J,M,N,O,P. Sec 12 Unit E,L,K,M,N. Sec 13 Unit C,D,E,F,G,J,K,L,M,N,O. Sec 14. Sec 15 Unit A,B,E – P. Sec 16 Unit I, K – P. Sec 17 Unit B,C,D,E, I – P. Sec 18 – Sec 23. Sec 24 Unit B – G, K,L,M,N. Sec 25 Unit B – G, J,K,L. Sec 26 – Sec 34. Sec 35 Unit C,D,E.

T 24S – R 29E

Sec 2 Unit A, B, C, D. Sec 3 Unit A

T 24S - R 30E

Sec 1 Unit A – H, J – N. Sec 2, Sec 3. Sec 4 Unit A,B,F – K, M,N,O,P. Sec 9 Unit A – L. Sec 10 Unit A – L, O,P. Sec 11. Sec 12 Unit D,E,L. Sec 14 Unit B – G. Sec 15 Unit A,B,G,H.

T 24S - R 31E

Sec 3 Unit B – G, J – O. Sec 4. Sec 5 Unit A – L, P. Sec 6 Unit A – L. Sec 9 Unit A – J, O,P. Sec 10 Unit B – G, K – N. Sec 35 Unit E – P. Sec 36 Unit E,K,L,M,N.

T 25S - R 31E

Sec 1 Unit C,D,E,F. Sec 2 Unit A – H.

API# 30-015-35237

02/06/2023

bp \ eng \ drilling \ history \ Leatherstocking #2 WBS 200831

Well: Leatherstocking 18 St. Com. 2 LOC: 810' FSL & 660' FWL Sec 18, T-18-S, R-28-E in Eddy Co., NM Operator: V-F Petroleum Inc.
Field: Illinois Camp; Morrow, North (Gas)

Elevation: GL= 3,597

KB-GL= 16

KB = 3,613

TD	Hole Sz	Tops & Perfs	Casing & Cement
460	17 1/2"		13 3/8" 48# H-40 CSG w/ 460 sx Hlite CMT
2,620	<u>11"</u>	T Seven Rivers @ 945 T Queen @ 1,485 T Grayburg @ 1,995 T San Angres @ 2,245 T Lovington Sd @ 2,370	8 5/8" 32# K-55 CSG w/ 650 sx C CMT
		T Wolfcamp @ 7,930 T Stawn @ 9,070 T Atoka @ 9,747	TOC @ 8,250 (CBL)
		T Morrow @ 10,076	Packer @ 10,184 2 3/8" Tbg @ 10,190 w/ plug in profile nipple
10,587	<u>7 7/8"</u>	Perfs: 10,238 - 10,333 (6 jspf, 191 Holes)	PBTD 10,490 4 1/2" 11.6# P-110 CSG w/ 500 sx H CMT

REMARKS:

EXISTING WELLBORE CONDITIONS 08-25-2020.

02/06/2023

bp \ eng \ drilling \ history \ Leatherstocking #2 WBS 200831

Well: Leatherstocking 18 St. Com. 2
LOC: 810' FSL & 660' FWL
Sec 18, T-18-S, R-28-E
in Eddy Co., NM
API# 30-015-35237

Operator: V-F Petroleum Inc.
Field: Illinois Camp; Morrow, North (Gas)

Elevation: GL= 3,597

KB-GL= 16

KB= 3,613

TD Hole Sz Tops & Perfs Casing & Cement 25 sacks cement 60' - surface 460 17 1/2" 13 3/8" 48# H-40 CSG w/ 460 sx Hlite CMT T Seven Rivers @ 945 35 sack cement plug @ 1,000' T Queen @ 1,485 35 sack cement plug @ 2,000' T Grayburg @ 1,995 T San Angres @ 2,245 9.5 ppg plug mud <u>11"</u> 2,620 T Lovington Sd @ 2,370 8 5/8" 32# K-55 CSG w/ 650 sx C CMT 100 sack cement plug 2700' - 2500' (TAG) 9.5 ppg plug mud 175 sack cement plug @ 5,000' - 4,500' (TAG) 9.5 ppg plug mud 100 sack cement plug @ 8,200' - 7,900' (Tag) Cut off 4 1/2" casing @ 8,200' T Wolfcamp (a) 7,930 TOC @ 8,250 (CBL) 9.5 ppg plug mud T Stawn @ 9,070 50 sack cement plug @ 9,000' T Atoka @ 9,747 9.5 ppg plug mud Capped w/ 25 sks.of cement T Morrow @ 10,076 CIBP @ 10,200' Perfs: 10,238 - 10,333 (6 jspf, 191 Holes) PBTD 10,490 10,587 7 7/8" 4 1/2" 11.6# P-110 CSG w/ 500 sx H CMT

REMARKS:

EXISTING WELLBORE AFTER P & A

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 183084

CONDITIONS

Operator:	OGRID:
V-F PETROLEUM INC	24010
P.O. Box 1889	Action Number:
Midland, TX 79702	183084
	Action Type:
	[C-103] NOI Plug & Abandon (C-103F)

CONDITIONS

Created By	Condition	Condition Date
gcordero	None	2/8/2023