Ceived by OCD: 3/28/2023 3:45:32 PN Office	State of New Mexico	Form C^{Pqpq_1}				
District I – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resources	Revised July 18, 2013 WELL API NO. 30-015-22755				
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION	5. Indicate Type of Lease				
<u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr. Santa Fe, NM 87505	STATE FEE X				
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 87505	Sana 1 C, 1441 07505	6. State Oil & Gas Lease No.				
SUNDRY NOTICE	7. Lease Name or Unit Agreement Name					
(DO NOT USE THIS FORM FOR PROPOSAL DIFFERENT RESERVOIR. USE "APPLICAT PROPOSALS.)	Waldrip JY 8. Well Number 1					
1. Type of Well: Oil Well X Ga	Type of Well: Oil Well 🔀 Gas Well 🗌 Other					
2. Name of Operator SILVERBAC	K OPERATING II, LLC	9. OGRID Number 330968				
	IH 10, Suite 201	10. Pool name or Wildcat ATOKA; GLORIETA-YESO				
4. Well Location	, 1X 78257	ATOKA, GLOKIETA-TESO				
4. Wen Location Unit Letter L : 2	2310 feet from the South line and	330 feet from the West line				
Section 34	Township 18S Range 26E	NMPM County Eddy				
1	1. Elevation (Show whether DR, RKB, RT, GR, etc. 3358' GR					
12. Check Apr	propriate Box to Indicate Nature of Notice	e Report or Other Data				
	· •	BSEQUENT REPORT OF:				
	PLUG AND ABANDON 🛛 REMEDIAL WO	·				
		RILLING OPNS. P AND A				
	/ULTIPLE COMPL CASING/CEME	NT JOB				
DOWNHOLE COMMINGLE						
CLOSED-LOOP SYSTEM	OTHER:					
13. Describe proposed or complete	ed operations. (Clearly state all pertinent details, a	nd give pertinent dates, including estimated date				
of starting any proposed work). completion or recompletion.	SEE RULE 19.15.7.14 NMAC. For Multiple Co.	mpletions: Attach wellbore diagram of proposed				
Silverback Operating II, LLC pl	ans to plug and abandon this well as follows:					
Silverback Operating II, LLC pl 1. MIRU workover rig. Load	ans to plug and abandon this well as follows: tbg and csg with water as needed. POOH with rod	ls and pump.				
Silverback Operating II, LLC pl		ls and pump.				
Silverback Operating II, LLC pl 1. MIRU workover rig. Load ND pumping tee. NU BOP 2. POOH with 2 3/8" tbg 3. GIH with CIBP on tbg and	tbg and csg with water as needed. POOH with rod set at 2,785'. Spot 25 sk cement plug on CIBP. W					
Silverback Operating II, LLC pl 1. MIRU workover rig. Load ND pumping tee. NU BOP 2. POOH with 2 3/8" tbg 3. GIH with CIBP on tbg and 4. PU and spot 25 sk cmt plug	tbg and csg with water as needed. POOH with rod set at 2,785'. Spot 25 sk cement plug on CIBP. W g from 854'-1,223'					
Silverback Operating II, LLC pl 1. MIRU workover rig. Load ND pumping tee. NU BOP 2. POOH with 2 3/8" tbg 3. GIH with CIBP on tbg and 4. PU and spot 25 sk cmt plug 5. PU and spot 25 sk cmt plug	tbg and csg with water as needed. POOH with rod set at 2,785'. Spot 25 sk cement plug on CIBP. W g from 854'-1,223'					
Silverback Operating II, LLC pl 1. MIRU workover rig. Load ND pumping tee. NU BOP 2. POOH with 2 3/8" tbg 3. GIH with CIBP on tbg and 4. PU and spot 25 sk cmt plug 5. PU and spot 25 sk cmt plug	tbg and csg with water as needed. POOH with rod set at 2,785'. Spot 25 sk cement plug on CIBP. W g from 854'-1,223' g from 0-369' l dry hole marker. Clean location as regulated.					
Silverback Operating II, LLC pl 1. MIRU workover rig. Load ND pumping tee. NU BOP 2. POOH with 2 3/8" tbg 3. GIH with CIBP on tbg and 4. PU and spot 25 sk cmt plug 5. PU and spot 25 sk cmt plug 6. Cut off wellhead and instal Wellbore schematics attached	tbg and csg with water as needed. POOH with rod set at 2,785'. Spot 25 sk cement plug on CIBP. W g from 854'-1,223' g from 0-369' l dry hole marker. Clean location as regulated.					
Silverback Operating II, LLC pl 1. MIRU workover rig. Load ND pumping tee. NU BOP 2. POOH with 2 3/8" tbg 3. GIH with CIBP on tbg and 4. PU and spot 25 sk cmt plug 5. PU and spot 25 sk cmt plug 6. Cut off wellhead and instal Wellbore schematics attached	tbg and csg with water as needed. POOH with rod set at 2,785'. Spot 25 sk cement plug on CIBP. W g from 854'-1,223' g from 0-369' l dry hole marker. Clean location as regulated.					
Silverback Operating II, LLC pl 1. MIRU workover rig. Load ND pumping tee. NU BOP 2. POOH with 2 3/8" tbg 3. GIH with CIBP on tbg and 4. PU and spot 25 sk cmt plug 5. PU and spot 25 sk cmt plug 6. Cut off wellhead and instal Wellbore schematics attached Spud Date:	tbg and csg with water as needed. POOH with rod set at 2,785'. Spot 25 sk cement plug on CIBP. W g from 854'-1,223' g from 0-369' l dry hole marker. Clean location as regulated.	OC. Tag cmt plug				
Silverback Operating II, LLC pl 1. MIRU workover rig. Load ND pumping tee. NU BOP 2. POOH with 2 3/8" tbg 3. GIH with CIBP on tbg and 4. PU and spot 25 sk cmt plug 5. PU and spot 25 sk cmt plug 6. Cut off wellhead and instal Wellbore schematics attached Spud Date:	tbg and csg with water as needed. POOH with rod set at 2,785'. Spot 25 sk cement plug on CIBP. W g from 854'-1,223' g from 0-369' l dry hole marker. Clean location as regulated.	OC. Tag cmt plug				
Silverback Operating II, LLC pl 1. MIRU workover rig. Load 3 ND pumping tee. NU BOP 2. POOH with 2 3/8" tbg 3. GIH with CIBP on tbg and 4. PU and spot 25 sk cmt plug 5. PU and spot 25 sk cmt plug 6. Cut off wellhead and instal Wellbore schematics attached Spud Date:	tbg and csg with water as needed. POOH with rod set at 2,785'. Spot 25 sk cement plug on CIBP. W g from 854'-1,223' g from 0-369' l dry hole marker. Clean location as regulated.	OC. Tag cmt plug lge and belief. DATE_03/28/2023				
Silverback Operating II, LLC pl 1. MIRU workover rig. Load ND pumping tee. NU BOP 2. POOH with 2 3/8" tbg 3. GIH with CIBP on tbg and 4. PU and spot 25 sk cmt plug 5. PU and spot 25 sk cmt plug 6. Cut off wellhead and instal Wellbore schematics attached Spud Date: I hereby certify that the information abo SIGNATUREFatma Abdallah	tbg and csg with water as needed. POOH with rod set at 2,785'. Spot 25 sk cement plug on CIBP. W g from 854'-1,223' g from 0-369' l dry hole marker. Clean location as regulated.	OC. Tag cmt plug				
Silverback Operating II, LLC pl 1. MIRU workover rig. Load - ND pumping tee. NU BOP 2. POOH with 2 3/8" tbg 3. GIH with CIBP on tbg and 4. PU and spot 25 sk cmt plug 5. PU and spot 25 sk cmt plug 6. Cut off wellhead and instal Wellbore schematics attached Spud Date:	tbg and csg with water as needed. POOH with rod set at 2,785'. Spot 25 sk cement plug on CIBP. W g from 854'-1,223' g from 0-369' l dry hole marker. Clean location as regulated.	OC. Tag cmt plug OC. Tag cmt plug Ige and belief. DATE_03/28/2023 Verbackexp.com_PHONE: (210) 585-3316				

•

CONDITIONS FOR PLUGGING AND ABANDONMENT

OCD - Southern District

The following is a guide or checklist in preparation of a plugging program, this is not all inclusive and care must be exercised in establishing special plugging programs in unique and unusual cases, Notify NMOCD District Office II at (575)-748-1283 at least 24 hours before beginning work. After MIRU rig will remain on well until it is plugged to surface. OCD is to be notified before rig down. Company representative will be on location during plugging procedures.

- 1. A notice of intent to plug and abandon a wellbore is required to be approved before plugging operations are conducted. A cement evaluation tool is required in order to ensure isolation of producing formations, protection of water and correlative rights. A cement bond log or other accepted cement evaluation tool is to be provided to the division for evaluation if one has not been previously run or if the well did not have cement circulated to surface during the original casing cementing job or subsequent cementing jobs. Insure all bradenheads have been exposed, identified and valves are operational prior to rig up.
- 2. Closed loop system is to be used for entire plugging operation. Upon completion, contents of steel pits are to be hauled to a permitted disposal location.
- 3. Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator as well as the contractor, to verify that this permit is in place prior to performing work. Drivers shall be able to produce a copy upon request of an NMOCD Field inspector.
- 4. Filing a subsequent C-103 will serve as notification that the well has been plugged.
- 5. A final C-103 shall be filed (and a site inspection by NMOCD Inspector to determine if the location is satisfactorily cleaned, all equipment, electric poles and trash has been removed to Meet NMOCD standards) before bonding can be released.
- 6. If work has not begun within 1 Year of the approval of this procedure, an extension request must be file stating the reason the well has not been plugged.
- 7. Squeeze pressures are not to exceed 500 psi, unless approval is given by NMOCD.
- 8. Produced water will not be used during any part of the plugging operation.
- 9. Mud laden fluids must be placed between all cement plugs mixed at 25 sacks per 100 bbls of water.
- 10. All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater. 50' of calculated cement excess required for inside casing plugs and 100% calculated cement excess required on outside casing plugs.
- 11. Class 'C' cement will be used above 7500 feet.
- 12. Class 'H' cement will be used below 7500 feet.
- 13. A cement plug is required to be set 50' above and 50' below, casing stubs, DV tools, attempted casing cut offs, cement tops outside casing, salt sections and anywhere the casing is perforated, these plugs require a 4 hour WOC and then will be tagged
- 14. All Casing Shoes Will Be Perforated 50' below shoe depth and Attempted to be Squeezed, cement needs to be 50' above and 50' Below Casing Shoe inside the Production Casing.

- 16. When setting the top out cement plug in production, intermediate and surface casing, wellbores should remain full at least 30 minutes after plugs are set
- 17. A CIBP is to be set within 100' of production perforations, capped with 100' of cement, WOC 4 hours and tag.
- 18. A CIBP with 35' of cement may be used in lieu of the 100' plug if set with a bailer. This plug will be placed within 100' of the top perforation, (WOC 4 hrs and tag).
- 19. No more than 3000' is allowed between cement plugs in cased hole and 2000' in open hole.
- 20. Some of the Formations to be isolated with cement plugs are: These plugs to be set to isolate formation tops
 - A) Fusselman
 - B) Devonian
 - C) Morrow
 - D) Wolfcamp
 - E) Bone Springs
 - F) Delaware
 - G) Any salt sections
 - H) Abo
 - I) Glorieta
 - J) Yates.
 - K) Cherry Canyon Eddy County
 - L) Potash----(In the R-111-P Area (Page 3 & 4), a solid cement plug must be set across the salt section. Fluid used to mix the cement shall be saturated with the salts that are common to the section penetrated and in suitable proportions, not more than 3% calcium chloride (by weight of cement) will be considered the desired mixture whenever possible, WOC 4 hours and tag, this plug will be 50' below the bottom and 50' above the top of the Formation.
- 21. If cement does not exist behind casing strings at recommended formation depths, the casing can be cut and pulled with plugs set at recommended depths. If casing is not pulled, perforations will be shot and cement squeezed behind casing, WOC and tagged. These plugs will be set 50' below formation bottom to 50' above formation top inside the casing

DRY HOLE MARKER REQUIRMENTS

The operator shall mark the exact location of the plugged and abandoned well with a steel marker not less than four inches in diameter, 3' below ground level with a plate of at least ¼" welded to the top of the casing and the dry hole marker welded on the plate with the following information welded on the dry hole marker:

1. Operator name2. Lease and Well Number3. API Number4. Unit Letter5. QuarterSection (feet from the North, South, East or West)6. Section, Township and Range7. Plugging Date8. County(SPECIAL CASES)------AGRICULTURE OR PRARIE CHICKEN BREEDING AREAS

In these areas, a below ground marker is required with all pertinent information mentioned above on a plate, set 3' below ground level, a picture of the plate will be supplied to NMOCD for record, the exact location of the marker (longitude and latitude by GPS) will be provided to NMOCD (We typically require a current survey to verify the GPS)

SITE REMEDIATION DUE WITHIN ONE YEAR OF WELL PLUGGING COMPLETION

R-111-P Area

T 18S – R 30E

Sec 10 Unit P. Sec 11 Unit M,N. Sec 13 Unit L,M,N. Sec 14 Unit C -P. Sec 15 Unit A G,H,I,J,K,N,O,P. Sec 22 Unit All except for M. Sec 23, Sec 24 Unit C,D,E,L, Sec 26 Unit A-G, Sec 27 Unit A,B,C

T 19S – R 29E

Sec 11 Unit P. Sec 12 Unit H-P. Sec 13. Sec 14 Unit A,B,F-P. Sec 15 Unit P. Sec 22 Unit A,B,C,F,G,H,I,J K,N,O,P. Sec 23. Sec 24. Sec 25 Unit D. Sec 26 Unit A- F. Sec 27 Unit A,B,C,F,G,H.

T 19S – R 30E

Sec 2 Unit K,L,M,N. Sec 3 Unit I,L,M,N,O,P. Sec 4 Unit C,D,E,F,G,I-P. Sec 5 Unit A,B,C,E-P. Sec 6 Unit I,O,P. Sec 7 – Sec 10. Sec 11 Unit D, G—P. Sec 12 Unit A,B,E-P. Sec 13 Unit A-O. Sec 14-Sec 18. Sec 19 Unit A-L, P. Sec 20 – Sec 23. Sec 24 Unit C,D,E,F,L,M,N. Sec 25 Unit D. Sec 26 Unit A-G, I-P. Sec 27, Sec 28, Sec 29 Unit A,B,C,D,F,G,H,I,J,O,P. Sec 32 Unit A,B,G,H,I,J,N,O,P. Sec 33. Sec 34. Sec 35. Sec 36 Unit D,E,F,I-P.

T 19S – R 31E

Sec 7 Unit C,D,E,F,L. Sec 18 Unit C,D,E,F,G,K,L. Sec 31 Unit M. Sec 34 Unit P. Sec 35 Unit M,N,O. Sec 36 Unit O,P.

T 20S – R 29E

Sec 1 Unit H,I,P. Sec 13 Unit E,L,M,N. Sec 14 Unit B-P. Sec 15 Unit A,H,I,J,N,O,P. Sec 22 Unit A,B,C,F,G,H,I,J,O,P. Sec 23. Sec 24 Unit C,D,E,F,G,J-P. Sec 25 Unit A-O. Sec 26. Sec 27 Unit A,B,G,H,I,J,O,P. Sec 34 Unit A,B,G,H. Sec 35 Unit A-H. Sec 36 Unit B-G.

T 20S – R 30E

Sec 1 – Sec 4. Sec 5 Unit A,B,C,E-P. Sec 6 Unit E,G-P. Sec 7 Unit A-H,I,J,O,P. Sec 8 – 17. Sec 18 Unit A,B,G,H,I,J,O,P. Sec 19 Unit A,B,G,H,I,J,O,P. Sec 20 – 29. Sec 30 Unit A-L,N,O,P. Sec 31 Unit A,B,G,H,I,P. Sec 32 – Sec 36.

T 20S – R 31E

Sec 1 Unit A,B,C,E-P. Sec 2. Sec 3 Unit A,B,G,H,I,J,O,P. Sec 6 Unit D,E,F,J-P. Sec 7. Sec 8 Unit E-P. Sec 9 Unit E,F,J-P. Sec 10 Unit A,B,G-P. Sec 11 – Sec 36.

T 21S – R 29E

Sec 1 – Sec 3. Sec 4 Unit L1 – L16,I,J,K,O,P. Sec 5 Unit L1. Sec 10 Unit A,B,H,P. Sec 11 – Sec 14. Sec 15 Unit A,H,I. Sec 23 Unit A,B. Sec 24 Unit A,B,C,D,F,G,H,I,J,O,P. Sec 25 Unit A,O,P. Sec 35 Unit G,H,I,J,K,N,O,P. Sec 36 A,B,C,F – P.

T 21S – R 30E

Sec 1 – Sec 36

T 21S – R 31E

Sec 1 – Sec 36

T 22S – R 28E

Sec 36 Unit A,H,I,P.

T 22S – R 29E

Sec 1. Sec2. Sec 3 Unit I,J,N,O,P. Sec 9 Unit G – P. Sec 10 – Sec 16. Sec 19 Unit H,I,J. Sec 20 – Sec 28. Sec 29 Unit A,B,C,D,G,H,I,J,O,P. Sec 30 Unit A. Section 31 Unit C – P. Sec 32 – Sec 36

T 22S – R 30E

Sec 1 – Sec 36

T 22S – R 31E

Sec 1 – Sec 11. Sec 12 Unit B,C,D,E,F,L. Sec 13 Unit E,F,K,L,M,N. Sec 14 – Sec 23. Sec 24 Unit C,D,E,F,K,L,M,N. Sec 25 Unit A,B,C,D. Sec 26 Unit A,B,C,D,G,H. Sec 27 – Sec 34.

T 23S – R 28E

Sec 1 Unit A

T 23S – R 29E

Sec 1 – Sec 5. Sec 6 Unit A – I, N,O,P. Sec 7 Unit A,B,C,G,H,I,P. Sec 8 Unit A – L, N,O,P. Sec 9 – Sec 16. Sec 17 Unit A,B,G,H,I,P. Sec 21 – Sec 23. Sec 24 Unit A – N. Sec 25 Unit D,E,L. Sec 26. Sec 27. Sec 28 Unit A – J, N,O,P. Sec 33 Unit A,B,C. Sec 34 Unit A,B,C,D,F,G,H. Sec 35. Sec 36 Unit B,C,D,E,F,G,K,L.

T 23S – R 30E

Sec 1 – Sec 18. Sec 19 Unit A – I,N,O,P. Sec 20, Sec 21. Sec 22 Unit A – N, P. Sec 23, Sec 24, Sec 25. Sec 26 Unit A,B,F-P. Sec 27 Unit C,D,E,I,N,O,P. Sec 28 Unit A – H, K,L,M,N. Sec 29 Unit A – J, O,P. Sec 30 Unit A,B. Sec 32 A,B. Sec 33 Unit C,D,H,I,O,P. Sec 34, Sec 35, Sec 36.

T 23S – R 31E

Sec 2 Unit D,E,J,O. Sec 3 – Sec 7. Sec 8 Unit A – G, K – N. Sec 9 Unit A,B,C,D. Sec 10 Unit D,P. Sec 11 Unit G,H,I,J,M,N,O,P. Sec 12 Unit E,L,K,M,N. Sec 13 Unit C,D,E,F,G,J,K,L,M,N,O. Sec 14. Sec 15 Unit A,B,E – P. Sec 16 Unit I, K – P. Sec 17 Unit B,C,D,E, I – P. Sec 18 – Sec 23. Sec 24 Unit B – G, K,L,M,N. Sec 25 Unit B – G, J,K,L. Sec 26 – Sec 34. Sec 35 Unit C,D,E.

T 24S – R 29E

Sec 2 Unit A, B, C, D. Sec 3 Unit A

T 24S – R 30E

Sec 1 Unit A – H, J – N. Sec 2, Sec 3. Sec 4 Unit A,B,F – K, M,N,O,P. Sec 9 Unit A – L. Sec 10 Unit A – L, O,P. Sec 11. Sec 12 Unit D,E,L. Sec 14 Unit B – G. Sec 15 Unit A,B,G,H.

T 24S – R 31E

Sec 3 Unit B – G, J – O. Sec 4. Sec 5 Unit A – L, P. Sec 6 Unit A – L. Sec 9 Unit A – J, O,P. Sec 10 Unit B – G, K – N. Sec 35 Unit E – P. Sec 36 Unit E,K,L,M,N.

T 25S – R 31E


Sec 1 Unit C,D,E,F. Sec 2 Unit A – H.

Waldrip JY #1 30-015-22755 API

Silverback Operating II, LLC plans to plug and abandon this well as follows

- 1. MIRU workover rig. Load tbg and csg with water as needed. POOH with rods and pump. ND pumping tee. NU BOP
- 2. POOH with 2 3/8" tbg
- 3. GIH with CIBP on tbg and set at 2,785'. Spot 25 sk cement plug on CIBP. WOC. Tag cmt plug
- 4. PU and spot 25 sk cmt plug from 854'-1,223'
- 5. PU and spot 25 sk cmt plug from 0-369'
- 6. Cut off wellhead and install dry hole marker. Clean location as regulated.

Wellbore schematics attached.



•

W	aldrin	IV #1	Propo	eed _		Sec-T	WN-RNG:	34-18S-2	6E-Unit L	-		30-015-22			
	aranp		торо	JEU			ige Calls:	2310' FS	L 330' FV	VL		Elev 3358' GR			
TS					Lat/L	_ong (NAD83):								
cmt: 0-369'	Α														
					CASIN	NG DETA	IL			-		-			
					#	HOLE	CSG	WGHT	GRADE	Тор	Depth	TOC	SX		
					Α	9 1/2	7	23	K-55	9	1,133	100	600 sacks		
					в	6 1/4	4 1/2	10.5	K-55	9	3,113	circulated	275 sacks		
					С										
					FORM	IATION T	OPS								
						FORMA		TOP (FT)	F	ORMATIC	ON		TOP		
					San A	ndres		1,039							
	в				Yeso			2,612							
					TUDE										
							GRADE	WCHT	TOP	DACE	1				
						DD 2/0	GRADE	WGHT	TOP	BASE	-				
		+	~		2	3/8				3,005.8	-				
	1	-		_				1			4				
35'-3,089' (w/24 .50	50' 0" holes)	WW		MM											
89' (w/24 .5(I	WW			PERF	ORATIO	N DETAIL		TOP	DASE			DEATMENT		
	I	WW				ORATIO	FORMATIC	DN	ТОР	BASE	Treated w		REATMENT pated water. 95	5,000# sand	
4 .50	I	W		MM	PERF	ORATIO		DN	TOP 2,835	BASE 3,089		/91,000 gal tre	REATMENT eated water, 95 20,000 100 mea		
.50	I					ORATIO	FORMATIC	DN				/91,000 gal tre	eated water, 95		
4 .50	I				A B	ORATIO	FORMATIC	DN				/91,000 gal tre	eated water, 95		
50	I	WW			A B C	ORATIO	FORMATIC	DN				/91,000 gal tre	eated water, 95		
50	I	WW			A B C D	ORATIO	FORMATIC	DN				/91,000 gal tre	eated water, 95		
	I	WW			A B C	ORATIO	FORMATIC	DN				/91,000 gal tre	eated water, 95		
24 .5	I	WW			A B C D	ORATIO	FORMATIC	DN				/91,000 gal tre	eated water, 95		
	I	WW			A B C D		FORMATIC	DN				/91,000 gal tre	eated water, 95		
	·	WW			A B C D E PLUG	S	FORMATIC		2,835	3,089		/91,000 gal tre	eated water, 95	sh w/ball sea	
)" I	I	WW			A B C D E PLUG #	S Sx	FORMATIC Yeso Class	Тор	2,835	3,089	75,000# 2	//91,000 gal tre 0-40 sand, & 2	eated water, 95	sh w/ball sea	
ו "ס	I	WW			A B C D E PLUG #	s sx 25	FORMATIC Yeso Class C	Top 2,416	2,835	3,089	75,000# 20	//91,000 gal tre 0-40 sand, & 2 Notes t plug to cover	eated water, 95 20,000 100 me: 	sh w/ball sea	
	,	WW			A B C D E PLUG # 1 2	s sx 25 25	FORMATIC Yeso Class C C	Top 2,416 854	2,835	3,089	75,000# 20	//91,000 gal tre 0-40 sand, & 2 Notes It plug to cover across surface :	eated water, 95 20,000 100 me: 	sh w/ball sea	
)''	I	WW			A B C D E PLUG # 1 2 3	s sx 25	FORMATIC Yeso Class C	Top 2,416	2,835	3,089	75,000# 20	//91,000 gal tre 0-40 sand, & 2 Notes It plug to cover across surface :	eated water, 95 20,000 100 me: 	sh w/ball sea	
	I	WW			A B C D E PLUG # 1 2 3 4	s sx 25 25	FORMATIC Yeso Class C C	Top 2,416 854	2,835	3,089	75,000# 20	//91,000 gal tre 0-40 sand, & 2 Notes It plug to cover across surface :	eated water, 95 20,000 100 me: 	sh w/ball sea	
1.50	I	WW			A B C D E PLUG # 1 2 3 4 5	s sx 25 25	FORMATIC Yeso Class C C	Top 2,416 854	2,835	3,089	75,000# 20	//91,000 gal tre 0-40 sand, & 2 Notes It plug to cover across surface :	eated water, 95 20,000 100 me: 	sh w/ball sea	
)" holes)				A B C D E PLUG # 1 2 3 4 5 6	s sx 25 25	FORMATIC Yeso Class C C	Top 2,416 854	2,835	3,089	75,000# 20	//91,000 gal tre 0-40 sand, & 2 Notes It plug to cover across surface :	eated water, 95 20,000 100 me: 	sh w/ball sea	
50	I				A B C D E PLUG # 1 2 3 4 5	s sx 25 25	FORMATIC Yeso Class C C	Top 2,416 854	2,835	3,089	75,000# 20	//91,000 gal tre 0-40 sand, & 2 Notes It plug to cover across surface :	eated water, 95 20,000 100 me: 	sh w/ball sea	
	" holes)	~			A B C D E PLUG # 1 2 3 4 5 6	s sx 25 25	FORMATIC Yeso Class C C	Top 2,416 854	2,835	3,089	75,000# 20	//91,000 gal tre 0-40 sand, & 2 Notes It plug to cover across surface :	eated water, 95 20,000 100 me: 	sh w/ball sea	
)" holes)	3,1			A B C D E PLUG # 1 2 3 4 5 6	s sx 25 25	FORMATIC Yeso Class C C	Top 2,416 854	2,835	3,089	75,000# 20	//91,000 gal tre 0-40 sand, & 2 Notes It plug to cover across surface :	eated water, 95 20,000 100 me: 	sh w/ball sea	

District I 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV 1220 S. St Francis Dr., Santa Fe, NM 87505 Phone: (505) 476-3470 Fax: (505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Operator:	OGRID:
Silverback Operating II, LLC	330968
19707 IH10 West, Suite 201	Action Number:
San Antonio, TX 78256	201671
	Action Type:
	[C-103] NOI Plug & Abandon (C-103F)

CONDITIONS

Created By	Condition	Condition Date
john.harrison	Perf & Sqz all csg shoes	4/13/2023

Page 9 of 9