

cceined by Opp Po Applephase Billion 8.	AM State of New Mexico	Form C-103 ¹ of 5
<u>District I</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resources	Revised July 18, 2013 WELL API NO.
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION	30-015-20325 5. Indicate Type of Lease
<u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.	STATE FEE
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 87505	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
SUNDRY NOT (DO NOT USE THIS FORM FOR PROPO	ICES AND REPORTS ON WELLS SALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A CATION FOR PERMIT" (FORM C-101) FOR SUCH	7. Lease Name or Unit Agreement Name CITY OF CARLSBAD
PROPOSALS.) 1. Type of Well: Oil Well ☐ Gas Well ✓ Other		8. Well Number #001
2. Name of Operator OXY USA INC.		9. OGRID Number 16696
3. Address of Operator	TV 77040	10. Pool name or Wildcat
PO BOX 4294, HOUSTON 4. Well Location	, IX 77210	[74120] CARLSBAD;STRAWN, SOUTH (GAS)
01111 201101	feet from the SOUTH line and 19	
Section 25	Township 22S Range 26E	NMPM County EDDY
	11. Elevation (Show whether DR, RKB, RT, GR, etc	.)
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or compof starting any proposed we proposed completion or recomposed COMPONS COMPONS CONTROL OF THE	PLUG AND ABANDON	AILLING OPNS. P AND A TIT JOB P AND A PAND A
Spud Date:	Rig Release Date:	
I hereby certify that the information	above is true and complete to the best of my knowledge	ge and beliet.
SIGNATURE <u>STEPHEN JAN</u>	ACEK TITLE REGULATORY ENGIN	IEERDATE
Type or print name STEPHEN JA For State Use Only	NACEK E-mail address: STEPHEN_JANA	CEK@OXY.COM PHONE: 713-493-1986
APPROVED BY: Conditions of Approval (if any):	TITLE Petroleum Speciali	stDATE 7/5/2023





TA Job Procedure

CITY OF CARLSBAD #001 30-015-20325 7/5/23

Note

Oxy is currently rigged up on the subject well and have decided to TA the wellbore.

Procedure

- 1. MIRU.
- 2. Pull tubing and packer out of the hole.
- 3. Set CIBP at 10320'. Leak test CIBP.
- 4. Dump bail 35 ft cement. WOC. Tag.
- 5. Circulate packer fluid.
- 6. Perform MIT at 500 psi for 30 minutes and BHT. Send MIT chart and BHT form to Oxy regulatory.
- 7. RDMO.

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone: (575) 748-1283 Fax: (575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 235863

CONDITIONS

Operator:	OGRID:
OXY USA INC	16696
P.O. Box 4294	Action Number:
Houston, TX 772104294	235863
	Action Type:
	[C-103] NOI Temporary Abandonment (C-103I)

CONDITIONS

Created By		Condition Date
john.harrison	None - Please provide MIT with Subsequent TA to receive approval length.	7/5/2023