D'		92:23 PM Ener	State of gy, Minerals							orm C-103 ¹ July 18, 2013
<u>District I</u> – (57 1625 N. Frenc District II – (5	ch Dr., Hobbs, NM 882	240					WELL AI 30-025-20		1001000	<i>vary</i> 10, 2010
,	t., Artesia, NM 88210	OII	L CONSER					e Type of I	ease	
	(505) 334-6178 zos Rd., Aztec, NM 874	410	1220 Sout			Dr.		ATE	FEE	Private
District IV – ((505) 476-3460 ancis Dr., Santa Fe, NM		Santa F	Fe, NM	[87505		6. State C	Dil & Gas L	ease No.	
	SUNDRY E THIS FORM FOR P	NOTICES AND					7. Lease	Name or U	nit Agreen	nent Name
	RESERVOIR. USE "A						Jal Matt	Yates L	Jnit	
1. Type of	Well: Oil Well	Gas Well	Other	njectio	า			^{lumber} 25		
2. Name of Driftwood C							9. OGRII 213843	O Number		
	of Operator						10. Pool	name or W	ildcat	
	1224 Jal New	Mexico 882	52				jalmat,tan	-yates,7rv	rs 33820/)
4. Well Lo Ur	nit Letter F	. 2500	_feet from the	FNL		line and 1	500	feet from t	_{he} FWL	line
	ection 18	•			Range	R37E	NMPM		County	Lea
		11. Elev	ation (Show w	hether 3125	DR, RKB	, RT, GR, etc	c.)			
				0120						
TEMPORAL PULL OR A DOWNHOL CLOSED-L OTHER:	REMEDIAL WOR RILY ABANDON ALTER CASING LE COMMINGLE OOP SYSTEM Clean c	CHANG MULTIP	ND ABANDOI E PLANS LE COMPL		CO	MEDIAL WO	RILLING OPN	🗌 AL		: Casing [] []
12 Dec	ariba proposed or	completed oner	tions (Close	lu stata			nd give nortir	ant datas	including	
of s proj Drift Pacl the v Pacl	scribe proposed or starting any proposed posed completion of twood Oil LLC, Rec ker. Pull the tubing well to PBTD. Eval ker, run in the hole a with packer fluid.	or recompletion. quest to pull the and packer. rig luate the well for and reset the pa	RULE 19.15. ² Jalmat #25 W up the Revers possible Acid acker as close	7.14 NN IW well se unit a job. Pe to perf	all pertine IAC. Fo and clean Ind pick u rform nec orations a	ent details, a r Multiple C n out the per p drill collars sessary work as can be se	ompletions: forations.our and or stimu pull and layo t -100' above	Attach well plan is to m lation tool v down all dril existing pe	lbore diagr nove in a W which is ne Il equipmen rforations a	estimated date am of /SU unset the eed first clean nt. pick up redu at 2856'.fill ann
of s proj Drift Pacl the v Pacl	starting any proposed completion twood Oil LLC, Rec ker. Pull the tubing well to PBTD. Eval ker, run in the hole	ed work). SEE or recompletion. quest to pull the and packer. rig luate the well for and reset the pa	RULE 19.15. ² Jalmat #25 W up the Revers possible Acid acker as close	7.14 NN IW well se unit a job. Pe to perf	all pertine IAC. Fo and clean Ind pick u rform nec orations a	ent details, a r Multiple C n out the per p drill collars æssary work as can be se t.Work will b	ompletions: A forations.our (and or stimu pull and layor t -100' above egin as soon	Attach well olan is to m lation tool v down all drii existing per as the wells proval: n fice 24 ho	Ibore diagr nove in a W which is ne Il equipment rforations a s are appro otify	estimated date am of /SU unset the eed first clean nt. pick up redu at 2856'.fill ann
of s proj Drift Pacl the v Pacl	starting any proposed completion twood Oil LLC, Rec ker. Pull the tubing well to PBTD. Eval ker, run in the hole	ed work). SEE or recompletion. quest to pull the and packer. rig luate the well for and reset the pa	RULE 19.15.7 Jalmat #25 W up the Revers possible Acid acker as close call the OCD	7.14 NN IW well se unit a job. Pe to perf	all pertind IAC. Fo and clean ind pick u rform neo orations a Chart tes	ent details, a r Multiple C n out the per p drill collars æssary work as can be se t.Work will b	ompletions: A forations.our and or stimu pull and layor t -100' above egin as soon	Attach well olan is to m lation tool v down all drii existing per as the wells proval: n fice 24 ho	Ibore diagr nove in a W which is ne Il equipment rforations a s are appro otify	estimated date am of /SU unset the eed first clean nt. pick up redu at 2856'.fill ann
of s proj Drift Pacl the v Pacl area	starting any propos posed completion of twood Oil LLC, Rec ker. Pull the tubing well to PBTD. Eval ker, run in the hole a with packer fluid.	ed work). SEE or recompletion. quest to pull the and packer. rig luate the well for e and reset the pa pre test packer.	RULE 19.15.7 Jalmat #25 W up the Revers possible Acid acker as close call the OCD	7.14 NN IW well se unit a job. Pe to perf for MIT	all pertind IAC. Fo and clean ind pick u rform nec orations a Chart tes	ent details, a r Multiple C n out the per p drill collars cessary work as can be se t.Work will b Con Q	ompletions: A forations.our and or stimu pull and layor t -100' above egin as soon dition of Ap CD Hobbs of of running N	Attach well plan is to m lation tool v down all dri existing per as the wells oproval: Bo ffice 24 ho AIT Test 4	Ibore diagr nove in a W which is ne Il equipment rforations a s are appro otify	estimated date am of /SU unset the eed first clean nt. pick up redu at 2856'.fill ann
of s proj Drift Pacl area Spud Date: I hereby cert	starting any proposes posed completion of twood Oil LLC, Red ker. Pull the tubing well to PBTD. Eval ker, run in the hole a with packer fluid.	ed work). SEE or recompletion. quest to pull the and packer. rig luate the well for e and reset the pa pre test packer.	RULE 19.15.7 Jalmat #25 W up the Revers possible Acid acker as close call the OCD Rig ue and comple	7.14 NN IW well se unit a job. Pe to perf for MIT	all pertinu IAC. Fo and clean ind pick u rform nec orations a Chart tes	ent details, a r Multiple C n out the per p drill collars cessary work as can be se t.Work will b Con Q	ompletions: A forations.our and or stimu pull and layor t-100' above egin as soon dition of Ap CD Hobbs of of running N	Attach well plan is to m lation tool v down all drii existing per as the wells proval: B fice 24 ho AIT Test 4	Ibore diagr nove in a W which is ne Il equipment rforations a s are appro otify	estimated date am of /SU unset the ed first clean nt. pick up redu at 2856'.fill ann oved by OCD.
of s proj Drift Pacl the v Pacl area Spud Date: I hereby cert	tarting any proposed completion of twood Oil LLC, Recker. Pull the tubing well to PBTD. Eval ker, run in the hole a with packer fluid.	and work). SEE or recompletion. quest to pull the part of the well for e and reset the well for performing the test packer.	RULE 19.15.7 Jalmat #25 W up the Revers possible Acid acker as close call the OCD Rig ue and comple	7.14 NN IW well se unit a job. Pe to perf for MIT Release ete to th TLE Pro	all pertinu IAC. Fo and clean ind pick u rform nec orations a Chart tes Date: e best of	ent details, a r Multiple C n out the per p drill collars cessary work as can be se t.Work will b Con OC prior of my knowled	ompletions: A forations.our and or stimu pull and layor t-100' above egin as soon dition of Ap CD Hobbs of of running N	Attach well olan is to m lation tool v down all dri existing per as the wells oproval: no flice 24 bo AIT Test 4	Ibore diagr nove in a W which is ne Il equipmen rforations a s are appro	estimated date am of /SU unset the ed first clean nt. pick up redu at 2856'.fill ann oved by OCD.

Released to Imaging: 9/18/2023 2:39:37 PM


Office	6 <i>Appropriate</i> District 2		State of New					orm C-103 ²
<u>District I</u> – (575)) 393-6161 Dr., Hobbs, NM 88240	Energy,	Minerals and	l Natural I	Resources	WELL A	API NO.	July 18, 2013
District II – (575	5) 748-1283 Artesia, NM 88210	OIL C	ONSERVA	TION DI	VISION	30-025-2		
District III - (50	5) 334-6178	12	20 South St	. Francis	Dr.		te Type of Lease ΓΑΤΕ ☐ FEE	
1000 Rio Brazos District IV – (50)	Rd., Aztec, NM 87410		Santa Fe, N				FATE FEE Oil & Gas Lease No.	Private
1220 S. St. Franc	cis Dr., Santa Fe, NM					0. State	on & Gas Lease 110.	
87505	SUNDRY NO	TICES AND RE	PORTS ON W	ELLS		7. Lease	Name or Unit Agreen	nent Name
	THIS FORM FOR PROP ESERVOIR. USE "APPL	OSALS TO DRILL	OR TO DEEPEN	OR PLUG B			-	
PROPOSALS.)		_				-	tt Yates Unit	
	Vell: Oil Well	Gas Well 🔽	Other Inject	tion			Number 25	
2. Name of C Driftwood Oil						213843	ID Number	
3. Address of	f Operator					10. Pool	name or Wildcat	
	224 Jal New Me	exico 88252				jalmat,ta	n-yates,7rvrs 33820)
4. Well Loca		. 2500 fee	FN	1		1500	EWI	
	Letter <mark>F</mark> ion 18	·icc	t from the $\frac{FN}{T25}$		line and R37E	NMPM	_feet from the <u>FWL</u>	line
Secti	1011 10		wnship T25 n <i>(Show wheth</i>	S Range			County	Lea
			31.	25 GR	<i>D</i> , <i>R</i> 1, <i>OR</i> , 0)		
	12. Check	Appropriate l	Box to Indic	ate Natur	e of Notic	ce, Report of	r Other Data	
	NOTICE OF I			1	CI			
PERFORM R		_			SU MEDIAL W		NT REPORT OF	
PULL OR AL		_			SING/CEM			
				_			—	
CLOSED-LOO		כ						
OTHER:	Clean out ir	njection well		-	HER:			
10 D								
	ibe proposed or com							
of star	rting any proposed v	vork). SEE RUL					inent dates, including e Attach wellbore diagr	
of star propo Driftwo	rting any proposed v osed completion or re ood Oil LLC. Reques	work). SEE RUL ecompletion. st to pull the Jalm	LE 19.15.7.14	NMAC. F	or Multiple	Completions: erforations.our	Attach wellbore diagr	am of /SU_unset the
of star propo Driftwo Packe	rting any proposed v osed completion or re ood Oil LLC, Reques er. Pull the tubing and	work). SEE RUL ecompletion. at to pull the Jalm d packer. rig up t	LE 19.15.7.14] nat #25 WIW w he Reverse un	NMAC. F rell and cleatit and pick	or Multiple an out the pe up drill colla	Completions: erforations.our irs and or stime	Attach wellbore diagr plan is to move in a W ulation tool which is ne	am of /SU_unset the ed first clean
of star propo Driftwo Packe the we Packe	rting any proposed v osed completion or re ood Oil LLC, Reques er. Pull the tubing and ell to PBTD. Evaluate er, run in the hole and	vork). SEE RUL ecompletion. st to pull the Jalm d packer. rig up t e the well for pos d reset the packet	LE 19.15.7.14 mat #25 WIW w he Reverse un sible Acid job. er as close to p	NMAC. F rell and clea it and pick Perform ne erforations	or Multiple an out the pe up drill colla ecessary wo as can be s	Completions: erforations.our irs and or stim rk. pull and lay et -100' above	Attach wellbore diagr plan is to move in a W ulation tool which is ne down all drill equipme existing perforations a	am of /SU unset the ed first clean nt. pick up redro at 2856'.fill annu
of star propo Driftwo Packe the we Packe	rting any proposed v osed completion or re ood Oil LLC, Reques er. Pull the tubing and ell to PBTD. Evaluate er, run in the hole and	vork). SEE RUL ecompletion. st to pull the Jalm d packer. rig up t e the well for pos d reset the packet	LE 19.15.7.14 mat #25 WIW w he Reverse un sible Acid job. er as close to p	NMAC. F rell and clea it and pick Perform ne erforations	or Multiple an out the pe up drill colla ecessary wo as can be s	Completions: erforations.our irs and or stim rk. pull and lay et -100' above	Attach wellbore diagr plan is to move in a W ulation tool which is ne down all drill equipme	am of /SU unset the ed first clean nt. pick up redro at 2856'.fill annu
of star propo Driftwo Packe the we Packe	rting any proposed v osed completion or re ood Oil LLC, Reques er. Pull the tubing and ell to PBTD. Evaluate er, run in the hole and	vork). SEE RUL ecompletion. st to pull the Jalm d packer. rig up t e the well for pos d reset the packet	LE 19.15.7.14 mat #25 WIW w he Reverse un sible Acid job. er as close to p	NMAC. F rell and clea it and pick Perform ne erforations	or Multiple an out the pe up drill colla ecessary wo as can be s	Completions: erforations.our irs and or stim rk. pull and lay et -100' above	Attach wellbore diagr plan is to move in a W ulation tool which is ne down all drill equipme existing perforations a	am of /SU unset the ed first clean nt. pick up redro at 2856'.fill annu
of star propo Driftwo Packe the we Packe	rting any proposed v osed completion or re ood Oil LLC, Reques er. Pull the tubing and ell to PBTD. Evaluate er, run in the hole and	vork). SEE RUL ecompletion. st to pull the Jalm d packer. rig up t e the well for pos d reset the packet	LE 19.15.7.14 mat #25 WIW w he Reverse un sible Acid job. er as close to p	NMAC. F rell and clea it and pick Perform ne erforations	or Multiple an out the pe up drill colla ecessary wo as can be s	Completions: erforations.our irs and or stim rk. pull and lay et -100' above	Attach wellbore diagr plan is to move in a W ulation tool which is ne down all drill equipme existing perforations a	am of /SU unset the ed first clean nt. pick up redro at 2856'.fill annu
of star propo Driftwo Packe the we Packe	rting any proposed v osed completion or re ood Oil LLC, Reques er. Pull the tubing and ell to PBTD. Evaluate er, run in the hole and	vork). SEE RUL ecompletion. st to pull the Jalm d packer. rig up t e the well for pos d reset the packet	LE 19.15.7.14 mat #25 WIW w he Reverse un sible Acid job. er as close to p	NMAC. F rell and clea it and pick Perform ne erforations	or Multiple an out the pe up drill colla ecessary wo as can be s	Completions: erforations.our irs and or stim rk. pull and lay et -100' above	Attach wellbore diagr plan is to move in a W ulation tool which is ne down all drill equipme existing perforations a	am of /SU unset the ed first clean nt. pick up redre at 2856'.fill annu
of star propo Driftwo Packe the we Packe	rting any proposed v osed completion or re ood Oil LLC, Reques er. Pull the tubing and ell to PBTD. Evaluate er, run in the hole and	vork). SEE RUL ecompletion. st to pull the Jalm d packer. rig up t e the well for pos d reset the packet	LE 19.15.7.14 mat #25 WIW w he Reverse un sible Acid job. er as close to p	NMAC. F rell and clea it and pick Perform ne erforations	or Multiple an out the pe up drill colla ecessary wo as can be s	Completions: erforations.our irs and or stim rk. pull and lay et -100' above	Attach wellbore diagr plan is to move in a W ulation tool which is ne down all drill equipme existing perforations a	am of /SU unset the ed first clean nt. pick up redre at 2856'.fill annu
of star propo Driftwo Packe the we Packe	rting any proposed v osed completion or re ood Oil LLC, Reques er. Pull the tubing and ell to PBTD. Evaluate er, run in the hole and	vork). SEE RUL ecompletion. st to pull the Jalm d packer. rig up t e the well for pos d reset the packet	LE 19.15.7.14 mat #25 WIW w he Reverse un sible Acid job. er as close to p	NMAC. F rell and clea it and pick Perform ne erforations	or Multiple an out the pe up drill colla ecessary wo as can be s	Completions: erforations.our irs and or stim rk. pull and lay et -100' above	Attach wellbore diagr plan is to move in a W ulation tool which is ne down all drill equipme existing perforations a	am of /SU unset the ed first clean nt. pick up redru at 2856'.fill anni
of star propo Driftwo Packe the we Packe	rting any proposed v osed completion or re ood Oil LLC, Reques er. Pull the tubing and ell to PBTD. Evaluate er, run in the hole and	vork). SEE RUL ecompletion. st to pull the Jalm d packer. rig up t e the well for pos d reset the packet	LE 19.15.7.14 mat #25 WIW w he Reverse un sible Acid job. er as close to p	NMAC. F rell and clea it and pick Perform ne erforations	or Multiple an out the pe up drill colla ecessary wo as can be s	Completions: erforations.our irs and or stim rk. pull and lay et -100' above	Attach wellbore diagr plan is to move in a W ulation tool which is ne down all drill equipme existing perforations a	am of /SU unset the ed first clean nt. pick up redr at 2856'.fill ann
of star propo Driftwo Packe the we Packe	rting any proposed v osed completion or re ood Oil LLC, Reques er. Pull the tubing and ell to PBTD. Evaluate er, run in the hole and	vork). SEE RUL ecompletion. st to pull the Jalm d packer. rig up t e the well for pos d reset the packet	LE 19.15.7.14 mat #25 WIW w he Reverse un sible Acid job. er as close to p	NMAC. F rell and clea it and pick Perform ne erforations	or Multiple an out the pe up drill colla ecessary wo as can be s	Completions: erforations.our irs and or stim rk. pull and lay et -100' above	Attach wellbore diagr plan is to move in a W ulation tool which is ne down all drill equipme existing perforations a	am of /SU unset the ed first clean nt. pick up redru at 2856'.fill anni
of star propo Driftwo Packe the we Packe area w	rting any proposed v osed completion or re ood Oil LLC, Reques er. Pull the tubing and ell to PBTD. Evaluate er, run in the hole and vith packer fluid. pre	vork). SEE RUL ecompletion. st to pull the Jalm d packer. rig up t e the well for pos d reset the packet	LE 19.15.7.14] nat #25 WIW w he Reverse un sible Acid job. r as close to p the OCD for M	NMAC. F rell and clea it and pick Perform ne erforations IT Chart te	or Multiple an out the pe up drill colla ecessary wo as can be s	Completions: erforations.our irs and or stim rk. pull and lay et -100' above	Attach wellbore diagr plan is to move in a W ulation tool which is ne down all drill equipme existing perforations a	am of /SU unset the ed first clean nt. pick up redre at 2856'.fill annu
of star propo Driftwo Packe the we Packe area w	rting any proposed v osed completion or re ood Oil LLC, Reques er. Pull the tubing and ell to PBTD. Evaluate er, run in the hole and	vork). SEE RUL ecompletion. st to pull the Jalm d packer. rig up t e the well for pos d reset the packet	LE 19.15.7.14] nat #25 WIW w he Reverse un sible Acid job. r as close to p the OCD for M	NMAC. F rell and clea it and pick Perform ne erforations	or Multiple an out the pe up drill colla ecessary wo as can be s	Completions: erforations.our irs and or stim rk. pull and lay et -100' above	Attach wellbore diagr plan is to move in a W ulation tool which is ne down all drill equipme existing perforations a	am of /SU unset the ed first clean nt. pick up redre at 2856'.fill annu
of star propo Driftwo Packe the we Packe area w	rting any proposed v osed completion or re ood Oil LLC, Reques er. Pull the tubing and ell to PBTD. Evaluate er, run in the hole and vith packer fluid. pre	vork). SEE RUL ecompletion. st to pull the Jalm d packer. rig up t e the well for pos d reset the packet	LE 19.15.7.14] nat #25 WIW w he Reverse un sible Acid job. r as close to p the OCD for M	NMAC. F rell and clea it and pick Perform ne erforations IT Chart te	or Multiple an out the pe up drill colla ecessary wo as can be s	Completions: erforations.our irs and or stim rk. pull and lay et -100' above	Attach wellbore diagr plan is to move in a W ulation tool which is ne down all drill equipme existing perforations a	am of /SU unset the ed first clean nt. pick up redro at 2856'.fill annu
of star propo Driftwo Packe the we Packe area w	rting any proposed v osed completion or re ood Oil LLC, Reques er. Pull the tubing and ell to PBTD. Evaluate r, run in the hole and vith packer fluid. pre	work). SEE RUI ecompletion. st to pull the Jalm d packer. rig up t e the well for pos d reset the packet test packer. call	LE 19.15.7.14] hat #25 WIW w he Reverse un sible Acid job. er as close to p the OCD for M	NMAC. F rell and clea it and pick Perform ne erforations IT Chart te ase Date:	or Multiple an out the pe up drill colla eccessary wo as can be s st.Work will	Completions: erforations.our irs and or stim rk. pull and lay et -100' above begin as soon	Attach wellbore diagr plan is to move in a W ulation tool which is ne down all drill equipme existing perforations a a as the wells are appro	am of /SU unset the ed first clean nt. pick up redre at 2856'.fill annu
of star propo Driftwo Packe the we Packe area w	rting any proposed v osed completion or re ood Oil LLC, Reques er. Pull the tubing and ell to PBTD. Evaluate er, run in the hole and vith packer fluid. pre	work). SEE RUI ecompletion. st to pull the Jalm d packer. rig up t e the well for pos d reset the packet test packer. call	LE 19.15.7.14] hat #25 WIW w he Reverse un sible Acid job. er as close to p the OCD for M	NMAC. F rell and clea it and pick Perform ne erforations IT Chart te ase Date:	or Multiple an out the pe up drill colla eccessary wo as can be s st.Work will	Completions: erforations.our irs and or stim rk. pull and lay et -100' above begin as soon	Attach wellbore diagr plan is to move in a W ulation tool which is ne down all drill equipme existing perforations a a as the wells are appro	am of /SU unset the ed first clean nt. pick up redro at 2856'.fill annu
of star propo Driftwo Packe the we Packe area w	rting any proposed v psed completion or re- pood Oil LLC, Requese er. Pull the tubing and ell to PBTD. Evaluate r, run in the hole and vith packer fluid. pre- 10/06/1979 y that the information	work). SEE RUI ecompletion. st to pull the Jalm d packer. rig up t e the well for pos d reset the packet test packer. call	LE 19.15.7.14] nat #25 WIW w he Reverse un sible Acid job. er as close to p the OCD for M Rig Rele	NMAC. F rell and clea it and pick Perform ne erforations IT Chart te ase Date:	or Multiple	Completions: erforations.our irs and or stim rk. pull and lay et -100' above begin as soon	Attach wellbore diagr plan is to move in a W ulation tool which is ne down all drill equipme existing perforations a a as the wells are appro	am of /SU unset the ed first clean nt. pick up redra at 2856'.fill annu oved by OCD.
of star propo Driftwo Packe the we Packe area w Spud Date:	rting any proposed v psed completion or re- pood Oil LLC, Requese per Pull the tubing and per Pull the TD. Evaluate r, run in the hole and vith packer fluid. pre- 10/06/1979 y that the information michael	n above is true a	LE 19.15.7.14] nat #25 WIW w he Reverse un sible Acid job. r as close to p the OCD for M Rig Rele nd complete to 	NMAC. F rell and clea it and pick Perform ne erforations IT Chart te ase Date:	or Multiple an out the pe up drill colla ecessary wo as can be s st.Work will f my knowle	Completions: erforations.our irs and or stim rk. pull and lay et -100' above begin as soon	Attach wellbore diagr plan is to move in a W ulation tool which is ne down all drill equipme existing perforations a a as the wells are appro-	am of /SU unset the ed first clean nt. pick up redra at 2856'.fill anni oved by OCD.
of star propo Driftwo Packe the we Packe area w Spud Date:	rting any proposed v psed completion or re- pool Oil LLC, Requese per Pull the tubing and ell to PBTD. Evaluate r, run in the hole and with packer fluid. pre- 10/06/1979 y that the information michael der hame Michael Der	n above is true a	LE 19.15.7.14] nat #25 WIW w he Reverse un sible Acid job. r as close to p the OCD for M Rig Rele nd complete to 	NMAC. F rell and clea it and pick Perform ne erforations IT Chart te ase Date:	or Multiple an out the pe up drill colla ecessary wo as can be s st.Work will f my knowle	Completions: erforations.our irs and or stim rk. pull and lay et -100' above begin as soon	Attach wellbore diagr plan is to move in a W ulation tool which is ne down all drill equipme existing perforations a a as the wells are appro	am of /SU unset the ed first clean nt. pick up redra at 2856'.fill anni oved by OCD.
of star propo Driftwo Packe the we Packe area w Spud Date: hereby certify SIGNATURE_ Type or print n For State Use	rting any proposed v psed completion or re- pool Oil LLC, Requese per Pull the tubing and ell to PBTD. Evaluate r, run in the hole and with packer fluid. pre- 10/06/1979 y that the information michael der hame Michael Der	nnis	LE 19.15.7.14] nat #25 WIW w he Reverse un sible Acid job. r as close to p the OCD for M Rig Rele nd complete to 	NMAC. F rell and clea it and pick Perform ne erforations IT Chart te ase Date: the best of Production address: <u>n</u>	or Multiple an out the pe up drill colla ecessary wo as can be s st.Work will f my knowle	Completions: erforations.our irs and or stim rk. pull and lay et -100' above begin as soon	Attach wellbore diagr plan is to move in a W ulation tool which is ne down all drill equipme existing perforations a a as the wells are appro-	am of /SU unset the ed first clean nt. pick up redra at 2856'.fill anni oved by OCD. 23 23 395-9970

•

To Whom these concerns,

Driftwood oil 213843 Just bought these from EXTEX oil Co and there isn't any current well bore diagrams available in the well file. Driftwood OIL hasn't pulled these wells since the purchase of the wells so, we will build a well bore diagram after the well has been cleaned out and an accurate update can be obtained. Thanks Mike Dennis

Received by OCD: 7/31/2023 4:02:23 PM



C:\Users\mdenn\Desktop\Driftwood Oil LLC WBD Jalmat 25 WIW Wellbore Diagram

District I 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV 1220 S. St Francis Dr., Santa Fe, NM 87505 Phone: (505) 476-3470 Fax: (505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

843
: 307
03] NOI Workover (C-103G)
5

CONDITIONS

Created By		Condition Date
kfortner	Run PWOT MIT/BHT	9/18/2023

Released to Imaging: 9/18/2023 2:39:37 PM

Page 5 of 5

.

Action 246307