Office State of New Mexico	Form C-103 <sup>1</sup>
<u>District I</u> – (575) 393-6161 Energy, Minerals and Natural Resout 1625 N. French Dr., Hobbs, NM 88240	WELL API NO.
District II - (575) 748-1283 811 S. First St., Artesia, NM 88210 OIL CONSERVATION DIVISION	ON 30-045-34144
District III – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410 1220 South St. Francis Dr.	5. Indicate Type of Lease STATE FEE
District IV – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 87505	State Oil & Gas Lease No. E-3707-5
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	7. Lease Name or Unit Agreement Name NEBU
PROPOSALS.)	8. Well Number 346
<ol> <li>Type of Well: Oil Well ☐ Gas Well ☑ Other</li> <li>Name of Operator SIMCOE LLC</li> </ol>	9. OGRID Number 6137
2 SINICOE ELC	0137
3. Address of Operator 1199 Main Ave, Durango, CO 81301	10. Pool name or Wildcat Basin Dakota
4Well Location Unit Letter P : 1240 feet from the South line and	
Section 36 Township 31N Range 8W	NMPM San Juan County
11. Elevation (Show whether DR, RKB, RT, 6414' GR	GR, etc.)
12. Check Appropriate Box to Indicate Nature of	Notice, Report or Other Data
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WORK ☐ ALTERING CASIN	
	NCE DRILLING OPNS.☐ P AND A ☐ /CEMENT JOB ☐
DOWNHOLE COMMINGLE	, octivities -
CLOSED-LOOP SYSTEM OTHER: OTHER:	П
<ol> <li>Describe proposed or completed operations. (Clearly state all pertinent d of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Mu proposed completion or recompletion.</li> </ol>	
MIRU service unit. Pull rodstring/pump/tubing if present in well. RIH cast iron brid blocide and corrosion inhibitor. Pressure test casing to 500 psi for 30 min. Pressure period. Open casing valves to check for flow or pressure change. Test shall be recorrolled and 1000 pound spring, calibrated within six months prior to MIT of casing. It details and plug set depth. Air gap and blind flange production flow lines. After a purbandoment has been completed, a workover rig will remove the cast iron bridge playeek period to determine if the well will return to a production status. If the decision and abandonment will be submitted. If the decision is made to produce the well, all for a flow ready status up to and including any removed flowmeters and well ties. So	e shall not decrease more than 50 psi over the 30 min reded using a chart recorder with a maximum two hour Submit chart, C-103, and wellbore diagram showing well eriod not to exceed 5 years after the temporary tug and monitor pressure buildup of the well for a two on is made to not produce the well, a request for plugging necessary flow and production lines will be reinstalled
Spud Date: Rig Release Date:	
hereby certify that the information above is true and complete to the best of my k	cnowledge and belief.
SIGNATURE Christy Kost TITLE Regulatory A	AnalystDATE 10/30/2023
	y.kost@ikavenergy.com PHONE: 970-822-8931
APPROVED BY: Monica Kushling TITLE Deputy Oil and Gs	DATE 11/3/2023
Conditions of Approval (if any):	

## **Procedure - Temporary Abandonment**

NEBU #346 (P) Sec 36, T31N, R8W San Juan County 30-045-34144

MIRU service unit.

Pull rodstring/pump/tubing if present in well.

RIH cast iron bridge plug and set at 7900'

Top off casing with 2% KCl w/biocide and corrosion inhibitor

Pressure test casing to 500 psi for 30 min. Pressure shall not decrease more than 50 psi over the 30 min period

Open casing valves to check for flow or pressure change.

Test shall be recorded using a chart recorder with a maximum two hour clock and 1000 pound spring, calibrated within six months prior to MIT of casing


Submit chart, C-103, and wellbore diagram showing well details and plug set depth.

Air gap and blind flange production flow lines.


After a period not to exceed 5 years after the temporary abandoment has been completed, a workover rig will remove the cast iron bridge plug and monitor pressure buildup of the well for a two week period to determine if the well will return to a production status. If the decision is made to not produce the well, a request for plugging and abandonment will be submitted.

If the decision is made to produce the well, all necessary flow and production lines will be reinstalled for a flow ready status up to and including any removed flowmeters and well ties. Surface facilities will be placed for production puroposes.

NEBU #346 (P) Sec 36, T31N, R8W San Juan County 30-045-34144



## NEBU #346 (P) Sec 36, T31N, R8W San Juan County 30-045-34144 Temporary Abandonment



District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone: (575) 748-1283 Fax: (575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. **Santa Fe, NM 87505** 

CONDITIONS

Action 280845

## **CONDITIONS**

Operator:	OGRID:
SIMCOE LLC	329736
1199 Main Ave., Suite 101	Action Number:
Durango, CO 81301	280845
	Action Type:
	[C-103] NOI Temporary Abandonment (C-103I)

## CONDITIONS

Created By	Condition	Condition Date
mkuehling	Testing Pressure cannot drop below 500 psi on a ta'd well - Notify NMOCD 24 hours prior to testing. Bradenhead test required prior to MIT day of MIT	11/3/2023