

**State Of New Mexico**  
**Energy, Minerals and Natural Resources Department**

12-Jun-25

**Maverick Permian LLC**  
1000 Main Street, Suite 2900  
Houston, TX 77002

**Pre Enforcement Notification**

Dear Operator:

The following inspection indicates that the well, equipment, location or operational status of the well failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date indicated.

Please notify the Compliance Officer copied on this letter, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

*INSPECTION DETAIL SECTION*

[30-025-02965] EAST VACUUM (GSA) UNIT #005

OGRID: 331199

H-32-17S-35E 1980 FNL 660 FEL

<b>Inspection Date</b>	<b>Type Inspection</b>	<b>Inspector</b>	<b>Inspection No.</b>
6/12/2025	Routine Inspection	[BZL] Barbara Lydick	iBZL2516354471
<b>Violation</b>	<b>Title</b>		<b>Corrective Action Due</b>
cBZL2516359028	19.15 Oil and Gas Mechanical Integrity Failure Recorded <i>(Auto Generated Violation - MIT Failure exits.)</i>		9/10/2025
cBZL2516359029	19.15.16.9 Sealing Off Strata Detection of Deficient Mechanical Integrity <i>(Received and entered operator reported FAILED BHT intermediate would not blow down WELL MUST BE SHUT IN ASAP)</i>		9/10/2025

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.

**Note:** Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data.