Office Office	State of New Mexico	Form C-103
District I	Energy, Minerals and Natural Resources	May 27, 2004
1625 N. French Dr., Hobbs, NM 88240	P	WELL API NO. 30-007-20741
District II 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION 1220 South St. Francis Dr.	5. J. I. d. T. C.
District III	1220 South St. Francis Dr.	p. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410	Conto Collain 10050505	
<u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM	Santa Latintoffly 52 BUTS	6. State Oil & Gas Lease No.
87505		46
	TICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPO	OSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	
	ICATION FOR PERMIT" (FORM C-101) FOR SUCH	VPR A
PROPOSALS.) 1. Type of Well: Oil Well	Gas Well Other Coalbed Methane	8. Well Number 292
2. Name of Operator	Gas well of Other Coalbed Methane	9. OGRID Number 180514
1 -	ASO E & D.COMDANV I D	9. OGRID Number 180514
3. Address of Operator	ASO E & P COMPANY, L.P.	10. Pool name or Wildcat
-	OOV 100 DATON NM 97740	Stubblefield Canyon – Vermejo Gas
	BOX 190, RATON, NM 87740	Stubblefield Canyon - Verifiejo Gas
4. Well Location		
Unit Letter <u>D</u> :	988 feet from the North line and 702	feet from theWestline
Section 2 Townsh	ip 31N Range 20E NMPM	Colfax County
	11. Elevation (Show whether DR, RKB, RT, GR, e	(c.)
8,002' (GL)		
Pit or Below-grade Tank Application or Closure		
Pit type Depth to Groundwater Distance from nearest fresh water well Distance from nearest surface water		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF II	NTENTION TO: SU	DCEATERE DEDAM LAL
		BSEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON 🔲 REMEDIAL WO	ORK ALTERING CASING
PERFORM REMEDIAL WORK ☐ TEMPORARILY ABANDON ☐	PLUG AND ABANDON REMEDIAL WO	RK ALTERING CASING N
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WO	RK ALTERING CASING N
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING	PLUG AND ABANDON REMEDIAL WO CHANGE PLANS COMMENCE D MULTIPLE COMPL CASING/CEME	RILLING OPNS. PAND A D
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER:	PLUG AND ABANDON REMEDIAL WO COMMENCE DO CASING/CEME	RILLING OPNS. ALTERING CASING RILLING OPNS. PAND A COMPLETION COMPLETION
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or com	PLUG AND ABANDON REMEDIAL WO CHANGE PLANS COMMENCE D CASING/CEME OTHER: pleted operations. (Clearly state all pertinent details,	RK
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or com of starting any proposed w	PLUG AND ABANDON REMEDIAL WO COMMENCE DO CASING/CEME	RK
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or com	PLUG AND ABANDON REMEDIAL WO CHANGE PLANS COMMENCE D CASING/CEME OTHER: pleted operations. (Clearly state all pertinent details,	RK
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or com of starting any proposed wor recompletion.	PLUG AND ABANDON REMEDIAL WOOD COMMENCE DOTHER: pleted operations. (Clearly state all pertinent details, vork). SEE RULE 1103. For Multiple Completions:	RK
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or com of starting any proposed wor recompletion. 03/02/07 Superior ran Cement Bond	PLUG AND ABANDON REMEDIAL WO COMMENCE DE CASING/CEME OTHER: Pleted operations. (Clearly state all pertinent details, vork). SEE RULE 1103. For Multiple Completions: I Log. Estimated cement top at 58'.	RILLING OPNS. ALTERING CASING RILLING OPNS. PAND A DATE OF PAND A
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or com of starting any proposed wor recompletion. 03/02/07 Superior ran Cement Bond Superior Wireline perf'd 1	PLUG AND ABANDON REMEDIAL WO COMMENCE DE CASING/CEME OTHER: Pleted operations. (Clearly state all pertinent details, work). SEE RULE 1103. For Multiple Completions: I Log. Estimated cement top at 58'. st stage - 2131'-2134', 2142'-2145', 2151'-2154' 3	RILLING OPNS. PAND A COMPletion Completion Completion Completion Attach wellbore diagram of proposed completion Holes
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING OTHER: 13. Describe proposed or come of starting any proposed we or recompletion. 03/02/07 Superior ran Cement Bond Superior Wireline perf'd 1 HES frac'd 1st stage - Pur Perf'd 2nd stage -	PLUG AND ABANDON REMEDIAL WO COMMENCE DE CASING/CEME OTHER: Pleted operations. (Clearly state all pertinent details, vork). SEE RULE 1103. For Multiple Completions: I Log. Estimated cement top at 58'.	RILLING OPNS. PAND A COMPletion Completion Completion Completion Attach wellbore diagram of proposed completion Holes
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or com of starting any proposed wor recompletion. 03/02/07 Superior ran Cement Bond Superior Wireline perf'd 1 HES frac'd 1st stage - Pur Perf'd 2nd stage - Frac'd 2nd stage - Frac'd 2nd stage - Pur Perf'd 3nd stage - Pur Perf'd 2nd stage - Pur Perf	PLUG AND ABANDON REMEDIAL WO COMMENCE DE CASING/CEME DE CASING/CEM	RILLING OPNS. PAND A DATE PAND A COMPletion Completion Completion And give pertinent dates, including estimated date Attach wellbore diagram of proposed completion 6 Holes # Linear gel with 45,137 lbs 20/40 sand. Linear gel with 18,456 lbs 20/40 sand.
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or com of starting any proposed wor recompletion. 03/02/07 Superior ran Cement Bond Superior Wireline perf'd 1 HES frac'd 1st stage - Pur Perf'd 2nd stage - Frac'd 2nd stage - Pur Perf'd 3rd stage - Pur	PLUG AND ABANDON REMEDIAL WO COMMENCE DE CASING/CEME DE CASING/CEM	ALTERING CASING RILLING OPNS. PAND A COMPletion Completion Completion Completion Attach wellbore diagram of proposed completion 6 Holes Linear gel with 45,137 lbs 20/40 sand. Linear gel with 18,456 lbs 20/40 sand. 48 Holes
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or com of starting any proposed wor recompletion. 03/02/07 Superior ran Cement Bond Superior Wireline perf'd 1 HES frac'd 1st stage - Pur Perf'd 2nd stage - Frac'd 2nd stage - Frac'd 2nd stage - Pur Perf'd 3rd stage - Frac'd 3rd stage - Frac'd 3rd stage - Frac'd 3rd stage - Frac'd 3rd stage - Pur Perf'd 3rd stage - Frac'd 3rd stage - Pur Perf'd 3rd stage - Pur P	PLUG AND ABANDON REMEDIAL WO COMMENCE DE CASING/CEME MULTIPLE COMPL CASING/CEME Detect operations. (Clearly state all pertinent details, work). SEE RULE 1103. For Multiple Completions: Log. Estimated cement top at 58'. St stage - 2131'-2134', 2142'-2145', 2151'-2154' 3 mped 414,845 scf 70% quality nitrogen foam with 20 1761'-1765', 1808'-1810' 24 Holes mped 515,167 scf 70% quality nitrogen foam with 20 1218'-1220', 1247'-1250', 1271'-1275', 1304'-1307' mped 288,191 scf 70% quality nitrogen foam with 20 19 mped 288,191 scf 70	ALTERING CASING RILLING OPNS. PAND A COMPletion Completion Completion Completion Attach wellbore diagram of proposed completion 6 Holes Linear gel with 45,137 lbs 20/40 sand. Linear gel with 18,456 lbs 20/40 sand. 48 Holes
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or com of starting any proposed wor recompletion. 03/02/07 Superior ran Cement Bond Superior Wireline perf'd 1 HES frac'd 1st stage - Pur Perf'd 2nd stage - Frac'd 2nd stage - Frac'd 2nd stage - Pur Perf'd 3rd stage - Frac'd 3rd stage - Frac'd 3rd stage - Frac'd 3rd stage - Pur Perf'd 4th stage - 04/17/07 Perf'd 4th stage -	PLUG AND ABANDON REMEDIAL WO COMMENCE DE CASING/CEME MULTIPLE COMPL CASING/CEME OTHER: pleted operations. (Clearly state all pertinent details, work). SEE RULE 1103. For Multiple Completions: I Log. Estimated cement top at 58'. Ist stage - 2131'-2134', 2142'-2145', 2151'-2154' 3 mped 414,845 scf 70% quality nitrogen foam with 20 1761'-1765', 1808'-1810' 24 Holes mped 515,167 scf 70% quality nitrogen foam with 20 1218'-1220', 1247'-1250', 1271'-1275', 1304'-1307' mped 288,191 scf 70% quality nitrogen foam with 20 184'-888', 902'-904', 929'-932' 36 Holes	RILLING OPNS. PAND A PAND A Completion Completion Completion Completion Attach wellbore diagram of proposed completion Holes Linear gel with 45,137 lbs 20/40 sand. Linear gel with 18,456 lbs 20/40 sand. Linear gel with 46,083 lbs 20/40 sand.
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comof starting any proposed wor recompletion. 03/02/07 Superior ran Cement Bond Superior Wireline perf'd 1 HES frac'd 1stage - Purperf'd 2nd stage - Frac'd 2nd stage - Frac'd 2nd stage - Frac'd 3nd stage - Frac'd 3nd stage - Frac'd 3nd stage - Frac'd 3nd stage - Frac'd 4nd st	PLUG AND ABANDON REMEDIAL WO COMMENCE DE CASING/CEME MULTIPLE COMPL CASING/CEME DIEST OTHER: Pleted operations. (Clearly state all pertinent details, york). SEE RULE 1103. For Multiple Completions: Log. Estimated cement top at 58'. St stage - 2131'-2134', 2142'-2145', 2151'-2154' 3 mped 414,845 scf 70% quality nitrogen foam with 20 1761'-1765', 1808'-1810' 24 Holes mped 515,167 scf 70% quality nitrogen foam with 20# 1218'-1220', 1247'-1250', 1271'-1275', 1304'-1307' mped 288,191 scf 70% quality nitrogen foam with 20# 884'-888', 902'-904', 929'-932' 36 Holes mped 214,370 scf 70% quality nitrogen foam with 20#	RILLING OPNS. PAND A PAND A Completion Completion Completion Completion Attach wellbore diagram of proposed completion Holes Linear gel with 45,137 lbs 20/40 sand. Linear gel with 46,083 lbs 20/40 sand. Linear gel with 33,752 lbs 20/40 sand.
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comof starting any proposed wor recompletion. 03/02/07 Superior ran Cement Bond Superior Wireline perf'd 1 HES frac'd 1stage - Purperf'd 2nd stage - Frac'd 2nd stage - Frac'd 2nd stage - Frac'd 3nd stage - Frac'd 3nd stage - Frac'd 3nd stage - Frac'd 3nd stage - Frac'd 4nd st	PLUG AND ABANDON REMEDIAL WO COMMENCE DE CASING/CEME MULTIPLE COMPL CASING/CEME OTHER: pleted operations. (Clearly state all pertinent details, work). SEE RULE 1103. For Multiple Completions: I Log. Estimated cement top at 58'. Ist stage - 2131'-2134', 2142'-2145', 2151'-2154' 3 mped 414,845 scf 70% quality nitrogen foam with 20 1761'-1765', 1808'-1810' 24 Holes mped 515,167 scf 70% quality nitrogen foam with 20 1218'-1220', 1247'-1250', 1271'-1275', 1304'-1307' mped 288,191 scf 70% quality nitrogen foam with 20 184'-888', 902'-904', 929'-932' 36 Holes	RILLING OPNS. PAND A PAND A Completion Completion Completion Completion Attach wellbore diagram of proposed completion Holes Linear gel with 45,137 lbs 20/40 sand. Linear gel with 46,083 lbs 20/40 sand. Linear gel with 33,752 lbs 20/40 sand.
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comof starting any proposed wor recompletion. 03/02/07 Superior ran Cement Bond Superior Wireline perf'd 1 HES frac'd 1stage - Purperf'd 2nd stage - Frac'd 2nd stage - Frac'd 2nd stage - Frac'd 3nd stage - Frac'd 3nd stage - Frac'd 3nd stage - Frac'd 3nd stage - Frac'd 4nd st	PLUG AND ABANDON REMEDIAL WO COMMENCE DE CASING/CEME MULTIPLE COMPL CASING/CEME DIEST OTHER: Pleted operations. (Clearly state all pertinent details, york). SEE RULE 1103. For Multiple Completions: Log. Estimated cement top at 58'. St stage - 2131'-2134', 2142'-2145', 2151'-2154' 3 mped 414,845 scf 70% quality nitrogen foam with 20 1761'-1765', 1808'-1810' 24 Holes mped 515,167 scf 70% quality nitrogen foam with 20# 1218'-1220', 1247'-1250', 1271'-1275', 1304'-1307' mped 288,191 scf 70% quality nitrogen foam with 20# 884'-888', 902'-904', 929'-932' 36 Holes mped 214,370 scf 70% quality nitrogen foam with 20#	RILLING OPNS. PAND A PAND A Completion Completion Completion Completion Attach wellbore diagram of proposed completion Holes Linear gel with 45,137 lbs 20/40 sand. Linear gel with 46,083 lbs 20/40 sand. Linear gel with 33,752 lbs 20/40 sand.
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or com of starting any proposed wor recompletion. 03/02/07 Superior ran Cement Bond O4/16/07 Superior Wireline perf'd 1 HES frac'd 1st stage - Pur Perf'd 2nd stage - Frac'd 2nd stage - Frac'd 3rd stage - Frac'd 3rd stage - Frac'd 4th stage - Frac'd 4th stage - Frac'd 4th stage - Pur O5/01/07 RIH tubing, rods and put I hereby certify that the information	PLUG AND ABANDON REMEDIAL WO COMMENCE DE CHANGE PLANS COMMENCE DE CASING/CEME DE	RILLING OPNS. PAND A NT JOB Completion Completion and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion 6 Holes Linear gel with 45,137 lbs 20/40 sand. Linear gel with 18,456 lbs 20/40 sand. 48 Holes Linear gel with 46,083 lbs 20/40 sand. Linear gel with 33,752 lbs 20/40 sand. Linear gel with 33,752 lbs 20/40 sand.
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or com of starting any proposed wor recompletion. 03/02/07 Superior ran Cement Bond O4/16/07 Superior Wireline perf'd 1 HES frac'd 1st stage - Pur Perf'd 2nd stage - Frac'd 2nd stage - Frac'd 3rd stage - Frac'd 3rd stage - Frac'd 4th stage - Frac'd 4th stage - Frac'd 4th stage - Pur O5/01/07 RIH tubing, rods and put I hereby certify that the information	PLUG AND ABANDON REMEDIAL WO COMMENCE DE CASING/CEME MULTIPLE COMPL CASING/CEME DIEST OTHER: Pleted operations. (Clearly state all pertinent details, york). SEE RULE 1103. For Multiple Completions: Log. Estimated cement top at 58'. St stage - 2131'-2134', 2142'-2145', 2151'-2154' 3 mped 414,845 scf 70% quality nitrogen foam with 20 1761'-1765', 1808'-1810' 24 Holes mped 515,167 scf 70% quality nitrogen foam with 20# 1218'-1220', 1247'-1250', 1271'-1275', 1304'-1307' mped 288,191 scf 70% quality nitrogen foam with 20# 884'-888', 902'-904', 929'-932' 36 Holes mped 214,370 scf 70% quality nitrogen foam with 20#	RILLING OPNS. PAND A NT JOB Completion Completion and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion 6 Holes Linear gel with 45,137 lbs 20/40 sand. Linear gel with 18,456 lbs 20/40 sand. 48 Holes Linear gel with 46,083 lbs 20/40 sand. Linear gel with 33,752 lbs 20/40 sand. Linear gel with 33,752 lbs 20/40 sand.
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or com of starting any proposed wor recompletion. 03/02/07 Superior ran Cement Bond 04/16/07 Superior Wireline perf'd 1 HES frac'd 1st stage - Pur Perf'd 2nd stage - Frac'd 2nd stage - Frac'd 2nd stage - Frac'd 3rd stage - Frac'd 3rd stage - Frac'd 4th stage -	PLUG AND ABANDON	ALTERING CASING RILLING OPNS. PAND A TOMPLETON Completion Completion And give pertinent dates, including estimated date Attach wellbore diagram of proposed completion Here are gel with 45,137 lbs 20/40 sand. Linear gel with 46,083 lbs 20/40 sand. Linear gel with 46,083 lbs 20/40 sand. Linear gel with 33,752 lbs 20/40 sand. Linear gel with 33,752 lbs 20/40 sand. Cion. Age and belief. I further certify that any pit or belowdrian or an (attached) alternative OCD-approved plan .
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or com of starting any proposed wor recompletion. 03/02/07 Superior ran Cement Bond 04/16/07 Superior Wireline perf'd 1 HES frac'd 1stage - Pur Perf'd 2nd stage - Frac'd 2nd stage - Frac'd 3rd stage - Frac'd 3rd stage - Frac'd 4th stage - Frac'd 4th stage - Frac'd 4th stage - Frac'd 4th stage - Pur 05/01/07 RIH tubing, rods and put I hereby certify that the information grade tank has been/will be constructed of SIGNATURE	PLUG AND ABANDON	RILLING OPNS. PAND A NT JOB Completion And give pertinent dates, including estimated date Attach wellbore diagram of proposed completion Holes Linear gel with 45,137 lbs 20/40 sand. Linear gel with 18,456 lbs 20/40 sand. Linear gel with 46,083 lbs 20/40 sand. Linear gel with 33,752 lbs 20/40 sand.
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or com of starting any proposed wor recompletion. 03/02/07 Superior ran Cement Bond 04/16/07 Superior Wireline perf'd 1 HES frac'd 1st stage - Pur Perf'd 2nd stage - Frac'd 2nd stage - Frac'd 2nd stage - Frac'd 3rd stage - Frac'd 3rd stage - Frac'd 4th stage -	PLUG AND ABANDON	RILLING OPNS. PAND A NT JOB Completion And give pertinent dates, including estimated date Attach wellbore diagram of proposed completion Holes Linear gel with 45,137 lbs 20/40 sand. Linear gel with 18,456 lbs 20/40 sand. Linear gel with 46,083 lbs 20/40 sand. Linear gel with 33,752 lbs 20/40 sand.
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or com of starting any proposed wor recompletion. 03/02/07 Superior ran Cement Bond O4/16/07 Superior Wireline perf'd 1 HES frac'd 1st stage - Pur Perf'd 2nd stage - Frac'd 2nd stage - Frac'd 3nd stage - Frac'd 3nd stage - Frac'd 3nd stage - Frac'd 4th stage - Frac'd 4th stage - Frac'd 4th stage - Frac'd 4th stage - Put O5/01/07 RIH tubing, rods and put I hereby certify that the information grade tank has been/will be constructed of SIGNATURE Shirley AM	PLUG AND ABANDON	RILLING OPNS. PAND A NT JOB Completion And give pertinent dates, including estimated date Attach wellbore diagram of proposed completion Holes Linear gel with 45,137 lbs 20/40 sand. Linear gel with 18,456 lbs 20/40 sand. Linear gel with 46,083 lbs 20/40 sand. Linear gel with 33,752 lbs 20/40 sand.
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or com of starting any proposed wor recompletion. 03/02/07 Superior ran Cement Bond 04/16/07 Superior Wireline perf'd 1 HES frac'd 1stage - Pur Perf'd 2nd stage - Frac'd 2nd stage - Frac'd 3rd stage - Frac'd 3rd stage - Frac'd 4th stage - Frac'd 4th stage - Frac'd 4th stage - Frac'd 4th stage - Pur 05/01/07 RIH tubing, rods and put I hereby certify that the information grade tank has been/will be constructed of SIGNATURE	PLUG AND ABANDON	RK
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or com of starting any proposed wor recompletion. 03/02/07 Superior ran Cement Bond O4/16/07 Superior Wireline perf'd 1 HES frac'd 1st stage - Pur Perf'd 2nd stage - Frac'd 2nd stage - Frac'd 3nd stage - Frac'd 3nd stage - Frac'd 3nd stage - Frac'd 4th stage - Frac'd 4th stage - Frac'd 4th stage - Frac'd 4th stage - Pur O5/01/07 RIH tubing, rods and put I hereby certify that the information grade tank has been/will be constructed of SIGNATURE Shirley AMI	PLUG AND ABANDON	RK
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or com of starting any proposed wor recompletion. 03/02/07 Superior ran Cement Bond O4/16/07 Superior Wireline perf'd 1 HES frac'd 1st stage - Pur Perf'd 2nd stage - Frac'd 2nd stage - Frac'd 3nd stage - Frac'd 3nd stage - Frac'd 3nd stage - Frac'd 4th stage - Frac'd 4th stage - Frac'd 4th stage - Frac'd 4th stage - Put O5/01/07 RIH tubing, rods and put I hereby certify that the information grade tank has been/will be constructed of SIGNATURE Shirley AM	PLUG AND ABANDON	RILLING OPNS. PAND A NT JOB Completion And give pertinent dates, including estimated date Attach wellbore diagram of proposed completion Holes Linear gel with 45,137 lbs 20/40 sand. Linear gel with 18,456 lbs 20/40 sand. Linear gel with 46,083 lbs 20/40 sand. Linear gel with 33,752 lbs 20/40 sand.