BEFORE THE OIL CONSERVATION DIVISION EXAMINER HEARING JULY 23, 2024

CASE Nos. 24279 & 24280

ANGEL RANCH SWD

EDDY COUNTY, NEW MEXICO



STATE OF NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT OIL CONSERVATION DIVISION

APPLICATIONS OF RILEY PERMIAN OPERATING COMPANY, LLC, FOR APPROVAL OF A SALT WATER DISPOSAL WELL, EDDY COUNTY, NEW MEXICO.

CASE NOS. 24279-24280

TABLE OF CONTENTS

MRC Exhibit A – Self-Affirmed Statement of Andrew Parker, Senior Vice President of Geosciences

- MRC Exhibit A-1 Locator Map
- MRC Exhibit A-2 Subsea Structure Map Top of Mississippian Lime with fault trace
- MRC Exhibit A-3 Subsea Structure Map Top of Cisco with fault trace
- MRC Exhibit A-4 Structural Cross-Section
- MRC Exhibit A-5 USGS Earthquake Activity and SRAs with fault trace
- MRC Exhibit A-6 UT Bureau of Economic Geology Basement Faults with SRAs

STATE OF NEW MEXICO
DEPARTMENT OF ENERGY, MINERALS AND NATURAL RESOURCES
OIL CONSERVATION DIVISION

APPLICATION OF RILEY PERMIAN OPERATING COMPANY, LLC, FOR APPROVAL OF A SALT WATER DISPOSAL WELL, EDDY COUNTY, NEW MEXICO.

CASE NO. 24279

APPLICATION OF RILEY PERMIAN OPERATING COMPANY, LLC, FOR APPROVAL OF A SALT WATER DISPOSAL WELL, EDDY COUNTY, NEW MEXICO.

CASE NO. 24280

SELF-AFFIRMED STATEMENT OF ANDREW PARKER, SENIOR VICE PRESIDENT OF GEOSCIENCES

1. My name is Andrew Parker, and I am employed by MRC Energy Company, an affiliate of MRC Permian Company and Matador Production Company (collectively, "Matador"), as a Senior Vice President of Geosciences. I have previously testified before the New Mexico Oil Conservation Division as an expert witness in petroleum geology.

2. I have reviewed the above-referenced applications filed by Riley Permian Operating Company, LLC ("Riley").

3. In Case Number 24279, Riley seeks approval of its Angel Ranch SWD #1, located in Section 12, Township 19 South, Range 27 East, NMPM, Eddy County, New Mexico, with a proposed injection interval listed in the Cisco formation at depts between 8,586' and 9,210.' I understand Riley is requesting average and maximum daily rates of injection of 15,000 BWPD and 20,000 BWPD, respectively, for this proposed SWD.

4. In Case Number 24280, Riley seeks approval of its Angel Ranch SWD #2, located in Section 11, Township 19 South, Range 27 East, NMPM, Eddy County, New Mexico, with a proposed injection interval listed in the Cisco formation at depts between 8,450' and 8,975.' I

BEFORE THE OIL CONSERVATION DIVISION
Santa Fe, New Mexico
Exhibit No. A
Submitted by: Matador Production Company
Hearing Date: July 23, 2024

Case Nos. 24279-24280

understand Riley is requesting average and maximum daily rates of injection of 15,000 BWPD and 20,000 BWPD, respectively, for this proposed SWD.

- 5. Matador has objected to both of Riley's proposed SWDs for two primary reasons: (i) Matador is concerned that Riley's proposed SWDs would present a significant risk of negatively impacting (i.e., watering out) the prospective Third Bone Spring target on Matador's adjacent acreage, and (ii) Matador is concerned that Riley's proposed SWDs would lead to an unreasonable increased risk of induced seismicity in this area. Matador's concerns are similar for both of Riley's proposed SWDs, so I will address those concerns for both SWDs below.
- 6. **Matador Exhibit A-1** is a locator map identifying the location of Riley's two proposed SWDs in Sections 11 and 12, Township 19 South, Range 27 East, NMPM, Eddy County, New Mexico. A red box identifies the general area where the two proposed SWDs are located, with the SWD locations identified in small yellow squares.
- of the Mississippi Lime formation. The contour intervals are 50 feet. I have also identified the locations of Riley's proposed Angel Ranch SWD #1 and Angel Ranch SWD #2 SWD with red and orange circles, respectively. The structure map shows the presence of a significant fault in this area, which I have shown using a red line on Exhibit A-2. As reflected on Exhibit A-2, this fault runs close to both of Riley's proposed SWD locations.
- 8. **Matador Exhibit A-3** contains a subsea structure map that I prepared off the top of the Cisco formation. The contour intervals are 50 feet. I have also identified the locations of Riley's proposed Angel Ranch SWD #1 and Angel Ranch SWD #2 SWD with red and orange circles, respectively. Although the fault identified in Exhibit A-2 is basement-rooted and offsets deeper stratigraphy, this structure map confirms the fault-propagated folding of the overlying

Cisco formation, which is the proposed injection interval for both of Riley's proposed SWDs. Fracturing associated with this fault-propagated folding through the Cisco and early Permian strata increases the risk of vertical communication between the water injection interval and the Third Bone Spring reservoir.

9. **Matador Exhibit A-4** is a structural cross-section that I prepared displaying openhole logs run from the five representative wells denoted from A to A' on Exhibit A-2 and Exhibit A-3. The wells in the cross-section contain gamma ray, resistivity, and porosity logs. Highlighted in green is the Third Bone Spring target that Matador intends to be developed on its adjacent acreage in this area. Highlighted in blue is the injection interval that Riley has proposed for its two proposed SWD locations.

Matador's Concerns that Riley's SWDs Could Wash Out the Third Bone Spring Target

- 10. As shown on Exhibit A-4, there is only approximately 400 feet of vertical separation between Riley's proposed SWD injection interval and Matador's Third Bone Spring target it intends to develop using horizontal wells. I do not identify any clear geologic barriers between the proposed injection interval and Matador's horizontal target that would prevent vertical migration of the produced water Riley proposes to inject into its SWDs into the shallower Third Bone Spring.
- 11. For this reason, I am concerned that there is a significant risk that Riley's proposed SWDs and the resultant injection of produced water could cause water to migrate into Matador's Third Bone Spring target and negatively impact the Third Bone Spring target, which would cause more water and less hydrocarbons to be produced from the target and thereby result in waste of the oil and gas present in the target that would not be produced but that otherwise would have.

12. My concerns are further compounded by the presence of the fault identified in MRC Exhibit A-2 and A-3. Due to the fault, the vertical separation between Riley's proposed injection interval and Matador's Third Bone Spring target could be much closer than 400 feet in parts of this area. In addition, the fault could allow for easier flow of water from the injection interval into the Third Bone Spring target, causing the negative impacts described above.

Matador's Concerns that Riley's SWDs Present Induced Seismicity Risk

- 13. **Matador Exhibit A-5** shows recent seismic activity of magnitudes greater than 3.5 to the west of the proposed Angel Ranch SWD wells. The seismic response radii are highlighted in red (3-mile radius), orange (6-mile radius), and yellow (10-mile radius). The Angel Ranch SWD wells both fall within a 10-mile radius of recent activity. At the bottom of Exhibit A-5, moment tensor data from 2 recent events demonstrates that the orientation of failure is roughly southwest to northeast, which is also sub-parallel to the fault orientation mapped in the Angel Ranch SWD area. This demonstrates that the mapped fault orientation is prone to failure in the modern stress environment.
- Matador Exhibit A-6 further supports the statements from paragraph 12 with published basement-rooted faults form the University of Texas Bureau of Economic Geology. Seismic activity west of Angel Ranch is following a significant regional offset in the basement (light blue to darker blue), and the Angel Ranch SWD wells are situated near a well-documented regional basement fault that runs parallel to the offset to the west. These parallel basement-rooted features are similarly stressed and prone to failure. Additional moment tensor data posted on this regional map further demonstrates that faults oriented southwest to northeast (i.e. 35-55 degrees) are prone to failure, regardless of being in a strike-slip, normal or reverse faulting regime.

- Accordingly, based on the fault identified in this area, the direction of the fault, and 15. the previous seismic events in this area, Matador is concerned that the approval of Riley's two applications would lead to additional induced seismicity risk in this area.
- Because there is not a clear, continuous geologic barrier that will effectively contain 16. the proposed injection, and injection into the Cisco formation will water out production in the overlying Third Bone Spring interval, Riley's applications must be denied. The proposed injection will also likely give rise to an unreasonable increased risk for induced seismicity in this area. Approving either application will likely result in waste and impair correlative rights.
- Matador Exhibits A-1 through A-6 were either prepared by me or compiled 17. under my direction and supervision.
- I affirm under penalty of perjury under the laws of the State of New Mexico that 18. the foregoing statements are true and correct. I understand that this self-affirmed statement will be used as written testimony in this case. This statement is made on the date next to my signature below. 7/16/2024 Date

5

Received by OCD: 7/16/2024 6:05:19 PM

Locator Map

Exhibit A-1

										Lea							+	
s zie Eddy	175,23E	175 2 AE	175 250	175 260	175 276	175 785	175 290	175.30£	Abo	Reef	175 33E	175 34E	175 196	175 361	175 176	175 3.RE	175) 39E3	BLKAB
5 2 1 E	185 23€	185 246	105 250	185 265	185 27E	185 28E	185 298	185 30E	185 316	185 326	185 33E	18534€	185 350	185 368	185 37E	185 386	185)	Gain
21E	195 236	195 2-€	195258	195 268	195 27E	19 286	195 295	191 301 YC	ungest	Goat S	еер	195 34E	195355	195,060	195 37E	195 3 HE	1953	SUK A10
					Project	Area			Capitar	Aquife	r						П	BLX A12
521E	205.236	205246	205 256	205 26E	MIN	205 288	205 29E	205 300	205 31E	205 32E	205 336	205 3 4E	205 358	205 34E	205 37E	205 3 NE	3963	BLK A28
Ħ	20,55 ZE	20:55						Y	ounges	t Capita	in							80X X28
1E	215/220	215 201	215 24E	215250	215 268	215 276	215 285	215 29E	215 300	215 316	294-221	215 33E	215 34E	215 356	215 36E	215 37E	Z	420
18	nsne	225 236	225 246	225-25E	nsul	225 27E	225 265	225 29€	225 30E	225 31E	225 32E	235.00	725 HE	225.75	275 365	225 37E	225 38L	Andre
16	изи	216 232	235 246	235 25€	235 26E	235 27E	235 2 8 E	235 29€	23530€	235316	235 32E	235 3 M	235 345	235 35£	23,534.0	235 37E	235 38E	BLK A 40
tE.	245 22E	245 23E	245 24E	245 258	245.26E	245.27E	245 28E	245.29E	245 30E	245316	:245326	245 338	245 34E	245 BE	245 36E	245 375	245 386	BLK AS 2
ne .	255 224	258,23E	255 24E	255 250	255 26E	255 27E	255 281	255 29£	255 30E	255 31E	255 125	255 JJE	255 34E	255 35E	2% 360	255 171	255 3.00	BLK ASS
4	265,228	265 23E	265 24E	265 25E	265 2 6 E	265 275	265 28E	100 New Mexi	000ftUS	197710	120	265 3 M	265 340	265 351	346.245	265 37E	265 38E	SLK A56
. 1	BLK64T15	BL SEATTHS.	8062715	BIVATTIS	BLXSOTIS	BUYESTEE	ulherson	Texas	X 8.X56	8UK 35	8LK 54	B.871 O	vino BUX C25	BUKC24	DLK C23:	SUC	022	EX 77 Wil

BEFORE THE OIL CONSERVATION DIVISION


Santa Fe, New Mexico
Exhibit No. A-1

Submitted by: Matador Production Company Hearing Date: July 23, 2024 Case Nos. 24279-24280



Subsea Structure Map (Top Miss Lime) A – A' Reference Line

Exhibit A-2



Map Legend

Angel Ranch #1



Angel Ranch #2



Fault Traces



C. I. = 50 ft

BEFORE THE OIL CONSERVATION DIVISION

Santa Fe, New Mexico Exhibit No. A-2


Submitted by: Matador Production Company Hearing Date: July 23, 2024

Case Nos. 24279-24280



Subsea Structure Map (Top Cisco) A – A' Reference Line

Exhibit A-3



Map Legend

Angel Ranch #1



Angel Ranch #2




Fault Traces



C. I. = 50 ft

Structural Cross-Section A – A'

Exhibit A-4




BEFORE THE OIL CONSERVATION DIVISION
Santa Fe, New Mexico
Exhibit No. A-4
Submitted by: Matador Production Company
Hearing Date: July 23, 2024
Case Nos. 24279-24280



USGS Earthquake Activity & Seismic Response Radii

Exhibit A-5



Map Legend

Angel Ranch #1




Angel Ranch #2



Fault Trace



<u>USGS Earthquakes</u> <u>Magnitude 3.5 or greater</u>



BEFORE THE OIL CONSERVATION DIVISION
Santa Fe, New Mexico
Exhibit No. A-5
Submitted by: Matador Production Company

Hearing Date: July 23, 2024

Case Nos. 24279-24280



BEG Basement Faults with SRA Radii

Exhibit A-6

