



**Volumetrics US Inc.**  
3001 N Cameron St, Victoria, TX-77901  
Phone: 361-827-4024

**Company:** OXY USA INC  
**Field/Location :** NMSW  
**Station Name :** FEDERAL 1-1  
**Station Number :** 2300150020  
**Sample Date:** 3/2/21 8:01 AM  
**Analysis Date:** 3/23/21 1:43 PM  
**Instrument:** VARIAN CP 490 GC  
**Calibration/Verification Date:** 3/23/2021  
**Heat Trace used:** YES

**Work Order** 4000230136  
**Sampled by:** VOLUMETRICS/JA  
**Sample Type :** SPOT-CYLINDER  
**Sample Temperature (F):** 50  
**Sample Pressure (PSIG):** 60  
**Flow rate (MCF/Day):** 30.8  
**Ambient Temperature (F):** 41  
**Sampling method:** FILL & EMPTY  
**Cylinder Number:** 1095

### NATURAL GAS ANALYSIS: GPA 2261

Components	Un-Normalized Mol%	Normalized Mol%	GPM 14.650	GPM 14.730	GPM 15.025
Hydrogen Sulfide	0.0000	0.0000			
Nitrogen	5.6205	5.7973			
Methane	63.0422	65.0250			
Carbon Dioxide	0.0798	0.0823			
Ethane	14.1343	14.5789	3.893	3.915	3.993
Propane	9.8799	10.1907	2.804	2.819	2.875
Isobutane	0.9613	0.9915	0.324	0.326	0.332
N-butane	2.0318	2.0957	0.660	0.663	0.677
Isopentane	0.3760	0.3878	0.142	0.142	0.145
N-Pentane	0.3170	0.3270	0.118	0.119	0.121
Hexanes Plus	0.5078	0.5238	0.228	0.230	0.234
<b>Total</b>	<b>96.9506</b>	<b>100.0000</b>			

Hexanes plus split (60%-30%-10%)

Physical Properties (Calculated)	14.650 psia	14.730 psia	15.025 psia
Total GPM Ethane+	8.169	8.214	8.378
Total GPM Iso-Pentane+	0.488	0.491	0.501
Compressibility (Z)	0.9957	0.9957	0.9956
Specific Gravity ( Air=1) @ 60 °F	0.8238	0.8239	0.8239
Molecular Weight	23.767	23.767	23.767

Gross Heating Value	14.650 psia	14.730 psia	15.025 psia
Dry, Real (BTU/Ft <sup>3</sup> )	1328.8	1336.1	1363.0
Wet, Real (BTU/Ft <sup>3</sup> )	1305.7	1312.9	1339.3
Dry, Ideal (BTU/Ft <sup>3</sup> )	1323.1	1330.3	1357.0
Wet, Ideal (BTU/Ft <sup>3</sup> )	1300.1	1307.2	1333.4

Temperature base 60 °F

**Comment:** FIELD H2S = 0 PPM

**Verified by**

Mostaq Ahammad  
Petroleum Chemist

**Approved by**

*Deann Friend*

Deann Friend  
Laboratory Manager

**UPSET FLARING EVENT SPECIFIC JUSTIFICATIONS FORM****Facility:** Federal 1-1 CTB**Flare Date:** 12/12/2021**Duration of event:** 2 Hours 30 Minutes**MCF Flared:** 310**Intermittent Flaring Times:** 02:21 AM to 04:51 AM**Cause:** Downstream Activity > DCP > High Line Pressure**Method of Flared Gas Measurement:** Gas Flare Meter 68873**Well API Associated with Facility:** 30-015-26843 Federal 1 #004

**Comments:** This upset event was not caused by any wells associated with the facility. This emissions event was caused by the unforeseen, unexpected, sudden, and unavoidable issue that was beyond the owner/operator's control, and did not stem from activity that could have been foreseen and avoided, and could not have been avoided by good design, operation, and preventative maintenance practices.

---

**1. Reason why this event was beyond Operator's control:**

This interruption, restriction or complete shut-in of the gas pipeline by a third-party pipeline operator is downstream of Oxy's custody transfer point and out of Oxy's control to avoid or prevent from happening and did not stem from any of Oxy's upstream facility activity that could have been foreseen and avoided, and could not have been avoided by good design, operation, and preventative maintenance practices.

In this case, there were multiple instances of high line pressure spikes in DCP's gas system pipeline, which impacted Oxy's ability to fully send gas to them as they were unable to handle the volume of gas loads sent to them. DCP's facility/equipment issues are downstream of Oxy's custody transfer point and control, yet greatly impacted the volume of gas flow from Oxy's upstream facility to their gas pipeline. DCP having recurring spikes in high line pressure in their gas sales service system pipeline, caused several brief instances of flaring at Oxy's upstream facility in a two-hour period, as it was not able to push the full volume of gas into DCP's gas service pipeline due to the restrictions and/or constraints on their gas sales service at various times. No advance warning was provided to Oxy personnel by DCP personnel regarding high line pressures issues with their gas service system pipeline.

The Federal 1-1 CTB flare is a gas gathering flare system for multiple tank batteries across Oxy's defined Lost Tank area. Oxy made every effort to shut in as much of production/wells as possible, yet it was absolutely critical to Oxy's operational safety and start up procedures to allow some production to occur at this facility, as it was necessary to maintain a minimal amount of gas flow to restart the facility's compression equipment, specifically the gas lift compressors, across the Lost Tank area, when DCP was ready and able to start taking gas. The minimal amount of gas flow allowed to be produced and flare was done out of necessity to protect personnel and equipment as a safeguard against potential issues that could occur when restarting production across the Lost Tank area.

## **2. Steps Taken to limit duration and magnitude of venting or flaring:**

It is OXY's policy to route its stranded gas to a flare during an unforeseen and unavoidable emergency or malfunction, that is beyond Oxy's control to avoid, prevent or foresee, to minimize emissions as much as possible, as part of the overall steps taken to limit duration and magnitude of flaring. In this case, there were multiple instances of high line pressure spikes in DCP's gas system pipeline, which impacted Oxy's ability to fully send gas to them as they were unable to handle the volume of gas loads sent to them. DCP's facility/equipment issues are downstream of Oxy's custody transfer point and control, yet greatly impacted the volume of gas flow from Oxy's upstream facility to their gas pipeline. DCP having recurring spikes in high line pressure in their gas sales service system pipeline, caused several brief instances of flaring at Oxy's upstream facility in a two-hour period, as it was not able to push the full volume of gas into DCP's gas service pipeline due to the restrictions and/or constraints on their gas sales service at various times. No advance warning was provided to Oxy personnel by DCP personnel regarding high line pressures issues with their gas service system pipeline.

This facility is unmanned, except when Oxy production techs are gathering data daily or conducting daily walk-throughs to ensure that there are no problems, circumstances and/or assist other personnel on-site for maintenance purposes. The Federal 1-1 CTB flare is a gas gathering flare system for multiple tank batteries across Oxy's defined Lost Tank area. Oxy made every effort to shut in as much of production/wells as possible, yet it was absolutely critical to Oxy's operational safety and start up procedures to allow some production to occur at this facility, as it was necessary to maintain a minimal amount of gas flow to restart the facility's compression equipment, specifically the gas lift compressors, across the Lost Tank area, when DCP was ready and able to start taking gas. The minimal amount of gas flow allowed to be produced and flare was done out of necessity to protect personnel and equipment as a safeguard against potential issues that could occur when restarting production across the Lost Tank area.

## **3. Corrective Actions taken to eliminate the cause and reoccurrence of venting or flaring:**

Oxy cannot take any corrective actions to eliminate the cause and potential reoccurrence of a DCP gas service flow pipeline restriction or shut-in, due to high line pressure spikes in their gas system pipeline, as this control issue is downstream of Oxy's custody transfer point and out of Oxy's control to avoid or prevent from happening or reoccurring. DCP's downstream facility issues will re-occur from time to time and may trigger a spike in their gas line pressure, which in turn, directly impacts Oxy's ability to send gas to them. When DCP's downstream facilities has equipment issues or greatly struggles to handle the volume of gas being sent to them by Oxy, DCP then restricts Oxy's ability to send gas, which then allows no other option but for Oxy to route its stranded gas not pushed into the DCP gas system pipeline, to flare. OXY makes every effort to control and minimize emissions as much as possible. The only actions that Oxy can take and handle that is within its control, is to communicate frequently with DCP personnel during these types of situations and adjust its production and/or compression equipment until DCP resumes normal gas service operations.

**District I**  
1625 N. French Dr., Hobbs, NM 88240  
Phone:(575) 393-6161 Fax:(575) 393-0720  
**District II**  
811 S. First St., Artesia, NM 88210  
Phone:(575) 748-1283 Fax:(575) 748-9720  
**District III**  
1000 Rio Brazos Rd., Aztec, NM 87410  
Phone:(505) 334-6178 Fax:(505) 334-6170  
**District IV**  
1220 S. St Francis Dr., Santa Fe, NM 87505  
Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

DEFINITIONS  
  
Action 68972

DEFINITIONS

Operator: OXY USA INC P.O. Box 4294 Houston, TX 772104294	OGRID: 16696
	Action Number: 68972
	Action Type: [C-129] Venting and/or Flaring (C-129)

DEFINITIONS

For the sake of brevity and completeness, please allow for the following in all groups of questions and for the rest of this application: <ul style="list-style-type: none"><li>• this application's operator, hereinafter "this operator";</li><li>• venting and/or flaring, hereinafter "vent or flare";</li><li>• any notification or report(s) of the C-129 form family, hereinafter "any C-129 forms";</li><li>• the statements in (and/or attached to) this, hereinafter "the statements in this";</li><li>• and the past tense will be used in lieu of mixed past/present tense questions and statements.</li></ul>
--

**District I**

1625 N. French Dr., Hobbs, NM 88240  
Phone:(575) 393-6161 Fax:(575) 393-0720

**District II**

811 S. First St., Artesia, NM 88210  
Phone:(575) 748-1283 Fax:(575) 748-9720

**District III**

1000 Rio Brazos Rd., Aztec, NM 87410  
Phone:(505) 334-6178 Fax:(505) 334-6170

**District IV**

1220 S. St Francis Dr., Santa Fe, NM 87505  
Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

QUESTIONS

Action 68972

**QUESTIONS**

Operator: OXY USA INC P.O. Box 4294 Houston, TX 772104294	OGRID: 16696
	Action Number: 68972
	Action Type: [C-129] Venting and/or Flaring (C-129)

**QUESTIONS****Prerequisites**

Any messages presented in this section, will prevent submission of this application. Please resolve these issues before continuing with the rest of the questions.

Incident Well	Not answered.
Incident Facility	[fAPP2127059734] FEDERAL 01 BATTERY

**Determination of Reporting Requirements**

Answer all questions that apply. The Reason(s) statements are calculated based on your answers and may provide additional guidance.

Was this vent or flare caused by an emergency or malfunction	Yes
Did this vent or flare last eight hours or more cumulatively within any 24-hour period from a single event	No
Is this considered a submission for a vent or flare event	Yes, minor venting and/or flaring of natural gas.

An operator shall file a form C-141 instead of a form C-129 for a release that, includes liquid during venting and/or flaring that is or may be a major or minor release under 19.15.29.7 NMAC.

Was there <b>at least 50 MCF</b> of natural gas vented and/or flared during this event	Yes
Did this vent or flare result in the release of <b>ANY</b> liquids (not fully and/or completely flared) that reached (or has a chance of reaching) the ground, a surface, a watercourse, or otherwise, with reasonable probability, endanger public health, the environment or fresh water	No
Was the vent or flare within an incorporated municipal boundary or withing 300 feet from an occupied permanent residence, school, hospital, institution or church in existence	No

**Equipment Involved**

Primary Equipment Involved	Other (Specify)
Additional details for Equipment Involved. Please specify	Emergency Flare > Downstream Activity > DCP > High Line Pressure

**Representative Compositional Analysis of Vented or Flared Natural Gas**

Please provide the mole percent for the percentage questions in this group.

Methane (CH4) percentage	65
Nitrogen (N2) percentage, if greater than one percent	6
Hydrogen Sulfide (H2S) PPM, rounded up	0
Carbon Dioxide (CO2) percentage, if greater than one percent	0
Oxygen (O2) percentage, if greater than one percent	0

If you are venting and/or flaring because of Pipeline Specification, please provide the required specifications for each gas.

Methane (CH4) percentage quality requirement	Not answered.
Nitrogen (N2) percentage quality requirement	Not answered.
Hydrogen Sulfide (H2S) PPM quality requirement	Not answered.
Carbon Dioxide (CO2) percentage quality requirement	Not answered.
Oxygen (O2) percentage quality requirement	Not answered.

**District I**  
1625 N. French Dr., Hobbs, NM 88240  
Phone:(575) 393-6161 Fax:(575) 393-0720  
**District II**  
811 S. First St., Artesia, NM 88210  
Phone:(575) 748-1283 Fax:(575) 748-9720  
**District III**  
1000 Rio Brazos Rd., Aztec, NM 87410  
Phone:(505) 334-6178 Fax:(505) 334-6170  
**District IV**  
1220 S. St Francis Dr., Santa Fe, NM 87505  
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico  
Energy, Minerals and Natural Resources  
Oil Conservation Division  
1220 S. St Francis Dr.  
Santa Fe, NM 87505

QUESTIONS, Page 2

Action 68972

QUESTIONS (continued)

Operator: OXY USA INC P.O. Box 4294 Houston, TX 772104294	OGRID: 16696
	Action Number: 68972
	Action Type: [C-129] Venting and/or Flaring (C-129)

QUESTIONS

Date(s) and Time(s)	
Date vent or flare was discovered or commenced	12/12/2021
Time vent or flare was discovered or commenced	02:21 AM
Time vent or flare was terminated	04:51 AM
Cumulative hours during this event	2

Measured or Estimated Volume of Vented or Flared Natural Gas	
Natural Gas Vented (Mcf) Details	Not answered.
Natural Gas Flared (Mcf) Details	Cause: Other   Other (Specify)   Natural Gas Flared   Released: 310 Mcf   Recovered: 0 Mcf   Lost: 310 Mcf ]
Other Released Details	Not answered.
Additional details for Measured or Estimated Volume(s). Please specify	Not answered.
Is this a gas only submission (i.e. only significant Mcf values reported)	Yes, according to supplied volumes this appears to be a "gas only" report.

Venting or Flaring Resulting from Downstream Activity	
Was this vent or flare a result of downstream activity	Yes
Was notification of downstream activity received by this operator	No
Downstream OGRID that should have notified this operator	[229153] DCP MIDSTREAM L.P.
Date notified of downstream activity requiring this vent or flare	Not answered.
Time notified of downstream activity requiring this vent or flare	Not answered.

Steps and Actions to Prevent Waste	
For this event, this operator could not have reasonably anticipated the current event and it was beyond this operator's control.	True
Please explain reason for why this event was beyond this operator's control	In this case, there were multiple instances of high line pressure spikes in DCP's gas system pipeline, which impacted Oxy's ability to fully send gas to them as they were unable to handle the volume of gas loads sent to them. DCP's facility/equipment issues are downstream of Oxy's custody transfer point and control, yet greatly impacted the volume of gas flow from Oxy's upstream facility to their gas pipeline. DCP having recurring spikes in high line pressure in their gas sales service system pipeline, caused several brief instances of flaring at Oxy's upstream facility in a two-hour period, as it was not able to push the full volume of gas into DCP's gas service pipeline due to the restrictions and/or constraints on their gas sales service at various times. No advance warning was provided to Oxy personnel by DCP personnel regarding high line pressures issues with their gas service system pipeline. The Federal 1-1 CTB flare is a gas gathering flare system for multiple tank batteries across Oxy's defined Lost Tank area. Oxy made every effort to shut in as much of production/wells as possible, yet it was absolutely critical to Oxy's operational safety and start up procedures to allow some production to occur at this facility, as it was necessary to maintain a minimal amount of gas flow to restart the facility's compression equipment, specifically the gas lift compressors, across the Lost Tank area, when DCP was ready and able to start taking gas. The minimal amount of gas flow allowed to be produced and flare was done out of necessity to protect personnel and equipment as a safeguard against potential issues that could occur when restarting production across the Lost Tank area.
Steps taken to limit the duration and magnitude of vent or flare	It is OXY's policy to route its stranded gas to a flare during an unforeseen and unavoidable emergency or malfunction, that is beyond Oxy's control to avoid, prevent or foresee, to minimize emissions as much as possible, as part of the overall steps taken to limit duration and magnitude of flaring. In this case, there were multiple instances of high line pressure spikes in DCP's gas system pipeline, which impacted Oxy's ability to fully send gas to them as they were unable to handle the volume of gas loads sent to them. DCP's facility/equipment issues are downstream of Oxy's custody transfer point and control, yet greatly impacted the volume of gas flow from Oxy's upstream facility to their gas pipeline. DCP having recurring spikes in high line pressure in their gas sales service system pipeline, caused several brief instances of flaring at Oxy's upstream facility in a two-hour period, as it was not able to push the full volume of gas into DCP's gas service pipeline due to the restrictions and/or constraints on their gas sales service at various times. No advance warning was provided to Oxy personnel by DCP personnel regarding high line pressures issues with their gas service system pipeline.
Corrective actions taken to eliminate the cause and reoccurrence of vent or flare	Oxy cannot take any corrective actions to eliminate the cause and potential reoccurrence of a DCP gas service flow pipeline restriction or shut-in, due to high line pressure spikes in their gas system pipeline, as this control issue is downstream of Oxy's custody transfer point and out of Oxy's control to avoid or prevent from happening or reoccurring. DCP's downstream facility issues will re-occur from time to time and may trigger a spike in their gas line pressure, which in turn, directly impacts Oxy's ability to send gas to them. When DCP's downstream facilities has equipment issues or greatly struggles to handle the volume of gas being sent to them by Oxy, DCP then restricts Oxy's ability to send gas, which then allows no other option but for Oxy to route its stranded gas not pushed into the DCP gas system pipeline, to flare. OXY makes every effort to control and minimize emissions as much as possible. The only actions that Oxy can take and handle that is within its control, is to communicate frequently with DCP personnel during these types of situations and adjust its production and/or compression equipment until DCP resumes normal gas service operations.

**District I**

1625 N. French Dr., Hobbs, NM 88240  
 Phone:(575) 393-6161 Fax:(575) 393-0720

**District II**

811 S. First St., Artesia, NM 88210  
 Phone:(575) 748-1283 Fax:(575) 748-9720

**District III**

1000 Rio Brazos Rd., Aztec, NM 87410  
 Phone:(505) 334-6178 Fax:(505) 334-6170

**District IV**

1220 S. St Francis Dr., Santa Fe, NM 87505  
 Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

ACKNOWLEDGMENTS

Action 68972

**ACKNOWLEDGMENTS**

Operator: OXY USA INC P.O. Box 4294 Houston, TX 772104294	OGRID: 16696
	Action Number: 68972
	Action Type: [C-129] Venting and/or Flaring (C-129)

**ACKNOWLEDGMENTS**

<input checked="" type="checkbox"/>	I acknowledge that I am authorized to submit a <i>Venting and/or Flaring</i> (C-129) report on behalf of this operator and understand that this report can be a <b>complete</b> C-129 submission per 19.15.27.8 and 19.15.28.8 NMAC.
<input checked="" type="checkbox"/>	I acknowledge that upon submitting this application, I will be creating a new incident file (assigned to this operator) to track any C-129 forms, pursuant to 19.15.27.7 and 19.15.28.8 NMAC and understand that this submission meets the notification requirements of Paragraph (1) of Subsection G and F respectively.
<input checked="" type="checkbox"/>	I hereby certify the statements in this report are true and correct to the best of my knowledge and acknowledge that any false statement may be subject to civil and criminal penalties under the Oil and Gas Act.
<input checked="" type="checkbox"/>	I acknowledge that the acceptance of any C-129 forms by the OCD does not relieve this operator of liability should their operations have failed to adequately investigate, report, and remediate contamination that poses a threat to groundwater, surface water, human health, or the environment.
<input checked="" type="checkbox"/>	I acknowledge that OCD acceptance of any C-129 forms does not relieve this operator of responsibility for compliance with any other applicable federal, state, or local laws and/or regulations.

**District I**

1625 N. French Dr., Hobbs, NM 88240  
Phone:(575) 393-6161 Fax:(575) 393-0720

**District II**

811 S. First St., Artesia, NM 88210  
Phone:(575) 748-1283 Fax:(575) 748-9720

**District III**

1000 Rio Brazos Rd., Aztec, NM 87410  
Phone:(505) 334-6178 Fax:(505) 334-6170

**District IV**

1220 S. St Francis Dr., Santa Fe, NM 87505  
Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

CONDITIONS

Action 68972

**CONDITIONS**

Operator: OXY USA INC P.O. Box 4294 Houston, TX 772104294	OGRID: 16696
	Action Number: 68972
	Action Type: [C-129] Venting and/or Flaring (C-129)

**CONDITIONS**

Created By	Condition	Condition Date
marialuna2	If the information provided in this report requires an amendment, submit a [C-129] Amend Venting and/or Flaring Incident (C-129A), utilizing your incident number from this event.	12/27/2021