

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

HOBBS OCD

NOV 14 2011

RECEIVED

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company: Chaparral Energy Co. LLC	Contact: Derek E. Presley
Address: 701 Cedar Lake Blvd. Oklahoma City, OK 73114	Telephone No.: (405) 426-4091 X 1491
Facility Name: WDQSU Sat. #2	Facility Type: INJECTION HEADER

Surface Owner: Bill Grobe	Mineral Owner	Lease No.:
---------------------------	---------------	------------

LOCATION OF RELEASE

NEARBY WELL: WDQSU #673
API # 30-025-29970-00-00

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	30	24S	38E	1,310'	SOUTH	802'	EAST	LEA

Latitude: 32.184706

Longitude: -103.093690

NATURE OF RELEASE

Type of Release: Produce water and oil	Volume of Release: 10bbbls	Volume Recovered: 2bbbls
Source of Release: 2" steel flow line ruptured 15' W. of header	Date and Hour of Occurrence: 11-4-11	Date and Hour of Discovery: 1:30pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom? Roy R. Rascon w/WEE / ET of NM, notified Geoffery L. @ NMOCD office	Date and Hour: 11-8-11 @ approx. 2:30	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
2" steel line from header to well, ruptured, leak source isolated, line removed for repair, new line installed on 11-8-11. Vacuum truck called in but only recovered about 2 bbls. of water.

Describe Area Affected and Cleanup Action Taken.*
Area affected is due west of header approx. size 80'n&s x 35'e&w, with puddle area in road area to south of header, one finger running to the south about 500'L with various width from 6' to 1'wide, and a separate finger on the lease rd going west about 400'L, with various widths from 6' to 1'wide. WEE / ET of NM contacted to investigate site and em leak area. Site will be delineated in accordance NMOCD regs.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
	Approved by District Supervisor: ENV. ENGINEER: 	
Printed Name: Derek E. Presley	Approval Date: 11/14/11	Expiration Date: 11/17/12
Title: Safety Specialist	Conditions of Approval: SUBMIT FINAL C-141 BY 01/17/12	Attached <input type="checkbox"/> IRP-11-11-2759
E-mail Address: derek.presley@chaparralenergy.com		
Date: 11/9/11	Phone: (405) 426-4091 X 1491	

* Attach Additional Sheets If Necessary

NOV 15 2011