

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company: Chaparral Energy LLC.	Contact: Derek Presely
Address: 701 Cedar Lake Blvd. Oklahoma City, OK 73114	Telephone No.: (405) 426-4091 X 1491
Facility Name: Yates State #2	Facility Type: oil well active

Surface Owner: STATE	Mineral Owner:	Lease No.:
----------------------	----------------	------------

LOCATION OF RELEASE API# 30,025,30255.00.00

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	16	12S	38E	2310'	NORTH	330'	EAST	LEA

Latitude: N33.2796459383444 Longitude: W103.09452468313

NATURE OF RELEASE
DEPTH TO GROUND WATER: 8' > 20' BGS

Type of Release: oil & produce water	Volume of Release: 15bbbls	Volume Recovered: 10bbbls
Source of Release: cable on rod rotator broke up high, wrapped up around 1" nipple on pumping "T", on upstroke broke 1" nipple and continued to pump	Date and Hour of Occurrence: 1-30-12 5:00am	Date and Hour of Discovery: 1-30-12 5:00am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? ETNM will set up C-141 and report to Geoffery Leking @ NMOCD Hobbs & NMSLO on return of signed initial C-141	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
Leak was caused when cable on rod rotator broke up high, wrapped up around 1" nipple on pumping "T", on upstroke broke 1" nipple and continued to pump. Pump jack shut down and repaired broken nipple, Chaparral Energy Crew headed to site to perform surface clean up.

Describe Area Affected and Cleanup Action Taken.* leak area centralized on well pad just south of pump jack, an area of approx. 20'W x 60'L about 1200sqft affected.
CLEAN UP ACTION: Earth Technologies of New Mexico contracted to delineate and setup cleanup plan for Chaparral

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION	
Printed Name: Derek Presely	Approved by ENV SPECIALIST: <i>Geoffery Leking</i> District Supervisor.	
Title: Safety Specialist	Approval Date: 02/01/12	Expiration Date: 04/01/12
E-mail Address: derek.presely@chaparralenergy.com	Conditions of Approval: SUBMIT FINAL	Attached <input type="checkbox"/>
Date: 1-31-12 Phone: (575) 396-3221	C-141 BY 04/01/12	IRP-2-12-2781

* Attach Additional Sheets If Necessary

FEB 06 2012