

**HOBBS OCD**

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St Francis Dr., Santa Fe, NM 87505

NOV 05 2012

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company	CHEVRON U.S.A Inc.	Contact	David Pagano
Address	56 Texas Camp Road, Lovington, NM 88260	Telephone No. Office:	575-396-4414 ext 275 Cellular: 505-787-9816
Facility Name	Vacuum Glorietta West Unit Battery	Facility Type	Production Tank Battery

Surface Owner	State of New Mexico	Mineral Owner	State of New Mexico	API No.	OGRID No. B-155
---------------	---------------------	---------------	---------------------	---------	-----------------

**LOCATION OF RELEASE**

CLOSEST WELL VGUWU #59  
API # 30-025-30971

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	36	17.0S	34.0E					Lea

Latitude 32.795804 Longitude -103.514502

**NATURE OF RELEASE**

Type of Release	Spill to Land	Volume of Release	45.8bbbls of Produced Water	Volume Recovered	30.00bbbls of oil
Source of Release	Water Injection Station Pump	Date and Hour of Occurrence	11/1/12 15:15	Date and Hour of Discovery	11/1/12 15:30
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Geoffrey Leking		
By Whom?	David Pagano	Date and Hour	11/2/12 15:30		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

N/A

Describe Cause of Problem and Remedial Action Taken.\*



6" buried injection line leaked underground. Cause of leak will be determined when line is excavated.

Describe Area Affected and Cleanup Action Taken.\*

Spill occurred in the pasture just south of the Battery. On discovery vacuum truck contacted and vacuumed up the standing fluids. Recovered 30.00bbbls and recovered liquids placed into 10K overflow tank to be re-circulated back into the system. Next steps are for the visually contaminated soil to be excavated up to 2 feet and sent off for disposal.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not-relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

**OIL CONSERVATION DIVISION**

Signature:		Approved by Environmental Specialist:	
Printed Name:	David Pagano	Approval Date:	11/5/12
Title:	Health & Environmental Specialist	Expiration Date:	01/07/13
E-mail Address:	david.pagano@chevron.com	Conditions of Approval:	SUBMIT FINAL
Date:	11/02/12	Phone:	505-787-9816
		C-141 IN BY 01/07/13	
		Attached <input type="checkbox"/>	
		IRP-11-12-2861	

\* Attach Additional Sheets If Necessary