

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

**HOBBS OCD** State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

**HOBBS OCD**

MAY 08 2013

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**RECEIVED**

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company	Oxy Permian Ltd.	Contact	CJ Summers
Address	1017 W. Stanolind Rd, Hobbs, NM	Telephone No.	(575) 397-8216
Facility Name	Prize 27 Federal #2	Facility Type	Battery
Surface Owner	BLM	Mineral Owner	
		API No.	30-025-31902

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	27	22S	32E	660'	South	660'	East	Lea

Latitude N 32.35709° Longitude W 103.65617°

**NATURE OF RELEASE**



Type of Release	Produced water	Volume of Release	200 bbls	Volume Recovered	180 bbls
Source of Release	Faulty check valve on the water transfer pump	Date and Hour of Occurrence	04/29/2013	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Jennifer Van Curen-BLM, Jim Amos-BLM and Geoffrey Leking-OCD		
By Whom?	Chancey Summers	Date and Hour	05/01/2013 @ 10:07 am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
A faulty check valve on the water transfer pump caused 200 bbls of produced water to leak onto the ground. 180 bbls of produced water were recovered via vacuum truck and the valve was repaired.

Describe Area Affected and Cleanup Action Taken.\*  
A faulty check valve on the water transfer pump caused 200 bbls of produced water to leak onto the ground. 180 bbls of produced water were recovered via vacuum truck and the valve was repaired. Remediation will be performed in accordance with an approved plan from NMOCD and the BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Chancey Summers	Approved by District Supervisor:  <b>Environmental Specialist</b>	
Title: HES Specialist	Approval Date: 05/09/13	Expiration Date: 07/09/13
E-mail Address: Chancey.Summers@oxy.com	Conditions of Approval: SUBMIT FINAL	Attached <input type="checkbox"/>
Date: 5/8/13 Phone: (575) 397-8216	C-141 BY 07/09/13	LRP-5-13-2919

\* Attach Additional Sheets If Necessary

MAY 20 2013