


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources



Form C-141  
Revised October 10, 2003

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

*JMW* 1322534364 OPERATOR  Initial Report  Final Report

Name of Company - Clayton Williams Energy, Inc. 25706	Contact - Dave Dunlap
Address - 6 Desta Drive, Ste 2100	Telephone No. 575-390-2062
Facility Name - Jenna Coim	Facility Type - SWD Facility
Surface Owner - BLM	Mineral Owner: BLM
Lease No. 25706	

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
I	5	17S	29 E	2110	South	990	East	Eddy Co.

Latitude Longitude API 30-015-29260

**NATURE OF RELEASE**

Type of Release - Produce Water	Volume of Release - 80 Bbls	Volume Recovered - 75 Bbls
Source of Release - SWD facility overflowed	Date and Hour of Occurrence 7-19-13 @ Early morning	Date and Hour of Discovery 7-19-13 @ ~ 0830 Hrs
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? BLM- Jim Amos	
By Whom? Dave Dunlap.... Production Field Foreman	Date and Hour 7-19-13 @ ~ 0900 Hrs	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. Na	

If a Watercourse was Impacted, Describe Fully. \* Na

Describe Cause of Problem and Remedial Action Taken \* The high fluid level automation system failed and allowed tanks to overflow water in to the fire wall (dikes) then on to the road near the battery. We have recovered all free fluids standing at present time which it consisted of ~ 40% rain water and produced water mixed. Also the automation system has been fixed. Delineation/Excavation process will be performed accordingly by BLM requirements once the soils affected become dry and up on meeting at the site with BLM reps.



Describe Area Affected and cleanup Action Taken:

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Luis Gonzalez</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Luis Gonzalez	Approved by District Supervisor: Signed By <i>Mike Bernice</i>	
Title: Environmental Regulatory Administrator	Approval Date: <b>AUG 13 2013</b>	Expiration Date:
E-mail Address: lgonzalez@claytonwilliams.com	Conditions of Approval: Remediation per OCD Rule & Guidelines, & like approval by BLM. <b>SUBMIT REMEDIATION</b>	Attached <input type="checkbox"/>
Date: July 22, 2013 Phone: 432-661-4708	PROPOSAL NO LATER THAN: <b>September 13, 2013</b>	

\* Attach Additional Sheets If Necessary

2RP-1816



**R.T. Hicks Consultants, Ltd**  
 901 Rio Grande Blvd NW Suite F-142  
 Albuquerque, NM 87104  
 Ph: 505.266.5004

**Air Photo and Groundwater Elevation**  
**Clayton Williams - Jenna Com 01**

**Figure 1**  
**August 2013**

**Bratcher, Mike, EMNRD**

---

**From:** Randall Hicks <r@rthicksconsult.com>  
**Sent:** Tuesday, August 13, 2013 5:54 AM  
**To:** Bratcher, Mike, EMNRD  
**Cc:** 'Gonzalez, Luis'; ericgarcia62@hotmail.com  
**Subject:** FW: Jenna com.. NMCOD-BLM CI41 SPILL REPORT  
**Attachments:** Jenna com.. NMCOD-BLM CI41 SPILL REPORT.doc; JennaGW Elev - Photo.pdf

Mike

We can find no written record of NMOCD notification of this release. Out of an abundance of caution, Luis asked that make sure you have the attached C-141 form, which was sent to BLM on July 22. We have a written record that immediate verbal notice was given to Jim Amos (see email string below), as Federal minerals were extracted when the well was a producer and the SWD serves wells with Federal minerals. We believe the surface owner is the State of NM.

OCD, BLM and the State Land Office can expect a final report within the next few weeks. The report will describe the following events and propose a remedy

1. Excavation of all soil with visible hydrocarbon staining to a lined area on the location
2. Repair of the system
3. Sampling and analysis of the in-place soil within the excavation footprint (conducted by me last week)
4. Sampling and analysis of the stockpiled soil

The attached map shows the location of the site and groundwater elevations determined from measurements of a number of wells in the area between Loco Hills and Artesia. The groundwater elevation beneath the site is about 3525 and the ground elevation is 3604 – thus the depth to water in this area is about 80 feet.

I think this gives you what you need for now.

Randall T. Hicks  
505-266-5004 (office)  
505-238-9515 (cell and best number to use)

---

**From:** Gonzalez, Luis  
**Sent:** Monday, July 22, 2013 2:33 PM  
**To:** 'Amos, James'  
**Subject:** Jenna com.. NMCOD-BLM CI41 SPILL REPORT

Thank you very much Jim!!

**Luis Gonzalez**  
*Environmental Regulatory Adm.*  
*Clayton Williams Energy, Inc.*  
*Southwest Royalties, Inc.*  
6 Desta Drive, Suite 2100  
Midland, TX 79705  
432-661-4708